

Surveyor:

ADT

DOI:

ASSIGNMENT

20/09/18

Date / Time:

19/9/18

Registered in Mexico:

Pre-assign / CCU / FTE

YN 4265 G



Insured Vehicle No.

Name of Insured

BABA PRODUCTS (S) P/L

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

Nature of Accident:

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

DHANAPAL MOORTHY

Driver Tel No.:

87372409 (VL: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OLD UPPER THAMSON RD

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chunni



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler: Typist:

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

IFNO or B 28, Ass. Lia:

Repair Cost:

S\$ 12840.00

Loss of Rental (LOR):

S\$ 1265.00

11

days x 115.00

Loss of Use (LOU):

S\$ 550.00

S\$ 50

x 11

days

Loss of Income (LOI):

S\$

(\$ x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$ 14657.00

Global Sum S\$:

14000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 14000.00

Name 1:

Chunni Motor Work Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ASSIGNMENT

COR Sept 2024

8HD 3578 P

Yr Rept: 2016 / Sept.

Model:

Type: M/Gar / M/Cycle / Bus / Van / Lorry / ☒ Private Motor /

Truck / Trailer or

Make:

Hyundai I40

CC: 1685

Colour:

Blue

ACC: Insured / STD / TH / HA

Sp. Number:

232909

Traffic: Insured / STD / TH / HA

Eng/Plt:

D4FDGU673190

Chassis:

KMHLB41UMGU093667

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Mod: ☒ S/Rth / STD / Rth or

Tyre Size:

F:

205/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Blanko

Front:

Rear:

R/Dat:

S

mm

R/Dat:

S

mm

L/Dat:

S

mm

L/Dat:

S

mm

D.O.A:

7/09/2018

D.O.A:

20/09/2018

Survey held at

Chunni AMK

Gen. of Damages: Fit / Rear / Q/S / N/S / U/C / Rooftop or

N/S Front 4 4/3 Body 4 N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Form:

Date:

Expected Cost:

OD / TP / WS / TP RES / OD RES / EVA / RV / MV

Is report Vehicle No:

at Workshop info:

id:

Insured:

Policy No:

Claims No:

Claim Request:

Excess:

(Client's Record)

Make of Vols:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or ~~Est~~ of Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Done:

Consistent? Yes or No

Est. Repairs:

10

days

Res:

Yes or No

Lump Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Validator: IN / OUT

Date / Time

Action / Instruction

BQ YN 4265 G

15/11/18

Insured + 12,000/- with 10 days 8 ✓

(Red) - 19918-44
45/1)

Over (Date, 1-5) Price for



Prel. Report

1)



Final Report

(Date/Time, 1-5) Return for

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

5 + 10, 11

Phone

Office

Report Format :

Lump Sum / L.B.: (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQI18017187/Dwa3

Date: 26.09.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 3578P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.09.2018 at the premises of M/s Chunni Motor Work Pte Ltd - Ang Mo Kio have the following to report:-

Workshop Estimate Amount	: S\$	21,918.44
Revised Estimate Amount	: S\$	14,655.30
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	14,655.30
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 days

Yours faithfully,

ANG BRYAN TANI
Licensed Appraiser

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

To Swamy by LKK

VEHICLE NO : SHD 3578P

DATE : 17.09.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Door (LH) <i>Replaced</i>			\$ 2,256.40	✓
	Front Door Gear / Regulator (LH) <i>HH</i>			\$ 250.60	X
	Front Door Mirror Assy (LH) <i>CHIC</i>			\$ 670.00	✓
	Front Door Power Motor, LH <i>HH</i>			\$ 172.70	X
	Door Centre Pillar Outer (LH) <i>Replaced</i>			\$ 2,527.80	✓
	Rear Door (LH) <i>reg</i>			\$ 2,201.10	X
	Front Wheel Rim (LH) <i>distorted</i>			\$ 325.30	✓
	Front Wheel Hub Cap (LH) <i>HH</i>			\$ 107.10	✓
	Front Wheel Bearing <i>2 Done</i>			\$ 150.90	✓
	Front Shock Absorber (Assy) (LH) <i>distorted</i>			\$ 342.20	✓
	Front Shock Absorber Mounting (LH) <i>HH</i>			\$ 108.80	X
	Front Drive Shaft (LH) <i>distorted</i>			\$ 1,030.80	✓
	Rack & Pinion Assy <i>Done</i>			\$ 969.60	✓
	STG Tie End <i>distorted</i>			\$ 62.60	✓
	Front Suspension Lower Arm (LH) <i>distorted</i>		9524.00	\$ 529.30	✓
	Knuckle Arm (LH) <i>distorted</i>		7619.20	\$ 552.00	✓
	ABS Sensor <i>HH</i>			\$ 234.00	X
	SUB TOTAL			\$ 12,491.20	
	LESS 20%			\$ 2,498.24	
	DISCOUNTED TOTAL			\$ 9,992.96	
	Front Door Comfort Logo (LH) <i>HCC</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (LH) <i>HCC</i>			\$ 100.00	Nett ✓
	Rear Door Advertisement Logo (LH) <i>HCC</i>		355.00	\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>HCC</i>			\$ 80.00	Nett ✓
	Front Tyre (LH) <i>HH</i>			\$ 216.00	Nett X
				\$ 571.00	
	Rear Fender With Housing (LH) <i>Replaced</i>			\$ 4,736.80	✓
	Rear Fender Inner Lining (LH) <i>HH</i>			\$ 169.30	X
	Rear Windscreen Moulding <i>HCC</i>			\$ 28.30	✓
	Rear Tyre Rim (LH) <i>HH photo</i>			\$ 325.30	X
	Rear Wheel Hup-Cap (LH/RH) <i>HH</i>			\$ 107.10	X
	Rear Wheelbearing ING & Hub <i>HH photo Done</i>			\$ 362.00	✓
	Rear Trailing Arm (LH) <i>HH photo</i>			\$ 192.00	X
	Rear Assist (LH) <i>HH</i>			\$ 145.70	X
	Rear Shock Absorber (LH) <i>HH</i>			\$ 276.30	X
	Rear Shock Absorber Mounting (LH) <i>HH</i>		6181.10	\$ 81.30	X
	Rear Upper Arm (LH) <i>HH photo distorted</i>			\$ 154.60	✓
	Rear Lower Arm (LH) <i>HH photo distorted</i>		4944.88	\$ 353.80	✓
	Rear Knuckle Arm (LH) <i>HH photo distorted</i>			\$ 545.60	✓
	SUB TOTAL			\$ 7,478.10	
	LESS 20%			\$ 1,495.62	
	DISCOUNTED TOTAL			\$ 5,982.48	

SHD 3578P

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Windscreen Sealant <i>N/C</i>			\$ 46.00	Nett ✓
	Rear Tyre (LH) <i>N/C</i>		46.00	\$ 216.00	Nett X
				\$ 262.00	
	Labour Charge				800.00
	Panel Beating			\$ 2,000.00	800
	Spray Painting Charge			\$ 1,400.00	700/-
	Wiring Charge			\$ 50.00	N/C
	Tuff Kote			\$ 100.00	40/-
	Towing Charge			\$ 50.00	N/C
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00	150/-
	Transfer of Door		\$ 120.00	\$ 240.00	60/-
	Remove/Refix Undercarriage (RR)			\$ 200.00	150/-
	Four Wheel Alignment			\$ 120.00	60/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	N/C
			2020.00 2120.00		
	TOTAL LABOUR			\$ 5,110.00	
	ESTIMATE TOTAL			\$ 21,918.44	
				14985.08	
				15085.08	
				45 12,000/-	
	20/09/2018 @ 1200hrs N/C Actual 21/09/2018 10 days <i>YH</i> 2 KK data <i>9</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHD 3578 P
Technician:
Mileage: 232909
Time Printed 20.9.18 1:11 PM

HYUNDAI i40

Front : Left

Actual	BEFORE	Specified Range
0°33'		-3°00' 3°00'
4°05'		-0°19' 5°41'
-22°35'		-1°30' 1°30'
19°20'		
19°53'		

Camber

Caster

Toe

SAI

Included Angle

Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-1°59'		-3°00' 3°00'
4°15'		-0°19' 5°41'
-0°47'		-1°30' 1°30'
16°48'		
14°49'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	2°32'		-3°00' 3°00'
Cross Caster	-0°09'		-3°00' 3°00'
Cross SAI	2°32'		-3°00' 3°00'
Total Toe	-23°22'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
9°28'		-3°30' 2°30'
19°44'		-1°30' 1°30'

Camber

Toe

Rear : Right

Actual	BEFORE	Specified Range
0°35'		-3°30' 2°30'
0°32'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	8°53'		-3°00' 3°00'
Total Toe	20°16'		-3°00' 3°00'
Thrust Angle	9°36'		-3°00' 3°00'

Nivitha (LKK Auto)

From: Justin Wong <justin.wong@eqinsurance.com.sg>
Sent: Wednesday, 19 September 2018 2:57 PM
To: assignments
Cc: Survey
Subject: FW: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18
Attachments: OI GIA - YN4265G.PDF; TP GIA - SHD3578P.PDF

3.22pm @ 19/9/18
vehicle in
person @ Lynn
arrange on 20/9/18

Dear LKK,

Kindly arrange for PRS and proceed with DS if liability is clear.

Regards,
Justin Wong
Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Wednesday, September 19, 2018 2:40 PM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Subject: Re: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

Dear Sir,

We agree to appoint LKK Auto Consultants P/L

Thank you

Regards,
Chunni Motor Work P/L

On Wed, Sep 19, 2018 at 11:31 AM, Justin Wong <justin.wong@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Sir/Mdm,

We refer to your email on PRI dated 18/09/2018.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee

9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070 Contact Person: Jasmine
11) Infiniti Appraisal Service Tel: 9009 9001 , 96684818 Fax: 6458 7432 Contact Person: Cedric / Edward	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,
Justin Wong
 Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
 did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify i

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Tuesday, September 18, 2018 10:00 AM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06, Tel : 6483 6016.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162.

Thank you for your kind assistance.

Your Ref : YN 4265G
Our Ref : SHD 3578P

Lim Jit Seng c/o
CHUNNI MOTOR WORK PTE LTD
Blk 10 Ang Mo Kio Industrial Park 2A
#03-19 AMK AutoPoint
Singapore 568047

Date: 20/11/18

The Motor Claims Department
EQ Insurance Company Ltd
5 Maxwell Road
A17-00 Tower Block
MND Complex
Singapore 69110
Dear Sir / Madam,

WITHOUT PREJUDICE

RE: ACCIDENT INVOLVING SHD 3578P / YN 4265G On 17.09.2018

ALONG Upper Thomson Rd Twds Ang Mo Kio Ave 1

I am the owner/hirer of motor vehicle/taxi, SHD 3578P, which was involved in the above-mentioned accident.

The motor vehicle/taxi was surveyed by your appointed appraiser at the premises of M/S CHUNNI MOTOR WORK PTE LTD. The accident was caused by your insured's negligent driving and or management of his vehicle. Therefore, I am claiming damages and losses sustained by me against you in connection with the accident based on the appraiser's recommendation.

Our claim is as follows:

1) Cost of Repair	SS	12,840.00
2) Loss of Rental	SS	1,495.00 (\$115 x 13 DAYS)
3) Loss of Income	SS	650.00 (\$50 x 13 DAYS)
4) GIA Report Fee	SS	
5) LTA Search Fee	SS	2.00
6) Survey Report Fee	SS	
	SS	<u>14,987.00</u>

We enclose herewith the following relevant supporting documents :

- a) Authorisation Letter
- b) Final repair bill(s)
- c) LTA Search
- d) GIA report(s)
- e) Insurance Certificate

Kindly look into the matter and revert as soon as possible. Thank you.

Yours faithfully

Lim Jit Seng



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/EQ1180117187/Dwa3

17 December 2018

Baba Products (S) Pte Ltd
705 Sims Dr
Singapore 387384

Dear Sir/Madam,

ACCIDENT INVOLVING YN 4265G AND SHD 3578P ON 17/09/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

LETTER OF AUTHORITY

To Whom It May Concern :

ACCIDENT INVOLVING SHD 3578P / YN 4265G

ALONG Upper Thomson Rd Twds Ang Mo Kio Ave 1 ON 17.09.2018

I, Lim Jit Seng, NRIC NO. S 2530420I of

Blk 412 Serangoon Central # 08-341 (S) 550412

Owner/hirer of motor vehicle Registration No SHD 3578P, insured by

Ms First Capital Insurance Ltd under Policy No. D-18088936MFSH

do hereby authorize M/s **Chunni Motor Work Pte Ltd** as my authorized representative to write,

negotiate and settle claim on my behalf in my claim against the owner and/or Motor Vehicle

Registration No. YN 4265G in respect of the above mentioned accident. I also

hereby authorize that the agreed settlement sum (cost of repair, loss of use, earnings and rental,

Survey report fee, LTA fee & GIA report fee) be made in favour of my representative, M/s

Chunni Motor Work Pte Ltd and that the said payment be forwarded to them as full and final

discharge of my claim.

Dated : 17.09.2018

Signature : Lim Jit Seng
(Company's chop if necessary)

CHUNNI MOTOR WORK
PTE LTD

LIM JIT SENG APT BLK 412 SERANGOON CENTRAL #08-341 SINGAPORE 550412	VEHICLE NO	DATE
	SHD 3578 P	16.11.2018
	MAKE	INVOICE NO
	HYUNDAI	8737
	MODEL	ACC DATE/TIME
	I40	17.09.2018 @ 13:20 HRS

Cost of Repair \$ 12,000.00

Sub-total \$ 12,000.00

Add : 7 % - GST \$ 840.00

Total \$ 12,840.00

(SINGAPORE DOLLARS: TWELVE THOUSAND EIGHT HUNDRED AND FORTY ONLY)



Our Ref: CT18090482

Date: 19 September 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	17/09/2018 @ 13:20 hrs
ALONG	UPP THOMSON RD TWDS AMK AVE 1
INVOLVING	YN4265G

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHD3578P** (the "Taxi"). The Taxi was hired to **LIM JIT SENG IC NO S25304201** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$115.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

SHD 3578P

OPERATED (TIME)	DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)	
					FROM	TO
2250	17.09.2018	Lim Jit Seng	Accident		15:00	4:45
2300	29.09.2018	Lim Jit Seng	Repair		unhol	09:30
0050						
2325						
0010						
0050						
2310						
0040						
1530						

Invoice

<https://www.giarmc.org.sg/claims/index.cfm?fusebox=MTRsas&fu...>

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-143340

Date of Request: 17/09/2018

Your Ref No: Online Purchase

Soon Hock Motor Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date: 17/09/2018

Enquiry By: Chris Lim Gan Koon

TP Vehicle No: YN4265G

Accident Date: 17/09/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YN4265G	EQ Insurance Company Ltd	20/11/2017-19/11/2018	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Invoice

<https://www.giarmc.org.sg/claims/index.cfm?fusebox=MTRsas&fu...>

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-18-143340

Date of Request: 17/09/2018

Your Ref No: Online Purchase

Soon Hock Motor Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date 17/09/2018
Enquiry By Chris Lim Gan Koon
TP Vehicle No. YN4265G
Accident Date 17/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Vivian Lau (LKKAUTO)

From: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Sent: Wednesday, 26 June, 2019 4:38 PM
To: Vivian Lau (LKKAUTO)
Cc: Admin A
Subject: EQ REF: DM18HO02476/WY, Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

Dear Vivian,

We refer to your email below.

We note that vehicle was returned to hirer on 29/9/2018 at 9.30am and repairer delay PRI for 1 more day.

Hence, LOI/LOR should be based on 11 days instead.

Mandate: \$14,547.00

Thank you.


Regards,

Tan Wei Yin
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 64969882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Vivian Lau (LKKAUTO) [mailto:vivianlau@lkkauto.com]
Sent: Monday, June 24, 2019 4:30 PM
To: Joel Goh <joel.goh@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: RE: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

EQI ref: TBA
LKK REF: CC4/EQI18017187/Dwa3

Dear Joel,

Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

We refer to the above matter

This accident happened on an abrupt lane change which probably caused the accident to happen.

We have surveyed the vehicle, and relevant supporting documents were enclosed for your perusal.

We seek your approval to offer to TP repairer **Chunni Motor Work Pte Ltd** is as follows:

	Amount Claimed	Amount Revised
1. Cost of Repair (+GST)	S\$ 23,452.74	S\$ 12,840.00
2. Loss of USE (\$115.00 x 13 days)	S\$ 1,495.00	S\$ 1,495.00 (Surveyor recommend 10 days)
3. Loss Of Rental (\$ 40.00 x 13day)	S\$ 650.00	S\$ 650.00
4. LTA Search	S\$ 2.00	S\$ 2.00
	S\$ 25,599.74	S\$ 14,987.00

Amount of claim at liability 100% S\$ 14,987.00

For your approval please

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Monday, 1 October, 2018 3:49 PM

To: 'Justin Wong' <justin.wong@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Subject: RE: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

EQI ref: TBA

LKK REF: CC4/EQI18017187/Dwa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SHD 3578P

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Kindly take note that the case handler in-charge Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 19 September, 2018 3:26 PM

To: 'Justin Wong' <justin.wong@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 20/09/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Justin Wong [<mailto:justin.wong@eqinsurance.com.sg>]

Sent: Wednesday, 19 September 2018 2:57 PM

To: assignments <assignments@lkkauto.com>

Cc: Survey <survey@jpknights.com>

Subject: FW: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

Dear LKK,

Kindly arrange for PRS and proceed with DS if liability is clear.

Regards,

Justin Wong

Executive | Claims

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify i

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]
Sent: Wednesday, September 19, 2018 2:40 PM
To: Justin Wong <justin.wong@eqinsurance.com.sg>
Subject: Re: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

Dear Sir,

We agree to appoint LKK Auto Consultants P/L

Thank you

Regards,
Chunni Motor Work P/L

On Wed, Sep 19, 2018 at 11:31 AM, Justin Wong <justin.wong@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Sir/Mdm,

We refer to your email on PRI dated 18/09/2018.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd	4) Priority Services

L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070 Contact Person: Jasmine
11) Infiniti Appraisal Service Tel: 9009 9001 , 96684818 Fax: 6458 7432 Contact Person: Cedric / Edward	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,
Justin Wong
Executive | Claims

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Tuesday, September 18, 2018 10:00 AM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: Accident involving veh no: SHD 3578P & YN 4265G on 17.09.18

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey in AMK Autopoint, Soon Hock Motor, #01-05/06, Tel : 6483 6016.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162.

Thank you for your kind assistance.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 03/07/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YN 4265G (Insd Veh)	Your Ref. No. : DM18HO02476/WY
	SHD 3578P (TP Veh)	Our Ref. No. : CC4/EQI18017187/Dwa3q2
Date of Accident	17/9/2018	

Liability	100%	
Final Repair Cost	: \$ 12,840.00	
Loss of Income	: \$ 550.00	11 days
Rental (If any)	: \$ 1,265.00	11 days
Others:	: \$ 2.00	
	: \$	
	14,657.00	
Final Settlement Sum	: \$ 14,000.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	CHUNNI MOTOR WORK PTE LTD	: \$ 14,000.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ118017187/Dwa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 03-07-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 4265G	Veh. Inspected	SHD 3578P	
Policy No.	DMCPHQ17-006430	Coverage (\$)	0.00	
Claim No.	DM18HO02476/WY	Excess (\$)	0.00	
Assign From	JUSTIN	Assign Date	19/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU093667	Colour	BLUE	
Odometer	232909	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT & N/S REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/09/2018	Inspection Date	20/09/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3578P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR (LH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR GEAR /REGULATOR (LH)	NOT NECESSARY	250.60	-
1	FRONT DOOR MIRROR ASSY (LH)	CRACKED	670.00	670.00
1	FRONT DOOR POWER MOTOR ,LH	NOT NECESSARY	172.70	-
1	DOOR CENTRE PILLAR OUTER (LH)	DENTED	2,527.80	2,527.80
1	REAR DOOR (LH)	TO REPAIR SEE LABOUR	2,201.10	-
1	FRONT WHEEL RIM (LH)	DISTORTED	325.30	325.30
1	FRONT WHEEL HUB CAP (LH)	BENT	107.10	107.10
1	FRONT WHEEL BEARING	DAMAGED	150.90	150.90
1	FRONT SHOCK ABSORBER (ASSY) (LH)	DISTORTED	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	969.60	969.60
1	STG TIE END	DISTORTED	62.60	62.60
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ABS SENSOR	NOT NECESSARY	234.00	-
1	REAR FENDER WITH HOUSING (LH)	DENTED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (LH)	NOT NECESSARY	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR TYRE RIM (LH)	NOT NECESSARY	325.30	-
2	REAR WHEEL HUP-CAP (LH/RH)	NOT NECESSARY	107.10	-
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (LH)	NOT NECESSARY	192.00	-
1	REAR ASSIST (LH)	NOT NECESSARY	145.70	-
1	REAR SHOCK ABSORBER (LH)	NOT NECESSARY	276.30	-
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	81.30	-
1	REAR UPPER ARM (LH)	DISTORTED	154.60	154.60
1	REAR LOWER ARM (LH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60

Report Ref No. CC4/EQ18017187/Dwa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,993.86	-3,141.02
			15,975.44	12,564.08
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COMFORT LOGO (LH) (SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOOG (LH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	FRONT TYRE (LH) (SN)	NOT NECESSARY	216.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR TYRE (LH) (SN)	NOT NECESSARY	216.00	-
			833.00	401.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR (LH).		2,000.00	800.00
	SPRAY PAINTING CHARGE.		1,400.00	700.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR .		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	TRANSFER OF DOOR .		240.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			-	-
			-	-
			-	-
			5,110.00	2,120.00
GRAND TOTAL			21,918.44	15,085.08

Report Ref No. CC4/EQ118017187/Dwa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,000.00
---	--	--	--	-----------

Report Ref No. CC4/EQ118017187/Dwa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Monday, 8 July 2019 12:03 PM
To: 'eqiprs@eqinsurance.com.sg'
Cc: 'vivianlau@lkkauto.com'
Subject: TP Direct Settlement - Accident Involving YN 4265G (OI) and SHD 3578P (TP) on 17/09/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933