

CHUNNI MOTOR WORK PTE LTD

To Survey by LKK

REPAIR ESTIMATE*

VEHICLE NO : SHD 3578P

DATE : 17.09.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (LH) <i>Dented</i>			\$ 2,256.40 ✓
	Front Door Gear / Regulator (LH) <i>HH</i>			\$ 250.60 X
	Front Door Mirror Assy (LH) <i>Chack</i>			\$ 670.00 ✓
	Front Door Power Motor, LH <i>HH</i>			\$ 172.70 X
	Door Centre Pillar Outer (LH) <i>Dented</i>			\$ 2,527.80 X ✓
	Rear Door (LH) <i>reg</i>			\$ 2,201.10 X
	Front Wheel Rim (LH) <i>2 dented</i>			\$ 325.30 2 ✓
	Front Wheel Hub Cap (LH) <i>1st</i>			\$ 107.10 ✓
	Front Wheel Bearing <i>2 D-m</i>			\$ 150.90 2 ✓
	Front Shock Absorber (Assy) (LH) <i>2 dented</i>			\$ 342.20 2 ✓
	Front Shock Absorber Mounting (LH) <i>HH</i>			\$ 108.80 X
	Front Drive Shaft (LH) <i>2 dented</i>			\$ 1,030.80 2 ✓
	Rack & Pinion Assy <i>2 D-m</i>			\$ 969.60 2 ✓
	STG Tie End <i>2 dented</i>			\$ 62.60 2 ✓
	Front Suspension Lower Arm (LH) <i>2 dented</i>			\$ 529.30 2 ✓
	Knuckle Arm (LH) <i>2 dented</i>			\$ 552.00 2 ✓
	ABS Sensor <i>HH</i>			\$ 234.00 X
	SUB TOTAL			\$ 12,491.20
	LESS 20%			\$ 2,498.24
	DISCOUNTED TOTAL			\$ 9,992.96
	Front Door Comfort Logo (LH) <i>HKL</i>			\$ 75.00 Nett ✓
	Front Door Advertisement Logo (LH) <i>HKL</i>			\$ 100.00 Nett ✓
	Rear Door Advertisement Logo (LH) <i>HKL</i>			\$ 100.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>HKL</i>			\$ 80.00 Nett ✓
	Front Tyre (LH) <i>HH</i>			\$ 216.00 Nett X
				\$ 571.00
	Rear Fender With Housing (LH) <i>Dented</i>			\$ 4,736.80 ✓ photo
	Rear Fender Inner Lining (LH) <i>HH</i>			\$ 169.30 X
	Rear Windscreen Moulding <i>HKL</i>			\$ 28.30 ✓
	Rear Tyre Rim (LH) <i>HH photo</i>			\$ 325.30 X
	Rear Wheel Hup-Cap (LH/RH) <i>HH</i>			\$ 107.10 X
	Rear Wheelbearing IN & Hub <i>HH photo</i>			\$ 362.00 X
	Rear Trailing Arm (LH) <i>HH photo</i>			\$ 192.00 X
	Rear Assist (LH) <i>HH</i>			\$ 145.70 X
	Rear Shock Absorber (LH) <i>HH</i>			\$ 276.30 X
	Rear Shock Absorber Mounting (LH) <i>HH</i>			\$ 81.30 X
	Rear Upper Arm (LH) <i>HH photo</i>			\$ 154.60 X
	Rear Lower Arm (LH) <i>HH photo</i>			\$ 353.80 X
	Rear Knuckle Arm (LH) <i>HH photo</i>			\$ 545.60 X
	SUB TOTAL			\$ 7,478.10
	LESS 20%			\$ 1,495.62
	DISCOUNTED TOTAL			\$ 5,982.48

SHD 3578P

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Windscreen Sealant <i>Nuc</i>			\$ 46.00	Nett ✓
	Rear Tyre (LH) <i>NH</i>			\$ 216.00	Nett X
				\$ 262.00	
	Labour Charge				
	Panel Beating			\$ 2,000.00	700/-
	Spray Painting Charge			\$ 1,400.00	700/-
	Wiring Charge			\$ 50.00	NH
	Tuff Kote			\$ 100.00	40/-
	Towing Charge			\$ 50.00	NH
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00	150/-
	Transfer of Door	\$	120.00	\$ 240.00	60/-
	Remove/Refix Undercarriage (RR)			\$ 200.00	NH
	Four Wheel Alignment			\$ 120.00	60/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	NH
	TOTAL LABOUR			\$ 5,110.00	
	ESTIMATE TOTAL			\$ 21,918.44	
20/09/2018 @ 1200hrs hlt Antml 2/5m 10 days <i>[Signature]</i> 2kk dtd <i>[Signature]</i>					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					