

Adrian LK. AXA



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP AXA
Xiao Tong

JHMRC1890HC200802

20/09/2018

Accident date: 20/09/2018

Estimated repair cost for vehicle no: SLN398L HONDA ODYSSEY 2.4 A '17

CHASSIS: JHMRC1890HC200802

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Rim <i>ct</i>		\$1,250.00 600(SN)
2	1	Front R/H Tyre <i>NEW</i>		\$550.00 x
3	1	Front R/H Lower Arm <i>Bent</i>		\$623.90 ✓
4	1	Front R/H Knuckle Arm <i>NEW</i>		\$322.90 ✓
5	1	Front R/H Knuckle Arm Bearing <i>New</i>		\$181.40 ✓
6	1	Front R/H Shock Absorber <i>NEW</i>		\$344.60 x
7	1	Front R/H Drive Shaft <i>2nd</i>		\$1,008.90 x
8	1	Front Steering Rack <i>1st</i>		\$3,979.60 x
9	1	Front R/H Head Lamp <i>ct</i>		\$2,237.70 ✓
10	1	Front R/H Head Lamp Lower Bracket <i>NEW</i>		\$39.50 x
11	1	Front Bumper <i>Repair</i>		\$686.30 x
12	10	Front Bumper Clip <i>2nd</i>	\$6.50	\$65.00 x
13	1	Front R/H Bumper Side Retainer <i>NEW</i>		\$29.00 x
14	1	Front R/H Fender <i>Repair</i>		\$537.80 x
15	1	Front R/H Door <i>Repair</i>		\$877.70 x
16	1	Front R/H Door Side Mirror Assy <i>Damaged</i>		\$1,201.70 ✓
17	1	Front R/H Door Side Mirror Cover <i>Repair</i>		\$119.00 x
18	1	Front R/H Door Side Mirror Lower Cover <i>Missing</i>		\$64.70 ✓
19	1	Front R/H Door Lower Protector <i>Replaced</i>		\$311.90 ✓
20	10	Front R/H Door Lower Protector Clip <i>NEW</i>	\$6.50	\$65.00 10
21	2	Front R/H Door Frame Sticker <i>NEW</i>	\$48.10	\$96.20 x
			Subtotal :-	<u>\$14,592.80</u>

4635.30

3705.04 S.N. 600

Labour charges

To remove & refit front R/H undercarriage	\$380.00 220
To remove & refit R/H drive shaft & steering rack	\$450.00 X
To remove & refit front R/H door, glass, lockl, trim board, rubber & frame sticker	\$220.00 X.
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
Towing fee	\$100.00 X
Tuff kote	130 \$150.00 X
Panel beating	\$1,400.00 450
Spray painting	\$1,400.00 690

Subtotal :- \$4,350.00

Total:- \$18,942.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claim is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

total: 5735.04
L/S: A.B.K.
05 Days
A.B.K.



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	CHEW MOTOR	DATE	Sep 20, 2018 2:39:19 PM
LICENSE NO.	SLN 398 L		
MILEAGE	20366		
REFERENCE	CUSTOM	MODEL	HONDA ODYSSEY (RCI

Front Wheel	SPECS	DIAGNOSIS	ADJUSTMEN
	min prv max Δ	L total R Δ	L total R Δ
TOTAL TOE	-1.00 0.00 1.00	5.20	5.00
PARTIAL TOE	-0.50 0.00 0.50	-1.60 6.80	0.50 4.50
SET BACK	---	-0°28"	-0°28"
CAMBER	-0°44" 0°00" 0°44"	-0°12" -1°30" 1°16"	-0°10" -1°32" 1°20"
CASTER	4°30" 5°30" 6°30"	5°06" 5°18" 0°12"	5°06" 5°18" 0°12"
KING-PIN	---	12°22" 12°18" 0°04"	12°22" 12°18" 0°04"
INCL ANGLE	---	12°10" 10°48"	12°12" 10°46"
Toe-out on turns	---	---	---
STEERING IN	---	---	---
STEERING OUT	---	---	---

Rear Wheel	SPECS	DIAGNOSIS	ADJUSTMEN
	min prv max Δ	L total R Δ	L total R Δ
TOTAL TOE	---	2.60	2.60
PARTIAL TOE	---	1.30 1.30	1.30 1.30
SET BACK	---	0°00"	0°00"
CAMBER	---	-1°36" -1°58" 0°22"	-1°36" -1°58" 0°22"
THRUST ANGLE	-0°08" 0.00 0°08"	0°00"	0°00"