

60 Woodlands Industrial Park E4 Singapore 757705 Tel: 65 6362 3422 Fax: 65 6368 7420

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre	re
Reg. No. : SHB 1018M Ref. No. TAX	9 / 18 / 2050
Make / Model : PRIUS	Reg. Date : 12/09/2014
Name of Driver : LEE YONG TENG	
Date/Time of Accident : 12/09/2018 17:46	The damages on the Taxi are as
Surveyer is Required ? YES / NO	indicated in the following diagram :
If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)	Front
Taxi is Towed Back ? YES / NO	
Replacement Taxi Issued ? YES / NO	
Accident Repair Job Card No. : 24097919	
Special Instruction to ARC, if any :	
	Rear
Signed : Date	
Section B - To be Completed by Service Advisor, Accident Repair Centre	
Chassis No : JTDKN36U205749097 Mileage	:
Date Prepared : Repair C	Completed date/time:
Summary of Repair Estimates	
Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges : \$ 1014.00	\$
Total Spray Painting Charges : \$ 1314.00	\$
Total Material Charges : \$ 2185.44	\$
Other Charges : \$ 580.00	\$
TOTAL : \$ 5093.44	\$ ()
	[4] days
Signature : Prepared by: FOO 14/09/2018 10:30	Adjusted by:
14/03/2010 10:30	
Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Complete	etion of Repair
QN No Invoice No	Invoice Date
Signed : Date	1 1

Ref. No. TAX 9 / 18 / 2050

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1014.00	600
Total Labour	\$ 1014.00	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO RESPRAY FRONT DOOR LH	378.00	200		
TO RESPRAY ROCKER PANEL MOULDING	180.00	80		
TO RESRAY REAR DOOR LH	378.00	200		
TO RESPRAY REAR FENDER LH	378.00	200		
Total Spray Painting & Panel Beating	\$ 1314.00	\$		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Quotation from ARC	Adjusted by Surveyor, if applicable
80.00	20
1,00.00	40
240.00	50
100.00	× nn
60.00	×nn
\$ 580.00	\$
	80:00 1,00:00 240:00 100:00

Ref.	No.	TAX	9	1	18	/	2050
101.	140.	17 17	-				

Part 4 - Spare Parts / Material Usage

Reservation No :

Page ()

	To be completed by Service	Adviso	or, ARC			1	Surveyor /
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (x Repair (R) Replace (/
67002-47070	DOOR FRT/LH	1	\$894.40	25%	\$670.80	1	DO
	STICKER DECAL SMRT (DOOR)	1	\$60.00	0%	\$60.00	1	/ ne (
67004-47080	DOOR RR/LH	1	\$954.50	25%	\$715.88	1	×R
68760-20122	HINGE UPPER LHR, DOOR	1	\$81.70	25%	\$61.28	1	?
68780-52031	HINGE LOWER LHR, DOOR	1	\$72.20	25%	\$54.15	1	2
75852-47900	MOULDING BODY, LH	1	\$673.60	25%	\$505.20	1	xR
61602-47091	FENDER RR/LH	1	\$766.80	25%	\$575.10	1	XR
	STICKER SMRT LOGO	1	\$7.80	0%	\$7.80	/	TARC
	STICKER DECAL 6555 8888	1	\$21.60	0%	\$21.60	1	/nks
	PIXEL STICKER	1	\$60.00	0%	\$60.00	1	TORC
				0%	\$0.00		
	NAZ LKK			0%	\$0.00		
	14/9/18 1530			0%	\$0.00		
	45			0%	\$0.00		
	40 Mys			0%	\$0.00		
	AFTER REPORT PHOTO		*.	0%	\$0.00		
		_		0%	\$0.00		
	LKK Auto Consultants hence notify the Repairer of the following:			0%	\$0.00		
	To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation			0%	\$0.00		
	Third party survey is on a "Without Prejudice" basis Mo illegal modification(s) is allowed.			0%	\$0.00		
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			0%	\$0.00		
	Acknowledged by Repairer			0%	\$0.00		
	Signature: Date:			0%	\$0.00		
		and .		0%	\$0.00		
				0%	\$0.00		
TOTAL MATERIALS LUMP SUM 20%					\$2,185.4	4	