Date/Time 21/1/18/09-50am
Insured: FBF 4141U
01-582 81123936
m No: 570688
icess.
D.O.A. 15 09 2018
H.O.D. Endorsement.  Vehicle IN OUT
3/Ggh3d1 DOA: 18/12/15

Smeyor	REF: NO	319	
	, , , , , , , , , , , , , , , , , , , ,	ASSIGNMENT	
rom:	Date:	Veh No. YL83328	E Yr Regn. Oct , 04
Estimated Cost:		Type: M.Car / M.Cycle / Bus / Van	/ \
DIFFWSI	TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
o Inspect Vehi		Make: # Toyots	Pyng = 2986
t Workshop m/	s Here Motor	Make: # Toyota Colour Silver	A/C: Insured / Std / NI / NA
f	nerg 1000	Sp. Reading \$35/85	
nsured:		Eng/No:	
Policy No.		C/No: ITEUI	35 9 00 bas 1010
laims No.		Gen. Cond: Good / Fair / Poor / Bi	urnt
um Insured:	Excess:	Steering: Ino Ger / Jammed / Leal	ked / Burnt or
(Client's Reco		Brake: In der / Jammed / Leal	
lake of Veh:	W.	Modi : Nip / S/Rim / STD A/Rin	
			RIP
(Policy Condit	tion)	R: 155	
	eh had commenced its		
repair	r at the time of inspection.	TOYO / YOKO or	
al, or Market \	Value:	Front	Rear
DAC Accident	Rport. Consistent?: Yes or No		R/Bal. 5/5 mn
GIA / PR See			L/Bal. 5/5 mn
st. Repairs:	7 days Res.: Yes or M		DOI 21-09-18
um Sum:	7 % 3 Val.: Yes or N	o Survey held at	15 5:30
	I REP. I 24 HRS	Des. of Damages   Frt   Rear / C	+ - v · /
AU I IVEA	Vehi	cle: IN/OUT and	
Date:	Person Contacted:	The U/C / Chassis frame / E	Body Structure affected due to collision
Date / Time	Agtion / Instruction \$7000	,	
		2 5 SEP 2018	
	RECEIVEL	17 J OFT FOLD	
	37		
Date/Time, File Pa	: Preli. Report	Days Of Repair:	
y .	: Final Report	Resurvey No. of Trip:	Survey Fee:
Date/Time, File Re		OWNERSCHIEGE TO THE STATE OF TH	Transportation
2)		Add Fee: Site Insp (\$	)S+RS,SI
		: Interview (\$	) Photos
Report Forr	mat: PRS -	: Tech. Invs (\$	) Others
Lump Sum	/ I.B.I: (\$	. Weekend (\$	
			pat to see the second s



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

NAS	IG INSUBANCE	Affiliated to Federation Internat					
IVI	SIG INSURANCE (	SINGAPORE) PTE LTD	Ref : CS3/MSG180	)17204/Gcd3			
16 #2	RAFFLES QUAY 4-01 HONG LEON	G BLDG SINGAPORE 048581	Date: 21-09-2018 Code: MSG				
1.	CONTROL MANAGEMENT	Policy Particulars	:- (THIRD PARTY CLA	\IM\			
	Insured Veh.	FBF 4141U	Veh. Inspected	YL 8332E			
	Policy No.	28842144VMF	Coverage (\$)	0.00			
	Claim No.	570688	Excess (\$)	0.00			
	Assign From	MERIMEN (JASMINE LOK)	Assign Date	21/09/2018			
2.		Vehicle Part	culars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.	N90			
	Chassis No.		Colour				
	Odometer		Steering				
	Brakes		Modification				
	General						
			ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre			mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre			mm			
		Description	on of Damages				
	The Jan Colonia						
	Accident Date	1 = 10 0 10 = 1 =	Information				
_	Survey held at		Inspection Date	21/09/2018			
	Repairer						
a.	Repairer	HENG MOTOR SERVICES					
	A) THE INSPECTION		marks				
	THE REPAIRER W	ON WAS CONDUCTED ON A "WIT STIMATE WAS NOT PRESENTED AS TOLD TO PREPARE THE EST EASE FIND DAMAGED VEHICLE	AT THE TIME OF INSPE	SIS. CTION.			

## ...CLAIM SUBFOLDER...(New Assignment)

Case	votified	Est Submitted	AdJ Assigned	Adj Rpt	Adj Sub	mitted:	Ins Auth'ed	Status	
Main	17 Sep 2018		21 Sep 2018 09:50 Assign					New Assign	
М	lain	Re	eference		Claim Details		Document	s	Show All
CLAIM SUE	FOLDER DE	TAILS	AND DESCRIPTION OF THE PARTY OF			[Created	by insurer]		
Insured:	Domino's	Pizza Singapore	e Pte. Ltd., Co.	Reg. No.: 2	200900719D	1.			
Main Claimant:		TLE BUILDERS P	and the second second	1.500.000.000.000.000					
Vehicle Reg. No.:	YL83321	E			Date of Loss:		18 00:00 - :59 ths and <b>16</b> Days	From LTA Reg	Date (Man Yr)
Claim Type:	<b>TP</b> / 570	688			Policy/Cover Note No.:		VMF (Comprehen: 01/11/2017 - 31		
Vehicle Reg. No. (Insured):	FBF4141U	J			Policy No. (Claimant):		- 03 - 04		
					Excess:				
Repairer:	Heng Mot	or Services (Def	fu) Blk 5 Defu La	ne 10, #01	-582, 539186 De	fu Lane - Te	el:		
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (H	IQ) - Tel: +	65 6827 7888	[Handled b	y Jasmine Lok K	heng Kwei -	6594 2550]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Imm.Adv	ice due 2	2/09/2018]		
Adj Asg. Remarks:	Liability (N	on-reporting). SJI	E DISAGREE APP	OINT LKK, C	CONTACT NO: 81	123936. WA	AITING FOR TP RE	PORT	
ASSOCIATI	ED MAIL RE	CEIVED					\(\nabla_1\)	/iew All   Con	npose Case Ma
There are no	mail for this	case.					_		
ALL ASSO	CIATED TAS	KS⊟				View All	Search Tasks	Create New Ta	sk   Complet
Due Date	Priority	Type Task	Group Subj	ect Han	dler Assign	ed By	Completed On	Created	removed instrumental contra
No results.					water and the second		10000000000000000000000000000000000000		

### > Back to OneMotoring

**Enquire Transfer Fee** 

Vehicle Details	
Vehicle No.:	YL8332E
Vehicle Type :	B31 - Goods (Open) Lorry (Metal Body)/Pickup
Vehicle Attachment 1:	With Hood
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model:	DYNA 150 D
Chassis No.:	JTFUF35Y006001010
Propellant :	Diesel
Engine No.:	5L5473096
Engine Capacity:	2986 cc
Maximum Power Output	
Maximum Laden Weight :	3550 kg
Unladen Weight:	1680 kg
Year Of Manufacture :	2004
Original Registration Date :	30 Oct 2004
Lifespan Expiry Date:	29 Oct 2024
COE Category:	C - Goods Vehicle & Bus
PQP Paid :	\$20,383.00
COE Expiry Date:	31 Jul 2019
Road Tax Expiry Date:	29 Oct 2018
Inspection Due Date :	29 Oct 2018
Intended Transfer Date:	25 Sep 2018
CO2 Emission:	
CO Emission :	•
HC Emission:	
NOx Emission :	•
PM Emission :	

The current road tax expiry is 29 Oct 2018. You may renew the road tax from 30 Jul 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 Oct 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 30 Oct 2018 to 29 Apr 2019)

	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee :	25.00		25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over	0.00	)2	0.00
Payment):			
Total Amount Payable:			25.00

Message

This vehicle has a road tax Over Payment of \$152.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: /ehicle Details	5585W
/ehicle No.:	YL8332E
/ehicle to be Exported:	No
ntended Deregistration Date:	25 Sep 2018
/ehicle Make:	TOYOTA
/ehicle Model:	DYNA 150 D
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	5L5473096
Chassis No.:	JTFUF35Y006001010
Maximum Power Output:	(*)
Open Market Value:	\$23,946.00
Original Registration Date:	30 Oct 2004
First Registration Date:	30 Oct 2004
Transfer Count:	4
Actual ARF Paid: Intended PARF Rebate Details	\$1,198.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	•
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	31 Jul 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$20,383.00
COE Rebate Amount:	\$3,462.00
Total Rebate Amount: Message	\$3,462.00
	vehicle can only be for a 5-year period, subject to the statutory

The information contained herein is correct as at 25 Sep 2018

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case I	votified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subi	mitted	Ins Auth'ed	Status		
Main	7 Sep 2018	21 Se 09:50		21 Sep 2018 09:50 Edit Adj Rpt		S\$0.00 View Rpt				Pending for Survey Report Cancel Case	
М	ain	Re	ference	С	laim	Details	$\Box$	Docume	nts	Show All	
CLAIM SUB	FOLDER DE	TAILS		and the same of the same of		Name and Address of the Owner, where the Owner, which is the Owner	[Create	ed by insurer]		NAME OF TAXABLE PARTY.	
Insured:	Domino's	Pizza Singapore	Pte. Ltd., Co.	Reg. No.: 20	09007	719D	1776				
Main Claimant:	NEW CAS	TLE BUILDERS P	TE.LTD., Co.	Reg. No.: 201	08055	585W					
/ehicle Reg. YL8332E						of Loss:	15/09/2018 00:00 - :59 [166 Months and 16 Days From LTA Reg Date (Man Yr			eg Date (Man Yr)	
Claim Type:	Claim Type: <b>TP</b> / 570688					y/Cover No.:	28842144VMF (Comprehensive) Coverage: 01/11/2017 - 31/10/2018				
Vehicle Reg. No. (Insured):	FBF4141U				2000000	y No. imant):					
					Exce	ess:					
Repairer:	Heng Mot	tor Services (Def	u) Blk 5 Defu La	ne 10, #01-5	82, 5	39186 De	fu Lane -	Tel:			
Handling Insurer:		urance (Singapo							25.00	500	
Adjuster:	22/09/20	Consultants Pte 018]	Ltd (HQ) - Tel:	6256-3561	. [Hai	ndled by )	KING GU	O QIANG] [Ir	nm.Advice	e due	
Adj Asg. Remarks:	Liability (N	Non-reporting). SJE	DISAGREE APP	OINT LKK. CO	NTAC	T NO: 81	123936. \	WAITING FOR TP	REPORT		
ASSOCIAT	ED MAIL RE	CEIVED			11 7.1				View All	Compose Case Ma	
There are no	mail for this	case.									
ALL ASSO	CIATED TAS	SKS <sup>-</sup>					View A	All Search Tasks	Create Ne	w Task   Comple	
Due Date	Priority	Type Task	Group Sub	iect Hand	ler	Assign	ned By	Completed O	n Crea	ted On Done	

### **Claim Documents**

\*YL8332E (570688)
[FBF4141U]
TP
NEW CASTLE BUILDERS PTE.LTD.
Sep 15 2018 12:00AM

Sep 15 2018 12:00AM
[Domino's Pizza Singapore Pte. Ltd.]
Heng Motor Services

_		ad Photos Compose New Letter		View in Brow	
Let	ters/Corresponder	ices	1 per p		•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/09/18 16:53	Non Reporting Letter to OI	0	Load HTM	_
Pho	tos/Images		3 per	page 🔻	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	24/09/18 15:35	General View	0	Load JPG	•
2	24/09/18 15:35	General View	0	Load JPG	•
3	24/09/18 15:35	General View	0	Load JPG	•
4	24/09/18 15:35	General View	0	Load JPG	•
5	24/09/18 15:35	General View	0	Load JPG	•
6	24/09/18 15:35	General View	0	Load JPG	•
7	24/09/18 15:35	General View	0	Load JPG	•
8	24/09/18 15:35	General View	0	Load JPG	•
9	24/09/18 15:35	General View	0	Load JPG	•
10	24/09/18 15:35	General View	0	Load JPG	•
11	24/09/18 15:35	General View	0	Load JPG	•
12	24/09/18 15:35	General View	0	Load JPG	•
13	24/09/18 15:35	General View	0	Load JPG	1
14	24/09/18 15:35	General View	0	Load JPG	•
15	24/09/18 15:35	General View	0	Load JPG	•
16	24/09/18 15:35	General View	0	Load JPG	•
17	24/09/18 15:35	General View	0	Load JPG	•
18	24/09/18 15:35	General View	0	Load JPG	✓
19	24/09/18 15:35	General View	0	Load JPG	•
20	24/09/18 15:35	General View	0	Load JPG	•
21	24/09/18 15:35	General View	0	Load JPG	•
22	24/09/18 15:35	General View	0	Load JPG	•
23	24/09/18 15:35	General View	0	Load JPG	•
24	24/09/18 15:35	General View	0	Load JPG	•
25	24/09/18 15:35	General View	0	Load JPG	•
26	24/09/18 15:35	General View	0	Load JPG	•
27	24/09/18 15:35	General View	0	Load JPG	1
28	24/09/18 15:35	General View	0	Load JPG	•
29	24/09/18 15:35	General View	0	Load JPG	•
30	24/09/18 15:35	General View	0	Load JPG	•
31	24/09/18 15:35	General View	0	Load JPG	•
32	24/09/18 15:35	General View	0	Load JPG	•

Lett	ers/Corresponde	nces	1 per	page ▼	•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
33	24/09/18 15:35	General View	0	Load JPG	•
34	24/09/18 15:35	General View	0	Load JPG	•
35	24/09/18 15:35	General View	0	Load JPG	•
36	24/09/18 15:35	General View	0	Load JPG	•
37	24/09/18 15:35	General View	0	Load JPG	•
38	24/09/18 15:35	General View	0	Load JPG	•
39	24/09/18 15:35	General View	0	Load JPG	•
40	24/09/18 15:35	General View	0	Load JPG	•
41	24/09/18 15:35	General View	0	Load JPG	•
42	24/09/18 15:35	General View	0	Load JPG	•
43	24/09/18 15:35	General View	0	Load JPG	•
44	24/09/18 15:35	General View	0	Load JPG	•
45	24/09/18 15:35	General View	0	Load JPG	•
46	24/09/18 15:35	General View	0	Load JPG	€
47	24/09/18 15:35	General View	0	Load JPG	•
48	24/09/18 15:35	General View	0	Load JPG	2
49	24/09/18 15:35	General View	0	Load JPG	✓
50	24/09/18 15:35	General View	0	Load JPG	✓
Do	cumentation		1 pe	rpage ▼	•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/09/18 16:51	PRI	0	Load PDF	
2	20/09/18 16:51	SJE DISAGREE APPOINT LKK	0	Load PDF	

### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
THE SEAS 21 See Man TAKE SEASON SHOWS	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18017204/GCD3S2

Date:

26/09/2018

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28842144VMF

Claimant Vehicle

YL8332E

Insured Vehicle No:

FBF4141U

No: Date of Loss: 15/09/2018

Nature of Claim:

TP

Claim No: 570688

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

YL8332E

TOYOTA DYNA 1.5T, 3.0 (A)

Make & Model: Reg. Date:

30/10/2004 (Man. Year: 2004)

Engine No: Chassis No:

Odometer:

5L5473096

535185 km

JTFUF35Y006001010

Colour:

Silver

Engine Capacity: Market Value/New Car Price: 2986 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185 R14

Rear Tyre Size:

155 R12 (D)

Front Left Side:

Bridgestone 5 mm

Rear Left Side:

Bridgestone 5/5 mm

Front Right Side:

Bridgestone 5 mm

Rear Right Side:

Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		0.00	0.00	0.00	
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
705245100 MA	Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

Date Inspected:

21/09/2018

21/09/2018

Inspected At:

Heng Motor Services (Defu) Blk 5 Defu Lane 10, #01-582

Singapore 539186

Estimated Period of Repair:

0.0 days

XING GUO QIANG Adjuster:

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

#### REPAIR DETAILS

Reference

(Last Synchronised: 26 Sep 2018) Part Source:

TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database) Parts: N/A

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for YL8332E)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >