

ASS. REC. BY:

REF:

CS/EOI18017217/ Usd302 Special Instruction

Surveyor

MCHW

## ASSIGNMENT (Office)

From (Person):

Joel Goh

of

EOI

Date/Time

21/9/18 @ 11:17am

Estimated Cost:

Bill to:

OD/TP/WS/TP-RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GBE9773T

Insured:

at Workshop m/s

Premium Carz

Tel: 6636 9100

of

1 Kaki Bkt Ave 6 # 01-90

Policy No:

DMep HQ1E-002373

Claim No:

Sum Insured:

Excess:

\$ 500.00 (no waiver)

Make of Veh:

(Client's Record)

D.O.A. 19/09/2018

CA / REV

REP. / REV 24 HRS up

H.O.D. Endorsement:

Date/Time:

12:01pm @ 21/9/18

Person Contacted:

Aun Teng

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

GBE9773T-X

21/09/18

@ 17:23 p.m. revised PA and authorise repair requested to Joel via email.

25/09/18

@ 16:22 p.m. authorise repair approved by Joel Goh via email.

25/09/18

@ 18:17 pm revert authorise repair to Eric/Aun Teng via email.  
(S\$4,683.95 Red - 42%)

CS/EQI 1801727/USD3

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBE 97737at Workshop m/s Prem

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: 000

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 50k

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 6 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

27427

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBE 97737Yr Regn: 5, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or NIMake: Nissan Cabstarc.c 2953Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 177643

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JNISC27242058629Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/70R15R: 155-213

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or wastlike

Front

Rear

R/Bal. 6 mmR/Bal. 6/6 mmL/Bal. 6 mmL/Bal. 6/6 mmD.O.A. 19/9/18D.O.I. 21/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ATA 32867 7yrs 7m.  
check cost plus?4/10/18 4/5 @ 6550 confirmed with Austory04/10/18 Confirmed HS \$ 6,550/- @ 6 days with Marcus.  
( \$ 4,683.95 Red - 42% )

RECEIVED 04 OCT 2019

Date/Time, File Pass to?

04/10/181) Typist ☐ : Preli. Report

Date/Time, File Return to?

☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: 230

Transportation: \_\_\_\_\_

\_\_\_\_ S + RS \_\_\_\_ SI

Photos

Others

TOTAL

230

Report Format :

Lump Sum / I.B.I: (\$ 6,550/- HS)

08/11/18 waf

ASS. REC. BY: Marcus

REF:

EQ1  
**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 97737at Workshop m/s 11km

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 922

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 50k

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 27427

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBC 97737 Yr Regn: 5-18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or CUMake: Nissan Cabstar c.c. 2953Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 177643 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JNISC27242058629Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/70R15R: 155R13 h.f.g.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or wastleke.

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6/6 mmL/Bal. 6 mm L/Bal. 6/6 mmD.O.A. 19/9/18 D.O.I. 21/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R.R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ATA 32867 7hrs 7m.

Date/Time, File Pass to?

☐

: Prell. Report

1) \_\_\_\_\_  
Date/Time, File Return to?☐

: Final Report

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, \_\_\_\_\_ \$

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

> **Back to OneMotoring**

**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	2742Z
<b>Vehicle Details</b>	
Vehicle No.:	GBE9773T
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	ZD30011595N
Chassis No.:	JN1SC2F24Z0858629
Maximum Power Output:	-
Open Market Value:	\$24,867.00
Original Registration Date:	14 May 2016
First Registration Date:	14 May 2016
Transfer Count:	0
Actual ARF Paid:	\$1,244.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 May 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$32,867.00
<b>Total Rebate Amount:</b>	<b>\$32,867.00</b>

The information contained herein is correct as at 21 Sep 2018

OK

**> Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	2742Z

**Vehicle Details**

Vehicle No.:	GBE9773T
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Sep 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	ZD30011595N
Chassis No.:	JN1SC2F24Z0858629
Maximum Power Output:	-
Open Market Value:	\$24,867.00
Original Registration Date:	14 May 2016
First Registration Date:	14 May 2016
Transfer Count:	0
Actual ARF Paid:	\$1,244.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	13 May 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$32,867.00
<b>Total Rebate Amount:</b>	<b>\$32,867.00</b>

The information contained herein is correct as at 21 Sep 2018

OK



## Shirley Hiew (LKK Auto)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Tuesday, 25 September 2018 4:22 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** 'SUR'; 'Nivitha (LKK Auto)'; assignments@lkkauto.com  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373) (DM18HO02505-JG)

Dear Shirley

Please proceed to authorize this OD up to S\$8,919.45.

Best Regards,

Joel Goh  
Executive | Claims



### EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti*

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Monday, September 24, 2018 10:07 AM  
**To:** Joel Goh  
**Cc:** 'SUR'; 'Nivitha (LKK Auto)'; assignments@lkkauto.com  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)

Hi Joel,

As spoken, authorization amount (estimate), inclusive check items is \$ 8,919.45.

Kindly let us have your approval of authorization.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Joel Goh [mailto:joel.goh@eqinsurance.com.sg]  
**Sent:** Monday, 24 September 2018 9:56 AM  
**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Cc:** 'SUR' <sur@lkkauto.com>; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>; assignments@lkkauto.com  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)

Dear Shirley

Please advise on the authorization amount.

Best Regards,

**Joel Goh**  
Executive | Claims



**EQ Insurance Company Limited**  
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
www.eqinsurance.com.sg



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Friday, September 21, 2018 5:23 PM  
**To:** Joel Goh  
**Cc:** 'SUR'; 'Nivitha (LKK Auto)'; assignments@lkkauto.com  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)

Dear Joel,

Enclosed herewith preliminary advice of GBE 9773T.

Damages consistent, repair cost economical. We have not authorise repair.

Kindly approve of authorization.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Friday, 21 September 2018 5:23 PM  
**To:** 'Joel Goh'  
**Cc:** 'SUR'; 'Nivitha (LKK Auto)'; 'assignments@lkkauto.com'  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)  
**Attachments:** GBE 9773T - Preli Advise.pdf

Dear Joel,

Enclosed herewith preliminary advice of GBE 9773T.

Damages consistent, repair cost economical. We have not authorise repair.

Kindly approve of authorization.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Friday, 21 September 2018 11:59 AM  
**To:** 'Joel Goh' <joel.goh@eqinsurance.com.sg>; assignments@lkkauto.com  
**Cc:** 'SUR' <sur@lkkauto.com>  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Joel Goh [mailto:joel.goh@eqinsurance.com.sg]  
**Sent:** Friday, 21 September 2018 11:17 AM  
**To:** Aunteng <aunteng@premiumcarz.com.sg>  
**Cc:** 'assignments' <assignments@lkkauto.com>  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)

Dear Aun Teng

Thank you for the attachment.  
We will assign LKK to conduct PRS.

## Nivitha (LKK Auto)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Friday, 21 September 2018 11:17 AM  
**To:** Aunteng  
**Cc:** 'assignments'  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)  
**Attachments:** GBE9773T est.pdf, GBE9773T.PDF

Dear Aun Teng

Thank you for the attachment.  
We will assign LKK to conduct PRS.

Dear LKK

Please assist to arrange for PRS for insured's vehicle.  
Excess: \$500.00 (no waiver)

Best Regards,

Joel Goh  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Aunteng [mailto:aunteng@premiumcarz.com.sg]  
**Sent:** Friday, September 21, 2018 10:41 AM  
**To:** Joel Goh  
**Subject:** Re: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)

Dear Joel

Attached estimate as requested.

Regards  
Aun Teng  
Premium Carz Services Pte Ltd  
Tel: 6636 9100 Fax: 6636 9113  
1 Kaki Bukit Avenue 6  
#01-90 Autobay@Kaki Bukit  
Singapore 417883

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** 21 September 2018 10:33:32  
**To:** Aunteng  
**Subject:** RE: Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)

Dear Aun Teng

Please assist forward a copy of the estimates before we arrange for survey.


Best Regards,

**Joel Goh**  
Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Aunteng [mailto:aunteng@premiumcarz.com.sg]  
**Sent:** Thursday, September 20, 2018 2:07 PM  
**To:** EQI PRS  
**Subject:** Own Damage Claim Survey - GBE9773T (Policy number: DMCPHQ18-002373)

Dear Officer-in-charge

Refer to the above matter.

Attached our client's accident report.

Our client's vehicle is ready for survey.

A copy of estimate will be ready and available to surveyor on site inspection. Please indicate whether you are sending your surveyor to our workshop.

Regards  
Aun Teng  
Premium Carz Services Pte Ltd  
Tel: 6636 9100 Fax: 6636 9113  
1 Kaki Bukit Avenue 6  
#01-90 Autobay@Kaki Bukit  
Singapore 417883



## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 25 September 2018 6:17 PM  
**To:** aunteng@premiumcarz.com.sg  
**Cc:** 'SUR'  
**Subject:** GBE 9773T OD (EQI)

Dear Aun Teng,

As instructed by our client, please proceed to repair the insured vehicle **GBE 9773T (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DMCPHQ18-002373

Date: 21 September 2018

Our Ref: CS/EQI18017217/Usd3

The Motor Claims Department  
EQ Insurance Company Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 9773T .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/09/2018 at the premises of M/s Premium Carz Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,750.95</u> .
Revised Estimate Amount	: S\$ <u>5,534.20</u> .
"Check" Items Amount	: S\$ <u>3,385.25</u> .
Market Value	: S\$ <u>50,000.00</u> .
LTA Reimbursement Value	: S\$ <u>32,867.00</u> .
Nett Value	: S\$ <u>17,133.00</u> .

**Description of Damage:**

The vehicle sustained damages at the front portion.



**Comments/ Present Status:**

Damages Consistent, repair cost economical.  
We have not authorize repair.  
Repair days: 6 Days

Yours faithfully,  
Marcus Chua  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/09/2018 10:50
Date Of Accident	19/09/2018 19:15
Exact Location Of Accident	TAMPINES AVE 10
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE9773T
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	EVERPAINT ENTERPRISE PTE LTD
Co Reg No	A200402742Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64872966

#### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 D F24 (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

#### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-002373
Cover Note Number	

#### Driver

Name of Driver	GAN ENG HUAT
NRIC No	S1304910F
Date Of Birth	17/10/1958
Occupation	OUTDOOR
Date Of Driving Pass	31/05/1979
Driving Experience	39 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97582676
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE8967H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver SAW CHENG HAI

NRIC/Passport Number

Contact Number 97877104

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



## SKETCH PLAN

Vehicle A: GBE9773T

B: GBE8967H



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 19/4/2018 at about 7.15 PM, whilst travelling along  
 Tampines Ave 10, vehicle B (GBE8967H) in front of me  
 suddenly slowed down. I couldn't stop in time  
 thus collided into the rear portion of vehicle B.

## DECLARATION

(We declare the foregoing particulars are true in every respect.)

  
 Police Officer's Signature  
 Date & Time:

(SEEKAR 201804050001 13)

  
 Driver's Signature  
 (If driver is not the policeholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Date : 20/9/2018

TO: EQ Insurance Company Limited  
5 Maxwell Road #17-00 Tower Block  
MND Complex  
Singapore 069110

Our Customer : Everpaint Enterprise Pte Ltd

Vehicle No : GBE9773T

Model : Nissan Cabstar

Manufacture Year : 2016

Date of Accident : 19/9/2018

Total Estimate Repair Days : 15

Total Pages : 2

Attn : Motor Claims Department

Fax : 6224 3903

Re: Own Damage Claims Under Policy Number : DMCPHQ18-002373

7-4253  
187.  
4890.95  
5.00 + 5.91  
1.00 + 2700  
8201.95

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Front bumper w/reinforcement	1	\$485.00	\$485.00	✓
2	Headlamp RH	1	\$265.00	\$265.00	✓
3	Headlamp LH	1	\$265.00	\$265.00	✓
4	Headlamp lower panel RH	1	\$55.00	\$55.00	✗
5	Headlamp lower panel LH	1	\$55.00	\$55.00	✗
6	Front grille assy	1	\$270.00	\$270.00	✓
7	Front grille "Nissan" logo	1	\$40.00	\$40.00	✓
8	Front panel	1	\$600.00	\$600.00	✓
9	Front panel "Cabstar" emblem	1	\$30.00	\$30.00	✓
10	Front grille bracket	1	\$35.00	\$35.00	✓
11	Front wiper garnish	1	\$320.00	\$320.00	✓
12	Side mirror holder RH	1	\$165.00	\$165.00	✓
13	Side mirror holder top cover RH	1	\$18.00	\$18.00	✓
14	Front windscreen moulding	2	\$55.00	\$110.00	✓
15	Front door RH	1	repair	repair	✗
16	Front door frame RH	1	repair	repair	✗
17	Front door pillar RH	1	repair	repair	✗
18	Rear door pillar RH	1	repair	repair	✗
19	Air-con cooling coil assy	1	\$650.00	\$650.00	✗
20	Air-con blower unit	1	\$400.00	\$400.00	✓
21	Heater unit	1	\$1,250.00	\$1,250.00	✓
	<b>Total</b>			<b>\$5,013.00</b>	
	<b>Cost Plus 15%</b>			<b>\$751.95</b>	
	<b>Sub Total 1</b>			<b>\$5,764.95</b>	
<b>A.</b>	<b>Spare Parts (S/Nett)</b>				
1	Front number plate	1	\$35.00	\$35.00	✗
2	Front windscreen sealant	1	\$50.00	\$50.00	40
3	ERP bracket	1	\$25.00	\$25.00	20
4	Front grille clip	7	\$3.00	\$21.00	✓
5	Alarm siren	1	\$65.00	\$65.00	50
6	ROC sticker front door RH	1	\$40.00	\$40.00	30
7	Heater pipe	2	\$80.00	\$160.00	100
8	Vacuum pipe	1	\$180.00	\$180.00	✓

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
9	Discharge pipe <i>huf</i>	1	\$170.00	\$170.00	<i>✓</i>
10	Suction pipe <i>huf</i>	1	\$190.00	\$190.00	<i>✓</i>
<b>Sub-Total 2</b>				<b>\$936.00</b>	
<b>Total for Parts (Exclude GST)</b>				<b>\$6,700.95</b>	
<b>B.</b>	<b>Labour</b>				
1	To check wiring.			\$80.00	<i>20</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$2,000.00	<i>1300</i>
3	Spray painting all affected parts & areas.			\$1,600.00	<i>980</i>
4	To remove and refit front windscreen glass.			\$120.00	<i>✓</i>
5	To remove and refit dashboard			\$250.00	<i>200</i>
6	To remove and replace damaged heater, cooling coil unit assy and to vacuum air-con system and charge up air-con gas.			\$180.00	<i>100</i>
<b>Total Labour</b>				<b>\$4,050.00</b>	<i>6200</i>
<b>Total Repair Cost</b>				<b>\$10,750.95</b>	

*2720*

*11233.95*

*11413.95*

*Not Authorized*

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	<i>Naresh Kumar</i>
Contact	<i>9009 6608</i>
Survey Date	<i>21/9/18</i>
Recommender	<i>Authorize / Not Authorize</i>
Before Paint	<i>Yes / No</i>

*take photo after repair  
6 days.*

*US \$ 6550/-*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Date : 26/9/2018

TO: EQ Insurance Company Limited  
5 Maxwell Road #17-00 Tower Block  
MND Complex  
Singapore 069110

Our Customer : Everpaint Enterprise Pte Ltd

Vehicle No : GBE9773T

Model : Nissan Cabstar

Manufacture Year : 2016

Date of Accident : 19/9/2018

Total Estimate Repair Days : 15

Total Pages : 2

Attn : Motor Claims Department

Fax : 6224 3903

Re: Own Damage Claims Under Policy Number : DMCPHQ18-002373

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front inner support	1	\$420.00	\$420.00	✓
	Total			\$420.00	
	Cost Plus 15%			\$63.00	
	Total Supplementary Repair Cost (Exclude GST from Supplier)			\$483.00	

Yours faithfully,

Aun Teng  
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No



Co. Reg No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

Date : 20/9/2018

TO: EQ Insurance Company Limited  
5 Maxwell Road #17-00 Tower Block  
MND Complex  
Singapore 069110

Our Customer : Everpaht Enterprise Pte Ltd

Vehicle No : GBE9773T

Model : Nissan Cabstar

Manufacture Year : 2016

Date of Accident : 19/9/2018

Total Estimate Repair Days : 15

Total Pages : 2

Attn : Motor Claims Department

Fax : 6224 3903

Re: Own Damage Claims Under Policy Number : DMCPHQ18-002373

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	<b>Spare Parts</b>				
1	Front bumper w/reinforcement	1	\$485.00	\$485.00	✓
2	Headlamp RH	1	\$265.00	\$265.00	✓
3	Headlamp LH	1	\$265.00	\$265.00	✓
4	Headlamp lower panel RH	1	\$55.00	\$55.00	X
5	Headlamp lower panel LH	1	\$55.00	\$55.00	X
6	Front grille assy	1	\$270.00	\$270.00	✓
7	Front grille "Nissan" logo	1	\$40.00	\$40.00	✓
8	Front panel	1	\$600.00	\$600.00	✓
9	Front panel "Cabstar" emblem	1	\$30.00	\$30.00	✓
10	Front grille bracket	1	\$35.00	\$35.00	✓
11	Front wiper garnish	1	\$320.00	\$320.00	✓
12	Side mirror holder RH	1	\$165.00	\$165.00	✓
13	Side mirror holder top cover RH	1	\$18.00	\$18.00	✓
14	Front windscreen moulding	2	\$55.00	\$110.00	✓
15	Front door RH	1	repair	repair	X
16	Front door frame RH	1	repair	repair	X
17	Front door pillar RH	1	repair	repair	X
18	Rear door pillar RH	1	repair	repair	X
19	Air-con cooling coil assy	1	\$650.00	\$650.00	?
20	Air-con blower unit	1	\$400.00	\$400.00	?
21	Heater unit	1	\$1,250.00	\$1,250.00	?
	<b>Total</b>			<b>\$5,013.00</b>	
	<b>Cost Plus 15%</b>			<b>\$751.95</b>	
	<b>Sub Total 1</b>			<b>\$5,764.95</b>	
A.	<b>Spare Parts (S/Nett)</b>				
1	Front number plate	1	\$35.00	\$35.00	X
2	Front windscreen sealant	1	\$50.00	\$50.00	40
3	ERP bracket	1	\$25.00	\$25.00	20
4	Front grille clip	7	\$3.00	\$21.00	✓
5	Alarm siren	1	\$65.00	\$65.00	50
6	ROC sticker front door RH	1	\$40.00	\$40.00	3.2
7	Heater pipe	2	\$80.00	\$160.00	?
8	Vacuum pipe	1	\$180.00	\$180.00	?



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
9	Discharge pipe	1	\$170.00	\$170.00	7
10	Suction pipe	1	\$190.00	\$190.00	7
<b>Sub-Total 2</b>				<b>\$936.00</b>	
<b>Total for Parts (Exclude GST)</b>				<b>\$6,700.95</b>	
<b>B.</b>	<b>Labour</b>				
1	To check wiring.			\$80.00	20
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$2,000.00	1000
3	Spray painting all affected parts & areas.			\$1,600.00	500
4	To remove and refit front windscreen glass.			\$120.00	5
5	To remove and refit dashboard			\$250.00	200
6	To remove and replace damaged heater, cooling coil unit assy and to vacuum air-con system and charge up air-con gas.			\$180.00	100
<b>Total Labour</b>				<b>\$4,050.00</b>	
<b>Total Repair Cost</b>				<b>\$10,750.95</b>	

Yours faithfully,

Aun Teng  
f Premium Carz Services Pte Ltd

Not Authorized

Surveyor's Details	
Name	Naresh Kumar
Contact	9009 6608
Survey Date	21/9/18
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

take photo after upon  
6 day.

US



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CS/EQI18017217/Usd3e2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 01-11-2018		
		Code : EQI		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected	GBE 9773T	
Policy No.	DMCPHQ18-002373	Coverage (\$)	0.00	
Claim No.		Excess (\$)	500.00	
Assign From	JOEL GOH	Assign Date	21/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN CABSTAR (A)	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1SC2F24Z0858629	Colour	SILVER	
Odometer	177643	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/70 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/70 R15	WEST LAKE	6 mm	
R/H Rear Tyre	155 R13 (D)	HIFLY	6/6 mm	
L/H Rear Tyre	155 R13 (D)	HIFLY	6/6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/09/2018	Inspection Date	21/09/2018	
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$50,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9773T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER W/REINFORCEMENT (WCP)	CUT	485.00	485.00
1	HEADLAMP RH (WCP)	CRACKED	265.00	265.00
1	HEADLAMP LH (WCP)	CRACKED	265.00	265.00
1	HEADLAMP LOWER PANEL RH (WCP)	TO REPAIR SEE LABOUR	55.00	-
1	HEADLAMP LOWER PANEL LH (WCP)	TO REPAIR SEE LABOUR	55.00	-
1	FRONT GRILLE ASSY (WCP)	CRACKED	270.00	270.00
1	FRONT GRILLE "NISSAN" LOGO (WCP)	NECESSARY	40.00	40.00
1	FRONT PANEL (WCP)	BADLY DENTED	600.00	600.00
1	FRONT PANEL "CABSTAR" EMBLEM (WCP)	NECESSARY	30.00	30.00
1	FRONT GRILLE BRACKET (WCP)	BENT	35.00	35.00
1	FRONT WIPER GARNISH (WCP)	DENTED / BENT	320.00	320.00
1	SIDE MIRROR HOLDER RH (WCP)	CRACKED	165.00	165.00
1	SIDE MIRROR HOLDER TOP COVER RH (WCP)	CRACKED	18.00	18.00
2	FRONT WINDSCREEN MOULDING @\$55.00 (WCP)	NECESSARY	110.00	110.00
1	FRONT DOOR RH (NPA) (WCP)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR FRAME RH (NPA) (WCP)	TO REPAIR SEE LABOUR	-	-
1	FRONT DOOR PILLAR RH (NPA) (WCP)	TO REPAIR SEE LABOUR	-	-
1	REAR DOOR PILLAR RH (NPA) (WCP)	TO REPAIR SEE LABOUR	-	-
1	AIR-CON COOLING COIL ASSY (WCP)	NOT NECESSARY	650.00	-
1	AIR-CON BLOWER UNIT (WCP)	CRACKED	400.00	400.00
1	HEATER UNIT (WCP)	CRACKED	1,250.00	1,250.00
1	FRONT INNER SUPPORT (ADDITIONAL) (WCP)	TO REPAIR SEE LABOUR	420.00	-
	COST PLUS 15%		814.95	637.95
			6,247.95	4,890.95
<b>SPECIAL NETT ITEMS</b>				
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	35.00	-

Report Ref No. CS/EQ118017217/Usd3e2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	ERP BRACKET (SN)	NECESSARY	25.00	20.00
7	FRONT GRILLE CLIP @\$3.00 (SN)	NECESSARY	21.00	21.00
1	ALARM SIREN (SN)	CRACKED	65.00	50.00
1	ROC STICKER FRONT DOOR RH (SN)	NECESSARY	40.00	30.00
2	HEATER PIPE @\$80.00 (SN)	TWISTED-1PC ONLY	160.00	80.00
1	VACUUM PIPE (SN)	BENT	180.00	180.00
1	DISCHARGE PIPE (SN)	BENT	170.00	170.00
1	SUCTION PIPE (SN)	NOT NECESSARY	190.00	-
			936.00	591.00
	<b>LABOUR</b>			
	TO CHECK WIRING.		80.00	20.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS. INCLUSIVE OF THE REPAIR OF HEADLAMP LOWER PANEL RH, HEADLAMP LOWER PANEL LH, FRONT DOOR RH, FRONT DOOR FRAME RH, FRONT DOOR PILLAR RH, REAR DOOR PILLAR RH AND FRONT INNER SUPPORT.		2,000.00	1,300.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		1,600.00	980.00
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.		120.00	120.00
	TO REMOVE AND REFIT DASHBOARD.		250.00	200.00
	TO REMOVE AND REPLACE DAMAGED HEATER, COOLING COIL UNIT ASSY AND TO VACUUM AIR-CON SYSTEM AND CHARGE UP AIR-CON GAS.		180.00	100.00
			-	-
			-	-
			-	-
			-	-
			4,230.00	2,720.00
<b>GRAND TOTAL</b>			<b>11,413.95</b>	<b>8,201.95</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,550.00</b>
<b>LESS EXCESS</b>				<b>-500.00</b>

Report Ref No. CS/EQ18017217/Usd3e2



NETT LIABILITY			6,050.00
----------------	--	--	----------

Report Ref No. CS/EQ18017217/Usd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.