

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 04 Oct 2018

Preliminary Advice

Vehicle No	: SGX293L	Accident Date	: 09/07/2018
Make	: AUDI TTC	Policy No.	: 2100230477-07
Assignment Date	: 12/07/2018	Excess	: S\$700.00
Date of Inspection	: 12/07/2018	Est. Duration of Repair	: 9 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,397.00
Revised Amount	:S\$	29,299.00
Check Items (Estimated)	:S\$	5,031.00
Total	:S\$	34,330.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00
COE / PARF Rebate	:S\$	38,661.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,339.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please refer to the diagnostic report, supplementary amount is \$ 4,984.00. Repairer is appealing to have the repair cost increased.