

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

Not Aduh
Zhu photo. kshirapaf.
21/9/18

GBG1655T Toyota Dyna

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 912.00 X
2	2	Front bumper bracket	\$ 230.00 X
3	1	Front bumper reinforcement	\$ 496.00 X
4	1	Front grille assy	\$ 368.00 —
5	1	Front panel assy	\$ 1,296.00 —
6	2	Front panel bracket	\$ 183.00 X
7	1	Front panel centre logo	\$ 108.00 —
8	1	Front left corner panel	\$ 183.00 X
9	1	Front right corner panel	\$ 183.00 X
10	1	Front left headlamp	\$ 876.00 ?
11	1	Front right headlamp	\$ 876.00 X
12	1	Front headlamp wire harness	\$ 450.00 X
13	1	Front horn	\$ 86.00 X
14	1	Front left step garnish	\$ 276.00 X
15	1	Front right step garnish	\$ 276.00 X
16	1	Front left signal lamp	\$ 95.00 X
17	1	Front right signal lamp	\$ 95.00 X
18	1	Front wiper panel	\$ 673.00 X
19	1	Front wiper panel left garnish	\$ 82.00 X
20	1	Front wiper panel right garnish	\$ 82.00 X
21	2	Front wiper nozzle	\$ 157.00 X
22	2	Front wiper arm	\$ 136.00 X
23	2	Front wiper blade	\$ 86.00 X
24	1	Front wiper linkage with motor assy	\$ 393.00 X
25	2	Front wiper nozzle grommet	\$ 38.00 X
26	1	Front wiper panel centre garnish	\$ 165.00 X
27	1	Front left wing mirror	\$ 579.00 X
28	1	Front right wing mirror	\$ 493.00 X
29	1	Front cabin assy	\$ 8,850.00 X
30	1	Front dashboard panel assy	\$ 1,278.00 X
31	1	Front dashboard centre console	\$ 699.00 X
32	1	Front dashboard glove box	\$ 205.00 X
33	1	Front towing hook	\$ 179.00 X
34	1	Front air-con condenser assy	\$ 1,410.00 X
35	1	Front evaporator coil with blower assy	\$ 2,659.00 ?
			\$ 25,153.00
Less 25%			\$ 6,288.25
			<u>\$ 18,864.75</u>

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

GBG1655T Toyota Dyna

No	Qty	Parts Description		Estimated Parts Price	
<u>Special Nett Items</u>					
1	6	Front grille clips	mm	\$ 20.00	✓
2	1	Front panel sealant	1cc	\$ 80.00	30
3	1	Front panel Dyna sticker	mm	\$ 50.00	✓
4	8	Front wiper panel clips	11	\$ 20.00	x
5	4	Front wiper panel left garnish clips	11	\$ 10.00	x
6	4	Front wiper panel right garnish clips	11	\$ 10.00	x
7	6	Front wiper panel centre garnish clips	11	\$ 20.00	x
8	1	Front air-con gas	refer 4/16/20	\$ 80.00	x
9	1	Front no plate	mm	\$ 80.00	20
				<u>\$ 370.00</u>	
Total parts				\$ 19,234.75	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

GBG1655T Toyota Dyna

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,800.00 1000
2	To putty and spray painting front portion.	\$ 1,800.00 800
3	To check wiring and focus front headlamp.	\$ 50.00 20
4	To apply anti rust proofing to front affected area.	\$ 120.00 50
5	To remove and install air-con system to facilitate the repair and refill gas.	\$ 150.00 100
6	To remove and install front dashboard panel to facilitate the repair.	\$ 350.00 200
7	To remove and install front cabin assy to facilitate the repair.	\$ 11 650.00 X
8	Towing service.	\$ 11 150.00 X
Total labour :		\$ 5,070.00

Total parts : \$ 19,234.75
Total labour : \$ 5,070.00
Total repair cost : \$ 24,304.75