

INS CASE OWNER: VO | CC 4, Arm 180 17222, Uf639 | LJK: 70656
 Surveyor: cks | DOI: ASSIGNMENT 21-9-18 | Date / Time: 20/9/2018
 Registered in Mexico: S8M 2020L

Pre-assign / CCU / FTE
 Insured Vehicle No.: PLN3330L | Claim No.: S8M 2020L
 Name of Insured: Lim Bee Seng | Policy No.: P1927073
 Insured Tel No.: _____ | HP: _____ | Make / Model: BMW 530
 Excess Sec II :\$S _____ | D.O.A.: 19/9/2018 | Place of Accident: NE 7 Jms
 Is driver the owner? (YES / NO) _____ | Nature of Accident: _____
 If NO, Driver Name / Age: Lim Koo Mui | OI GIA REPORT: YES / NO, TP GIA REPORT: YES / NO
 Driver Tel No.: 82889986 (V/L: YES / NO) | Insured Liability: % Final ? Yes / No
S8M 2020L

INSRS: WSP: Jm Auto. | INSRS: WSP: _____ | INSRS: WSP: _____ | INSRS: WSP: _____
 Tel: _____ | Tel: _____ | Tel: _____ | Tel: _____
 Liability: _____ | Liability: _____ | Liability: _____ | Liability: _____
 RMKS: _____ | RMKS: _____ | RMKS: _____ | RMKS: _____

| Date/Time | STAGE | DATE / PIC |
|------------------|--|------------|
| <u>21/9</u> | <u>S8M 2020L - X, PLN3330L - X</u> | |
| <u>21/9</u> | <u>21/9 01:19. Sent out 1st letter.</u> | |
| <u>5/10/2018</u> | <u>Spoke to Q2D (Mr Lim Koo Mui) on his accident statement</u> | |
| <u>4:50pm</u> | <u>3 for chain collision and Q2D is the last vehicle, injured TP</u> | |
| | <u>Lim and H/D. Issue OI have HCD protector and want to</u> | |
| | <u>know the claim amount, will update him when we</u> | |
| | <u>finish the claim cost, spoke to Q2 22/10/2018</u> | |
| | <u>LOD is</u> | |
| | <u>IO and Mandate uploaded - KV approval</u> | |
| | <u>After repair photo</u> | |

| | | | |
|--|--|---|----------------------------------|
| PRELIMINARY ADVICE | | Date/Time: <u>19/9</u> | Sent By: <u>Jm</u> |
| FINALIZATION | | Date/Time: _____ | Confirm with: _____ |
| Repair Cost: | \$S <u>7000.00</u> | (2 days) Reduction: <u>3524</u> % | Confirm by: _____ |
| FINAL SETTLEMENT | | Date/Time: <u>22/10/18</u> | Confirm with: <u>Toni</u> |
| Final Liability: | % <u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>28</u> | Email: <input checked="" type="checkbox"/> | Call: <input type="checkbox"/> |
| Repair Cost: | \$S <u>7490.00</u> | If NO or B 28, Ass. Lin: <u>2 for chain collision</u> | |
| Loss of Rental (LOR): | \$S <u>800.00</u> (7 days) X \$100.00 | <u>100%, Q2D is last vehicle</u> | |
| Loss of Use (LOU): | \$S <u>-</u> (3 x days) | | |
| Loss of Income (LOI): | \$S <u>-</u> (3 x days) | | |
| LOR only <input checked="" type="checkbox"/> | LOU only <input type="checkbox"/> | LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one] | |
| GIA/LTA Search | \$S <u>-</u> | | |
| Medical | \$S <u>-</u> | | |
| Disbursement | \$S <u>-</u> (e.g. Tow/Independent) | | |
| Legal Cost | \$S <u>-</u> | | |
| Total: | \$S <u>8290.00</u> | Global Sum \$S: _____ | |
| FINAL PAYMENT | | Date/Time: _____ | Confirm with: _____ |
| Payee 1: | \$S <u>7490.00</u> | Name 1: | <u>Jin Auto Services Pte Ltd</u> |
| Payee 2: (Strike if N.A.) | \$S <u>-</u> | Name 2: | |
| Payee 3: (Strike if N.A.) | \$S <u>-</u> | Name 3: | |

Bumbyer

mercus

REF: ASM(AxA)

ASSIGNMENT

From

Date: 21/09/08

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SBM 2020L

at Workshop m/s

Jim Auto

of

Blk 14 Defu Lane 10 #01-412

Insured

Policy No.

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

17800

IDAC Accident Report

Consistent? Yes or No

BIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

1st price - 50% //

L/A 9097

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SBM 2020L

Yr Regn

11/09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Toyota Vios

CC 1497

Colour:

Grey

A/C Insured / Std / NI / NA

Sp. Reading

235440

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053H/9305133093

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/9/08

D.O.I.

21/9/08

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & fl.

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

1/11/2019 1/hrs NH 8703

. \$12,804.85

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel 62898126 Fax 62870580

Company Reg No:200704370C GST Reg No :200704370C

Your ref : SBM2020L

Date: 20.09.2018

MA353HY9

M/S AXA INSURANCE SINGAPORE PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SBM2020L(TOYOTA VIOS)

DATE OF ACCIDENT : 19/9/2018

TO SUPPLY :

List Items(FRONT)

| | | | | | | |
|----|--------|----------------------------|-------|----|----------|---|
| 1 | 1 PC | FRONT BUMPER | DD | \$ | 407.20 | — |
| 2 | 10 PCS | FRONT BUMPER CLIPS | neu | \$ | 38.00 | — |
| 3 | 1 PC | FRONT BUMPER GRILLE | To... | \$ | 213.50 | — |
| 4 | 1 PC | FRONT BUMPER GRILLE CHROME | neu | \$ | 83.40 | — |
| 5 | 1 PC | FRONT BUMPER BADGE | neu | \$ | 47.60 | — |
| 6 | 1 PC | FRONT BUMPER REINFORCEMENT | DD | \$ | 372.00 | — |
| 7 | 1 PC | FRONTSUPPORT PANEL | R | \$ | 788.60 | X |
| 8 | 2 PCS | FRONT HEADLAMP | 11 | \$ | 1,050.60 | X |
| 9 | 1 PC | FRONT BUMPER GRILLE | To... | \$ | 74.70 | — |
| 10 | 1 PC | BONNET | R | \$ | 452.50 | X |
| 11 | 1 PC | BONNET LOCK | neu | \$ | 82.20 | — |

50%
LESS 25% \$ 3,610.30
\$ (902.58) 13186

| | | | | | | |
|----|------|---------------------------|-----|----|----------|---|
| 12 | 1 PC | FRONT NUMBER PLATE S.NETT | neu | \$ | 2,707.73 | — |
| | | | | \$ | 40.00 | — |

Labour Cost(FRONT)

| | | | | | | |
|----|--|---|--|----|--------|-----|
| 13 | | SPRAY PAINTING | | \$ | 800.00 | 600 |
| | | LABOUR CHARGE TO REMOVE & RENEW FRONT | | \$ | 800.00 | 600 |
| 14 | | DAMAGED PARTS | | | | |
| | | LABOUR CHARGE TO REPLACE & REFIX AIRCON | | \$ | 160.00 | 100 |
| 15 | | PARTS & TO REFILL FREON GAS | | | | |
| 16 | | CHECK WIRING | | \$ | 35.00 | 20 |

(TOTAL FRONT PARTS AND LABOUR) BAL C/F \$ 4,542.73 1320

Not Attached
2/5 = 7020/-
8 day.
21/9/18
The ph. Attorney
TOTAL 7041.55

BAL B/F \$ 4,542.73

List Items(REAR)

| | | | | | | |
|----|--------|-------------------------------------|--------|----|--------|---|
| 17 | 1 PC | BOOT LID | 30/50 | \$ | 510.80 | ✓ |
| 18 | 1 PC | BOOT LID RUBBER | 70/100 | \$ | 175.30 | ✓ |
| 19 | 1 PC | BOOT LID LOCK & LOCK COVER | 70/1 | \$ | 95.90 | ✓ |
| 20 | 1 PC | BOOT LID CATCH | 11 | \$ | 24.70 | X |
| 21 | 1 PC | BOOT LID BADGE | 11 | \$ | 47.70 | ✓ |
| 22 | 1 PC | BOOT LID "VIOS" EMBLEM | 11 | \$ | 44.20 | ✓ |
| 23 | 1 PC | BOOT LID "E" EMBLEM | 11 | \$ | 34.30 | ✓ |
| 24 | 1 PC | BOOT LID NUMBER PLATE LIGHT GARNISH | 11 | \$ | 125.70 | X |
| 25 | 1 PC | BOOT LID NUMBER PLATE LIGHT | 11 | \$ | 56.90 | X |
| 26 | 2 PCS | BOOT LID HINGE | 3/4 | \$ | 95.60 | ✓ |
| 27 | 2 PCS | REAR LAMP | 3/4 | \$ | 714.20 | ✓ |
| 28 | 1 PC | REAR END PANEL | 30/50 | \$ | 571.80 | ✓ |
| 29 | 1 PC | REAR END PANEL GARNISH | 70/1 | \$ | 200.70 | ✓ |
| 30 | 1 PC | REAR BUMPER | 12/5 | \$ | 407.50 | ✓ |
| 31 | 10 PCS | REAR BUMPER CLIP | 11 | \$ | 38.00 | ✓ |
| 32 | 2 PCS | REAR BUMPER REFLECTOR | 11 | \$ | 165.60 | ✓ |
| 33 | 2 PCS | REAR BUMPER SIDE RETAINER | 3/4 | \$ | 184.60 | ✓ |

210 Rear floor panel top side sponges @ 18/120 30/50 ✓
 LESS 25% \$ (873.38)
 \$ 2,620.13

Special Nett items

| | | | | | | |
|----|------|-------------------|----|----|--------|-----|
| 34 | 1 PC | REAR NUMBER PLATE | 11 | \$ | 40.00 | 40 |
| 35 | 1 PC | REVERSE SENSOR | 11 | \$ | 250.00 | 200 |
| | | | | \$ | 290.00 | |

Labour Cost(REAR)

| | | | | | | |
|----|--|---|--|----|----------|------|
| 36 | | SPRAY PAINTING | | \$ | 1,250.00 | 1000 |
| 37 | | LABOUR CHARGE TO REMOVE, RENEW THE ABOVE | | \$ | 1,100.00 | 1000 |
| 38 | | DAMAGED PARTS AND REPAIR FENDERS PANEL | | | | |
| 38 | | REMOVE CARPETS | | \$ | 120.00 | 80 |
| 39 | | LABOUR CHARGE TO REMOVE AND RENEW REVERSE | | \$ | 80.00 | 50 |
| 40 | | SENSOR | | | | |
| 40 | | TUFF COATING | | \$ | 120.00 | 60 |
| 41 | | WIRING | | \$ | 35.00 | 20 |

TOTAL REAR PARTS \$ 5,905.13 2210

TOTAL COST \$ 10,447.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 of 2

P-6463-10

less 50%

3231.55

S.V 280

lahan 3530

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref : SBM2020L

5/10/2018

M/S AXA INSURANCE PTE LTD

DEAR SIR / MADAM

SUPPLEMENTARY ITEM FOR SBM2020L (TOYOTA VIOS)

TO SUPPLY :

Nett Items

1) 1PC RADIATOR 1496.32

| | |
|----------|-------------------|
| 50% CM | \$1,607.10 |
| LESS 25% | (\$401.78) |
| | <u>\$1,205.33</u> |

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62896126 Fax: 62870590

Company Reg No: 200704370C GST Reg No: 200704370C

Your ref : SBM2020L

Date: 20.09.2018

M/S AXA INSURANCE SINGAPORE PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SBM2020L(TOYOTA VIOS)

DATE OF ACCIDENT : 19/9/2018

TO SUPPLY :

List Items(FRONT)

| | | | | | | |
|----|--------|----------------------------|-------|----|----------|---|
| 1 | 1 PC | FRONT BUMPER | ps | \$ | 407.20 | ✓ |
| 2 | 10 PCS | FRONT BUMPER CLIPS | ru | \$ | 38.00 | ✓ |
| 3 | 1 PC | FRONT BUMPER GRILLE | To. n | \$ | 213.50 | ✓ |
| 4 | 1 PC | FRONT BUMPER GRILLE CHROME | ru | \$ | 83.40 | ✓ |
| 5 | 1 PC | FRONT BUMPER BADGE | ru | \$ | 47.60 | ✓ |
| 6 | 1 PC | FRONT BUMPER REINFORCEMENT | | \$ | 372.00 | ? |
| 7 | 1 PC | FRONT SUPPORT PANEL | | \$ | 788.60 | ? |
| 8 | 2 PCS | FRONT HEADLAMP | | \$ | 1,050.60 | ? |
| 9 | 1 PC | FRONT BUMPER GRILLE | To. n | \$ | 74.70 | ✓ |
| 10 | 1 PC | BONNET | R | \$ | 452.50 | X |
| 11 | 1 PC | BONNET LOCK | ru | \$ | 82.20 | ✓ |

LESS 25% \$ (902.58)

\$ 2,707.73

| | | | | | | |
|----|------|---------------------------|------|----|-------|---|
| 12 | 1 PC | FRONT NUMBER PLATE S.NETT | h. n | \$ | 40.00 | ✓ |
|----|------|---------------------------|------|----|-------|---|

Labour Cost(FRONT)

| | | | | | | |
|----|--|---|--|----|--------|-----|
| 13 | | SPRAY PAINTING | | \$ | 800.00 | 600 |
| | | LABOUR CHARGE TO REMOVE & RENEW FRONT | | \$ | 800.00 | 600 |
| 14 | | DAMAGED PARTS | | | | |
| | | LABOUR CHARGE TO REPLACE & REFIX AIRCON | | \$ | 160.00 | ? |
| 15 | | PARTS & TO REFILL FREON GAS | | | | |
| 16 | | CHECK WIRING | | \$ | 35.00 | 70 |

(TOTAL FRONT PARTS AND LABOUR) BAL C/F \$ 4,542.73

Not Attached
over
2/5/5
8 Aug.
21/9/18
The Mr. Henry

BAL B/F \$ 4,542.73

List Items(REAR)

| | | | | | | |
|---|--------|-------------------------------------|--------|----|----------|---|
| 17 | 1 PC | BOOT LID | 30150 | \$ | 510.80 | — |
| 18 | 1 PC | BOOT LID RUBBER | 750701 | \$ | 175.30 | — |
| 19 | 1 PC | BOOT LID LOCK & LOCK COVER | 701 | \$ | 95.90 | — |
| 20 | 1 PC | BOOT LID CATCH | 11 | \$ | 24.70 | X |
| 21 | 1 PC | BOOT LID BADGE | 111 | \$ | 47.70 | — |
| 22 | 1 PC | BOOT LID "VIOS" EMBLEM | 111 | \$ | 44.20 | — |
| 23 | 1 PC | BOOT LID "E" EMBLEM | 111 | \$ | 34.30 | — |
| 24 | 1 PC | BOOT LID NUMBER PLATE LIGHT GARNISH | 11 | \$ | 125.70 | X |
| 25 | 1 PC | BOOT LID NUMBER PLATE LIGHT | 11 | \$ | 56.90 | X |
| 26 | 2 PCS | BOOT LID HINGE | 111 | \$ | 95.60 | — |
| 27 | 2 PCS | REAR LAMP | 300 | \$ | 714.20 | — |
| 28 | 1 PC | REAR END PANEL | 30150 | \$ | 571.80 | — |
| 29 | 1 PC | REAR END PANEL GARNISH | 111 | \$ | 200.70 | — |
| 30 | 1 PC | REAR BUMPER | 115 | \$ | 407.50 | — |
| 31 | 10 PCS | REAR BUMPER CLIP | 111 | \$ | 38.00 | — |
| 32 | 2 PCS | REAR BUMPER REFLECTOR | 111 | \$ | 165.60 | — |
| 33 | 2 PCS | REAR BUMPER SIDE RETAINER | 111 | \$ | 184.60 | — |
| 2105 Rear floor panel top side sponges @ 181 x 2 = 362.00 | | | | \$ | 3,493.50 | — |
| LESS 25% | | | | \$ | (873.38) | — |
| | | | | \$ | 2,620.13 | — |

Special Nett items

| | | | | | | |
|----|------|-------------------|-----|----|--------|----|
| 34 | 1 PC | REAR NUMBER PLATE | 111 | \$ | 40.00 | 40 |
| 35 | 1 PC | REVERSE SENSOR | 111 | \$ | 250.00 | — |
| | | | | \$ | 290.00 | — |

Labour Cost(REAR)

| | | | | | | |
|----|--|---|--|----|----------|------|
| 36 | | SPRAY PAINTING | | \$ | 1,250.00 | 1000 |
| 37 | | LABOUR CHARGE TO REMOVE, RENEW THE ABOVE DAMAGED PARTS AND REPAIR FENDERS PANEL | | \$ | 1,100.00 | 1000 |
| 38 | | REMOVE CARPETS | | \$ | 120.00 | 80 |
| 39 | | LABOUR CHARGE TO REMOVE AND RENEW REVERSE SENSOR | | \$ | 80.00 | 50 |
| 40 | | TUFF COATING | | \$ | 120.00 | 60 |
| 41 | | WIRING | | \$ | 35.00 | 20 |

TOTAL REAR PARTS \$ 5,905.13

TOTAL COST \$ 10,447.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Page 2 of 2

3181.63
2705

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 7682J |
| Vehicle Details | |
| Vehicle No.: | SBM2020L |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 21 Sep 2018 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | VIOS E AUTO |
| Primary Colour: | Silver |
| Manufacturing Year: | 2009 |
| Engine No.: | 1NZX976022 |
| Chassis No.: | MR053HY9305133093 |
| Maximum Power Output: | 80.0 kW (107 bhp) |
| Open Market Value: | \$12,717.00 |
| Original Registration Date: | 02 Nov 2009 |
| First Registration Date: | 02 Nov 2009 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$12,717.00 6358 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 01 Nov 2019 |
| PARF Rebate Amount: | \$6,994.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 01 Nov 2019 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 10 |
| QP Paid: | \$18,899.00 |
| COE Rebate Amount: | \$2,103.00 |
| Total Rebate Amount: | \$9,097.00 |

The information contained herein is correct as at 21 Sep 2018

13

OK

- 2016 Hyundai Elantra / Avante
- A New Chapter - Skoda Singapore
- Finding Job in automotive sector as fresh grad, need a...

Toyota vios

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home > Used Cars > KSL Automotive Pte Ltd > Toyota Vios 1.5A E

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Vehicle Number Plates

BUY & SELL

Your AUSPICIOUS & UNIQUE Vehicle No.

Do you know? We are Singapore's BIGGEST PLAYER with the most vehicle plate numbers for sale?

Click here to see all Auspicious Numbers!

Close

UOB
Business
Loan for SME



Get up to S\$550,000 to grow your business and receive \$400 shopping vouchers! T&Cs apply.

Compare

Toyota Vios 1.5A E

OverviewFinancialAccessoriesSimilarResearchPhotosMap



KSL Automotive
Your Trusted Partner in Automotive

Add to Shortlist (0)Add to CompareAdd a NoteReport ErrorMore ActionsShare

Car Details

| | | |
|---------------|--|---|
| Price | \$16,800 | |
| Depreciation | \$10,380 /yr | View models with similar depreciation |
| Reg Date | 24-Sep-2009 (1yr 2days COE left) | |
| Manufactured | 2009 | |
| Mileage | - | |
| Transmission | Auto | |
| Engine Cap | 1,497 cc | |
| Road Tax | \$684 /yr | |
| Power | 80.0 kW (107 bhp) | View specs of the Toyota Vios (2007-2013) |
| Curb Weight | 1,095 kg | |
| Features | Auto Transmission, ABS, Dual SRS Airbags, Fuel Efficiency Of 15Km Per Litre, 1.5 Litre VVT-I 16 Valves Inline DOHC Engine. | |
| Accessories | | |
| Description | Only 1 Female Careful Driver Owner, Very Well Maintain Of The Vehicle, No Repair Needed! In House Loan Available! Well Maintained, Low Fuel Consumption, Suitable And Affordable Unit. Door Step Viewing Available. Call Us Now! | |
| COE | \$18,020 | |
| OMV | \$12,717 | |
| ARF | \$12,717 | |
| Dereg Value | \$8,806 as of today (change) | |
| No. of Owners | 1 | |
| Type of Veh | Mid-Size Sedan | |
| Category | PAAF Car | |
| Availability | Available | |

Add to ShortlistAdd to CompareAdd a Note

Posted on: 19-Sep-2018 | Last Updated on: 21-Sep-2018



Seller Information

| | | |
|-------------------|--|----------|
| Company | KSL Automotive Pte Ltd • dealer's present • 46 vehs sold 65 vehs available | |
| Address | 2A Kian Teck Avenue Level 3 Search cars nearby this location | |
| Office No | 62660777 | |
| Contact Person(s) | Derek | 96872514 |
| | Zak | 87770188 |
| | Rox | 98252048 |
| | Gary | 96692872 |

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 22 October 2018 4:28 PM
To: 'Jouis'
Subject: RE: SBM2020L THIRD PARTY SURVEY Accident Involving vehicle SBM2020L
And SLN3330L ON 19/9/18 *** LKK REF: CC4/ASM18017222/Ufa3
Attachments: DV SBM 2020L.pdf
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Your Ref: SBM 2020L
Our Ref: CC4/ASM18017222/Ufa3

Dear Jouis,

We refer to the above matter.

Thank you for your acceptance.

Please duly sign the DV attached and return with Rental Tax Invoice for payment processing.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Jouis [mailto:jouis@jinauto.com.sg]
Sent: Monday, 22 October 2018 3:37 PM
To: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>

Poh Kin (LKKAUTO)

From: jous <jous@jinauto.com.sg>
Sent: Monday, 22 October 2018 3:37 PM
To: Poh Kin (LKKAUTO)
Subject: RE: SBM2020L THIRD PARTY SURVEY Accident Involving vehicle SBM2020L
And SLN3330L ON 19/9/18 *** LKK REF: CC4/ASM18017222/Ufa3

Dear Poh Kin

Ok we settle as follow :

| | |
|---------------------------------------|----------------------------|
| 1. Cost of Repair (w/gst) | S\$ 7,490.00 |
| 2. Loss of Rental (\$100.00 x 8 days) | <u>S\$ 800.00</u> |
| | <u>S\$ 8,290.00</u> |

Thank you & Best Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590
Email : jous@jinauto.com.sg

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Monday, 22 October 2018 11:24 AM
To: jous <jous@jinauto.com.sg>
Subject: RE: SBM2020L THIRD PARTY SURVEY Accident Involving vehicle SBM2020L And SLN3330L ON 19/9/18 ***
LKK REF: CC4/ASM18017222/Ufa3
Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Your Ref: SBM 2020L
Our Ref: CC4/ASM18017222/Ufa3

Dear Jouis,

ROAD TRAFFIC ACCIDENT INVOLVING SLN 3330L AND SBM 2020L ON 19/09/2018

We refer to the above matter and your letter of demand dated 12th October 2018.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Monday, 22 October 2018 11:24 AM
To: 'jouis'
Subject: RE: SBM2020L THIRD PARTY SURVEY Accident Involving vehicle SBM2020L
And SLN3330L ON 19/9/18 *** LKK REF: CC4/ASM18017222/Ufa3

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Your Ref: SBM 2020L
Our Ref: CC4/ASM18017222/Ufa3

Dear Joius,

ROAD TRAFFIC ACCIDENT INVOLVING SLN 3330L AND SBM 2020L ON 19/09/2018

We refer to the above matter and your letter of demand dated 12th October 2018.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

| | |
|---------------------------------------|----------------------------|
| 1. Cost of Repair (w/gst) | S\$ 7,490.00 |
| 2. Loss of Rental (\$100.00 x 8 days) | <u>S\$ 800.00</u> |
| | <u>S\$ 8,290.00</u> |

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Thursday, 11 October 2018 6:24 PM
To: 'Jouis'
Cc: Admin A
Subject: RE: SBM2020L THIRD PARTY SURVEY Accident Involving vehicle SBM2020L And SLN3330L ON 19/9/18 *** LKK REF: CC4/ASM18017222/Ufa3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/ASM18017222/Ufa3
Your Ref: SBM 2020L

Dear Jouis,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SLN 3330L, SBM 2020L AND OTHERS ON 19/09/2018

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Re:<S8M00W6O> IA with Mandate Revise uploaded

Type

🔗 Question

Message

Hi Hsiao Tong Pls proceed based on your IA for COR on \$7k-VO

Reply

<< <S8M00W6O> IA with mandate uploaded

Type

🔗 Question

Message

Dear Vale, we refer to the above matter. The said chain collision involved 3 vehicles whereby our insured was the last vehicle. In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%. We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. Propose settlement amount is between \$ 6,196.99 to \$7,266.99. All the relevant documents had been uploaded in SMART CLAIM. For your kind attention and instruction. Thank you- Pohkin 11/10/2018

Reply



<S8M00W6O> IA with Mandate Revise uploaded

Type

🔔 Question

Message

Dear Vale, we refer to the above matter. We hereby re-seek your approval to offer Third Party repairer "Jin Auto Services Pte Ltd" is as follows: - 1)COR(w/gst): \$7,490.00 + 2) Loss of Rental (8days x \$100.00): \$800.00 =Total: \$8,290.00. **08days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin - 17/10/2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408935 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11/10/2018

Survey Details:

| | |
|---------------------|---------------------------|
| Date of loss | 19-Sep-18 |
| Date of appointment | 20-Sep-18 |
| Date of survey | 21-Sep-18 |
| Location of survey | JIN AUTO SERVICES PTE LTD |

Vehicle Details:

| | | |
|----------------------|-----------------------------|-----------|
| Claim Type: | THIRD PARTY CLAIM | |
| Vehicle number | SBM2020L | |
| Make and Model | TOYOTA VIOS E AUTO - 1497cc | |
| Date of registration | 2-Nov-09 | |
| Excess | | |
| Market Value | \$ | 17,800.00 |
| Part Rebate | \$ | 9,097.00 |
| Nett Loss | \$ | 8,703.00 |

Repair details:

| | | |
|------------------|----|-----------|
| Initial Estimate | \$ | 10,447.85 |
|------------------|----|-----------|

Proposed/Revised repair cost:

| | | |
|-------------------------|----|----------|
| Parts | \$ | 2,627.40 |
| Check items (estimate) | \$ | 1,265.60 |
| Labour | \$ | 3,430.00 |
| Total | \$ | 7,323.00 |
| Lump Sum(if applicable) | \$ | - |

| | |
|---------------------------|--------|
| Number of days for repair | 8 days |
|---------------------------|--------|



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

| |
|--|
| |
|--|

Mandate:

| Liability(TP) | 100% | 100% |
|---------------------------|----------------------------------|----------------------------------|
| | with check item | no check item |
| Proposed repair cost | \$6,259.50 (\$5,850.00 + 7% GST) | \$5,189.50 (\$4,850.00 + 7% GST) |
| Loss of use | \$ - | \$ - |
| Loss of rental (estimate) | \$1,000.00(\$100.00 x 10 days) | \$1,000.00(\$100.00 x 10 days) |
| Loss of income | \$ - | \$ - |
| LTA search fees | \$ 7.49 | \$ 7.49 |
| Others | \$ - | \$ - |
| Proposed Total | \$ 7,266.99 | \$ 6,196.99 |

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Business Registration No:200704370C GST Registration No:200704370C

Date:12/10/2018

M/S AXA Insurance Singapore Pte Ltd

Dear Sir/Madam

ACCIDENT INVOLVING VEHICLE SBM2020L & SLN3330L ON 19/9/18

We are instructed by the owner SBM2020L to write, negotiate and settle claim on his behalf for the above mentioned accident. Our client's vehicle SBM2020L was inspected and surveyed by your appointed surveyor's. We are now seeking the total amount of claim as follow:

| | | |
|----------------|------|---------|
| 1) Repair cost | \$\$ | 7490.00 |
| 2) Rental | | 960.00 |
| | | <hr/> |
| | SS | 8450.00 |
| | | <hr/> |

The following documents are enclosed to support our claims:

- Repair bill & Rental agreement

Yours faithfully

Jouis Seow

Email: jouis@jinauto.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

8th October 2018

LIM BEE SENG

Block 459 Segar Road,
#13-185,
Singapore 670459.

Attn: Lim Kee Meng Andre

Dear Sir,

OUR REF : CC4/ASM18017222/Ufa3

YOUR REF : SLN 3330L

**ROAD TRAFFIC ACCIDENT INVOLVING SLN 3330L, SBM 2020L AND OTHERS
ALONG PIE TOWARDS JURONG ON 19.09.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s Jin Auto Services Pte Ltd, acting on behalf of the owner of SBM 2020L against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AXA Insurance Pte Ltd.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to pohkin@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2132 or email us at pohkin@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Poh Kin, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORISATION

To: Jin Auto Services Pte Ltd

Dear Sir

ACCIDENT INVOLVING SBM 2020L & SLN 3330L ON 19/9/18

I/We, the owner of Vehicle Registration Number, SBM 2020L hereby authorise you to repair my/our vehicle repair, submit, correspond, negotiate and settle my/our claim for cost of repair and/or uninsured losses arising from the above accident.

I/We further authorise you M/S Jin Auto Services Pte Ltd, to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me/us in respect of my/our claim above.

I/We hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my /our behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me/us in person.

I/We further confirm that the acceptance by M/s Jin Auto Services Pte Ltd of the settlement amount in respect of such claim shall constitute the full discharge of my/our claim in respect of such loss and damage.

Signed by :



Name :

Ang Suan Lee

NRIC NO:

S727682J

Date:

21/9/18



redefining / insurance

CLAIM REF : S8M00W60
INSURED : LIM BEE SENG

DISCHARGE VOUCHER

We/I ANG SOON LEE (HONG SHUNLI), NRIC No. 57217682/J hereby agree to accept the sum of dollars [Eight thousand two hundred ninety only] (S\$ 8,290.00) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their insured or the driver of motor vehicle no. SLN 3330L as a result of an accident along on 19th September 2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SBM 2020L.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said insurer, owner and/or driver of vehicle no. SLN 3330L in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SLN 3330L.

Dated this 24 day of Oct 2018

Claimant's Signature : _____

NRIC no./ Company Stamp : 57217682 J.

Occupation/ Business : _____

Address : _____

Telephone No. : _____

Witness's Name : _____

Witness's Signature : _____

Witness's NRIC No. : _____



JIN AUTO SERVICES PTE LTD

Blk 14 #01- 410/412 Defu Lane 10 Singapore 539195

Tel: 6289 8126 (24 hrs) Fax: 6287 0590

Email: jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg. No: 200704370C

TAX INVOICE

M/s

AXA Insurance Singapore Pte Ltd

Invoice No: 16242

Vehicle No: SBM2020L

Date: 12/10/18

[illegible]

N.B No responsibility will be accepted for any loss or damage to any Vehicles or parts left in this workshop for any reason whatsoever.

E. & O. E.

ADD GST

TOTAL



JIN AUTO SERVICES PTE LTD



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/000

No. 19735

Date, 28/9/18

OFFICIAL RECEIPT

Received from

Ang Soon Lee

the sum of Dollars

Nine hundred sixty only

being Payment Of

854 57307 (20/9/18 - 28/9/18)

\$

960/-

Cash/Cheque No.

DAWN ENTERPRISES



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Nº 36120

RENTAL AGREEMENT

DATE 20/9/2018

HIRER'S PARTICULARS

Name Ang Soon Lee
Address BLK 532 Hougang Ave 6
06-305 (530532)

I/C or Passport No. S721762J Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (HP) _____ (Residence) _____

DRIVER'S PARTICULARS

Name _____

Address _____

I/C or Passport No. _____ Country _____

Occupation _____

Date of Birth _____ Age _____

Driving Licence No. _____ Date Passed _____

Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licensed to carry 09 passengers only.
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus cost of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$85,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

CHARGES

| | |
|--------------------------------|-----------|
| 8 Day at \$ 120 per days | \$ 960.00 |
| Day at \$ per week | |
| Day at \$ per month | |
| TOTAL AMOUNT | \$ 960.00 |
| AMOUNT PAID | |
| BALANCE DUE | |
| Days Extension From To | |
| Amount Deposit (refundable) \$ | |

SCHEDULE

MODEL

| | | |
|-----------|---------|---------|
| SJ4 SF30J | | T/A/T/S |
| Date | Time | Mileage |
| 20/9/18 | 9:30 am | |
| 28/9/18 | 11:30 | |

FROM

20/9/18

TO

28/9/18

I/we have read and understood the terms and conditions above and hereby agreed to abide:

Hirer's Signature

Driver/Guarantor's Signature

DAWN ENTERPRISES

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| | | | |
|-------------------|----------------------|--------|-----------------|
| Vehicle No: | SLN 3330L (Insd veh) | Model: | TOYOTA VIOS (A) |
| | SBM 2020L (TP veh) | | |
| Date of Accident: | 19/09/2018 | | |

| | | | |
|-----------------------|---|------------------------------|--|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Repair Estimate | : | \$ | 12,449.10 |
| Final Repair Cost | : | \$ | 7,490.00 |
| Loss of Use | : | \$ | days at \$0.00 per day |
| Rental (If any) | : | \$ | 800.00 8 days |
| LTA / GIA Search Fee | : | \$ | 0.00 |

| | | | |
|---------|---|----|------|
| Others: | : | \$ | 0.00 |
|---------|---|----|------|

| | | | |
|----------------------|---|----|----------|
| | : | \$ | |
| Final Settlement Sum | : | \$ | 8,290.00 |

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ 100 ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

| Payment Instruction: Payee's Breakdown | | | |
|--|---------------------------|---|-------------|
| 1) | JIN AUTO SERVICES PTE LTD | : | \$ 8,290.00 |

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

30/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---------------------------------|---|
| AXA INSURANCE PTE LTD | | Ref : CC4/ASM18017222/Ufa3q2 | |
| 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH | | Date : 30-01-2019 Code : ASM |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SLN 3330L | Veh. Inspected | SBM 2020L |
| Policy No. | P1927873 | Coverage (\$) | 0.00 |
| Claim No. | S8M00W60 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 20/09/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA VIOS (A) | c.c | 1497 |
| Engine No. | HIDDEN | Year of Reg. | 2009 |
| Chassis No. | MR053HY9305133093 | Colour | GREY |
| Odometer | 235440 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195/55 R15 | HANKOOK | 6 mm |
| L/H Front Tyre | 195/55 R15 | HANKOOK | 6 mm |
| R/H Rear Tyre | 195/55 R15 | HANKOOK | 6 mm |
| L/H Rear Tyre | 195/55 R15 | HANKOOK | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 19/09/2018 | Inspection Date | 21/09/2018 |
| Survey held at | JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 8 Working Days | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBM 2020L

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER (CONSISTENT) | DENTED | ✓ 407.20 | 407.20 |
| 10 | FRONT BUMPER CLIPS (CONSISTENT) | NECESSARY | ✓ 38.00 | 38.00 |
| 1 | FRONT BUMPER GRILLE (CONSISTENT) | TORN | ✓ 213.50 | 213.50 |
| 1 | FRONT BUMPER GRILLE CHROME (CONSISTENT) | CRACKED | ✓ 83.40 | 83.40 |
| 1 | FRONT BUMPER BADGE (CONSISTENT) | NECESSARY | ✓ 47.60 | 47.60 |
| 1 | FRONT BUMPER REINFORCEMENT (CONSISTENT) | DENTED | ✓ 372.00 | 372.00 |
| 1 | FRONT SUPPORT PANEL (CONSISTENT) | TO REPAIR SEE LABOUR | ✓ 788.60 | - |
| 2 | FRONT HEADLAMP (CONSISTENT) | NOT NECESSARY | ✓ 1,050.60 | - |
| 1 | FRONT BUMPER GRILLE (CONSISTENT) | TORN | ✓ 74.70 | 74.70 |
| 1 | BONNET (CONSISTENT) | TO REPAIR SEE LABOUR | ✓ 452.50 | - |
| 1 | BONNET LOCK (CONSISTENT) | TWISTED | ✓ 82.20 | 82.20 |
| 1 | BOOT LID (CONSISTENT) | BADLY DENTED | ✓ 510.80 | 510.80 |
| 1 | BOOT LID RUBBER (CONSISTENT) | TWISTED | ✓ 175.30 | 175.30 |
| 1 | BOOT LID LOCK & LOCK COVER (CONSISTENT) | TWISTED | ✓ 95.90 | 95.90 |
| 1 | BOOT LID CATCH (CONSISTENT) | NOT NECESSARY | ✓ 24.70 | - |
| 1 | BOOT LID BADGE (CONSISTENT) | NECESSARY | ✓ 47.70 | 47.70 |
| 1 | BOOT LID 'VIOS' EMBLEM (CONSISTENT) | NECESSARY | ✓ 44.20 | 44.20 |
| 1 | BOOT LID 'E' EMBLEM (CONSISTENT) | NECESSARY | ✓ 34.30 | 34.30 |
| 1 | BOOT LID NUMBER PLATE LIGHT GARNISH (CONSISTENT) | NOT NECESSARY | ✓ 125.70 | - |
| 1 | BOOT LID NUMBER PLATE LIGHT (CONSISTENT) | NOT NECESSARY | ✓ 56.90 | - |
| 2 | BOOT LID HINGE (CONSISTENT) | BENT | ✓ 95.60 | 95.60 |
| 2 | REAR LAMP (CONSISTENT) | BROKEN | ✓ 714.20 | 714.20 |
| 1 | REAR END PANEL (CONSISTENT) | BADLY DENTED | ✓ 571.80 | 571.80 |
| 1 | REAR END PANEL GARNISH (CONSISTENT) | TWISTED | ✓ 200.70 | 200.70 |
| 1 | REAR BUMPER (CONSISTENT) | DISTORTED | ✓ 407.50 | 407.50 |
| 10 | REAR BUMPER CLIP (CONSISTENT) | NECESSARY | ✓ 38.00 | 38.00 |
| 2 | REAR BUMPER REFLECTOR (CONSISTENT) | CRACKED | ✓ 165.60 | 165.60 |
| 2 | REAR BUMPER SIDE RETAINER (CONSISTENT) | BENT | ✓ 184.60 | 184.60 |

Report Ref No. CC4/ASM18017222/Ufa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No :2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|-----------|---------------------------|-------------------|
| 2 | REAR FLOOR PANEL TOP SIDE SPONGES (CONSISTENT) | TORN | 362.00 | 362.00 |
| 1 | RADIATOR (CONSISTENT) (ADDITIONAL) | CRACKED | 1,607.10 | 1,496.30 |
| | LESS 25% DISCOUNT | | -2,268.23 | - |
| | LESS 50% DISCOUNT | | - | -3,231.55 |
| | | | 6,804.67 | 3,231.55 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | FRONT NUMBER PLATE (SN) (CONSISTENT) | BENT | 40.00 | 40.00 |
| 1 | REAR NUMBER PLATE (SN) (CONSISTENT) | CRACKED | 40.00 | 40.00 |
| 1 | SET REVERSE SENSOR (SN) (CONSISTENT) | SHORTED | 250.00 | 200.00 |
| | | | 330.00 | 280.00 |
| | <u>LABOUR</u> | | | |
| | SPRAY PAINTING. | | 800.00 | 600.00 |
| | LABOUR CHARGE TO REMOVE & RENEW FRONT DAMAGED PARTS, INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL AND BONNET. | | 800.00 | 600.00 |
| | LABOUR CHARGE TO REPLACE & REFIX AIRCON PARTS & TO REFILL FREON GAS. | | 160.00 | 100.00 |
| | CHECK WIRING . | | 35.00 | 20.00 |
| | SPRAY PAINTING. | | 1,250.00 | 1,000.00 |
| | LABOUR CHARGE TO REMOVE, RENEW THE ABOVE DAMAGED PARTS AND REPAIR FENDERS PANEL . | | 1,100.00 | 1,000.00 |
| | REMOVE CARPETS. | | 120.00 | 80.00 |
| | LABOUR CHARGE TO REMOVE AND RENEW REVERSE SENSOR. | | 80.00 | 50.00 |
| | TUFF COATING. | | 120.00 | 60.00 |
| | WIRING . | | 35.00 | 20.00 |
| | | | - | - |
| | | | - | - |
| | | | - | - |
| | | | 4,500.00 | 3,530.00 |
| GRAND TOTAL | | | 11,634.67 | 7,041.55 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 7,000.00 |

Report Ref No. CC4/ASM18017222/Ufa3q2



Report Ref No. CC4/ASM18017222/Ufa3q2

A handwritten signature in black ink, appearing to be 'Chua' followed by a stylized surname.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

| | |
|--------------|--|
| Claim | SBR00W60 |
| Reference | CCA/ASM18017222/Ufa3a2 |
| Loss Date | 19 September 2018 |
| Request Date | 20 September 2018 |
| Due Date | |
| Vendor Name | LKK AUTO CONSULTANTS PTE LTD (TP) |
| Type of Loss | Third Party Vehicle Damage |
| Services | Pending verification - Direct Settlement |

| | |
|------------------------------|--------------------------|
| Actions | |
| Next Step | Wait for Approve Invoice |
| <button>Add Invoice</button> | |

| | |
|--|--------------|
| Vehicle Information | |
| Incident Vehicle Registration # | SBM2020L |
| Make | TPVD UNKNOWN |
| Model | |
| Service Address | |
| ... | |
| Primary Contact/Insured | |
| LIM BEE SEHG BLK 117 POTONG PASIR AVENUE 1, #0B-92A, 350117, Singapore | |
| ADMIN@CHESSA.COM.SG | |
| Claim Handler | |
| OH Vale 6568804897 vale.oh@aka.com.sg | |

| Actions | |
|-----------|--------------------------|
| Next Step | Wait for Approve Invoice |
| | <div> Add Invoice </div> |

Additional Instructions

NON-REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+

Upload Documents

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---|---------------------|----------|---------|------------------|
| <div> <div>📄</div> <div>Accident Statement</div> </div> | Reports & Statement | | Merimen | |

