

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref : SBM2020L

Date: 20.09.2018

M/S AXA INSURANCE SINGAPORE PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SBM2020L(TOYOTA VIOS)

DATE OF ACCIDENT : 19/9/2018

TO SUPPLY :

List Items(FRONT)

1	1 PC	FRONT BUMPER	DO	\$	407.20	✓
2	10 PCS	FRONT BUMPER CLIPS	re	\$	38.00	✓
3	1 PC	FRONT BUMPER GRILLE	To.1	\$	213.50	✓
4	1 PC	FRONT BUMPER GRILLE CHROME	re	\$	83.40	✓
5	1 PC	FRONT BUMPER BADGE	re	\$	47.60	✓
6	1 PC	FRONT BUMPER REINFORCEMENT		\$	372.00	?
7	1 PC	FRONTSUPPORT PANEL		\$	788.60	?
8	2 PCS	FRONT HEADLAMP		\$	1,050.60	?
9	1 PC	FRONT BUMPER GRILLE	To.1	\$	74.70	✓
10	1 PC	BONNET	R	\$	452.50	X
11	1 PC	BONNET LOCK	1.1	\$	82.20	✓

SV.
LESS 25% \$ 3,610.30
\$ (902.58)
\$ 2,707.73

12	1 PC	FRONT NUMBER PLATE S.NETT	3.1	\$	40.00	✓
----	------	---------------------------	-----	----	-------	---

Labour Cost(FRONT)

13		SPRAY PAINTING		\$	800.00	600
		LABOUR CHARGE TO REMOVE ,& RENEW FRONT		\$	800.00	600
14		DAMAGED PARTS				
		LABOUR CHARGE TO REPLACE & REFIX AIRCON		\$	160.00	?
15		PARTS & TO REFILL FREON GAS				
16		CHECK WIRING		\$	35.00	20

(TOTAL FRONT PARTS AND LABOUR) BAL C/F \$ 4,542.73

Not Attached
2/5 R
Sdy.
21/9/18
The ph. Attorney

BAL B/F \$ 4,542.73

List Items(REAR)

17	1 PC	BOOT LID	301500	\$	510.80	✓
18	1 PC	BOOT LID RUBBER	750701	\$	175.30	✓
19	1 PC	BOOT LID LOCK & LOCK COVER	701	\$	95.90	✓
20	1 PC	BOOT LID CATCH	11	\$	24.70	✗
21	1 PC	BOOT LID BADGE	nee	\$	47.70	✓
22	1 PC	BOOT LID "VIOS" EMBLEM	nee	\$	44.20	✓
23	1 PC	BOOT LID "E" EMBLEM	nee	\$	34.30	✓
24	1 PC	BOOT LID NUMBER PLATE LIGHT GARNISH	11	\$	125.70	✗
25	1 PC	BOOT LID NUMBER PLATE LIGHT	11	\$	56.90	✗
26	2 PCS	BOOT LID HINGE	301	\$	95.60	✓
27	2 PCS	REAR LAMP	300	\$	714.20	✓
28	1 PC	REAR END PANEL	301500	\$	571.80	✓
29	1 PC	REAR END PANEL GARNISH	701	\$	200.70	✓
30	1 PC	REAR BUMPER	015	\$	407.50	✓
31	10 PCS	REAR BUMPER CLIP	nee	\$	38.00	✓
32	2 PCS	REAR BUMPER REFLECTOR	c ne	\$	165.60	✓
33	2 PCS	REAR BUMPER SIDE RETAINER	301	\$	184.60	✓

215 Rear floor panel top side sponges @ 181x22 302011 ✓
 LESS 25% \$ (873.38)
 \$ 2,620.13

Special Nett items

34	1 PC	REAR NUMBER PLATE	c ne	\$	40.00	40
35	1 PC	REVERSE SENSOR	shell	\$	250.00	✓
				\$	290.00	

Labour Cost(REAR)

36		SPRAY PAINTING	\$	1,250.00	1000
		LABOUR CHARGE TO REMOVE , RENEW THE ABOVE	\$	1,100.00	1000
37		DAMAGED PARTS AND REPAIR FENDERS PANEL			
38		REMOVE CARPETS	\$	120.00	80
		LABOUR CHARGE TO REMOVE AND RENEW REVERSE	\$	80.00	50
39		SENSOR			
40		TUFF COATING	\$	120.00	60
41		WIRING	\$	35.00	20

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 of 2

TOTAL REAR PARTS \$ 5,905.13

TOTAL COST \$ 10,447.85

3181.63
 2708