

1/1/2018

INS. CASE OWNER:

CC 6/AIG1801 JMC, U/KH/SZ

LKK:
IDAC:

Surveyor:

Marius

DOI:

21/9/18

Date / Time:

21/9/18

Registered in Merimen:

21/9/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKR 8446P

Claim No.:

960711267834

Name of Insured:

PHIMP NEW ORY

Policy No.:

180017289

Insured Tel No.:

HP: 8282629

Make / Model:

WOWO

Excess Sec II:SS

D.O.A: 20/9/18

Place of Accident:

BOUNDARY KB

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L, YES / NO)

OI GIA REPORT (YES / NO) : TP GIA REPORT (YES / NO)

Insured Liability: % Final ? Yes / No

SIX 3457E



INSRS:
WSP:
Tel:
Liability:
RMKS:

KIM
MUEL



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
20/9/18 VIC	SIX 3457E - X	SKR 8446P - X
19/3/19	OI disputing liability. Get TP video from TP to update OI after seeing video on liability. And OI state claim that TP is speeding. Drop email to OI.	Call OI: 15/3/19 LUNA After call ltr to OI: 15/3/19 VIC
15/3/19	OI DISPUTED LIABILITY Email ltr to OI.	
28.6.19	FILE PASS TO TPISI TO PREPARE REPORT.	

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by: CUS

FINALIZATION Date/Time: Confirm with: Confirm by: CUS

Repair Cost: 45 SS33,400 (12 days) Reduction: 56 % Email Call

FINAL SETTLEMENT Date/Time: 28.08.19 Confirm with: JASON Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 5 If NO or B 28, Ass. Lia: OI TURNING e (ONTAR JUNCTION)

Repair Cost: vIKST SS33,738.00

Loss of Rental (LOR): SS 1,500.00 (15 days) x \$100

Loss of Use (LOU): SS - (5 x days)

Loss of Income (LOI): SS - (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS 0.00

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost: SS -

Total: SS 37,240.00 **Global Sum SS:**

FINAL PAYMENT Date/Time: 28.08.19 Confirm with: JASON Email Call

Payee 1: SS 37,240.00 Name 1: KIM (MUEL) AUTO PTE LTD

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

(08/11/13) wef

ASS. REC. BY: MARCUS

REF:

AIW/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX3953L

at Workshop m/s 1 km due

of _____

Insured: SKR 8546

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 112

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

220 J

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLX3953L Y. Regn: 1, 14

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: BMW 520i c.c. 1997

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 132280 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBASA320000D33967

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40/22 19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>7</u> mm		R/Bal. <u>7</u> mm	
L/Bal. <u>7</u> mm		L/Bal. <u>7</u> mm	
D.O.A. <u>20/9/18</u>		D.O.I. <u>21/9/18</u>	

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 82565 Syas Pall
20/9/18 1044 29435

Date/Time, File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: _____

1) _____
Date/Time, File Return to?

Resurvey No. of Trip: _____

2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: _____
Transportation: _____
S + RS, _____ \$
Photos _____
Others _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

KIM CHWEE AUTO PTE LTD
 1 KAKI BUKIT AVENUE 6
 #01-46/48/50
 SINGAPORE 417883

Not Affected
 2/6/18
 21/9/18
 1/5 \$33,400
 12 day

VEHICLE NO: SLX 3953L

QTY	PARTICULAR			
1 PCS	BONNET	2465.32	Buc	\$2,866.20 ✓
1 PCS	BONNET INSULATOR		Dis	\$266.50 ✓
2 PCS	BONNET HINGES @\$150.00		Bed/Tow	\$300.00 ✓
1 SET	BONNET INSULATOR CLIPS		RR	\$50.00 ✓
1 PCS	front BONNET LOGO	\$2.00	AEC	\$105.00 ✓
2 PCS	BONNET DAMPERS @\$266.00		SW	\$532.00 ✓
2 PCS	BONNET LOCK BRACKETS @\$145.00		Bed/Tow	\$290.00 ✓
1 PCS	BONNET LOCK CABLE		Jm	\$288.00 ✓
1 PCS	BONNET LOCK UPPER		Twl	\$166.00 ✓
2 PCS	BONNET LOCK LOWERS @\$210.00		Twl	\$420.00 ✓
1 PCS	FRONT BUMPER	1718	Dis	\$2,450.00 ✓
1 PCS	FRONT BUMPER REINFORCEMENT	711	Dis	\$842.00 ✓
2 PCS	FRONT BUMPER REINFORCEMENT BRACKETS @\$285.00		Bed/Tow	\$570.00 ✓
2 PCS	FRONT BUMPER REINFORCEMENT BRACKET STARYS @\$105.00		o/s bed	\$210.00 1PC
2 PCS	FRONT BUMPER SIDE HOLDERS @\$145.00		Bed/Tow	\$290.00 ✓
1 PCS	FRONT BUMPER SPONGE		To.n	\$245.00 ✓
2 PCS	FRONT FENDERS @\$1050.00	\$874	N/S R o/s w/gad	\$2,100.00 1PC
2 PCS	FRONT FENDER INNER SHIELDS @\$352.00	\$294	o/s Bed/Tow	\$704.00 1PC
1 SET	FRONT FENDER INNER SHIELD CLIPS		RR	\$60.00 ✓
1 PCS	FRONT FENDER INNER PANEL O/S		n	\$1,010.00 X
1 PCS	FRONT SUPPORT TOP PANEL OUTER		Bed/Tow	\$355.00 ✓
1 PCS	FRONT SUPPORT TOP PANEL INNER		Bed/Tow	\$485.00 ✓
2 PCS	FRONT SUPPORT BARS @\$90.00		n	\$180.00 X
1 PCS	FRONT BUMPER TOW COVER		Tow	\$35.00 ✓
1 PCS	FRONT BUMPER NUMER PLATE GARNISH		NP	\$95.00 X
2 PCS	FRONT BUMPER NOZZLE COVERS @\$45.00		o/s B/W	\$90.00 1PC
2 PCS	FRONT BUMPER NOZZLE JETS @\$210.00		o/s CR	\$420.00 1PC
2 PCS	FRONT BUMPER NOZZLE COVER SPRINGS @\$15.00		o/s M/S	\$30.00 1PC
2 PCS	FRONT GRILLES @\$190.00		CR/B/W	\$380.00 ✓
1 PCS	FRONT BUMPER CENTRE GRILLE		B/W	\$115.00 ✓
2 PCS	FRONT BUMPER CENTRE LOWER SIDE GRILLES @\$60.00		Dis	\$120.00 ✓
4 PCS	FRONT BUMPER PDC SENSORS @\$305.00	265 x 3 = 795	Shield	\$1,220.00 3PCS
1 PCS	FRONT BUMPER INNER BRAKE AIR DUCT O/S		B/W	\$80.00 ✓
1 PCS	FRONT BUMPER INNER AUXILIARY AIR DUCT		B/W	\$315.00 ✓
2 PCS	LED - HEADLAMP ASSYS @\$3800.00,		N/S CR o/s B/W	\$7,600.00 ✓
1 PCS	HEADLAMP DRIVER MODULE O/S (XENON)	485	CR	\$899.00 ✓
1 PCS	HEADLAMP HID BALLAST O/S		n	\$850.00 X
1 PCS	HEADLAMP LOWER BRACKET O/S		CR	\$155.00 ✓
1 PCS	INTERCOOLER		o/s bed	\$913.00 ✓

157

1 PCS	AIR CON CONDENSER	1122-43	O/S	\$1,450.00	✓
1 PCS	AIR CON COOLING PIPE		11	\$388.00	X
1 PCS	AIR CON DISCHARGE HOSE		11	\$392.00	X
1 PCS	AIR CON SUCTION HOSE		11	\$390.00	X
1 PCS	FRONT BUMPER FOG LAMP COVER O/S		O/S	\$105.00	✓
1 PCS	FRONT BUMPER FOG LAMP O/S		CRU	\$318.00	✓
1 PCS	FRONT BUMPER FOG LAMP GARNISH O/S		O/S	\$102.00	✓
1 PCS	FRONT BUMPER UNDER COVER		Toon	\$225.00	✓
1 SET	FRONT BUMPER UNDER COVER CLIPS		MR	\$45.00	✓
1 PCS	RADIATOR	1064.00	Suf/2ur	\$1,415.00	✓
2 PCS	RADIATOR TOP BRACKETS @\$25.00		11	\$50.00	X
2 PCS	RADIATOR TOP BUSHES @\$29.00		11	\$58.00	X
1 PCS	RADIATOR FAN MOTOR ASSY		Suf/2ur	\$1,215.00	✓
1 PCS	FRONT AIR DUCT		Toon	\$329.00	✓
1 PCS	FRONT BUMPER TOP RUBBER STRIP		MR	\$102.00	✓
1 PCS	POWER STEERING OIL COOLING PIPE		11	\$360.00	X
1 PCS	FRONT WINDSCREEN	1233-60	BRD	\$2,150.00	✓
1 PCS	FRONT WINDSCREEN MOULDING		MR	\$185.00	✓
2 PCS	ENGINE MOUNTINGS @\$390.00		11	\$780.00	X
1 PCS	GEARBOX MOUNTING		11	\$311.00	X
1 PCS	DRIVER AIR BAG		Actual	\$2,480.00	✓
1 PCS	DRIVER AIR BAG SPIRAL SENSOR		Actual	\$325.00	✓
1 PCS	PASSENGER AIR BAG	2850	Actual	\$3,015.00	✓
1 PCS	DASHBOARD		Bus	\$1,420.00	✓
1 PCS	AIR BAG CONTROL UNIT	1100	Actual	\$1,850.00	✓
2 PCS	SEATBELTS @\$850.00		11	\$1,700.00	X
2 PCS	SEATBELT BUCKETS @\$620.00	455-	O/S Actual	\$1,240.00	IPC
1 PCS	ROOF LINING		Toon	\$2,166.20	✓
1 PCS	ROOF AIR BAG N/S	2450	Actual	\$2,800.00	✓
1 PCS	FRONT WHEEL HOUSING PANEL O/S		R	\$1,250.00	X
1 PCS	FRONT CHASSIS MEMBER O/S		R	\$899.00	X
1 PCS	OIL COOLER PUMP		11	\$420.00	X
1 PCS	ALTERNATOR		11	\$1,820.00	X
1 PCS	AIR CON COMPRESSOR		11	\$2,118.00	X
1 PCS	FRONT SHOCK ABSORBER O/S		11	\$655.00	X
1 PCS	FRONT KNUCKLE ARM O/S		11	\$1,019.00	X
1 PCS	FRONT WHEEL HUB O/S		11	\$620.00	X
1 PCS	FRONT WHEEL HUB BEARING O/S		11	\$350.00	X
2 PCS	FRONT FENDER INNER TOP SIDE GARNISHS @\$380.00		CRU/Top	\$760.00	✓
1 PCS	BATTERY CABLE TERMINATOR		Actual	\$399.20	✓
1 PCS	HORN UNIT	85	BRD	\$1,850.00	✓
1 PCS	FRONT PDC SENSOR WIRE		Toon	\$299.00	✓
1 PCS	HEADLAMP TOP PANEL O/S		BRD/100	\$288.00	✓
				\$68,215.10	
	S.NETT ITEM				
1 PCS	FRONT LICENCE PLATE W/HOLDER		BRD	\$50.00	40
1 PCS	FRONT WINDSCREEN PRIVATE HIRE STICKER		MR	\$50.00	30
1 PCS	FRONT SPORT RIM O/S		11	\$1,200.00	X

(5/20)

1 BOL	RADIATOR COOLANT	ru	\$80.00	50
1 BOL	AIR CON OIL	ru	\$80.00	50
1 SET	FRONT BUMPER RIVET	ru	\$50.00	✓
LABOUR CHARGES:				
	TOWING CHARGE KINGROLLER		\$180.00	120
	TO CHECK WIRING		\$100.00	30
	TO DISMANTLE & REPLACING PDC SENSOR		\$100.00	50
	TO DISMANTLE & REFIX ENGINE FOR FACELITATE REPAIR CHASSIS	11	\$500.00	X
	TO REPROGRAMME & RESET AIR BAG		\$380.00	300
	TO SPRAY RUST PROOFING		\$180.00	100
	TO REFILL AIR CON GAS		\$150.00	100
	TO CONDUCT WHEEL ALIGNMENT		\$120.00	60
	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE	11	\$380.00	X
	TO DISMANTLE & REPLACING ROOF LINING		\$200.00	180
	TO DISMANTLE & REPLACING FRONT DASHBOARD		\$380.00	300
	TO DISMANTLE & REPLACING AIR BAG SYSTEM	Repair	\$480.00	X
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,500.00	900
	TO PUTTY & SPRAY PAINTING		\$1,800.00	1000
	TOTAL		\$76,175.10	X

3760

UK Autogloss.com's hence notify the Repairer of the following:

- To be paid before any money paid
- To repair damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 8250J

Vehicle Details

Vehicle No.: SLX3953L
Vehicle to be Exported: No
Intended Deregistration Date: 21 Sep 2018
Vehicle Make: B.M.W.
Vehicle Model: 520I AT D/AB 2WD 4DR LED NAV
Primary Colour: Black
Manufacturing Year: 2013
Engine No.: B0660588N20B20B
Chassis No.: WBA5A32000D333967
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$47,692.00
Original Registration Date: 27 Jan 2014
First Registration Date: 27 Jan 2014
Transfer Count: 1
Actual ARF Paid: \$53,769.00 *26884*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Jan 2024
PARF Rebate Amount: \$40,326.00

Intended COE Rebate Details

COE Expiry Date: 26 Jan 2024
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$79,000.00
COE Rebate Amount: \$42,239.00
Total Rebate Amount: \$82,565.00

The information contained herein is correct as at 21 Sep 2018

OK



bmw 520 Price Range Depreciation 2014 Vehicle Type Submit

Advanced Search

Home > Used Cars > Cosmo Automobiles > BMW 5 Series 520i Luxury

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



UNIVERSITY FOUNDATION

EXPO

SUNTEC Level 3 Hall 310-311

September

FRI 21 SAT 22

3-9pm 12-7pm

Specially for Sec 4, O, N, A levels & Dip



6100 9800



VERSEAS Education

Compare

BMW 5 Series 520i Luxury

Overview Financial Accessories Similar Research Photos Map



Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$115,888	
Depreciation	\$16,640 /yr	View models with similar depreciation
Reg Date	22-Jan-2014 (5yrs 4mths COE left)	
Manufactured	2013	
Mileage	32,800 km (7k /yr)	
Transmission	Auto	
Engine Cap	1,997 cc	
Road Tax	\$1,210 /yr	
Power	135.0 kW (181 bhp)	View specs of the BMW 5 Series Sedan (2010-2017)
Curb Weight	1,615 kg	
Features	2.0L 4 Cylinders Inline Twin Power Turbocharged Powerful 181Bhp, Smooth And Reliable 8 Speed Steptronic Transmission, ABS, ESP, Airbags.	
Accessories	LED Headlights, Keyless Entry/Start/Stop, All Round Parking Sensors, Reverse Camera, iDrive With Navigation/Bluetooth, Electrical Seats, Fog Lamps.	
Description	Fully Agent Service, New Facelift Led Model, Perfect Condition! Only Driven 7k Km/Yr! Parked In Sheltered Carpark All The Time. Viewing By Appointment Only! Call Now.	
COE	\$78,700	
OMV	\$47,981	
ARF	\$54,174	
Dereg Value	\$82,633 as of today (change)	
No. of Owners	1	
Type of Veh	Luxury Sedan	
Category	PARF Car, Low Mileage Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note



Seller Information

Company	Cosmo Automobiles * dealer's pricelist * 117 vehs sold 75 vehs available	
Address	210 Turf Club Road Lot A16/A23 Search cars nearby this location	
Location	Car Mall @ The Grandstand	
Office No	64651090	
Contact Person(s)	Derrick	91012525
	Andrew	90990920



BMW 520i Price Range Depreciation 2014 Vehicle Type

Advance Search

Home » Used Cars » Car Empire Automobiles Pte Ltd » BMW 5 Series 520i

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle



BMW 5 Series 520i

Overview Financial Accessories Similar Research Photos Map


Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$110,000	
Depreciation	\$15,770 /yr	View models with similar depreciation
Reg Date	14-Jan-2014	(5yrs 3mths 23days COE left)
Manufactured	2013	
Mileage	97,000 km (20.7k /yr)	
Transmission	Auto	
Engine Cap	1,997 cc	
Road Tax	\$1,210 /yr	
Power	135.0 kW (181 bhp)	View specs of the BMW 5 Series Sedan (2010-2017)
Curb Weight	1,615 kg	
Features	2.0L 4 Cylinders Inline TwinPower Turbocharged, 8 Speed Steptronic Transmission, ABS, ESP, SRS Airbags, Keyless Entry Push/Start, Cruise Control.	
Accessories	Adaptive LED Headlights, Touch Pad, I-Drive With Navi, Bluetooth/Aux/USB Input, Comfort Access Trunk Lid, Digital Odometer, Paddle Shifters, Keyless.	
Description	Full Service History With PML. Facelifted Luxury Model With Digital Odometer And Adaptive LED Lights! Huge Boot Space! Flexible Loan And Trade-In Available. In House Loan With Fast Approval/Delivery. Vicom/STA Welcome. Serious Offers Will Be Considered, Call Now For Any Enquiry Or Viewing.	
COE	\$92,289	
OMV	\$46,721	
ARF	\$52,410	
Dereg Value	\$88,360 as of today (change)	
No. of Owners	3	
Type of Veh	Luxury Sedan	
Category	PARF Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 15-Sep-2018 | Last Updated on: 15-Sep-2018
 Tags: BMW 520i, 2014 BMW 520i, BMW, 520i, Used BMW



Seller Information

Company	Car Empire Automobiles Pte Ltd	
	» dealer's pricelist	
	» 48 vehs sold 47 vehs available	
Address	33 Ubi Avenue 3 #01-74	
	Search cars nearby this location	
Location	Vertex	
Office No	85715708	
Contact Person(s)	Jay	9278917
	Lucas Lim	8750676
	Roy Koh	9048350
	WONG	9853837

Useful Services

- STA Vehicle Inspection**: Afraid of lemons? Request to have this car evaluated professionally. Vehicle Evaluation
- Free Valuation**: Find out the market value for your car. Get a free Car Valuation.

Compare

Upfront Payment

» more Financial Info

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 6 August 2019 10:43 AM
To: Foo, Chityan
Subject: [MANDATE REQUEST] Your ref : 7657312638SG, ACCIDENT ON 20/09/2018 INVOLVING SKR 8546P (OI) & SLX 3953L (TP)

Your ref : **7657312638SG**
Our ref : CC6/AIG18017224/Ueb3

Dear Sirs,

ACCIDENT ON 20/09/2018 INVOLVING SKR 8546P (OI) & SLX 3953L (TP)

We refer to the above matter.

The accident occurred when our insured make a right turn @ control junction collided with third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " **KIM CHWEE AUTO PTE LTD**" at **\$ 37,240.00 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 81,507.36	\$ 35,738.00
2. Loss of Rental (15days x \$100)	\$ 1,500.00	\$ 1,500.00 (15days x \$100)
3. LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 83,009.36	<u>\$ 37,240.00</u>

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

8/28/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SLX3953L (7657312638SG)**
[SKR8546P]

TP

POH HUAT CAR SERVICES

Sep 20 2018 4:00PM

[PHILIP HENDRY]

Kim Chwee Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 23/08/2019 15:36 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$37240.00) - SLX3953L - Claim Handler: Foo, Chit Yan

Approved:37240.00:kindly ensure supporting docs in order.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

15 MARCH 2019

PHILIP HENDRY
22 JALAN TARI PIRING
SINGAPORE 799175

By Post & By Email

Dear Sir/Madam,

OUR REF : CC6/AIG18017224/Uhb3
YOUR REF : SKR 8546P
ACCIDENT INVOLVING SKR 8546P AND SLX 3953L ALONG BOUNDARY ROAD ON
20.09.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLX 3953L against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

Please be informed that your No Claim Discount (NCD – if applicable) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Phendry77@hotmail.com
(Email)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018 Edit Reg		21 Sep 2018 00:00 Edit Adj Rpt	\$533,400.00 Edit Estimates	\$533,400.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	PHILIP HENDRY, ID: S7763161E		
Main Claimant:	POH HUAT CAR SERVICES, Co. Reg. No.: 53318250J		
Vehicle Reg. No.:	SLX3953L	Date of Loss:	20/09/2018 16:00 - :59 [55 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7657312638SG	Policy/Cover Note No.:	1800017989 (Comprehensive)
Vehicle Reg. No. (Insured):	SKR8546P	Policy No. (Claimant):	5100772419
		Excess:	
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 02/10/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (23/08/2019): Alert - Adj Mandate Approved (\$537240.00) - SLX3953L - Claim Handler: Foo, Chit ...
- AIG_SG_EXPRESS (15/08/2019): Alert - Adj Mandate Maintained - SLX3953L - Claim Handler: Foo, Chit Yan
- AIG_SG (24/09/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLX3953L (7657312638SG)
[SKR8546P]**

**TP
POH HUAT CAR SERVICES
Sep 20 2018 4:00PM
[PHILIP HENDRY]
Kim Chwee Auto Pte Ltd**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View In Browser ▾
Letters/Correspondences			1 per page ▾ <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 <input type="checkbox"/> Edit <input type="checkbox"/>
Assessment Reports			1 per page ▾ <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail <input type="checkbox"/>
1	24/09/18 15:27	Accident Statement From:OD - Reg. No: SKR8546P, Claimant: PHILIP HENDRY	1 <input type="checkbox"/> Load HTM <input type="checkbox"/>
Photos/Images			3 per page ▾ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	21/09/18 19:44	Chassis Number	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
2	21/09/18 19:44	Odometer Reading	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
3	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
4	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
5	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
6	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
7	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
8	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
9	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
10	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
11	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
12	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
13	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
14	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
15	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
16	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
17	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
18	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
19	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
20	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
21	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
22	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
23	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
24	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
25	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
26	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
27	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
28	21/09/18 19:45	General View	1 <input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
30	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
31	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
32	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
33	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
34	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
35	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
36	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
37	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
38	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
42	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
43	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
44	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
46	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
47	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
48	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
49	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
50	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
51	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
52	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
53	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
54	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
55	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
56	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
57	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
58	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
59	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
60	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
61	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
62	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
63	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
64	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
65	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
66	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
67	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
68	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
69	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
70	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
71	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
72	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
73	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
74	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
75	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
76	21/09/18 19:45	General View	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
77	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
78	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
79	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
80	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
81	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
82	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
83	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
84	21/09/18 19:45	General View	 Load JPG	<input checked="" type="checkbox"/>
85	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	24/09/18 20:57	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
125	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	24/09/18 20:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	24/09/18 20:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
172	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
173	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	24/09/18 21:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
184	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
198	24/09/18 21:02	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
199	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
200	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
201	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
202	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
203	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
204	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
207	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
208	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
209	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
216	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
217	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
218	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
219	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
220	24/09/18 21:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
221	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
222	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
223	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
224	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
225	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
226	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
227	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
228	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
229	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
230	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
231	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
232	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
233	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
234	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
235	24/09/18 21:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
236	24/09/18 21:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
237	24/09/18 21:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
238	24/09/18 21:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
239	24/09/18 21:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
240	24/09/18 21:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
241	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
242	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
243	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
244	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
245	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
246	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
247	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
248	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
249	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
250	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
251	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
252	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
253	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
254	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
255	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
256	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
257	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
258	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
259	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
260	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
261	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
262	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
263	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
264	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
265	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
266	25/09/18 20:12	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	24/09/18 17:45	TP GIA REPORT		Load PDF
2	15/03/19 15:19	EMAIL TO OI		Load PDF
3	15/03/19 15:19	LETTER TO OI		Load PDF
4	05/08/19 19:12	GIA SEARCH		Load PDF
5	05/08/19 19:12	RENTAL MILEAGE		Load PDF
6	05/08/19 19:12	RENTAL RECEIPT		Load PDF
7	05/09/19 12:01	LOD		Load PDF
8	05/09/19 12:01	AUTHORISATION TO ACT		Load PDF
9	05/09/19 12:01	RELEASE VOUCHER		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	23/08/19 14:53	Clear Report		Load DOCX

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKR8546P (Insd veh)	Model:	BMW 520I 2.0 (A)
	SLX3953L (TP veh)		
Date of Accident:	20/09/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	: \$		81,507.36
Final Repair Cost	: \$		35,738.00
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		1,500.00 15 days
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		
	: \$		
Final Settlement Sum	: \$		37,240.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	: \$	37,240.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

05 Sep
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18017224/UEB3S2
Date: 05/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800017989
Claimant Vehicle No : SLX3953L **Insured Vehicle No :** SKR8546P
 Date of Loss: 20/09/2018 Nature of Claim: TP Claim No: 7657312638SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX3953L**
 Make & Model: BMW 520I, 2.0 (A) Engine No: B0660588N20B20B
 Reg. Date: 27/01/2014 (Man. Year: 2013) Chassis No: WBA5A32000D333967
 Colour: Black Odometer: 132280 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40ZR19 Rear Tyre Size: 245/40ZR19
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	69,725.10	40,529.69	29,195.41	41.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,450.00	3,140.00	3,310.00	51.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	76,175.10	43,669.69	32,505.41	42.67
Approved Total (Overridden) (S\$)		33,400.00		
(S\$)	76,175.10	33,400.00	42,775.10	56.15
+ GST 7.00/7.00% (S\$)	5,332.26	2,338.00	2,994.26	56.15
Nett Amount (S\$)	81,507.36	35,738.00	45,769.36	56.15
+ Car Rental (15.0 x S\$100.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		37,240.00		

INSPECTION

Date of Assignment: 21/09/2018
 Date Inspected: 21/09/2018 Inspected At: Kim Chwee Auto Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$116,000

LTA REBATE: \$82,565

NETT VALUE: \$33,435

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,866.20 F	*2,465.32 FL
2	1		*BONNET INSULATOR	Distorted	266.50 F	*266.50 FL
3	2		*BONNET HINGES	Bent / Twisted	300.00 F	*300.00 FL
4	1		*SET BONNET INSULATOR CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*FRONT LOGO	Necessary	105.00 F	*82.00 FL
6	2		*BONNET DAMPERS	Serviceable	532.00 F	*- FL
7	2		*BONNET LOCK BRACKETS	Bent / Twisted	290.00 F	*290.00 FL
8	1		*BONNET LOCK CABLE	Jammed	288.00 F	*288.00 FL
9	1		*BONNET LOCK UPPER	Twisted	166.00 F	*166.00 FL
10	2		*BONNET LOCK LOWERES	Twisted	420.00 F	*420.00 FL
11	1		*FRONT BUMPER	Distorted	2,450.00 F	*1,718.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Distorted	842.00 F	*711.00 FL
13	2		*FRONT BUMPER REINFORCEMENT BRACKETS	Torn	570.00 F	*570.00 FL
14	1		*FRONT BUMPER REINFORCEMENT BRACKET STARYS	O/s Bent	210.00 F	*105.00 FL
15	2		*FRONT BUMPER SIDE HOLDERS	Bent / Twisted	290.00 F	*290.00 FL
16	1		*FRONT BUMPER SPONGE	Torn	245.00 F	*245.00 FL
17	1		*FRONT FENDERS	N/s Repair / O/s Warped	2,100.00 F	*874.00 FL
18	1		*FRONT FENDER INNER SHIELDS	O/s Deformed / Torn	704.00 F	*294.00 FL
19	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 F	*60.00 FL
20	1		*FRONT FENDER INNER PANEL O/S	Repair	1,010.00 F	*- FL
21	1		*FRONT SUPPORT TOP PANEL OUTER	Bent / Twisted	355.00 F	*355.00 FL
22	1		*FRONT SUPPORT TOP PANEL INNER	Bent / Twisted	485.00 F	*485.00 FL
23	2		*FRONT SUPPORT BARS	Repair	180.00 F	*- FL
24	1		*FRONT BUMPER TOW COVER	Torn	35.00 F	*35.00 FL
25	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not fitted	95.00 F	*- FL
26	1		*FRONT BUMPER NOZZLE COVERS	O/s Broken	90.00 F	*45.00 FL
27	1		*FRONT BUMPER NOZZLE JETS	O/s Cracked	420.00 F	*210.00 FL
28	1		*FRONT BUMPER NOZZLE COVER SPRINGS	O/s Missing	30.00 F	*15.00 FL
29	2		*FRONT GRILLES	Cracked / Broken	380.00 F	*380.00 FL
30	1		*FRONT BUMPER CENTRE GRILLE	Broken	115.00 F	*115.00 FL
31	2		*FRONT BUMPER CENTRE LOWER SIDE GRILLES	Distorted	120.00 F	*120.00 FL
32	4		*FRONT BUMPER PDC SENSORS	Shorted 3pcs Only	1,220.00 F	*795.00 FL
33	1		*FRONT BUMPER INNER BRAKE AIR DUCT O/S	Broken	80.00 F	*80.00 FL
34	1		*FRONT BUMPER INNER AUXILIARY AIR DUCT	Broken	315.00 F	*315.00 FL
35	2		*LED - HEADLAMP ASSYS	N/s Cracked / O/s Broken	7,600.00 F	*7,600.00 FL
36	1		*HEADLAMP DRIVER MODULE O/S (XENON)	Cracked	899.00 F	*485.00 FL
37	1		*HEADLAMP HID BALLAST O/S	Not Necessary	850.00 F	*- FL
38	1		*HEADLAMP LOWER BRACKET O/S	Cracked	155.00 F	*155.00 FL
39	1		*INTERCOOLER	Dented / Bent	913.00 F	*913.00 FL
40	1		*AIR CON CONDENSER	Distorted	1,450.00 F	*1,122.43 FL
41	1		*AIR CON COOLING PIPE	Not Necessary	388.00 F	*- FL
42	1		*AIR CON DISCHARGE HOSE	Not Necessary	392.00 F	*- FL
43	1		*AIR SUCTION HOSE	Not Necessary	390.00 F	*- FL
44	1		*FRONT BUMPER FOG LAMP COVER O/S	Distorted	105.00 F	*105.00 FL
45	1		*FRONT BUMPER FOG LAMP O/S	Cracked	318.00 F	*318.00 FL
46	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Distorted	102.00 F	*102.00 FL
47	1		*FRONT BUMPER UNDER COVER	Torn	225.00 F	*225.00 FL
48	1		*SET FRONT BUMPER UNDER COVER CLIPS	Necessary	45.00 F	*45.00 FL
49	1		*RADIATOR	Bent / Punctured	1,415.00 F	*1,064.00 FL
50	2		*RADIATOR TOP BRACKETS	Not Necessary	50.00 F	*- FL
51	2		*RADIATOR TOP BUSHES	Not Necessary	58.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*RADIATOR FAN MOTOR ASSY	Bent / Jammed	1,215.00 F	*1,215.00 FL
53	1		*FRONT AIR DUCT	Torn	329.00 F	*329.00 FL
54	1		*FRONT BUMPER TOP RUBBER STRIP	Twisted	102.00 F	*102.00 FL
55	1		*POWER STEERING OIL COOLING PIPE	Not Necessary	360.00 F	*- FL
56	1		*FRONT WINDSCREEN	Broken	2,150.00 F	*1,233.60 FL
57	1		*FRONT WINDSCREEN MOULDING	Necessary	185.00 F	*185.00 FL
58	2		*ENGINE MOUNTINGS	Not Necessary	780.00 F	*- FL
59	1		*GEARBOX MOUNTING	Not Necessary	311.00 F	*- FL
60	1		*DRIVER AIR BAG	Activated	2,480.00 F	*2,480.00 FL
61	1		*DRIVER AIR BAG SPIRAL SENSOR	Activated	325.00 F	*325.00 FL
62	1		*PASSENGER AIR BAG	Activated	3,015.00 F	*2,850.00 FL
63	1		*DASHBOARD	Burst	1,420.00 F	*1,420.00 FL
64	1		*AIR BAG CONTROL UNIT	Activated	1,850.00 F	*1,100.00 FL
65	2		*SEATBELTS	Not Necessary	1,700.00 F	*- FL
66	1		*SEATBELT BUCKETS	O/s Activated	1,240.00 F	*455.00 FL
67	1		*ROOF LINING	Torn	2,166.20 F	*2,166.20 FL
68	1		*ROOF AIR BAG N/S	Activated	2,800.00 F	*2,450.00 FL
69	1		*FRONT WHEEL HOUSING PANEL O/S	Repair	1,250.00 F	*- FL
70	1		*FRONT CHASSIS MEMBER O/S	Repair	899.00 F	*- FL
71	1		*OIL COOLER PUMP	Not Necessary	420.00 F	*- FL
72	1		*ALTERNATOR	Not Necessary	1,820.00 F	*- FL
73	1		*AIR CON COMPRESSOR	Not Necessary	2,118.00 F	*- FL
74	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	655.00 F	*- FL
75	1		*FRONT KNUCKLE ARM O/S	Not Necessary	1,019.00 F	*- FL
76	1		*FRONT WHEEL HUB O/S	Not Necessary	620.00 F	*- FL
77	1		*FRONT WHEEL HUB BEARING O/S	Not Necessary	350.00 F	*- FL
78	2		*FRONT FENDER INNER TOP SIDE GARNISHS	Cracked / Twisted	760.00 F	*760.00 FL
79	1		*BATTERY CABLE TERMINTOR	Activated	399.20 F	*399.20 FL
80	1		*HORN UNIT	Broken	1,850.00 F	*95.00 FL
81	1		*FRONT PDC SENSOR WIRE	Torn	299.00 F	*299.00 FL
82	1		*HEADLAMP TOP PANEL O/S	Bent / Dented	288.00 F	*288.00 FL
83	1		*FRONT LICENCE PLATE W/HOLDER	Broken	50.00 FS	*40.00 FS
84	1		*FRONT WINDSCREEN PRIVATE HIRE STICKER	Necessary	50.00 FS	*30.00 FS
85	1		*FRONT SPORT RIM O/S	Not Necessary	1,200.00 FS	*- FS
86	1		*BOL RADIATOR COOLANT	Necessary	80.00 FS	*50.00 FS
87	1		*BOL AIR CON OIL	Necessary	80.00 FS	*50.00 FS
88	1		*SET FRONT BUMPER RIVET	Necessary	50.00 FS	*50.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	69,725.10	42,651.25
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	2,121.56
Total Parts (\$\$)	69,725.10	40,529.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES KINGROLLER.	New	180.00	120.00
2	TO CHECK WIRING.	New	100.00	30.00
3	TO DISMANTLE & REPLACING PDC SENSOR.	New	100.00	50.00
4	TO DISMANTLE & REFIX ENGINE FOR FACILITATE REPAIR CHASSIS.	New	500.00	0.00
5	TO REPROGRAMME & RESET AIR BAG.	New	380.00	300.00
6	TO SPRAY RUST PROOFING.	New	180.00	100.00
7	TO REFILL AIR CON GAS.	New	150.00	100.00
8	TO CONDUCT WHEEL ALIGNMENT.	New	120.00	60.00
9	TO DISMANTLE & REFIX FRONT UNDERCARRIAGE.	New	380.00	0.00
10	TO DISMANTLE & REPLACING ROOF LINING.	New	200.00	180.00
11	TO DISMANTLE & REPLACING FRONT DASHBOARD.	New	380.00	300.00
12	TO DISMANTLE & REPLACING AIR BAG SYSTEM.	New	480.00	0.00
13	LABOUR FOR PANEL BEATING & REPLACING PARTS.	New	1,500.00	900.00
14	TO PUTTY & SPRAY PAINTING.	New	1,800.00	1,000.00
Gross Labour Cost (S\$)			6,450.00	3,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >