

ISS2010

INS. CASE OWNER:

*EXTRACTED*

CC<sup>h</sup> /AIG1801

*72ND, PL 46752*

LKK:  
IDAC:

Surveyor:

*Ragul*

DOI:

ASSIGNMENT

*20/1/18*

Date / Time:

*20/1/18*

Registered in Merimen:

*2/1/18*

Pre-assign / CCU / FTE



Insured Vehicle No.:

*SLU 2467X*

Claim No.:

*440370559436*

Name of Insured:

*WONG SOKE WAI*

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

*16/1/18*

Place of Accident:

Is driver the owner? ( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

*418 12479*



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

*SMRT*



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time		STAGE	DATE / PIC
<i>20/1/18</i>	<i>SKM12479-X</i>	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	<i>17/1/19 - Khoo</i>
		After call ltr to OI:	
<i>20/02/19</i>	<i>SM 2467X-X</i>	Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
		PIR:	<input type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
		LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: *49* \$S ( *6* days) Reduction: *49* % Email  Call

FINAL SETTLEMENT Date/Time: *27/1/19* Confirm with: *Tom Lee Goh* Email  Call

Final Liability: % *100* (Agreed / Assessed) BOLA S/N No. : *27* If NO or B 28, Ass. Lia: *COLD RATE - ENDED TP*

Repair Cost: \$S *5400.00*

Loss of Rental (LOR): \$S *1070.00* ( *8* days) x *\$133.75*

Loss of Use (LOU): \$S - (S x days)

Loss of Income (LOI): \$S - (S x days)

LOR only  LOU only  LOR + LOU  LOR + LO  [Tick only one]

GIA/LTA Search \$S *7.00*

Medical: \$S -

Disbursement: \$S - (e.g. Tow/ Independent)

Legal Cost \$S -

Total: \$S *6477.00* Global Sum \$S: *6400.00*

FINAL PAYMENT Date/Time: Confirm with: Email  Call

Payee 1: \$S *6400.00* Name 1: *SMRT Taxis Pte Ltd*

Payee 2: (Strike if N.A.) \$S Name 2:

Payee 3: (Strike if N.A.) \$S Name 3:

*27/1/19*





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315



Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18017230/R1ub3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-09-2018	
Code : AIG			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLU 2467X	Veh. Inspected	SHB 1947G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/09/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	16/09/2018	Inspection Date	20/09/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

VIC

**Section A - Accident Details**

Registration Number	SHB1947G
Case Reference Number	TAX/09/18/2086
Registration Date	06/08/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MOHAMMAD KHALIL BIN KAMARI
Type of Accident	Head to Rear
Accident Date and Time	16/09/18 2:45 PM
Accident Reported Date and Time	19/09/18 12:30 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	16/09/18 4:30 PM
Replacement Vehicle Issued?	No
Job Card Number	24097995
Special Instruction to ARC, if any	TOWED \$40 / AIG - LKK
Prepared Date and Time	22/09/18 7:11 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Top View

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$1,014.00
Total Spray Cost	\$1,656.00	\$600.00
Total Spare Part Cost	\$5,760.62	\$2,664.00
Total Other Cost	\$1,118.00	\$520.00
<b>TOTAL COST</b>	<b>\$9,548.62</b>	<b>\$4,798.00</b>
Lump Sum Total	\$0.00	\$4,800.00 (L/S)
Number of Repair Days	6.0	6.0
Prepared / Adjusted By	Kim Ming Chin	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	01/10/2018 9:29 AM	29/09/2018 9:45 AM
Signature		
Remarks		LUMPSUM REPAIR



SMRT Accident Vehicle Repair Estimates

SMRT Vehicle Services Pte Ltd  
 60 Woodlands Industrial Park East, Singapore 757026  
 FAX Number: 63665533  
 Estimator Telephone Number: 66602023  
 Accident Reporting Number: 98542672

Date Generated: 13/12/2018  
 User ID: FehSun

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1812-0309	Invoice Number	
Quotation Date	13.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$1,014.00 ✓
<b>Total Labour</b>	<b>\$1,014.00</b>	<b>\$1,014.00</b>

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00 ✓
TO RESPRAY REAR PANEL	\$180.00	\$100.00 ✓
TO RESPRAY TAIL GATE	\$378.00	\$200.00 ✓
TO RESPRAY SPOILER	\$180.00	\$0.00 ^^ X
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00 ^^ X
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00 ^^ X
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,858.00</b>	<b>\$600.00</b>



Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00 ✓
TO TEST AND REFIT SENSOR SYSTEM	\$120.00	\$120.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00 xan
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$60.00 ✓
TOWING CHARGE	\$56.00	\$40.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00 ✓
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$120.00 ✓
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00 xan
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$80.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 xan
<b>Total Other Costs</b>	<b>\$1,116.00</b>	<b>\$520.00</b>

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	de
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace	re
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace	bt
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	bt
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check	X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	re
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	re
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace	ca
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace	ca



**Section A - Accident Details**

Registration Number	SHB1947G
Case Reference Number	TAX/09/18/2086
Registration Date	06/08/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MOHAMMAD KHALIL BIN KAMARI
Type of Accident	Head to Rear
Accident Date and Time	16/09/18 2:45 PM
Accident Reported Date and Time	19/09/18 12:30 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	16/09/18 4:30 PM
Replacement Vehicle issued?	No
Job Card Number	24097995
Special Instruction to ARC, if any	TOWED \$40 / AIG - LKK
Prepared Date and Time	22/09/18 7:11 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$1,014.00 ✓
Total Spray Cost	\$1,655.00	\$600.00 ✓
Total Spare Part Cost	\$5,760.62	\$3,253.55
Total Other Cost	\$1,116.00	\$520.00 ✓
<b>TOTAL COST</b>	<b>\$9,546.62</b>	<b>\$5,387.55</b>
Lump Sum Total	\$0.00	\$5,400.00 (L/S)
Number of Repair Days	6.0	6.0
Prepared / Adjusted By	Kim Ming Chin	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	01/10/2018 9:29 AM	29/09/2018 9:45 AM
Signature		
Remarks		LKK LUMPSUM REPAIR

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1812-0309	Invoice Number	
Quotation Date	13.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$1,014.00
<b>Total Labour</b>	<b>\$1,014.00</b>	<b>\$1,014.00</b>

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY SPOILER	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,656.00</b>	<b>\$600.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00
TO TEST AND REFIT SENSOR SYSTEM	\$120.00	\$120.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$60.00
TOWING CHARGE	\$56.00	\$40.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$60.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$120.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$80.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
<b>Total Other Costs</b>	<b>\$1,116.00</b>	<b>\$520.00</b>

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	0.00	\$104.70	Replace	Replace

52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	0.00	\$104.70	Replace	Replace	/
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1.00	\$157.40	0.00	\$141.66	Replace	Replace	/
	SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	/
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	/
76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$86.58	Replace	Replace	/
76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace	/
76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.58	Replace	Replace	/
52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check	X
52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Check	X
52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X
52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	/
58308-47011	UNDER COVER SUBASSY, RR FLOOR	1.00	\$514.50	0.00	\$385.88	Replace	Replace	/
67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	/
69350-47030	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace	/
67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	/
69415-47020	TAILGATE LOCK, COVER	1.00	\$15.70	25.00	\$11.78	Replace	Replace	/
69431-47010	STRIKER, BACK DOOR	1.00	\$48.90	25.00	\$36.68	Replace	Replace	/
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	/
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	/
75575-47030	MOULDING BACK WINDOW, LOWER NO. 1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	/
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	/
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	/
78801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X
75310-47020	EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
75442-47030	NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X
75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
	NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace	/
	NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace	/
76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	X
58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace	/
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check	X
64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check	X
58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Not Given	X
4008314	SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	/
58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Not Given	X
52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X
52563-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given	X
81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X
81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>			<b>\$9,031.71</b>		<b>\$4,066.94</b>			

4066.94  
 -202  
 3253.55  
 +1014.00  
 +1120.00  
 -----  
 5387.55  
 L/S \$5400/-

## SMRT Accident Taxi Repair Estimates

**Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre**

Reg. No. : SHB 1947G Ref. No. TAX 9 / 18 / 2086

Make / Model : TOYOTA PRIUS Reg. Date : 06/08/2014

Name of Driver : MOHAMMAD KHALIL BIN KAMARI

Date/Time of Accident : 16/09/2018 14:45

Surveyer is Required ? YES / NO


If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)

Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 24097995

Special Instruction to ARC, if any :



Signed : \_\_\_\_\_ Date : \_\_\_\_\_

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36UX05747405 Mileage : \_\_\_\_\_

Date Prepared : \_\_\_\_\_ Repair Completed date/time: \_\_\_\_\_

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ 1,014.00	\$ _____
Total Spray Painting Charges :	\$ 1,656.00	\$ _____
Total Material Charges :	\$ 5,741.71	\$ _____
Other Charges :	\$ 1,116.00	\$ _____
<b>TOTAL</b> :	<b>\$ 9,527.71</b>	<b>\$ 0.00 ( )</b>

No. of Repair Days : [ 6 ] [ 6 days - long term ]

Signature : Prepared by: MING  
20/09/2018 15:20

Adjusted by: *Pine*  
20/09/19 @ 1610

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

QN No. \_\_\_\_\_ Invoice No. \_\_\_\_\_ Invoice Date \_\_\_\_\_

Signed : \_\_\_\_\_ Date : \_\_\_\_\_

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1014.00	700
<b>Total Labour</b>	<b>\$ 1,014.00</b>	<b>\$</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200
TO RESPRAY BUMPER BEAM	180.00	100
TO RESPRAY REAR PANEL	180.00	100
TO RESPRAY TAIL GATE	378.00	200
TO RESPRAY SPOILER	180.00	X
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	X
TO RESPRAY REAR SPARE TYRE PANEL	180.00	X
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$ 1,656.00</b>	<b>\$ 0</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60
TO WASH AND VACUUM	60.00	X
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60
TOWING CHARGE	56.00	? receipt
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	80

TO REPLACE SUNDRY PARTS	100.00	
<b>Total Other Costs</b>	<b>\$ 1,116.00</b>	<b>\$</b>

Section D - Details of Repair Estimates

Part 4 - Spare Parts / Material Usage

Ref. No. TAX 9 / 18 / 2052

Reservation No : \_\_\_\_\_

Page ( 1 )

To be completed by Service Advisor, ARC							Surveyor Adj
Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (/)	Not given (x) Repair (R) Replace (/)
52159-47905	BUMPER REAR	1	458.60	25%	343.95	/	DE ✓
52161-16010	BUMPER CLIPS	10	1.61	25%	12.07	/	na ✓
52023-12240	BUMPER REINFORCEMENT REAR	1	205.70	25%	154.27	/	BA ✓
52016-47030	ARM SUB-ASSY, RR BUMPER LH	1	139.60	25%	104.70	/	?
52015-47050	ARM SUB-ASSY, RR BUMPER RH	1	139.60	25%	104.70	/	?
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1	157.40	25%	118.05	/	?
	SENSOR REVERSE	1	180.00	0%	180.00	/	na ✓
	PIXEL STICKER	2	60.00	0%	120.00	/	na ✓
76087-47020	BUMPER LIP COVER RR/RH	1	118.10	25%	88.57	/	DE ✓
76088-47020	BUMPER LIP COVER RR/LH	1	72.20	25%	54.15	/	me ✓
76891-47020	BUMPER LIP REAR	1	228.90	25%	171.67	/	me ✓
52591-47021	BUMPER SEAL, RR RH	1	65.70	25%	49.27	/	?
52592-47021	BUMPER SEAL, RR LH	1	88.90	25%	66.68	/	?
52576-47020	BUMPER SIDE RETAINER RR/LH	1	94.80	25%	71.10	/	?
52575-47020	BUMPER SIDE RETAINER RR/RH	1	94.80	25%	71.10	/	CR ✓
58308-47011	UNDER COVER SUBASSY, RR FLOOR	1	514.50	25%	385.87	/	?
67005-47241	TAILGATE ASY	1	1007.90	25%	755.92	/	PA ✓
69350-47030	TAILGATE DOOR LOCK	1	444.10	25%	333.07	/	PA ✓
67881-47022	TAILGATE DOOR WEATHER STRIP	1	353.40	25%	265.05	/	cut ✓
69415-47020	TAILGATE LOCK, COVER	1	15.70	25%	11.77	/	DE ✓
69431-47010	STRIKER, BACK DOOR	1	48.90	25%	36.67	/	PA ✓
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25%	22.05	/	na ✓
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25%	22.05	/	na ✓

75575 -47030	MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25%	22.05	/	✓
	SEALANT W/SCREEN	3	37.00	0%	111.00	/	✓
75374-47051	NAME PLATE (HYBRID)	1	51.90	25%	38.92	/	✓
76801-47070-B0	TAILGATE OUTSIDE GARNISH	1	504.90	25%	378.68	/	X
75310-47020	EMBLEM REAR	1	60.30	25%	45.23	/	X
	STICKER DECAL SMRT	1	7.80	0%	7.80	/	X
	STICKER DECAL 6555 8888	1	21.60	0%	21.60	/	X
75442-47030	NAME PLATE (PRIUS)	1	60.80	25%	45.60	/	X
75443-47030	NAME PLATE (TOYOTA)	1	51.90	25%	38.93	/	X
	NUMBER PLATE FRAME	1	12.00	0%	12.00	/	✓
	NUMBER PLATE	1	15.00	0%	15.00	/	✓
76085-47910	SPOILER REAR	1	953.70	25%	715.28	/	X
58307-47060	END PANEL	1	602.10	25%	451.57	/	✓
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1	46.10	25%	34.58	/	?
64716-47031B0	END PANEL COVER, DECK TRIM, RR	1	121.10	25%	90.83	/	?
58336-12090	REINFORCEMENT, RR	1	34.60	25%	25.95	/	<del>✓</del> X
4006314	SEALANT SIKAFLEX	1	37.00	0%	37.00	/	✓
58311-47071	SPARE TYRE PANEL	1	667.70	25%	500.77	/	X
52562-47010	TAIL LAMP BRACKET, RH	1	30.70	25%	23.02	/	X
52563-47010	TAIL LAMP BRACKET, LH	1	30.70	25%	23.03	/	X
81551-47180	TAIL LAMP RH	1	557.80	10%	502.02	/	X
81561-47170	TAIL LAMP LH	1	548.40	10%	493.56	/	X
<b>TOTAL MATERIALS</b>		<b>LUMP SUM 20%</b>		<b>\$</b>		<b>5,741.71</b>	

## View Received Message

This mail is associated with :

**\*SHB1947G (9407205593SG)**  
**[SLU2467X]**

TP  
SMRT TAXIS PTE LTD  
Sep 16 2018 2:00PM  
[WONG SOKE WAI]  
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (AIG\_SG), sent on **24/09/2018 14:34 PM.**  
**To** LKK\_HQ  
**Subject** No OI GIA Report

Hi

Pls be advice that no OI GIA report received  
Pls find OI details below for your further actions

OI name : WONG SOKE WAI

Address :  
103 SPOTTISWOODE PARK ROAD SPOTTISWOODE PARK #22-104 SINGAPORE 080103

Mobile No: 98555182

Thanks & Regards,  
Yin Rui, Hor (Viviane)

*Cpegwon@gmail.com*

### DOCUMENTS SUMMARY

There are no documents.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18017230/R1ub3

26 September, 2018

**WONG SOKE WAI**

103 SPOTTISWOODE PARK ROAD SPOTTISWOODE PARK #22-104  
SINGAPORE 080103

Dear Sirs,

**ACCIDENT INVOLVING SHB 1947G AND SLU 2467X ON 16/09/2018 ALONG /  
AT LAVENDER STREET AND KALLANG ROAD**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Thin Thin  
Claims  
Tel : 6841 2360  
Fax: 6741 4108  
Email : [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. *Claims Manager*  
*AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

## Vic (LKKAuto)

---

**From:** Khoo, Kay-Eng <Kay-Eng.Khoo@aig.com>  
**Sent:** Tuesday, 26 March, 2019 2:55 PM  
**To:** Hsiao Tong (LKKAuto); Vic (LKKAuto)  
**Cc:** Ler, Bernard-JQ  
**Subject:** FW: Accident Involving SHB1947G and SLU2467X on September 16 2018// LKK REF: CC3/AIG18017230/R1hb3 AIG ENCRYPT  
**Attachments:** OI report.pdf  
**Importance:** High

Dear Hsiao Tong/Vic,

Reference to email below, have you acted on the email?

Do be advised that we have sighted and noted the report is still not in Merimen and we have contacted the insured to do the necessary on reporting.

Meanwhile, please upload the photos and video footage of third party vehicle to Merimen on urgent basis.

**Khoo Kay Eng**  
AIG  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1026

[kay-eng.khoo@aig.com](mailto:kay-eng.khoo@aig.com) | [www.aig.sg](http://www.aig.sg)



**AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.**  
[Click here to find out more](#)

Follow us:



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Khoo, Kay-Eng  
**Sent:** Tuesday, March 19, 2019 1:19 PM

**To:** Hsiao Tong (LKKAUTO); Vic (LKKAUTO)

**Cc:** Ler, Bernard-JQ; Admin A

**Subject:** RE: Accident Involving SHB1947G and SLU2467X on September 16 2018// LKK REF: CC3/AIG18017230/R1hb3 AIG ENCRYPT

Dear Hsiao Tong,

Thank you for your swift response.

Dear Vic,

Here is OI's Police Report

Please engage OI to for the reporting to be done and submitted via Merimen at our authorized workshop.

Thereafter, please manage the PD claim and also ascertain the relationship between driver and owner.

Thank you.

**Khoo Kay Eng**

AIG

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1026

[kay-eng.khoo@aig.com](mailto:kay-eng.khoo@aig.com) | [www.aig.sg](http://www.aig.sg)



**AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.**  
[Click here to find out more](#)

Follow us:



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Hsiao Tong (LKKAUTO) [<mailto:chewht@lkkauto.com>]

**Sent:** Tuesday, March 19, 2019 12:11 PM

**To:** Khoo, Kay-Eng; Vic (LKKAUTO)

**Cc:** Ler, Bernard-JQ; Admin A

**Subject:** RE: Accident Involving SHB1947G and SLU2467X on September 16 2018// LKK REF: CC3/AIG18017230/R1hb3

Dear Mr Khoo,

Thank you for your email.

The case is handled by Vic.

Hi Vic,

Kindly assist. (Case previously was handled by Thin Thin)

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Khoo, Kay-Eng <Kay-Eng.Khoo@aig.com>

**Sent:** Tuesday, 19 March 2019 11:49 AM

**To:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

**Cc:** Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>

**Subject:** Accident Involving SHB1947G and SLU2467X on September 16 2018

Our Ref: 94072055935G003

Your Ref: SLU2467X

Hi Hsiao Tong,

Noted this case in Merimen - may we check what is the current status of matter at your end?

Is the PD direct settlement in progress already?

**Khoo Kay Eng**

**AIG**

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1026

[kay-eng.khoo@aig.com](mailto:kay-eng.khoo@aig.com) | [www.aig.sg](http://www.aig.sg)



**Celebrating 100 Years:**  
Visit [100.aig](http://100.aig) to learn more.

**AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.  
[Click here to find out more](#)**

Follow us:



**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18017230/R1hb3

17 APRIL 2019

**WONG SOKE WAI**

103 SPOTTIS WOODS PARK ROAD SPOTTISWOODE PARK  
#22-104  
SINGAPORE 080103

Dear Sir/Madam,

**ACCIDENT INVOLVING SLU2467X & SHB1947G ALONG/AT ALONG LAVENDER STREET AND KALLANG ROAD ON 16/09/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SHB1947G against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

KHANCHNA  
Case Handler  
DID: 6841-2360  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018 <a href="#">Edit Reg</a>		20 Sep 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,400.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>WONG SOKE WAI</b> , ID: S1813310E								
Main Claimant:	<b>SMRT TAXIS PTE LTD</b> , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	<b>SHB1947G</b>	Date of Loss:	16/09/2018 15:00 - :59 [49 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 9407205593SG</b>	Policy/Cover Note No.:	1700087479 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLU2467X</b>	Policy No. (Claimant):	D-18090213MFSH						
		Excess:							
Repairer:	<b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ]								
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 02/10/2018]								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>	<a href="#">Compose Case Mail</a>				
• AIG_SG (24/09/2018): No OI GIA Report									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SHB1947G (9407205593SG)**  
**[SLU2467X]**

TP

**SMRT TAXIS PTE LTD**

**Sep 16 2018 3:00PM**

**[WONG SOKE WAI]**

**SMRT Automotive Services Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			View	View in Browser ▾
<b>Video</b>			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	01/04/19 14:21	<b>Video - Accident</b>		Load MP4
<b>Letters/Correspondences</b>			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	<b>Third Party Express Settlement - Payment Breakdown</b>		Edit
<b>Photos/Images</b>			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	26/03/19 15:05	<b>Odometer Reading</b>		Load JPG <input checked="" type="checkbox"/>
2	26/03/19 15:05	<b>Chassis Number</b>		Load JPG <input checked="" type="checkbox"/>
3	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
4	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
5	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
6	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
7	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
8	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
9	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
10	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
11	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
12	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
13	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
14	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
15	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
16	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
17	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
18	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
19	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
20	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
21	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
22	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
23	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
24	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
25	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
26	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
27	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
28	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
29	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
30	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
31	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
32	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
33	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
34	26/03/19 15:05	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
35	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
36	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
37	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
38	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
39	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
40	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
41	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
42	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
43	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
44	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
45	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
46	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
47	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
48	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
49	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
50	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
51	26/03/19 15:05	General View		<input checked="" type="checkbox"/>
52	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
53	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
54	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
55	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
56	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
57	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
58	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
59	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
60	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
61	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
62	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
63	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
64	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
65	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
66	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
67	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
68	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
69	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
70	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
71	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
72	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
73	26/03/19 15:06	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/09/18 17:36	TP ESTIMATE- MARKED		
2	21/09/18 17:36	TP GIA REPORT		
3	26/09/18 09:12	Non reporting letter		
4	10/04/19 09:26	TP SCENE PHOTOS		
5	17/04/19 10:41	LETTER TO OI		
6	16/10/19 10:50	LOD		
7	16/10/19 10:50	AUTHORISATION TO ACT		
8	16/10/19 10:50	RELEASE VOUCHER		
9	16/10/19 10:50	WORKSHOP INVOICE		
10	16/10/19 10:50	RENTAL RECEIPT		
11	16/10/19 10:50	RENTAL MILEAGE		
12	16/10/19 10:50	LTA SEARCH		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	11/09/19 09:04	OI GIA REPORT		

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	SLU2467X (Insd veh)	<b>Model:</b>	TOYOTA PRIUS TAXI 1.8 (A)
	SHB1947G (TP veh)		
<b>Date of Accident:</b>	16/09/2018		

Global Sum Settlement	:	[ X ] Yes	[ ] No
Repair Estimate	:\$		12,966.20
Final Repair Cost	:\$		6,400.00
Loss of Use	:\$		days at \$0.00 per day
Rental (if any)	:\$		8 days
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$		6,400.00
<b>Is Third Party Workshop GIA Registered?</b> [ ] YES [ X ] NO (Kindly indicate below)			
<b>A) For Non GIA Registered Workshop:</b>		Agreed Liability ____ 100 ____ (%)	
<b>B) For GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

<b>Payment Instruction: Payee's Breakdown</b>			
1)	SMRT TAXIS PTE LTD	:\$	6,400.00
2)		:\$	
3)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

16 Oct  
2019

Date

**Please attach all the supporting documents to the form.**  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/  
Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG18017230/R1DB3S2  
**Date:** 16/10/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700087479  
**Claimant Vehicle No :** SHB1947G **Insured Vehicle No :** SLU2467X  
 Date of Loss: 16/09/2018 Nature of Claim: TP Claim No: 9407205593SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB1947G**  
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR6103934  
 Reg. Date: 06/08/2014 (Man. Year: 2014) Chassis No: JTDKN36UX05747405  
 Colour: Maroon Odometer: 436899 km  
 Engine Capacity: 1798 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm  
 Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,180.20	4,066.94	5,113.26	55.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,786.00	2,134.00	1,652.00	43.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,966.20</b>	<b>6,200.94</b>	<b>6,765.26</b>	<b>52.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,966.20</b>	<b>5,400.00</b>	<b>7,566.20</b>	<b>58.35</b>
<b>+ Car Rental (8.0 x S\$133.75/day) (S\$)</b>		1,070.00		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>6,477.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>6,400.00</b>		

### INSPECTION

Date of Assignment: 20/09/2018  
 Date Inspected: 20/09/2018 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)  
 60 Woodlands Industrial Park E4  
 Singapore 757705  
 Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD RASUL

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F	
2	1		*BUMPER CLIPS (DISC 25%) 10pcs	Necessary	16.10 F	*12.08 F	
3	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F	
4	1		*BUMPER LIP COVER RR/RH (DISC 25%)	Cracked	118.10 F	*88.58 F	
5	1		*BUMPER LIP COVER RR/LH (DISC 25%)	Cracked	72.20 F	*54.15 F	
6	1		*BUMPER LIP REAR (DISC 25%)	Cut	228.90 F	*171.68 F	
7	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Necessary	94.80 F	*71.10 F	
8	1		*TAILGATE ASY (DISC 25%)	Bent	1,007.90 F	*755.93 F	
9	1		*TAILGATE DOOR LOCK (DISC 25%)	Bent	444.10 F	*333.08 F	
10	1		*TAILGATE DOOR WEATHERSTRIP (DISC 25%)	Necessary	353.40 F	*265.05 F	
11	1		*TAILGATE LOCK, COVER (DISC 25%)	Cut	15.70 F	*11.78 F	
12	1		*STRIKER, BACK DOOR (DISC 25%)	Bent	48.90 F	*36.68 F	
13	1		*TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	Necessary	29.40 F	*22.05 F	
14	1		*TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	Necessary	29.40 F	*22.05 F	
15	1		*MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F	
16	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F	
17	1		*END PANEL (DISC 25%)	Bent	602.10 F	*451.58 F	
18	1		*SENSOR REVERSE (SN)	Not Working	180.00 F	*180.00 F	
19	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F	
20	3		*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F	
21	1		*NUMBER PLATE FRAME (SN)	Cut	12.00 F	*12.00 F	
22	1		*NUMBER PLATE (SN)	Bent	15.00 F	*15.00 F	
23	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F	
24	1		*ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F	
25	1		*ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F	
26	1		*ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	Cracked	157.40 F	*141.66 F	
27	1		*BUMPER SEAL, RR RH	Serviceable	65.70 F	*- F	
28	1		*BUMPER SEAL, RR LH	Serviceable	88.90 F	*- F	
29	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F	
30	1		*UNDER COVER SUBASSY, RR FLOOR (DISC 25%)	Cracked	514.50 F	*385.88 F	
31	1		*SPOILER REAR	Serviceable	953.70 F	*- F	
32	1		*END PANEL COVER, DECK TRIM HOLE	Serviceable	46.10 F	*- F	
33	1		*END PANEL COVER, DECK TRIM, RR	Serviceable	121.10 F	*- F	
34	1		*REINFORCEMENT, RR	Serviceable	34.60 F	*- F	
35	1		*TAILGATE OUTSIDE GARNISH	Not Necessary	504.90 F	*- F	
36	1		*EMBLEM REAR	Not Necessary	60.30 F	*- F	
37	1		*STICKER DECAL SMRT	Not Necessary	7.80 F	*- F	
38	1		*STICKER DECAL 6555 8888	Not Necessary	21.60 F	*- F	
39	1		*NAME PLATE (PRIUS)	Not Necessary	60.80 F	*- F	
40	1		*NAME PLATE (TOYOTA)	Not Necessary	51.90 F	*- F	
41	1		*SPARE TYRE PANEL	Not Necessary	667.70 F	*- F	
42	1		*TAIL LAMP BRACKET, RH	Not Necessary	30.70 F	*- F	
43	1		*TAIL LAMP BRACKET, LH	Not Necessary	30.70 F	*- F	
44	1		*TAIL LAMP RH	Not Necessary	557.80 F	*- F	
45	1		*TAIL LAMP LH	Not Necessary	548.40 F	*- F	
					<b>Total Parts (\$\$)</b>	<b>9,180.20</b>	<b>4,066.94</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODYWORK.	New	1,014.00	1,014.00
2	SPRAY PAINT.	New	1,656.00	600.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	40.00
4	TO TEST AND REFIT SENSOR SYSTEM.	New	120.00	120.00
5	TO WASH AND VACUUM.	New	60.00	0.00
6	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	60.00
7	TOWING CHARGE.	New	56.00	40.00
8	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	60.00
9	TO REMOVE AND REFIX REAR WINDSCREEN.	New	240.00	120.00
10	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	0.00
11	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	80.00
12	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,786.00</b>	<b>2,134.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >