

SMRT Accident Taxi Repair Estimates

Section A - To be completed by Claims Advisor/Duty Officer at Accident Reporting Centre

Reg. No. : SHB 1947G Ref. No. TAX 9 / 18 / 2086

Make / Model : TOYOTA PRIUS Reg. Date : 06/08/2014

Name of Driver : MOHAMMAD KHALIL BIN KAMARI

Date/Time of Accident : 16/09/2018 14:45

Surveyer is Required ? YES / NO

If Yes, VICOM / LKK / LH Teo / AIS (Please circle one)


Taxi is Towed Back ? YES / NO

Replacement Taxi Issued ? YES / NO

Accident Repair Job Card No. : 24097995

Special Instruction to ARC, if any :

The damages on the Taxi are as indicated in the following diagram :



Signed : _____ Date : _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX05747405 Mileage : _____

Date Prepared : _____ Repair Completed date/time: _____

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	\$ <u>1,014.00</u>	\$ _____
Total Spray Painting Charges :	\$ <u>1,656.00</u>	\$ _____
Total Material Charges :	\$ <u>5,741.71</u>	\$ _____
Other Charges :	\$ <u>1,116.00</u>	\$ _____
TOTAL :	\$ <u>9,527.71</u>	\$ <u>0.00</u> ()

No. of Repair Days : [6] [6 days - Lump sum]

Signature : Prepared by: MING
20/09/2018 15:20

Adjusted by: Pone
20/09/19 @ 1610

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

QN No. _____ Invoice No. _____ Invoice Date _____

Signed : _____ Date : _____

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1014.00	700
Total Labour	\$ 1,014.00	\$

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200
TO RESPRAY BUMPER BEAM	180.00	100
TO RESPRAY REAR PANEL	180.00	100
TO RESPRAY TAIL GATE	378.00	200
TO RESPRAY SPOILER	180.00	X
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	X
TO RESPRAY REAR SPARE TYRE PANEL	180.00	X
Total Spray Painting & Panel Beating	\$ 1,656.00	\$ 0

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60
TO WASH AND VACUUM	60.00	X
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60
TOWING CHARGE	56.00	? receipt
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	80

100.00	
Total Other Costs	\$ 1,116.00

Section D - Details of Repair Estimates

Part 4 - Spare Parts / Material Usage

Ref. No. TAX 9 / 18 / 2052

Reservation No : _____

Part Number	Parts Description	Qty	List Price (\$)	Discount (%)	Final Price (\$)	Repair (R) Replace (I)	Surveyor Adj
							Not given (x) Repair (R) Replace (I)
52159-47905	BUMPER REAR	1	458.60	25%	343.95	/	DE ✓
52161-16010	BUMPER CLIPS	10	1.61	25%	12.07	/	DE ✓
52023-12240	BUMPER REINFORCEMENT REAR	1	205.70	25%	154.27	/	BA ✓
52016-47030	ARM SUB-ASSY, RR BUMPER LH	1	139.60	25%	104.70	/	?
52015-47050	ARM SUB-ASSY, RR BUMPER RH	1	139.60	25%	104.70	/	?
89997-30070	ANTENNA, ELECTRICAL LOWER REAR	1	157.40	25%	118.05	/	?
	SENSOR REVERSE	1	180.00	0%	180.00	/	AM ✓
	PIXEL STICKER	2	60.00	0%	120.00	/	AM ✓
76087-47020	BUMPER LIP COVER RR/RH	1	118.10	25%	88.57	/	DE ✓
76088-47020	BUMPER LIP COVER RR/LH	1	72.20	25%	54.15	/	MIS ✓
76891-47020	BUMPER LIP REAR	1	228.90	25%	171.67	/	MIS ✓
52591-47021	BUMPER SEAL, RR RH	1	65.70	25%	49.27	/	?
52592-47021	BUMPER SEAL, RR LH	1	88.90	25%	66.68	/	?
52576-47020	BUMPER SIDE RETAINER RR/LH	1	94.80	25%	71.10	/	?
52575-47020	BUMPER SIDE RETAINER RR/RH	1	94.80	25%	71.10	/	CRA ✓
58308-47011	UNDER COVER SUBASSY, RR FLOOR	1	514.50	25%	385.87	/	?
67005-47241	TAILGATE ASY	1	1007.90	25%	755.92	/	BA ✓
69350-47030	TAILGATE DOOR LOCK	1	444.10	25%	333.07	/	BA ✓
67881-47022	TAILGATE DOOR WEATHER STRIP	1	353.40	25%	265.05	/	cut ✓
69415-47020	TAILGATE LOCK, COVER	1	15.70	25%	11.77	/	DE ✓
69431-47010	STRIKER, BACK DOOR	1	48.90	25%	36.67	/	BA ✓
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25%	22.05	/	AM ✓
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25%	22.05	/	AM ✓

75575 -47030	MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25%	22.05	/	see -	
	SEALANT W/SCREEN	3	37.00	0%	111.00	/	see -	
75374-47051	NAME PLATE (HYBRID)	1	51.90	25%	38.92	/	see -	
76801-47070-B0	TAILGATE OUTSIDE GARNISH	1	504.90	25%	378.68	/	X	
75310-47020	EMBLEM REAR	1	60.30	25%	45.23	/	X	
	STICKER DECAL SMRT	1	7.80	0%	7.80	/	X	
	STICKER DECAL 6555 8888	1	21.60	0%	21.60	/	X	
75442-47030	NAME PLATE (PRIUS)	1	60.80	25%	45.60	/	X	
75443-47030	NAME PLATE (TOYOTA)	1	51.90	25%	38.93	/	X	
	NUMBER PLATE FRAME	1	12.00	0%	12.00	/	cut -	
	NUMBER PLATE	1	15.00	0%	15.00	/	see -	
76085-47910	SPOILER REAR	1	953.70	25%	715.28	/	X	
58307-47060	END PANEL	1	602.10	25%	451.57	/	pt -	
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	1	46.10	25%	34.58	/	?	
64716-47031B0	END PANEL COVER, DECK TRIM, RR	1	121.10	25%	90.83	/	?	
58336-12090	REINFORCEMENT, RR	1	34.60	25%	25.95	/	pt X	
4006314	SEALANT SIKAFLEX	1	37.00	0%	37.00	/	see -	
58311-47071	SPARE TYRE PANEL	1	667.70	25%	500.77	/	X	
52562-47010	TAIL LAMP BRACKET, RH	1	30.70	25%	23.02	/	X	
52563-47010	TAIL LAMP BRACKET, LH	1	30.70	25%	23.03	/	X	
81551-47180	TAIL LAMP RH	1	557.80	10%	502.02	/	X	
81561-47170	TAIL LAMP LH	1	548.40	10%	493.56	/	X	
TOTAL MATERIALS					LUMP SUM 20%		\$	5,741.71