



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 7429 C

Parts	(a) Cost / List Price Items	\$	2,912.40
	Plus/Less 25%	\$	728.10
	Total of Cost / List	\$	2,184.30
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	2,384.30
Labour		\$	1,170.00
Total		\$	3,554.30

*Not Authorized
1-131
Resurvey B6 pain*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 26/9/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : L Date: 26/9/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLF 7429 C**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU703532133**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	?
2	Rear bumper <i>Re</i>	1	\$497.50		✓
3	Rear bumper clip <i>me</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>Re</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Re</i>	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		?
7	Rear bumper lower garnish centre <i>Re/L</i>	1	\$582.60		✓
8	Rear bumper tow cover <i>Re</i>	1	\$31.70		✓
9	Tail end panel	1	\$596.60		?
10	Tail end panel garnish <i>Re</i>	1	\$151.60		X
11	Tail end panel garnish clip <i>me</i>	10	\$35.00		X
12	Boot weatherstrip <i>Re</i>	1	\$353.10		X
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Labour