

ASS. REC. BY:

REF:

CS/CTI18017233/TI9d302

Special Instruction:

Surveyor
menmen

Taufik

ASSIGNMENT (Office)

From (Person):

Irene tuy

of

CTI

Date/Time

21/9/18 @ 1:12pm

Estimated Cost:

Bill to:

OD ☒ TI / WS / TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

SMD 4122 E

Insured:

SJU 536S

at Workshop m/s

Vermogen Ace

Tel:

6358 3031

of

G Benoi Jutor

Policy No:

DMPCSN1031771707

Claim No:

SNM18D04555C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/09/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

2:04pm @ 21/9/18

Person Contacted:

pila

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SMD 4122E -X

SJU 536S - NA/CTI17011020/h4

D.O.A: 3/6/17

REF: CFI

ASSIGNMENT

24/1/18

From: Date: 24/1/18

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD 4122E

at Workshop m/s: vermogen

of: G Benoi Sefor

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Moring

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS 1 up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SMD 4122E Yr Regn: 2018 Aug.

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vell fire 2.5 C.C. 2493.

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 6189 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: AGH 300174800.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R14 R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm


R/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 24/1/18 1430.

Survey held at: Vermogen.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 30 JAN 2019

Date/Time, File Pass to? 30/1/19

1) 20/1/19

Date/Time, File Return to?

2)

Report Format: MED-TP

Lump Sum / I.B.I. (\$) 6700

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: 220

Transportation: S + RS, SI

Photos

Other:

TOTAL 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Sep 2018		21 Sep 2018 13:12 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	VMG AUTO PTE LTD		
Vehicle Reg. No.:	SMD4122E	Date of Loss:	20/09/2018 00:00 - :59
Claim Type:	TP / SNM18D04555C02	Policy/Cover Note No.:	DMPCSN1031771707
Vehicle Reg. No. (Insured):	SJU536S	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18017233/T1qd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-09-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 536S	Veh. Inspected	SMD 4122E	
Policy No.	DMPCSN1031771707	Coverage (\$)	0.00	
Claim No.	SNM18D04555C02	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAY)	Assign Date	21/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/09/2018	Inspection Date	21/09/2018	
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Lucas Lee

From: pila@vermogen-group.com
Sent: Thursday, 20 September, 2018 4:06 PM
To: Claims Dept of CTI
Cc: 'Tejano Exequiel Dawal'; 'Edmond Lim'; 'Yira Rahman'; 'Minoko Chan'; 'Baldoz Juan Paulo Bongon'; 'Glorioso Eric Paul Patambang'; 'Luis Tan'; desmond@vermogen-group.com
Subject: Accident involving SMD4122E & SJU536S (Your Insured) on 20/09/2018 - PLEASE ARRANGE TP SURVEY
Attachments: 4122.pdf

Dear officer in-charge,

Refer to above attachment kindly arrange our client's vehicle for pre-repair survey at **Vermogen Ace Pte Ltd** here at **6 Benoi Sector**.

VEHICLE IN WORKSHOP

Beside, we would like to check for the liability on this matter.

Kindly check & revert to us as soon as possible.

Thanks & regards,

Pila

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6358 3031

Fax: 6694 4929

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAUTO)

From: Minoko Chan <minoko@vermogen-group.com>
Sent: Wednesday, 30 January 2019 12:51 PM
To: Taufikh (LKKAUTO)
Cc: Pila Ng; Tezano Exequiel Dawal; Baldoz Juan Paulo Bongon; desmond; Vmg admin; Vermogen Ace; Luis Tan; Shiau Chan (LKKAUTO); Glorioso Eric Paul Patambang; Edmond Lim
Subject: Re: SMD4122E FINALISE

Dear Taufik,

We agreed to accept your final revise lump sum COR @ \$ 6,700.00 & 6 repair days (excluding PRS/RS/Weekend & PH).

Thank you.

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

On Wed, Jan 30, 2019 at 10:58 AM Taufikh (LKKAUTO) <Taufikh@lkkauto.com> wrote:

Hi Minoko,

COR L/\$6700 , 6 days.

Regards

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2018 13:43
Date Of Accident	20/09/2018 12:15
Exact Location Of Accident	INSIDE TAN BOON LIAT PREMISES, OUTRAM RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD4122E
Insured/Policyholder	
Name Of Registered Owner	VMG AUTO PTE. LTD
Co Reg No	201713576D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90022161
Alternative Phone No	OFFICE-90022161

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE-2.4 V (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101650010
Cover Note Number	

Driver

Name of Driver	KOH CHONG HOW
NRIC No	S7335072G
Date Of Birth	15/09/1973
Occupation	OUTDOOR
Date Of Driving Pass	05/02/1996
Driving Experience	22 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90022161
Fax Number	
Contact Number	OFFICE-90022161
Email Address	NOEMAIL

Address	248 TAMPINES ST 21 #03-261
Postcode	S521248
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	6
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE
Passenger 3	NAME: : - GENDER: : FEMALE
Passenger 4	NAME: : - GENDER: : MALE
Passenger 5	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU536S
-----------------------------	---------

Vehicle Make/Model/Colour

VOLKSWAGON PASSAT

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUREAU (IAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was fetching passengers of Grab from Gerteng Centre to Tan Boon Liat Building to drop them. When we enter the Building, we were travelling slow as it inside the carpark. While turning left on the round left, suddenly the passat came in fast and hit my front of car. No passengers was injure during the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SMD4122E

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING

OWN INSURER : NTUC

CLAIM TYPE : TP

Date of Accident : 20/9/2018

Vehicle Reg. No. : SMD4122E

Vehicle Reg. Date: 17-Aug-2018

Make / Model : TOYOTA VELLFIRE 2.5Z G-

Engine No. : 2ARJ054184

Chassis No. : AGH300174800

COST OF CLAIMS

Parts Cost / List Items : \$ -

Plus/Less 20% \$ -

Total Cost / List : \$ -

Special Nett Items : \$ 175.00

Total Parts Amount : \$ 175.00

Total Labour Amount : \$ 4,340.00

Gross Total : \$ 4,515.00

GST % : 7% \$ 316.05

Nett Amount : \$ 4,831.05

Surveyor Name and Company :

Tayfun 97495749

Date of survey : 24/9/18 @ 1430

Part by Part / Lump Sum : 5-6 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sur@lkkauto.com

Fax No : _____

HP No : _____

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

4827.75

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SMD4122E**

Vehicle Reg. Date: **17/8/2018**

Make / Model : **TOYOTA VELLFIRE 2.5Z G-EDITON CVT**

Engine No. : **2ARJ054184**

Chassis No. : **AGH300174800**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT BONNET	bt ✓			
2	2	FRONT BONNET HINGE	Ry ✓			
3	1	FRONT BONNET CHROME GARNISH	ana ✓			
4	1	FRONT BONNET LOCK ASSY	x			
5	1	FRONT BONNET RUBBER	x			
6	1	FRONT BONNET INSULATOR	x			
7	1	FRONT BONNET INSULATOR CLIP SET	xle ✓			
8	1	FRONT BUMPER	de ✓			
9	1	FRONT BUMPER SIDE RETAINER	na ✓			
10	1	FRONT BUMPER UPPER RETAINER	na ✓			
11	1	FRONT BUMPER PAD	?			
12	1	FRONT BUMPER CLIP SET	na ✓			
13	1	FRONT BUMPER COVER HOLE	BA ?			
14	1	FRONT BUMPER GRILLE LOWER CENTER MOULDING	cut ✓			
15	1	FRONT BUMPER LOWER GRILLE	de ✓			
16	1	FRONT BUMPER LOWER GRILLE COVER	cut ✓			
17	1	FRONT BUMPER SIDE MOULDING	cut ✓			
18	1	FRONT BUMPER SPONGE	?			
19	1	FRONT BUMPER REINFORCEMENT	?			
20	1	SENSOR ASSY, MILLIMETER WAVE RADAR	cut ✓			
21	1	FRONT GRILLE BASE	BA ?			
22	1	FRONT GRILLE LOGO	x			
23	1	FRONT GRILLE LOGO MOULDING	x			
24	2	FRONT GRILLE UPPER CHROME MOULDING	x ?			
25	2	FRONT GRILLE LOWER CHROME MOULDING	x ?			
26	1	FRONT GRILLE LOWER MOULDING	Rx ✓			
27	1	FRONT GRILLE UPPER SEAL	x ✓			
28	1	FRONT GRILLE CLIP SET	na ✓			
29	1	FOGLAMP GARNISH RH	cut ✓			
30	1	FOGLAMP RH	x			
31	1	HEADLAMP ASSY RH	cut ✓			
32	1	HEADLAMP COVER RH	Ry ✓			
33	1	HEADLAMP PANEL RH	Ry ✓			
34	1	ENGINE UNDER COVER	x			
35	1	ENGINE UNDER COVER SEAL	x			
36	1	SUPPORT TOP PANEL	x			
37	1	SUPPORT LOWER PANEL	x			
38	2	SUPPORT PANEL LH/RH	x			
39	1	SUPPRT PANEL TOP GARNISH	x			
40	1	SUPPORT PANEL TOP GARNISH CLIPS SET	x			

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SMD4122E**

Vehicle Reg. Date: **17/8/2018**

Make / Model : **TOYOTA VELLFIRE 2.5Z G-EDITON CVT**

Engine No. : **2ARJ054184**

Chassis No. : **AGH300174800**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	RADIATOR AIR GUIDE RH	X			
42	1	WASHER TANK	X			
43	1	WASHER TANK NECK	X			
44	1	WASHER TANK MOTOR	X			
45	1	FRONT FENDER SIDE MIRROR LH	RY			
46	2	FRONT FENDER LH	Rx			
47	2	FRONT FENDER INNER SHIELD	X			
48	2	FRONT FENDER INNER SHIELD CLIPS SET	X			
49	1	AIR CON CONDENSER	X			
50	1	RADIATOR	X			
51	1	FRONT NUMBER PLATE WITH CASING	am	45	\$ 55.00	
52	1	TOP UP GAS	X		\$ 120.00	
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SMD4122E**
Vehicle Reg. Date: **17/8/2018**
Make / Model : **TOYOTA VELLFIRE 2.5Z G-EDITON CVT**
Engine No. : **2ARJ054184**
Chassis No. : **AGH300174800**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To knock & straighten on accident area, to remove & refit damage parts.front portion	\$ 1,600.00	650 700
2	To putty & respray panting and polish accident area.front portion	\$ 1,600.00	800 800
3	To check & rectify wiring after disconnect and connect	\$ 180.00	30
4	To rust proof affected areas.	\$ 180.00	30
5	To remove and refit radiator,condenser.	\$ 180.00	100 ?
6	To reset check light on	\$ 300.00	120
7	TO repair chassis member	\$ 300.00	X
8			
9			
10			
11			
12			
13			
14			
15			

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORMATTN TO: LKK-TAUFIK
Surveyor Name and CompanyDate of Accident : 20/9/2018BILL TO: CHINA TAIPING
TP Insurer

VEHICLE REG. NO.


SMD4122ETYPE OF CLAIM: TPMake / Model : TOYOTA VELLFIRE 2.5Z G-EDITON C**COST OF CLAIMS**Parts Cost / List : \$ 11,282.00Supp. Parts : \$ 417.00Special Nett : \$ 45.00Total Parts : \$ 8,819.25Total Labour : \$ 1,680.00TOTAL REPAIR COST : \$ 10,499.25

Total Parts Cost/List :	\$	11,699.00
Plus / Less : 25%	\$	2,924.75
Total :	\$	8,774.25

Lump Sum Discount : 20%	\$	2,099.85
Lump Sum Amount:	\$	8,399.40

Final Lump Sum Amount : \$ 8,400.00Submitted by / Date : MINOKONo. of Repair Days: 6

Confirmed by / Date : _____



10812

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SMD4122E**
 Vehicle Reg. Date: **17/8/2018**
 Make / Model : **TOYOTA VELLFIRE 2.5Z G-EDITON CVT**
 Engine No. : **2ARJ054184**
 Chassis No. : **AGH300174800**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT BONNET		\$ 742.00		\$ 742.00
2	2	FRONT BONNET HINGE		\$ 134.00		
3	1	FRONT BONNET CHROME GARNISH		\$ 531.00	4313	\$ 531.00
4	1	FRONT BONNET LOCK ASSY		\$ 116.00		
5	1	FRONT BONNET RUBBER		\$ 47.00		
6	1	FRONT BONNET INSULATOR		\$ 175.00		
7	1	FRONT BONNET INSULATOR CLIP SET		\$ 50.00		\$ 50.00
8	1	FRONT BUMPER		\$ 1,872.00	1300	\$ 1,872.00
9	1	FRONT BUMPER SIDE RETAINER		\$ 127.00		\$ 127.00
10	1	FRONT BUMPER UPPER RETAINER		\$ 83.00		\$ 83.00
11	1	FRONT BUMPER PAD		\$ 50.00		\$ 50.00
12	1	FRONT BUMPER CLIP SET		\$ 50.00		
13	1	FRONT BUMPER COVER HOLE		\$ 43.00		\$ 43.00
14	1	FRONT BUMPER GRILLE LOWER CENTER MOULDING		\$ 187.00		\$ 187.00
15	1	FRONT BUMPER LOWER GRILLE		\$ 184.00		\$ 184.00
16	1	FRONT BUMPER LOWER GRILLE COVER		\$ 264.00		\$ 264.00
17	1	FRONT BUMPER SIDE MOULDING		\$ 187.00		\$ 187.00
18	1	FRONT BUMPER SPONGE		\$ 69.00		\$ 69.00
19	1	FRONT BUMPER REINFORCEMENT		\$ 447.00		\$ 447.00
20	1	SENSOR ASSY, MILLIMETER WAVE RADAR - no damage photo.		\$ 1,473.00	nn x	\$ 1,473.00
21	1	FRONT GRILLE BASE		\$ 1,335.00	1220	\$ 1,335.00
22	1	FRONT GRILLE LOGO		\$ 798.00		
23	1	FRONT GRILLE LOGO MOULDING		NO USE		
24	2	FRONT GRILLE UPPER CHROME MOULDING		\$ 374.00		\$ 187.00
25	2	FRONT GRILLE LOWER CHROME MOULDING		\$ 374.00		\$ 187.00
26	1	FRONT GRILLE LOWER MOULDING		NO USE		
27	1	FRONT GRILLE UPPER SEAL		\$ 67.00		
28	1	FRONT GRILLE CLIP SET		\$ 50.00		\$ 50.00
29	1	FOGLAMP GARNISH RH		\$ 611.00		\$ 611.00
30	1	FOGLAMP RH		\$ 275.00		
31	1	HEADLAMP ASSY RH		\$ 2,197.00	1800	\$ 2,197.00
32	1	HEADLAMP COVER RH		\$ 97.00		
33	1	HEADLAMP PANEL RH		\$ 357.00		
34	1	ENGINE UNDER COVER	x	\$ 157.00		\$ 157.00
35	1	ENGINE UNDER COVER SEAL		\$ 219.00		
36	1	SUPPORT TOP PANEL		\$ 344.00		
37	1	SUPPORT LOWER PANEL		\$ 242.00		
38	2	SUPPORT PANEL LH/RH		\$ 714.00		
39	1	SUPPRT PANEL TOP GARNISH		\$ 187.00		
40	1	SUPPORT PANEL TOP GARNISH CLIPS SET		\$ 50.00		

8376.

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SMD4122E**
 Vehicle Reg. Date: **17/8/2018**
 Make / Model : **TOYOTA VELLFIRE 2.5Z G-EDITON CVT**
 Engine No. : **2ARJ054184**
 Chassis No. : **AGH300174800**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	RADIATOR AIR GUIDE RH		\$ 87.00		
42	1	WASHER TANK		\$ 47.00		
43	1	WASHER TANK NECK		\$ 136.00		
44	1	WASHER TANK MOTOR		\$ 127.00		
45	1	FRONT FENDER SIDE MIRROR LH		\$ 181.00		
46	2	FRONT FENDER		\$ 2,294.00		
47	2	FRONT FENDER INNER SHIELD <i>LM-Xun</i>		\$ 498.00	<i>RH-M/S</i>	\$ 249.00
48	2	FRONT FENDER INNER SHIELD CLIPS SET		\$ 50.00		
49	1	AIR CON CONDENSER		\$ 1,447.00		
50	1	RADIATOR		\$ 1,758.00		
51	1	FRONT NUMBER PLATE WITH CASING			\$ 45.00	
52	1	TOP UP GAS			\$ -	
53	0	0				
54	0	0				
55	0	0	<i>Parts</i>			8625
56	0	0	<i>25/L</i>			6468.75
57	0	0	<i>SN</i>			45
58	0	0	<i>Labor</i>			1680
59	0	0	<i>Supp.</i>			215.25
60	0	0				8409
61	0	0				
62	0	0				4596700
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

21904

45

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SMD4122E**
Vehicle Reg. Date: **17/8/2018**
Make / Model : **TOYOTA VELLFIRE 2.5Z G-EDITON CVT**
Engine No. : **2ARJ054184**
Chassis No. : **AGH300174800**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To knock & straighten on accident area, to remove & refit damage parts.front portion	\$ 1,600.00	\$ 700.00 ✓
2	To putty & respray panting and polish accident area.front portion	\$ 1,600.00	\$ 800.00 ✓
3	To check & rectify wiring after disconnect and connect	\$ 180.00	\$ 30.00 ✓
4	To rust proof affected areas.	\$ 180.00	\$ 30.00 ✓
5	To remove and refit radiator,condenser.	\$ 180.00	X nn ✓
6	To reset check light on	\$ 300.00	\$ 120.00 ✓
7	TO repair chassis member	\$ 300.00	X nn ✓
8			1680
9			
10			
11			
12			
13			
14			
15			

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SMD4122E
 Vehicle Reg. Date: 17/8/2018
 Make / Model : TOYOTA VELLFIRE 2.5Z G-EDITON CVT
 Engine No. : 2ARJ054184
 Chassis No. : AGH300174800

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	FRONT PARKING SENSOR RH		\$ 380.00	250	\$ 380.00
2	1	FRONT BUMPPER FOG LAMP GARNISH RH (SMAL		\$ 37.00		\$ 37.00
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

47 ent /
 47 ent /
 287
 250 - 215.25 =

...CLAIM SUBFOLDER...(Pending for Survey Report)































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018		21 Sep 2018 13:12 Edit Adj Rpt	S\$6,700.00 Edit Estimates	S\$6,700.00 View Rpt		Pending for Survey Report Cancel Case
































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: VMG AUTO PTE LTD									
Vehicle Reg. No.: SMD4122E		Date of Loss: 20/09/2018 00:00 - :59 [1 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04555C02		Policy/Cover Note No.: DMPCSN1031771707							
Vehicle Reg. No. (Insured): SJU536S		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel: 66944919									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/10/2018]									
Adj Asg. Remarks: NO EST, ASSIGN ADRIAN LING AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD4122E (SNM18D04555C02)
[SJU536S]
TP
VMG AUTO PTE LTD
Sep 20 2018 12:00AM
[-]
Vermogen Ace Pte Ltd (benoi)

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
2	30/01/19 14:26	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
3	30/01/19 14:26	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
4	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
5	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
6	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
7	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
8	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
9	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
10	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
11	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
12	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
13	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
14	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
15	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
16	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
17	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
18	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
19	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
20	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
21	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
22	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
23	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
24	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
25	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
26	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
27	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
28	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
29	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
30	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
31	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
32	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
33	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
34	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
35	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
36	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					
37	30/01/19 14:26	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
49	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
50	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
51	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
52	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
53	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
54	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
55	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
56	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
57	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
58	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
59	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
60	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
61	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
62	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
63	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
64	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
65	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
66	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
67	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
68	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
69	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
70	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
71	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
72	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
73	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
74	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
75	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
76	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
77	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
78	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
79	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
80	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
81	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
82	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
83	30/01/19 14:26	General View	 Load JPG	<input checked="" type="checkbox"/>
84	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	30/01/19 14:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/09/18 13:12	PRS	 Load PDF	
2	21/09/18 13:12	TP GIA	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/01/19 16:15	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18017233/T1QD3E2

Date: 30/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1031771707

Claimant Vehicle
No: SMD4122EInsured Vehicle
No: SJU536S

Date of Loss: 20/09/2018

Nature of Claim: TP

Claim
No: SNM18D04555C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD4122E

Make & Model: TOYOTA VELLFIRE, 2.4 V (A)

Reg. Date: 17/08/2018 (Man. Year: 2018)

Colour: White

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 2ARJ054184

Chassis No: AGH300174800

Odometer: 6189 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Front Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size: 235/50 R18

Rear Left Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,785.75	6,729.00	10,056.75	59.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,340.00	1,680.00	2,660.00	61.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,125.75	8,409.00	12,716.75	60.20
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	21,125.75	6,700.00	14,425.75	68.29
+ GST 7.00/7.00% (S\$)	1,478.80	469.00	1,009.80	68.29
Nett Amount (S\$)	22,604.55	7,169.00	15,435.55	68.29

INSPECTION

Date of Assignment: 21/09/2018

Date Inspected: 24/09/2018 Inspected At:

Vermogen Ace Pte Ltd (benoi) (HQ)
6 Benoi Sector
Singapore 629904

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2019)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.4 V (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD4122E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	742.00 FL	*742.00 FL
2	2		*FRONT BONNET HINGE	Repair	134.00 FL	*- FL
3	1		*FRONT BONNET CHROME GARNISH	Cracked	531.00 FL	*431.00 FL
4	1		*FRONT BONNET LOCK ASSY	Not Necessary	116.00 FL	*- FL
5	1		*FRONT BONNET RUBBER	Not Necessary	47.00 FL	*- FL
6	1		*FRONT BONNET INSULATOR	Not Necessary	175.00 FL	*- FL
7	1		*SET FRONT BONNET INSULATOR CLIP	Necessary	50.00 FL	*50.00 FL
8	1		*FRONT BUMPER	Deformed	1,872.00 FL	*1,300.00 FL
9	1		*FRONT BUMPER SIDE RETAINER	Necessary	127.00 FL	*127.00 FL
10	1		*FRONT BUMPER UPPER RETAINER	Necessary	83.00 FL	*83.00 FL
11	1		*FRONT BUMPER PAD	Deformed	50.00 FL	*50.00 FL
12	1		*SET FRONT BUMPER CLIP	Not Necessary	50.00 FL	*- FL
13	1		*FRONT BUMPER COVER HOLE	Deformed	43.00 FL	*43.00 FL
14	1		*FRONT BUMPER GRILLE LOWER CENTER MOULDING	Cut	187.00 FL	*187.00 FL
15	1		*FRONT BUMPER LOWER GRILLE	Deformed	184.00 FL	*184.00 FL
16	1		*FRONT BUMPER LOWER GRILLE COVER	Cut	264.00 FL	*264.00 FL
17	1		*FRONT BUMPER SIDE MOULDING	Cut	187.00 FL	*187.00 FL
18	1		*FRONT BUMPER SPONGE	Deformed	69.00 FL	*69.00 FL
19	1		*FRONT BUMPER REINFORCEMENT	Bent	447.00 FL	*447.00 FL
20	1		*SENSOR ASSY, MILLIMETER WAVE RADAR	Not Necessary	1,473.00 FL	*- FL
21	1		*FRONT GRILLE BASE	Cracked	1,335.00 FL	*1,220.00 FL
22	1		*FRONT GRILLE LOGO	Not Necessary	798.00 FL	*- FL
23	1		*FRONT GRILLE LOGO MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*FRONT GRILLE UPPER CHROME MOULDING (2PCS)	Cut-1pc only	374.00 FL	*187.00 FL
25	1		*FRONT GRILLE LOWER CHROME MOULDING (2PCS)	Cut-1pc only	374.00 FL	*187.00 FL
26	1		*FRONT GRILLE LOWER MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
27	1		*FRONT GRILLE UPPER SEAL	Not Necessary	67.00 FL	*- FL
28	1		*SET FRONT GRILLE CLIP	Necessary	50.00 FL	*50.00 FL
29	1		*FOGLAMP GARNISH RH	Cut	611.00 FL	*611.00 FL
30	1		*FOGLAMP RH	Not Necessary	275.00 FL	*- FL
31	1		*HEADLAMP ASSY RH	Cut	2,197.00 FL	*1,800.00 FL
32	1		*HEADLAMP COVER RH	Repair	97.00 FL	*- FL
33	1		*HEADLAMP PANEL RH	Repair	357.00 FL	*- FL
34	1		*ENGINE UNDER COVER	Deformed	157.00 FL	*157.00 FL
35	1		*ENGINE UNDER COVER SEAL	Not Necessary	219.00 FL	*- FL
36	1		*SUPPORT TOP PANEL	Not Necessary	344.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*SUPPORT LOWER PANEL	Not Necessary	242.00 FL	*- FL
38	2		*SUPPORT PANEL LH / RH	Not Necessary	714.00 FL	*- FL
39	1		*SUPPORT PANEL TOP GARNISH	Not Necessary	187.00 FL	*- FL
40	1		*SET SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FL	*- FL
41	1		*RADIATOR AIR GUIDE RH	Not Necessary	87.00 FL	*- FL
42	1		*WASHER TANK	Not Necessary	47.00 FL	*- FL
43	1		*WASHER TANK NECK	Not Necessary	136.00 FL	*- FL
44	1		*WASHER TANK MOTOR	Not Necessary	127.00 FL	*- FL
45	1		*FRONT FENDER SIDE MIRROR LH	Repair	181.00 FL	*- FL
46	2		*FRONT FENDER	Repair	2,294.00 FL	*- FL
47	2		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FL	*- FL
48	1		*AIR CON CONDENSER	Not Necessary	1,447.00 FL	*- FL
49	1		*RADIATOR	Not Necessary	1,758.00 FL	*- FL
50	1		*FRONT NUMBER PLATE WITH CASING	Cut	45.00 FS	*45.00 FS
51	1		*FRONT PARKING SENSOR RH	Cut	380.00 FL	*250.00 FL
52	1		*FRONT BUMPER FOG LAMP GARNISH RH (SMAL	Cut	37.00 FL	*37.00 FL
53	1		*FRONT FENDER INNER SHIELD	O/S Torn / N/S Not Necessary	498.00 FL	*249.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,366.00	8,957.00
- List Item Discount on L Items 25.00/25.00% (S\$)	5,580.25	2,228.00
Total Parts (S\$)	16,785.75	6,729.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOP UP GAS (NPA)	New	0.00	0.00
2	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT DAMAGE PARTS FRONT PORTION	New	1,600.00	700.00
3	TO PUTTY & RESPRAY PAINTING AND POLISH ACCIDENT AREA. FRONT PORTION	New	1,600.00	800.00
4	TO CHECK & RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	180.00	30.00
5	TO RUST PROOF AFFECTED AREAS	New	180.00	30.00
6	TO REMOVE AND REFIT RADIATOR, CONDENSER	New	180.00	0.00
7	TO RESET CHECK LIGHT ON	New	300.00	120.00
8	TO REPAIR CHASSIS MEMBER	New	300.00	-
Gross Labour Cost (\$\$)			4,340.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >