

Trans-cab Auto Services Pte Ltd

AAD1809-149

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9980X*Not Authorised*
6-Sep @ 2201

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9980X

VF1ABL15AUC278121

RENAULT

LATITUDE

17.9.2018

AXA**PART****LIST**

1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT LH	\$	151.41
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER RETAINER FRT RH	\$	150.77
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	HEADLAMP LH	\$	1,184.43
1	HEADLAMP PANEL FRT LH	\$	152.15
1	FENDER PANEL FRT LH	\$	783.83
1	WHEELARCH FRT LH	\$	278.84
1	FENDER BRACKET LOWER LH	\$	15.79
1	FENDER INSULATOR LH	\$	130.84
1	DOOR PANEL FRT LH	\$	2,844.66
1	DOOR HINGE UPPER LH	\$	261.28
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK FRT LH	\$	194.77
1	DOOR LOCK FRT LH	\$	908.75
1	DOOR CATCH FRT LH	\$	131.23
1	DOOR HANDLE OUTER FRT LH	\$	477.76
1	DOOR HANDLE COVER FRT LH	\$	13.22
1	DOOR HANDLE MODULE FRT LH	\$	133.60
1	DOOR REGULATOR FRT LH	\$	505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	120.97

X

Trans-cab Auto Services Pte Ltd

AAD1809-149

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9980X

1	DOOR PANEL REAR LH	\$	2,844.66
1	DOOR GUIDE REAR LH	\$	176.82
1	DOOR HINGE UPPER LH	\$	274.50
1	DOOR HINGE LOWER LH	\$	300.55
1	DOOR CHECK REAR LH	\$	203.06
1	DOOR LOCK REAR LH	\$	908.75
1	DOOR HANDLE OUTER REAR LH	\$	126.49
1	DOOR HANDLE CAP REAR LH	\$	35.52
1	DOOR HANDLE SEAL REAR LH	\$	7.89
1	DOOR HANDLE COVER REAR LH	\$	13.22
1	DOOR HANDLE MODULE REAR LH	\$	133.60
1	DOOR REGULATOR REAR LH	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75
1	DOOR REGULATOR NUT REAR LH	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH	\$	423.10
1	DOOR MOULDING REAR LH	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH	\$	1,509.06
1	DOOR WATER SHIELD REAR LH	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33
1	DOOR GRAB HANDLE REAR LH	\$	210.96
1	DOOR BLIND REAR LH	\$	741.80
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66
1	DOOR SEAL REAR LH	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64
1	DOOR MIRROR ASSY LH	\$	1,483.40
1	ROCKER PANEL INNER GARNISH LH	\$	466.51
1	ROCKER PANEL INNER LH	\$	1,024.79

Trans-cab Auto Services Pte Ltd**AAD1809-149**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9980X

1	ROCKER PANEL CENTER LH
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMEPR BRACKET SIDE LH REAR
1	BUMEPR RETAINER LH REAR

\$	<i>R</i> 990.25
\$	<i>Sm</i> 1,108.46
\$	<i>Sm</i> 768.84
\$	<i>Sm</i> 113.47
\$	<i>Sm</i> 135.97
\$	<i>Sm</i> 44.99

} X

\$	31,495.43
10% \$	3,149.54
\$	28,345.89

Special Nett

1	FRONT FENDER ADVERTISEMENT STICKER
1	FRONT DOOR ADVERTISEMENT STICKER
1	REAR DOOR ADVERTISEMENT STICKER
1	REAR FENDER ADVERTISEMENT STICKER
1	DOOR CHECK BOLT
1	DOOR GUIDE SCREW
1	DOOR HINGE BOLT
1	DOOR HINGE NUT RH
1	DOOR CHECK BOLT
1	DOOR CHECK NUT
1	DOOR LOCK SCREW L70Y
1	DOOR CATCH SCREW L70Y
1SET	PARKING AID
1SET	REAR BUMPER CLIP
1SET	BUMPER BRACKET CTR CLIP
1SET	BUMPER BRACKET SIDE CLIP RH RR
1SET	BUMEPR RETAINER RH CLIP RR
1SET	BUMEPR BRACKET SIDE CLIP LH RR
1SET	BUMEPR RETAINER CLIP LH RR
1SET	BUMPER LOWER REAR RIVET
1SET	BUMPER LOWER REAR CLIP

\$	<i>nn</i> 300.00
\$	300.00
\$	300.00
\$	300.00
\$	22.69
\$	10.85
\$	10.85
\$	14.60
\$	22.69
\$	3.75
\$	6.12
\$	10.06
\$	700.00
\$	66.00
\$	33.00
\$	10.00
\$	20.00
\$	10.00
\$	20.00
\$	22.00
\$	<i>nn</i> 66.00

} X

TOTAL \$ 2,248.63**TOTAL PARTS \$ 30,594.52**

Trans-cab Auto Services Pte Ltd**AAD1809-149**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9980X**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>nn</i> 6,000.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	5,000.00 <i>22d</i>
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>✓</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Towing Fees.	\$	<i>nn</i> 120.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1809-149**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9980X

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *un* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *m* 380.00 X**TOTAL \$ 14,890.00****Over All Total \$ 45,484.52****LUMP SUM (REPAIR DAY)***20 DAYS**1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: