

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9816Z**AAD1809-168***Not Authored
1/1 Sep @ 3200h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9816Z

VF1ABL15AUC273235

RENAULT

LATITUDE

18.9.2018

AIG

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	DOOR PANEL FRT RH
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	RADIATOR FAN COWLING
1	RADIATOR FAN MOTOR LH
1	RADIATOR FAN MOTOR RH
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	DOOR MIRROR ASSY RH
1	DOOR PANEL FRT RH
1	BONNET
1	BONNET INSULATOR

	LIST
\$	<i>PHICM</i> 1,259.42 ✓
\$	<i>Sn</i> 181.75 X
\$	<i>Sn</i> 394.68 X
\$	<i>Dir</i> 150.77 ✓
\$	<i>Sn</i> 123.88 X
\$	<i>Sn</i> 472.83 X
\$	<i>Sn</i> 266.80 X
\$	<i>Sn</i> 207.21 X
\$	<i>R</i> 914.08 X
\$	<i>ngcm</i> 1,184.43 ✓
\$	<i>R</i> 152.15 X
\$	<i>Sn</i> 1,184.43 X
\$	<i>R</i> 152.15 X
\$	<i>R</i> 783.83 ✓
\$	<i>Dir</i> 278.84 X
\$	<i>Sn</i> 15.79 X
\$	<i>Sn</i> 130.84 X
\$	<i>R</i> 2,844.66 } X
\$	<i>Sn</i> 1,707.78 }
\$	<i>na</i> 225.36 }
\$	<i>na</i> 1,353.75 }
\$	<i>Sn</i> 820.54 }
\$	<i>Sn</i> 967.36 }
\$	<i>Sn</i> 1,479.46 }
\$	<i>Sn R</i> 615.90 }
\$	<i>R</i> 89.79 }
\$	<i>Sn</i> 1,483.40 }
\$	<i>R</i> 2,844.66 }
\$	<i>R</i> 1,941.63 }
\$	<i>Sn</i> 405.73 }

Trans-cab Auto Services Pte Ltd**AAD1809-168**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9816Z

1	BONNET STRUT LH	\$	Sn 88.61	}
1	BONNET STRUT RH	\$	Sn 88.61	
1	BONNET HINGE LH	\$	Sn 348.31	
1	BONNET HINGE RH	\$	Sn 348.31	
1	BONNET LOCK	\$	Sn 305.48	
1	BONNET CABLE	\$	Sn 119.19	
1	BONNET CABLE COVER	\$	Sn 161.03	
1	BONNET SEAL OUTER	\$	Sn 92.36	
1	BONNET SEAL INNER	\$	Sn 157.28	
1	SUBFRAME OUTER FRT	\$	Sn 2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	Sn 92.36	
1	SUBFRAME BRACKET OUTER RH	\$	Sn 92.36	
1	ENGINE UNDERTRAY	\$	Sn 564.98	
1	A/C CONDENSER	\$	Sn 2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	Sn 39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	Sn 39.67	
1	A/C CONDENSER GARNISH LH	\$	Sn 58.81	
1	A/C CONDENSER GARNISH RH	\$	Sn 59.60	
1	LOWER ARM RH	\$	Sn 685.76	
1	KUNCKLE ARM RH	\$	Sn 846.98	
1	ABSORBER FRT RH	\$	Sn 360.54	
1	STABILIZER BAR FRT	\$	Sn 604.65	
1	DRIVESHAFT RH	\$	Sn 1,747.45	
1	WIPER RESERVOIR	\$	Sn 348.25	
1	WIPER RESERVOIR NECK	\$	Sn 136.11	
1	WIPER RESERVOIR MOTOR	\$	Sn 270.06	

TOTAL	\$	36,963.11
10%	\$	3,696.31
	\$	33,266.80

Specical Nett

1SET	BUMPER CLIP FRT	\$	na na 66.00 X
1	BUMPER BRACKET CLIP FRT RH	\$	na 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	na 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	na 69.00 X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00 X

Trans-cab Auto Services Pte Ltd

AAD1809-168

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9816Z

2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	✓
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30	} X
2	BONNET STRUT L70Y	\$	sh	88.61	
2	BONNET CABLE CLIP L70Y	\$	na	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85	
1	WINDSCREEN SEALANT	\$	na	253.80	
1	FRONT WINDSCREEN MOULDING	\$	na	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	na	80.00	
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	na	50.00	} X
1	FRONT RIGHT TYRE	\$	sh	330.00	
1	FRONT RIGHT TYRE RIM	\$	sh	380.00	

TOTAL	\$	1,734.88
--------------	-----------	-----------------

TOTAL PARTS	\$	35,001.68
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00	4001
----	----------	------

Putty and spray painting of the affected portion.

\$	4,000.00	4401
----	----------	------

To rust-proofing of the affected areas.

\$	170.00	301
----	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	na	380.00	X
----	----	--------	---

To check steering geometry and computer wheel alignment

\$	na	220.00	X
----	----	--------	---

To transfer of tire, rim and on wheel balancing.

\$	na	170.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd

AAD1809-168

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9816Z

To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	4 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	4 380.00	X
To replace, refix and top up coolant for radiator	\$	4 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	4 170.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	4 170.00	X

TOTAL	\$	11,090.00
--------------	-----------	------------------

Over All Total	\$	46,091.68
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**15 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: