

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5634C**AAD1809-196***Not Authorised*
U/Sing &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5634C

VF1ABL15AUC279629

RENAULT

LATITUDE

19.9.2018

Ali

PART		LIST	
1	BUMPER COVER FRT	\$	<i>CM</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Dri</i> 181.75 ✓
1	BUMPER ABSORBER FRT	\$	<i>Arti</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>CM</i> 150.77 ✓
1	BUMPER SUPPORT FRT	\$	<i>CM</i> 123.88 ✓
1	BUMPER UNDERTRAY FRT	\$	<i>CM</i> 472.83 ✓
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Art</i> 207.21 ✓
1	BUMPER BEAM FRT	\$	<i>Bt</i> 914.08 ✓
1	HEADLAMP RH	\$	<i>Art</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43 X
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>Bt</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>CM</i> 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	<i>R</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84 X
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66 X
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78 X
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36 X
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75 X
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54 X
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36 X
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46 X
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90 X
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
1	DOOR MIRROR ASSY RH	\$	<i>Art</i> 1,483.40 ✓
1	DOOR PANEL FRT RH	\$	<i>Art</i> 2,844.66 X
1	BONNET	\$	<i>R</i> 1,941.63 X
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73 X

Trans-cab Auto Services Pte Ltd**AAD1809-196**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5634C

1	BONNET STRUT LH	\$	<i>Sm</i>	88.61	
1	BONNET STRUT RH	\$	<i>Sm</i>	88.61	
1	BONNET HINGE LH	\$	<i>R</i>	348.31	
1	BONNET HINGE RH	\$	<i>R</i>	348.31	
1	BONNET LOCK	\$	<i>R</i>	305.48	
1	BONNET CABLE	\$	<i>Sm</i>	119.19	
1	BONNET CABLE COVER	\$	<i>Sm</i>	161.03	
1	BONNET SEAL OUTER	\$	<i>Sm</i>	92.36	
1	BONNET SEAL INNER	\$	<i>Sm</i>	157.28	
1	SUBFRAME OUTER FRT	\$	<i>Sm</i>	2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	<i>Sm</i>	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	<i>Sm</i>	92.36	
1	ENGINE UNDERTRAY	\$	<i>Sm</i>	564.98	
1	A/C CONDENSER	\$	<i>Sm</i>	2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	<i>Sm</i>	39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	<i>Sm</i>	39.67	
1	A/C CONDENSER GARNISH LH	\$	<i>Sm</i>	58.81	
1	A/C CONDENSER GARNISH RH	\$	<i>Sm</i>	59.60	
1	LOWER ARM RH	\$		685.76	?
1	KUNCKLE ARM RH	\$	<i>R</i>	846.98	✓
1	ABSORBER FRT RH	\$		360.54	?
1	STABILIZER BAR FRT	\$		604.65	?
1	DRIVESHAFT RH	\$		1,747.45	?
1	WIPER RESERVOIR	\$	<i>R</i>	348.25	✓
1	WIPER RESERVOIR NECK	\$		136.11	?
1	WIPER RESERVOIR MOTOR	\$		270.06	?

TOTAL	\$	36,963.11
10%	\$	3,696.31
	\$	33,266.80

Specical Nett

1SET	BUMPER CLIP FRT	\$	<i>R</i>	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i>	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i>	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i>	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i>	70.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5634C**AAD1809-196**

2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
1SET	WHEELARCH CLIP FRT RH	\$	nn	30.50	✓
6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	X
2	BONNET STRUT L70Y	\$	sn	88.61	X
2	BONNET CABLE CLIP L70Y	\$	nn	6.31	X
2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	X
1	WINDSCREEN SEALANT	\$	nn	253.80	X
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	X
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	X
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	nn	80.00	60sn
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	nn	50.00	15sn
1	FRONT RIGHT TYRE	\$	nn	330.00	109in
1	FRONT RIGHT TYRE RIM	\$	nn	380.00	✓

TOTAL	\$	1,734.88
--------------	-----------	-----------------

TOTAL PARTS	\$	35,001.68
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	500
Putty and spray painting of the affected portion.	\$	4,000.00	660
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	60
To transfer of tire, rim and on wheel balancing.	\$	170.00	20

Trans-cab Auto Services Pte Ltd

AAD1809-196

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5634C

To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	nn 170.00	X

TOTAL	\$	11,090.00
--------------	-----------	------------------

Over All Total	\$	46,091.68
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~15 DAYS~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: