

ASS. REC. BY:

REF: CS/FCI18017247/K1+d3m

Special Instruction:

Surveyor: Kalvin
CWS

ASSIGNMENT (Office)

From (Person): Karen Tan

of FCI

Date/Time: 21/9/18 @ 3:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6800H

Insured: SH 91264

at Workshop m/s: Premier Automotive

Tel: 6544 6689

of 23 Changi South Ave 2 #03-02

Policy No:

Claim No: D18006950MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 20/09/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 3:13pm @ 21/9/18

Person Contacted:

Vincent

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6800H - CS/FCI18012560/K1+bg2 BOA: 8/7/18
	SH 91264 - CC3/FCI17015244/K1+eb3q2 Don: 3/8/17
24/9/18 @ 12:04pm	revised to Karen Tan by email.

Surveyor: Kevin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 6800H Yr Regn: 29 May 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: KIA Optima c.c. 1685

Colour: Silver A/C: Ins / Std / NI / NA

Sp. Reading: 425121 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: KNAHM 814 MFS 593571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size; F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front 7 mm Rear 7 mm

R/Bal. 7 mm L/Bal. 7 mm

L/Bal. 7 mm D.O.A. 20/9/8 D.O.I. 21/9/8

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>25/9/8</u>	<u>Labour r/p \$330 / 26% (Red: 3272.90; 90%) FCI 4s</u>

RECEIVED 22 SEP 2018

Date/Time, File Pass to? : Preli. Report

1) 25/9/2018 : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	130
Transportation:	50
_____ S + RS _____ SI	50
Photos	22
Others	
TOTAL	252

Report Format : TP
Lump Sum / I.B.I: (\$ 330)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18017247/K1td3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9126U	Veh. Inspected	SHC 6800H
Policy No.		Coverage (\$)	0.00
Claim No.	D18006950MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	21/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/09/2018	Inspection Date	21/09/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18006950MFSH

Date: 24 September 2018

Our Ref: CS/FCI18017247/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6800H

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/09/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,602.90</u>
Revised Estimate Amount	: <u>S\$ 330.00</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-09-2018	Our Ref No. D18006950MFSH
Accident Date	20-09-2018	Claim Type. Third Party
Insured Vehicle	SH9126U	Third Party Vehicle. SHC6800H
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244381)



PRI Documents



Close



PRI Header Details

Claim No	D18006950MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : VINCENT CHUA)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446689 , Phone: 62148880 , Fax: 6214151: EmailId: VINCENT.CHUA@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9126U	TP Vehicle No	SHC6800H
PRI Recieved Date	20-09-2018 08:52:46 PM	Surveyor Appointed Date	21-09-2018 03:07:12 PM	Surveyor Accept Date	21-09-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	21-09-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 24 September 2018 12:04 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18006950MFSH/1
Attachments: CSFCI18017247K1td3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SHC 6800H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 21 September 2018 3:11 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006950MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 21 September 2018 3:07 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18006950MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:	29 May 2015 / 09:10:03	Receipt No.:	AACCK001-AX239-150529-000002
Asset Type:	Vehicle	Transaction Amount:	\$65,428.00
Asset ID:	SHC6800H	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150529091003285768		
Vehicle No.:	SHC6800H		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	29 May 2015		
Original Registration Date:	29 May 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5593571		
Engine No.:	D4FDEH313364		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$21,451.00		
Minimum PARF Benefit:	\$8,719.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	29 May 2015 09:10:03		
COE No.:	2015052901002467C		
COE Expiry Date:	28 May 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,756.00		
Lifespan Expiry Date:	28 May 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Sep-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6800 H

1 pc	Rear bumper	X repair	\$	696.00
1 pc	Rear bumper lower cover	X SK	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X SK	\$	58.00
1 pc	Rear bumper inner sponge	X SK	\$	114.00
1 pc	Rear bumper reinforcement	X SK	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X SK	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	SK	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	X SK	\$	36.00
			\$	1,861.00
			Less 10%	\$ 186.10
			\$	1,674.90

S/NETT

1 set	Rear bumper clips	X 11	\$	48.00
1 set	Reverse sensor	X SK	\$	280.00
1 pc	Rear bumper top protector	SK	\$	80.00 50
Sundry			\$	50.00 X 11
To dismantle / replace reverse sensor to new bumper and reset to the same			\$	120.00 X 11
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$	180.00 X 11
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc			\$	100 650.00
To putty and spray painting on rear bumper, end panel			\$	400.00 100
To apply rustproofing on the repaired and replaced panels.			\$	120.00 X 11
			\$	3,602.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the spray painting
- To display damaged parts during resurvey
- Parts prices are on "best price" basis
- Third party survey to be done on "Pro-udice" basis
- No illegal modification allowed
- Supplementary to be submitted to relevant and appropriate insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahri CREK
21/9/18 1636
2071
HS
After Repair photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017247/K1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9126U	Veh. Inspected	SHC 6800H	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18006950MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	21/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5593571	Colour	SILVER	
Odometer	425121	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2018	Inspection Date	21/09/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6800H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	SERVICEABLE	206.00	-
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S	SERVICEABLE	108.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
	LESS 10% DISCOUNT		-186.10	-
			1,674.90	-
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SERVICEABLE	280.00	-
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			458.00	50.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL, ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		650.00	100.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, END PANEL.		400.00	180.00

Report Ref No. CS/FCI18017247/K1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,470.00	280.00
GRAND TOTAL			3,602.90	330.00
RECOMMENDED COST OF REPAIRS				330.00

Report Ref No. CS/FCI18017247/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.