

ASS. REC. BY:

REF: CS/CTI 18017252/ Ngd3% Special Instruction:

Surveyor:

Mehimen

Ngz

ASSIGNMENT (Office)

From (Person):

Juwyn Tay

of

CTI

Date/Time:

21/9/18 @ 3:45pm

Estimated Cost:

Bill to:

OD TP / WS / TP-RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 2102R

Insured:

PC6030T

at Workshop in/:

Zhong Cheng Enterprise

Tel:

9338 2869

of

Blk 6, Yew Tee Ind. Est. 399J

Policy No:

DMB18N1691261701

Claim No:

SNM18D04545C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 19/09/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

4:50pm @ 21/9/18

Person Contacted:

Ms. Sini

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	15/11/18 - vehicle still not will will change.
	SKT 2102R - X	
	PC 6030 T - X	
21/9/18-	VNI yet	
1/10/18-	vehicle still not in.	
17/10/18-	VNI yet	
2/11/18-	vehicle still not in (winding roads from runner)	

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lun Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN/OUT

Veh No: SKT 2102 R Yr Regn: 27 May 2013
 Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MAZDA 3 c.c. 1,496
 Colour: BLACK A/C: Insur'd / Std / NI / NA
 Sp. Reading: 68787 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6BM42A860301050
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/60 R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front		Rear
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm
D.O.A. <u>19/9/18</u>		U.O.I. <u>19/11/18</u>

 Survey held at ZHONG CHENG
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>5/4/19</u>	<u>FINALIZED LUMP SUM REPAIR \$4,050.00 / 5 Days</u> <u>(Red to 3210.50, 48%)</u>
<u>RECEIVED 30 APR 2019</u>	

Date/Time, File Pass to? : Preli Report
 : Final Report
 Date/Time, File Return to?
 Report Format: WER-TP
 Lump Sum / I.B.I. (\$) 4050

Days Of Repair: 5
 Resurvey No. of Trip: 2
 Add Fee: Site Insp (\$ _____) S + RS _____ \$
 Interview (\$ _____) Photos
 Tech. Invo (\$) Others
 Weekend (\$ _____)
 Survey Fee: _____
 Transportation: _____
 TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Sep 2018		21 Sep 2018 15:45 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ALBERT PANG TRANSPORT, Co. Reg. No.: 52922438X		
Main Claimant:	CHENG MENG FURNITURE GROUP (PTE.) LTD., Co. Reg. No.: 196400375H		
Vehicle Reg. No.:	SKT2102R	Date of Loss:	19/09/2018 13:00 - :59
Claim Type:	TP / SNM18D04545C02	Policy/Cover Note No.:	DMB1SN1691261701 (Comprehensive)
Vehicle Reg. No. (Insured):	PC6030T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Zhong Cheng Enterprise (HQ) BLK 6 YEW TEE INDUSTRIAL ESTATE 399J WOODLANDS ROAD, 678008 Woodlands - Tel: 9826-4959		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/10/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/09/2018 15:45
Date Of Accident	19/09/2018 13:15
Exact Location Of Accident	INFRONT OF ORCHARD HOTEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT2102R
Insured/Policyholder	
Name Of Registered Owner	CHENG MENG FURNITURE GROUP (PTE.) LTD.
Co Reg No	196400375H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94555812
Alternative Phone No	OFFICE-67459900

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084531658-01 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	ONG TIONG HOCK
NRIC No	S1434097A
Date Of Birth	06/09/1960
Occupation	OUTDOOR
Date Of Driving Pass	15/02/1978
Driving Experience	40 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94555812
Fax Number	
Contact Number	OTHERS-94555812
EMail Address	NOEMAIL

Address	BLK 79A TOA PAYOH CENTRAL #32-09
Postcode	311079
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE CAME TO A STOPPED INFRONT OF ORCHARD HOTEL TO CHECK FOR TRAFFIC CLEARANCE BEFORE MAKING A RIGHT TURN. AT THAT POINT OF TIME THERE WAS A STATIONARY BUS PARKED OPPOSITE SIDE AGAINST THE FLOW OF TRAFFIC WITH THE HAZARD LIGHT SWITCH ON AND THERE WAS ALSO A STATIONARY BUS PARKED ON MY RIGHT SIDE BLOCKING MY VIEW. I GIVE WAY TO AN UNKNOWN VAN. WHEN THE UNKNOWN VAN DROVE PAST I SLOWLY MADE A RIGHT TURN, THE BUS WHICH WAS PARKED ON THE OPPOSITE SIDE SUDDENLY REVERSED HIS VEHICLE PC 6030T. THUS, VEHICLE PC 6030T REAR LEFT PORTION COLLIDED INTO THE FRONT LEFT PORTION OF MY VEHICLE. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC6030T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	CAI XIANGWEI
NRIC/Passport Number	G2110505N
Contact Number	96327409
Address	98789907 - BOSS
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

19 SEP 2018



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Policy Information

Policy No.	5084531658-01	Policyholder Name	CHENG HONG FURNITURE GRO	Policyholder NRIC	196400375H
Certificate No.					
Address	3 KALLANG PUDDING ROAD SINGAPORE 349308				
Product Name	PRIVATE CAR INSURANCE	Plan			
Group Policy Flag	N				
Policy Issue Date	13/10/2017	Effective Date	27/11/2017 00:00	Expiry Date	26/11/2018 23:59
Excess Type	All Claims Excess				
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outlife Singapore OD Excess	600	Outside Singapore TP Excess	0	Young/Inexperience Driver/Excess	
Agent	ARWIN PTE LTD	Agent Tel.	68423301	GST Flag	Y
Co-Insurance Flag	No				
Open Policy Info					
Certificate Info					

Policyholder Mailing Address

Address 1	3 KALLANG PUDDING ROAD	Address 2	SINGAPORE 349308	Address 3	
Address 4		Address Type	Singapore address	Post Code	349308
Unit No.		Related Policy Number	5084531658-01		

Insured Object: SKY2102R

Vehicle No.	SKY2102R	Model	3	Make	MAZDA
Vehicle Type	396	Date of Registration	27/05/2015		
Classis No.	JH58H42A8G0301050	Engine No.	PS20261908	Vehicle Capacity	
No. of Seats	5	Parallel Import	0	Imported/Reconditioned	0
Off peak car	0				

Coverage	Coverage Category	Sum Insured	Excess Description	Remark
drive CLASSIC Own Damage or Loss		999,999,999.99		
drive CLASSIC TPI		999,999,999.99		
drive CLASSIC TPPD		1,000,000.00		
drive CLASSIC Own Damage or Loss in transit		999,999,999.99		
drive CLASSIC Windscreen Damage		999,999,999.99		
drive CLASSIC Personal Accident for PH		20,000.00		
drive CLASSIC Personal Accident for Driver Liability		10,000.00		
drive CLASSIC Personal Accident for Passenger		10,000.00		
drive CLASSIC Medical Expenses		300.00		
drive CLASSIC Towing Fee		200.00		
drive CLASSIC Own Damage Benefit		99,999,999.99		

Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
<input type="button" value="Continue"/> <input type="button" value="Cancel"/>				

Vehicle no. : SKT2102R

Model : Mazda 3

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

\$

- 1 1 pc LH front fender XR
- 2 1 pc LH front fender inner shield ?
- 3 1 pc Front bumper / CRK
- 4 1 pc bumper reinforcement ?
- 5 1 pc bumper chrome / CRK
- 6 1 pc Front grille ~~XXXX~~ @ \$145.50 each ~~Q~~ / CRK
- 7 1 pc Bonnet / DEF
- 8 1 pc Bonnet lock ?
- 9 1 pc LH headlamp / SCR
- 10 1 pc Front support panel ? / BT
- 11 1 pc Top garnish ?
- 12 1 pc Fog lamp cover LH / MIS

\$ -
\$ -
\$ -

Less 20%

Nett Items

- 1 1 set LH front fender inner shield fasteners ?
- 2 1 pc front bumper retainer / NEC
- 3 1 set bumper fastener / NEC
- 4 1 pc headlamp bracket RH ?
- 5 1 set headlamp fastners ?
- 6 1 pc Fog lamp LH ?
- 7 1 pc Front bumper logo emblem / NEC
- 8 1 set top garnish clips ?

Special Nett

- 1 1 front carplate w housing ? (sewing 4 (2013)) \$ 60.00
 - 2 1 front sensor ? \$ 380.00
- \$ 440.00

Vehicle no. : SKT2102R

Model : Mazda 3

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

			\$
1	1 pc	LH front fender	\$ 369.90 / R
2	1 pc	LH front fender inner shield	\$ 157.00 ? XSVL
3	1 pc	Front bumper	900 \$ 975.10 / CRK
4	1 pc	bumper reinforcement	500 \$ 595.10 ? / BT
5	1 pc	bumper chrome	\$ 198.50 / CRK
6	1 pc	Front grille upper	\$ 169.80 / CRK
7	1 pc	Bonnet	1,000 \$ 1,107.50 / DEF
8	1 pc	Bonnet lock	\$ 217.50 ? XSVL
9	1 pc	LH headlamp	700 \$ 795.90 / SCR
10	1 pc	Front support panel	400 \$ 499.90 ? / BT
11	1 pc	Top garnish	\$ 142.90 ? / DEF
			4,011.20 \$ 5,229.10
Less 20%			\$ 1,045.82
			3,208.96 \$ 4,183.28

Nett Items

1	1 set	LH front fender inner shield fasteners	\$ 28.00 ? XSVL
2	1 pc	front bumper retainer	\$ 26.00 / NEK
3	1 set	bumper fastener	\$ 28.00 / NBL
4	1 pc	headlamp bracket RH	\$ 26.00 ? XSVL
5	1 pc	Fog lamp LH	\$ 135.50 ? / CRK
6	1 pc	Front bumper logo emblem	\$ 58.00 / NBL
7	1 set	top garnish clips	\$ 18.00 ? / NEK
8	1 pc	Fog lamp cover LH	\$ 73.50 / MBL
			339 \$ 393.00
Less 10%			\$ 39.30
			305.10 \$ 353.70

Special Nett

1	1	front carplate w housing	\$ 60.00 ? XSVL
2	1	front sensor	\$ 380.00 ? XSVL
			\$ 440.00

Vehicle no. : SKT2102R

Model : Mazda 3

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

			\$
1	1 pc	bumper lower grille	\$ 149.90 ? ASVC
2	1 pc	Towing cover	\$ 79.50 ? ASVC
			\$ 229.40
Less 20%			\$ 45.88
			<u>\$ 183.52</u>

Vehicle no. : SKT2102R

Model : Mazda 3

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
		B/F	\$ -
LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts	\$ 1,100.00 700
2		To anti-rust	\$ 100.00 50
3		To remove & refix radiator/condenser/top up coolant & gas for checking	\$ 200.00 ? 100
4		To putty and spray-paint of affected areas	\$ 1,200.00 700
			<u>\$ 2,600.00</u>

1,550

NAZ LKIC
 19/11/18
 5 days
 L/S
 CHECK ITEMS PHOTOS
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3760.50

PARTS \$4,011.20
 LESS 20% \$ 3,208.96
 NETT LESS 10% \$ 305.10

LABOUR \$1,550
\$ 5,064.06

Grand - Total \$ -

-LESS 20% LIS \$ 4,051.24

L1STOTAL \$ 4,050.00 / 5 REPAIR DAYS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Sep 2018		21 Sep 2018 15:45 Edit Adj Rpt	S\$4,050.00 Edit Estimates	S\$4,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ALBERT PANG TRANSPORT , Co. Reg. No.: 52922438X								
Main Claimant:	CHENG MENG FURNITURE GROUP (PTE.) LTD. , Co. Reg. No.: 196400375H								
Vehicle Reg. No.:	SKT2102R	Date of Loss:	19/09/2018 13:00 - :59 [41 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04545C02	Policy/Cover Note No.:	DMB1SN1691261701 (Comprehensive)						
Vehicle Reg. No. (Insured):	PC6030T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Zhong Cheng Enterprise (HQ) BLK 6 YEW TEE INDUSTRIAL ESTATE 399J WOODLANDS ROAD, 678008 Woodlands - Tel: 9826-4959								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 02/10/2018]								
Adj Asp. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
• CHINA_TAIPING (27/12/2018): Alert - Adj Mandate Approved (S\$0.00) - SKT2102R - Claim Handler: Jowyn Tay									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKT2102R (SNM18D04545C02)
[PC6030T]

TP

CHENG MENG FURNITURE GROUP (PTE.) LTD.

Sep 19 2018 1:00PM

[ALBERT PANG TRANSPORT]

Zhong Cheng Enterprise

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	20/09/18 17:16	Accident Statement	1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	20/09/18 17:16	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>
2	20/09/18 17:16	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>
3	20/09/18 17:16	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>
4	20/09/18 17:16	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>
5	20/09/18 17:16	Chassis Number <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>
6	20/09/18 17:16	Accident Photo <small>[Linked Accident Report Documents]</small>	1	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	05/04/19 12:01	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	05/04/19 12:01	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
19	05/04/19 12:01	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
20	05/04/19 12:01	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
21	05/04/19 12:01	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
22	05/04/19 12:01	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
23	05/04/19 12:01	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
24	05/04/19 12:01	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>
25	05/04/19 12:01	Dismantled Parts	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
26	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
27	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
28	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
29	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
30	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
31	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
32	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
33	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
34	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
35	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
36	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
37	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
38	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
39	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
40	05/04/19 12:01	Dismantled Parts		<input checked="" type="checkbox"/>
41	05/04/19 12:02	Photo After Spray		<input checked="" type="checkbox"/>
42	05/04/19 12:02	Photo After Spray		<input checked="" type="checkbox"/>
43	05/04/19 12:02	Photo After Spray		<input checked="" type="checkbox"/>
44	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
45	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
46	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
47	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
48	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
49	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
50	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
51	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
52	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
53	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
54	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
55	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
56	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
57	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
58	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
59	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
60	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
61	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
62	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
63	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
64	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
65	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
66	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
67	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
68	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
69	08/04/19 16:20	Dismantled Parts		<input checked="" type="checkbox"/>
70	08/04/19 16:22	General View		<input checked="" type="checkbox"/>
71	08/04/19 16:22	General View		<input checked="" type="checkbox"/>
72	08/04/19 16:22	General View		<input checked="" type="checkbox"/>
73	08/04/19 16:22	General View		<input checked="" type="checkbox"/>
74	08/04/19 16:22	General View		<input checked="" type="checkbox"/>
75	08/04/19 16:22	General View		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
76	08/04/19 16:22	General View	Load JPG	<input checked="" type="checkbox"/>
77	08/04/19 16:22	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/09/18 13:57	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	20/09/18 13:57	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	20/09/18 13:58	Driver's Work Permit + Driving License [Linked Accident Report Documents]	Load TIF	
4	20/09/18 13:58	Certificate of Insurance [Linked Accident Report Documents]	Load TIF	

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/09/18 15:44	PRS	Load PDF	
2	21/09/18 15:45	O1 GIA	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/09/18 17:16	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/09/18 17:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	20/09/18 17:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	20/09/18 17:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	20/09/18 17:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	20/09/18 17:16	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
6	20/09/18 17:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	20/09/18 13:57	Sketch Plan Sketch Plan	Load TIF	
2	20/09/18 13:57	Sketch Plan #2 Accident Statement	Load TIF	
3	20/09/18 13:58	Driver's Work Permit + Driving License	Load TIF	
4	20/09/18 13:58	Certificate of Insurance	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118017252/NQD3Q2
Date: 06/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN1691261701	
Claimant Vehicle No: SKT2102R	Insured Vehicle No:	PC6030T	
Date of Loss: 19/09/2018	Nature of Claim: TP	Claim No:	SNM18D04545C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT2102R		Engine No:	P520261908
Make & Model:	MAZDA 3, 1.5 SEDAN (A)		Chassis No:	JM6BM42A8G0301050
Reg. Date:	27/03/2015 (Man. Year: 2015)		Odometer:	68787 km
Colour:	Black			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,160.50	3,514.06	1,646.44	31.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,550.00	1,050.00	40.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,760.50	5,064.06	2,696.44	34.75
Approved Total (Overridden) (S\$)		4,050.00		
Nett Amount (S\$)	7,760.50	4,050.00	3,710.50	47.81

INSPECTION

Date of Assignment:	21/09/2018	
Date Inspected:	19/11/2018 Inspected At:	Zhong Cheng Enterprise (HQ) BLK 6 YEW TEE INDUSTRIAL ESTATE 399J WOODLANDS ROAD Singapore 678008
Estimated Period of Repair:	5.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
Parts: 143	MAZDA 3 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKT2102R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT FENDER	Repair	369.90 FL	*- FL
2	1		*LH FRONT FENDER INNER SHIELD	Serviceable	157.00 FL	*- FL
3	1		*FRONT BUMPER	Cracked	975.10 FL	*900.00 FL
4	1		*BUMPER REINFORCEMENT	Bent	595.10 FL	*500.00 FL
5	1		*BUMPER CHROME	Cracked	198.50 FL	*198.50 FL
6	1		*FRONT GRILLE UPPER	Cracked	169.80 FL	*169.80 FL
7	1		*BONNET	Deformed	1,107.50 FL	*1,000.00 FL
8	1		*BONNET LOCK	Serviceable	217.50 FL	*- FL
9	1		*LH HEADLAMP	Scratched	795.90 FL	*700.00 FL
10	1		*FRONT SUPPORT PANEL	Bent	499.90 FL	*400.00 FL
11	1		*TOP GARNISH	Deformed	142.90 FL	*142.90 FL
12	1		*SET LH FRONT FENDER INNER SHIELD FASTENERS	Not Necessary	28.00 FN	*- FN
13	1		*FRONT BUMPER RETAINER	Necessary	26.00 FN	*26.00 FN
14	1		*SET BUMPER FASTENER	Necessary	28.00 FN	*28.00 FN
15	1		*HEADLAMP BRACKET RH	Serviceable	26.00 FN	*- FN
16	1		*FOG LAMP LH	Cracked	135.50 FN	*135.50 FN
17	1		*FRONT BUMPER LOGO EMBLEM	Necessary	58.00 FN	*58.00 FN
18	1		*SET TOP GARNISH CLIPS	Necessary	18.00 FN	*18.00 FN
19	1		*FOG LAMP COVER LH	Missing	73.50 FN	*73.50 FN
20	1		*FRONT CARPLATE W HOUSING	Serviceable	60.00 FS	*- FS
21	1		*FRONT SENSOR	Serviceable	380.00 FS	*- FS
22	1		*BUMPER LOWER GRILLE	Serviceable	149.90 FL	*- FL
23	1		*TOWING COVER	Serviceable	79.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	6,291.50	4,350.20
- List Item Discount on L Items 20.00/20.00% (S\$)	1,091.70	802.24
- Nett Item Discount on N Items 10.00/10.00% (S\$)	39.30	33.90

Total Parts (S\$)	5,160.50	3,514.06
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,100.00	700.00
2	TO ANTI-RUST	New	100.00	50.00
3	TO REMOVE & REFIX RADIATOR /CONDENSER /TOP UP COOLANT & GAS FOR CHECKING	New	200.00	100.00
4	TO PUTTY AND SPRAY -PAINT OF AFFECTED AREAS	New	1,200.00	700.00
			Gross Labour Cost (S\$)	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >