

SWIYEN/NT
Menmen
From Operator

Kenneth
Pauline Thum

SWIYEN/NT 2018/09/16

ASSIGNMENT (Office)

MSIG

Date/Time: 21/09/2018 @ 2-48pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJM 5262R

Insured: SLC 5316Z

at Workshop no: Cheng Hwe Motor

Tel: 6755 6142

of Blk 1019 #01-574/382 Yishun Ind. Park A

Policy No: A80440834QMX

Claim No: 570810

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 16/09/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 4:37pm @ 21/9/18

Person Contacted: Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJM 5262R -X
	SLC 5316Z -X
110-	Revert via menmen. preli advice.
25110	61 Sp @ 335d (afirm) Used @ 1132.48, 25%.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Sep 2018		21 Sep 2018 14:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RAVINDRAN S/O PULAVAZHI KRISHNAN ACHUTHAN NAIR, ID: S1272469A, Tel: +6596497570, Email: SANJONYA@YAHOO.COM_SG		
Main Claimant:	WU YAOPING, ID: S8321034F		
Vehicle Reg. No.:	SJM5262R	Date of Loss:	16/09/2018 21:00 - :59 [116 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 570810	Policy/Cover Note No.:	A80440834QMX (Comprehensive) Coverage: 19/09/2017 - 18/09/2018
Vehicle Reg. No. (Insured):	SLC5316Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/09/2018]		
Driver/Custodian (Insured):	RAVINDRAN S/O PULAVAZHI KRISHNAN ACHUTHAN NAIR (61 / Male), NRIC: S1272469A, Tel: +6596497570		
Adj Asg. Remarks:	Liability not clear. TP agree with SJE - assign LKK Auto Consultants Pte Ltd.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 01 Oct 2018

Preliminary Advice

Insured Vehicle No	: SLC5316Z	Accident Date	: 16/09/2018
TP Vehicle No	: SJM5262R	Assignment Date	: 21/09/2018
Make	: MAZDA RX-8	Est. Duration of Repair	: 4.00
Date of Inspection	: 28/09/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,200.00 LABOUR ONLY
Revised Amount	:S\$	950.00 LABOUR ONLY
Check Items (Estimated)	:S\$	0.00
Total	:S\$	950.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

PARF/COE Rebate Enquiry

> Back to One Motoring

SJM 5762R
70/11/2016

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1034F
Vehicle Details	
Vehicle No.:	SJM5262R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2018
Vehicle Make:	MAZDA
Vehicle Model:	RX-8 1.3 A
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	13B542594
Chassis No.:	SE3P301096
Maximum Power Output:	158.0 kW (211 bhp)
Open Market Value:	\$27,048.00
Original Registration Date:	07 Jan 2009
First Registration Date:	07 Jan 2009
Transfer Count:	1
Actual ARF Paid:	\$27,048.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jan 2019
PARF Rebate Amount:	\$13,524.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jan 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$6,509.00
COE Rebate Amount:	\$188.00
Total Rebate Amount:	\$13,712.00

The information contained herein is correct as at 17 Sep 2018

OK

I
A
D
O
D
Dr
Ge
Mo
au
or
y

workshop () reporting Only

SJM5262R

PARTS		COST	LIST
IPC FRT BUMPER	B1-		
IPC - u - LOGO	M-		
SPUS - u - CLIPS	M-		
IPC - u - LH GRASSH	C-		
IPC FRT LH FENDER	B-		
SPUS - u - CLIPS	M-		
IPC LH Headlamp	C-		

[Signature]
4/10/18

LABOURS		COST
R & R fr bumper, grille, fr LH fender, headlamp, R & R fr fender innerpanel & realign the same.		500/2 400
Putty & respray fr bumper, fr LH fender & inner panel & all affected areas		500/2 400
R & R fr LH rim	hr	80 600
To conduct comp comp wheel alignment		60 ✓
useproaching		60 30%

Cheng Hoe Motor Pte Ltd

Blk 1019, Vishnu Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 16/09/2018

TP Veh Reg No: SLC5316Z

Estimate No: ES1891106/AMK

Date: 28 Sep 2018

Policy No: MA001537

Veh Reg No: SJM5262R

Make/Model: MAZDA RX8 1.3 A

Chassis No: SE3P301096

Engine No: 13B542594

Reg. Date: 07/01/2009

Not Authored
61 Reg & 335d
Resurvey After Paint

4 days

Estimate Repair Cost to Vehicle No :SJM5262R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT BUMPER	919.10	1 PC	919.10	✓
2 FRT BUMPER LOGO	38.00	1 PC	38.00	✓
3 FRONT BUMPER CLIP	7.60	5 PC	38.00	✓
4 FRONT BUMPER LH FOG LAMP GARNISH	63.40	1 PC	63.40	✓
5 FRONT LH FENDER	751.00	1 PC	751.00	✓
6 FRONT LH FENDER CLIP	7.60	6 PC	45.60	✓
7 HEADLAMP LH	2,248.00	1 PC	2,248.00	✓
			4,103.10	
		Less 20%	820.62	3,282.48
Labour				
8 REMOVE & REFIN FRT BUMPER,GRILLE,FRT LH FENDER,HEADLAMP,KNOCKING & REPAIR FRT FENDER INNER PANEL & REALIGN THE SAME	500.00	1 LA	500.00	40d
9 PUTTY & RESPRAY FRT BUMPER,FRT LH FENDER & INNER PANEL & ALL AFFECTED AREAS	500.00	1 LA	500.00	40d
10 REMOVE & REFIN FRONT LH RIM	80.00	1 LA	80.00	60d
11 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
12 RUSTPROOFING	60.00	1 LA	60.00	30d
			1,200.00	1,200.00
			Total	SS 4,482.48
			Add GST @ 7%	313.77
			Total Amount Payable	SS 4,796.25

VEHICLE LYING AT :
 NO.10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-04 AMK AUTOPOINT
 SINGAPORE 568047
 TEL : 64812001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018		21 Sep 2018 14:48 Edit Adj Rpt	\$43,350.00 Edit Estimates	\$43,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	RAVINDRAN S/O PULAVAZHI KRISHNAN ACHUTHAN NAIR, ID: S1272469A, Tel: +6596497570, Email: SANJONYA@YAHOO.COM.SG								
Main Claimant:	WU YAOPING, ID: S8321034F								
Vehicle Reg. No.:	SJM5262R	Date of Loss:	16/09/2018 21:00 - :59 [116 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 570810	Policy/Cover Note No.:	A80440834QMX (Comprehensive) Coverage: 19/09/2017 - 18/09/2018						
Vehicle Reg. No. (Insured):	SLC5316Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/10/2018]								
Driver/Custodian (Insured):	RAVINDRAN S/O PULAVAZHI KRISHNAN ACHUTHAN NAIR (61 / Male), NRIC: S1272469A, Tel: +6596497570								
Adj Asp. Remarks:	Liability not clear. TP agree with SJE - assign LKK Auto Consultants Pte Ltd.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM5262R (570810)
 [SLC5316Z]
 TP
 WU YAOPING
 Sep 16 2018 9:00PM
 [RAVINDRAN S/O PULAVAZHI KRISHNAN ACHUTHAN NAIR]
 Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser		
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	21/09/18 09:24	Accident Statement <small>From: SC - Reg. No: SLC5316Z, Claimant: RAVINDRAN S/O PULAVAZHI KRISHNAN ACHUTHAN NAIR</small>	1	Load HTM				
LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	01/10/18 16:34	Adjuster Immediate Advice	1	Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
2	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
3	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
4	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
5	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
6	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
7	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
8	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
9	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
10	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
11	25/10/18 14:44	General View	1	Load JPG	<input checked="" type="checkbox"/>			
12	25/10/18 14:44	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>			
13	25/10/18 14:44	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>			
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	21/09/18 09:24	SJM5262R E-FILE REPORT <small>From: SC - Reg. No: SLC5316Z, Claimant: RAVINDRAN S/O PULAVAZHI KRISHNAN ACHUTHAN NAIR</small>	1	Load PDF				
2	21/09/18 09:27	TP AGREE SJE -assign LKK	1	Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18017254/KQD3Q2
Date: 26/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80440834QMX
Claimant Vehicle No : SJM5262R	Insured Vehicle No :	SLC5316Z
Date of Loss: 16/09/2018	Nature of Claim:	TP Claim No: 570810

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM5262R	Engine No:	13B542594
Make & Model:	MAZDA RX-8, 1.3 (A)	Chassis No:	SE3P301096
Reg. Date:	07/01/2009 (Man. Year: 2008)	Odometer:	193816 km
Colour:	Metallic Black		
Engine Capacity:	1308 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50Z R19	Rear Tyre Size:	225/50Z R19
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,282.48	3,282.48	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	950.00	250.00	20.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,482.48	4,232.48	250.00	5.58
Approved Total (Overridden) (S\$)		3,350.00		
	(S\$)	4,482.48	3,350.00	1,132.48
	+ GST 7.00/7.00% (S\$)	313.77	234.50	79.27
	Nett Amount (S\$)	4,796.25	3,584.50	1,211.75

INSPECTION

Date of Assignment:	21/09/2018	
Date Inspected:	28/09/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)
Parts: M1-COUPE	MAZDA RX-8 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJM5262R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Bent	919.10 FL	*919.10 FL	
2	1		*FRT BUMPER LOGO	Necessary	38.00 FL	*38.00 FL	
3	5		*FRONT BUMPER CLIP	Necessary	38.00 FL	*38.00 FL	
4	1		*FRONT BUMPER LH FOG LAMP GARNISH	Cut	63.40 FL	*63.40 FL	
5	1		*FRONT LH FENDER	Bent	751.00 FL	*751.00 FL	
6	6		*FRONT LH FENDER CLIP	Necessary	45.60 FL	*45.60 FL	
7	1		*HEADLAMP LH	Cut	2,248.00 FL	*2,248.00 FL	
					Sub Total (\$\$)	4,103.10	4,103.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	820.62	820.62
					Total Parts (\$\$)	3,282.48	3,282.48

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ,GRILLE,FRT LH FENDER ,HEADLAMP ,KNOCKING & REPAIR FRT FENDER INNER PANEL & REALIGN THE SAME	New	500.00	400.00
2	PUTTY & RESPRAY FRT BUMPER ,FRT LH FENDER & INNER PANEL & ALL AFFECTED AREAS	New	500.00	400.00
3	REMOVE & REFIX FRONT LH RIM	New	80.00	60.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
5	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (S\$)			1,200.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >