

242

23/03/2003

ASS. REC. BY:

REF: CS/MSG18017260/ Tlcd30 Special Instruction:

Survivor:

menmen

Taufich

ASSIGNMENT (Office)

From (Person):

Christina Wang

of

MSIG

Date/Time:

21/9/18 @ 4:09pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 6474J

Insured:

SKM 5207P

at Workshop in/s

Performance Motor

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

A27849501QMY

Claim No:

570734

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/09/2018

CA / REV / REP. / REV 24 HRS

1up

24/09/2018

H.O.D. Endorsement:

Date/Time:

5:17pm @ 21/9/18

Person Contacted:

Caroline

Vehicle

IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKZ 6474J - X

SKM 5207P -

7/11/18

Revert

IA

via

email.

20/11/18

Pending

finalise

from member.

8/13/2018

Tupkin

REF: MSIG

ASSIGNMENT

From: Date: 24/9/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

3KZ 6474J

at Workshop m/s

Performance Motor

of

303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Kevin

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. 1-24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

3KZ 6474J

Yr Regn:

2016 Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 216D

C.C.

1446

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

30804

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBSA 2E32060837008

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24/9/18 2172

Survey held at

PMU

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/3

Continued final sig \$17,467.20 and 12 days with Caroline. (Red 3851.85, 18%)

RECEIVED 25 MAR 2019

25/3/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

12

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

: S + RS: \$

: Photos

: Others

TOTAL

200
10
210

Report Format: TP

Lump Sum / I.R. (\$17,467.20)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18017209/T1sd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 21-09-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBF 1334A	Veh. Inspected	SLZ 695R	
Policy No.	MSD/VMFT/18-990313-WTT	Coverage (\$)	0.00	
Claim No.	MSC/V/18-001256	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	21/09/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/09/2018	Inspection Date	24/09/2018	
Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2018		21 Sep 2018 16:09 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	KOH CHENG CHYE, ID: S2512381F, Tel: +6597514413, Email: KOHCHENG52@GMAIL.COM		[Created by insurer]
Main Claimant:	CHAN WYMEN, ID: S7722118B		
Vehicle Reg. No.:	SKZ6474J	Date of Loss:	18/09/2018 15:00 - :59 [31 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 570734	Policy/Cover Note No.:	A27849501QMY (Comprehensive) Coverage: 12/03/2018 - 11/03/2019
Vehicle Reg. No. (Insured):	SKM5207P	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/09/2018]		
Driver/Custodian (Insured):	KOH CHENG CHYE (66 / Male), NRIC: S2512381F, Tel: +6597514413		
Adj Asg. Remarks:	ON WP. Car is in. Liability 100%. Contact Person: Caroline / 6319 0174.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Celine Fong (LKKAuto)

From: Celine Fong (LKKAuto)
Sent: Friday, 22 March 2019 3:37 PM
To: 'PBSP'; SUR
Subject: RE: FINAL REPORT / SKZ6474J

Dear Caroline,

Confirmed final fig \$17,467.20

Repair days: 12

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 26 February 2019 6:23 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SKZ6474J

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 10,195.00
Total Parts : 7,272.20
Total Labour & Parts : 17,467.20

Repair days: 12

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 07 Nov 2018

Preliminary Advice

Insured Vehicle No	: SKM5207P	Accident Date	: 18/09/2018
TP Vehicle No	: SKZ6474J	Assignment Date	: 21/09/2018
Make	: BMW 216D	Est. Duration of Repair	: 12.00
Date of Inspection	: 24/09/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,757.60
Revised Amount	:S\$	15,299.25
Check Items (Estimated)	:S\$	3,880.35
Total	:S\$	19,179.60

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2118B
Vehicle Details	
Vehicle No.:	SKZ6474J
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	216D GRAN TOURER LED NAV 7 SEATER
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	35479420B37C15A
Chassis No.:	WBA2E32060P837008
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$31,447.00
Original Registration Date:	29 Jan 2016
First Registration Date:	29 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$26,026.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2026
PARF Rebate Amount:	\$19,519.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,301.00
COE Rebate Amount:	\$35,138.00
Total Rebate Amount:	\$54,657.00

The information contained herein is correct as at 22 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	19/09/2018 12:16
Date Of Accident	18/09/2018 15:45
Exact Location Of Accident	THOMSON ROAD JUNCTION OF BRADELL ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKZ6474J
Insured/Policyholder	
Name Of Registered Owner	CHAN WYMEN
NRIC No	S7722118B
Email Address	WYMEN.CHAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83182394
Alternative Phone No	OTHERS-98157240
Vehicle Particulars	
Manufacturer	BMW
Model	216D
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00445066
Cover Note Number	
Driver	
Name of Driver	CHAN WYMEN
NRIC No	S7722118B
Date Of Birth	15/08/1977
Occupation	INDOOR
Date Of Driving Pass	12/07/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83182394
Fax Number	
Contact Number	OTHERS-98157240
EEmail Address	WYMEN.CHAN@GMAIL.COM

Address	80 KIM SENG ROAD #19-08
Postcode	239426
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	ONG KIAN SAN ADRIAN
Phone Number	81182486
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKM5207P
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH CHENG CHYE
NRIC/Passport Number	S2512381F
Contact Number	97514413
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKL8682K
Vehicle Make/Model/Colour	VOLKSWAGEN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG KIAN SAN ADRIAN
NRIC/Passport Number	S8209454G
Contact Number	81182486
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

19/9/2018
10:45AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at a red light (on Thomson Road, junction of Braddell Road, near Mt Alvernia Hospital) when I was rear-ended by a Mercedes Benz, SKM5207P driven by Mr KOH CHENG HYE (S2512381F) when he failed to stop. This resulted in my car (SK76474J) ~~to~~ to move forward and hit the Volkswagen in front (SKL8682K) driven by Mr ONG KIAN SAN ADRIAN (S8209454G).

Video of accident is available from my front car camera

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

19/9/2018

10:45AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

20 SEP 2018

E S T I M A T E

Estimate No. : b1 48500
Date Estimated : 20/09/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chan Wymen (Chen Wymen)
80 Kim Seng Road
#19-08

Singapore 239426

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKZ6474J	P837008	29/01/2016	216d G TOURER	0

DESCRIPTION

VALUE

To replace frt bumper, rear bumper, rear tailgate, end panel, reinforcement & all attachments cause by accident.

4250 5,100.00

Painting on frt bumper, rear bumper, rear tailgate, end panel, trunk floor

3811 4,235.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451? 531.00

To replace rear windscreen glass.

574 487 574.00

To conduct water leak tests.

75 65 75.00

To supply and install rear windscreen solar film.

X451 531.00

To check electrical wiring systems for proper function. (Type follow the FB)

250. 150. 177.00

To carry out body cavity preservation.
(Per panel) Tailgate

100 118.00

To carry out body cavity preservation.
(For cut panel) End panel

NM X451 531.00

To supply ^{Front} rear emboss number plate.

67 83.00

Sundries.

NEC 7 150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Labour 1:

12,105.00

DESCRIPTION

QTY PRIC

VALUE

REAR SILENCER

1 1,167.45

bt 1,167.45

TAILPIPE TRIM CHROME

1 107.85

wt 107.85

HOLDER EXHAUST SYSTEM

1 55.80

27.20 de 55.80

BOOTLID

1 1,174.95

bt 1,174.95

TAIL PANEL

1 355.20

nn 355.20

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48500
Date Estimated : 20/09/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKZ6474J	P837008	29/01/2016	216d G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
FRT IMPACT ABSORBER	1	47.80	de ? 47.80
GRILLE BUMPER MIDDLE OPEN (PDC)	1	95.05	de ? 95.05
LH FINISHER (LUXURY LINE)	1	52.55	un ? 52.55
LH SUPPORT FOG LAMP (GESCHLOSSEN)	1	77.60	de ? 77.60
FRT BUMPER PANEL PRIMED (PMA)	1	842.00	de ? 842.00
GRILLE SIDE OPEN LH (LUXURY LINE+PD	1	95.85	un ? 95.85
RR BUMPER LH SIDE GUIDE	1	60.00	un ? 60.00
RR BUMPER RH SIDE GUIDE	1	60.00	un ? 60.00
REAR BUMPER CARRIER	1	423.80	de ? 423.80
SUPPORT	1	48.45	de ? 48.45
RR BUMPER LH INNER SIDE GUIDE	1	65.90	de ? 65.90
RR BUMPER RH INNER SIDE GUIDE	1	65.90	de ? 65.90
REAR BUMPER TRIM STRIP (CHROM)	1	105.65	un ? 105.65
REAR BUMPER PANEL PRIMED (LINES PDC	1	966.25	de ? 966.25
SET MOUNTS PDC SENSOR REAR	1	62.95	un ? 62.95
REAR BUMPER TOWING FLAP EYE PRIMED	1	41.80	de ? 41.80
LICENCE PLATE HOLDER	1	68.95	de ? 68.95
FRT LH GRILLE (LUXURY)	1	86.05	un ? 86.05
FRT RH GRILLE (LUXURY)	1	86.05	un ? 86.05
GROMMET	2	0.75	un ? 1.50
PLAQUE 74MM	1	69.50	un ? 69.50
REAR WINDOW	1	655.40	un ? 655.40
AIR DUCT	1	190.50	de ? 190.50
PLAQUE 82MM	1	69.50	un ? 69.50
DECOUPING RING PDC TORQUE CONVERTER	8	5.05	un ? 40.40
PDC SENSOR MEDITERRANBLAU WC10	2	380.65	un ? 761.30
BLIND RIVET AVIBVLB	23	0.55	un ? 12.65
SCREW (SF PLUS M5X15)	5	0.55	un ? 2.75
(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	un ? 281.55
(DG) CLEANER R1 (100ML)	1	26.15	un ? 26.15
(DG) CLEANER R1 (100ML)	1	26.15	un ? 26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	un ? 263.10
PUNCH RIVET N4	19	0.55	un ? 10.45
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	un ? 27.85

Total Parts : 8,652.60

21770.05

Surveyor's Tel : 77495749
Authorized Date :
Time :
RECURRY PARTS PHOTO BY SURVEYOR Yes / No :
Surveyor's Email : fauher@thand2.com
No. of Working Days (incl. weekend) : 11 - 12 days

Labour 1 : 12,105.00
Parts : 8,652.60
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 1,453.03
Grand Total : 22,210.63

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

21,319.05

FACSIMILE MESSAGE

TIME _____

FAX NO _____
NO OF PAGES _____
(INCLUSIVE OF THIS PAGE)

FAX NO. _____

FAX NO. _____
TEL NO. 91165600

If this fax is not received in order, please do call us. Thank you.

BMW 216d

SKZ6474J

P837008

H -
 W -
 X NN
 B -
 X NN

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 48500
Date Estimated : 20/09/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Chan Wymen (Chen Wymen)
80 Kim Seng Road
#19-08

Singapore 239426

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE
SKZ6474J	P837008	29/01/2016	216d G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	4.00		10.20 <i>nk</i> ✓
# CLAMPING BUSH *	54.30	1.00		54.30 <i>bt</i> ✓
# FRT BUMPER TOP CARRIER *	368.90	1.00		368.90 <i>bt</i> ✓

Total Labour :	451.00
Total Parts :	433.40
Total Labour & Parts :	884.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 48500
Date Estimated : 20/09/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Chan Wymen (Chen Wymen)
80 Kim Seng Road
#19-08

Singapore 239426

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKZ6474J	P837008	29/01/2016	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front/rear bumpers and attachments, boot lid, front air duct include making good the tail end panel, trunk floor panel and knocking out dents caused by the accident	4250.00		4,250.00	
To spray paint front bumper, rear bumper, boot lid, tail end panel and trunk floor panel	3811.00		3,811.00	
* To replace rear exhaust silencer include alignment of system and conducting checks for leak	451.00		451.00	
* To replace rear windscreen glass	574.00		574.00	
* To conduct water leak tests	75.00		75.00	
* To check electrical wiring systems and lightings at the front and rear section for proper function	250.00		250.00	
To carry out body cavity preservation (Per panel)	100.00		100.00	
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	
To supply rear emboss number plate	83.00		83.00	
Sundries	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	4.00		10.20
# CLAMPING BUSH *	54.30	1.00		54.30
REAR SILENCER	1,167.45	1.00		1,167.45
HOLDER EXHAUST SYSTEM	27.20	1.00		27.20
TAILPIPE TRIM CHROME	107.85	1.00		107.85
BOOTLID	1,174.95	1.00		1,174.95
FRT IMPACT ABSORBER	47.80	1.00		47.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

FRT BUMPER PANEL PRIMED (PMA)	842.00	1.00	842.00
# FRT BUMPER TOP CARRIER *	368.90	1.00	368.90
REAR BUMPER CARRIER	423.80	1.00	423.80
SUPPORT	48.45	1.00	48.45
RR BUMPER LH INNER SIDE GUIDE	65.90	1.00	65.90
RR BUMPER RH INNER SIDE GUIDE	65.90	1.00	65.90
REAR BUMPER TRIM STRIP (CHROM)	105.65	1.00	105.65
REAR BUMPER PANEL PRIMED (LINES PDC	966.25	1.00	966.25
SET MOUNTS PDC SENSOR REAR	62.95	1.00	62.95
REAR BUMPER TOWING FLAP EYE PRIMED	41.80	1.00	41.80
LICENCE PLATE HOLDER	68.95	1.00	68.95
FRT LH GRILLE (LUXURY)	86.05	1.00	86.05
FRT RH GRILLE (LUXURY)	86.05	1.00	86.05
GROMMET	0.75	2.00	1.50
PLAQUE 74MM	69.50	1.00	69.50
AIR DUCT	190.50	1.00	190.50
PLAQUE 82MM	69.50	1.00	69.50
DECOUPING RING PDC TORQUE CONVERTER	5.05	8.00	40.40
PDC SENSOR MEDITERRANBLAU WC10	380.65	2.00	761.30
(DG) CLEANER R1 (100ML)	26.15	1.00	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	10,195.00
Total Parts :	7,272.20
Total Labour & Parts :	17,467.20
Deduction for Excess :	0.00
Total Repair Costs less Excess:	17,467.20
GST @7%:	1,222.70
Grand Total :	18,689.90

...CLAIM SUBFOLDER...(Pending for Survey Report)


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Sep 2018		21 Sep 2018 16:09 Edit Adj Rpt	S\$17,467.20 Edit Estimates	S\$17,467.20 View Rpt		Pending for Survey Report Cancel Case





























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOH CHENG CHYE , ID: S2512381F, Tel: +6597514413, Email: KOHCHENG52@GMAIL.COM								
Main Claimant:	CHAN WYMEN , ID: S7722118B								
Vehicle Reg. No.:	SKZ6474J	Date of Loss:	18/09/2018 15:00 - :59 [31 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 570734	Policy/Cover Note No.:	A27849501QMY (Comprehensive) Coverage: 12/03/2018 - 11/03/2019						
Vehicle Reg. No. (Insured):	SKM5207P	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/10/2018]								
Driver/Custodian (Insured):	KOH CHENG CHYE (66 / Male) , NRIC: S2512381F, Tel: +6597514413 Email: KOHCHENG52@GMAIL.COM								
Adj Asg. Remarks:	ON WP. Car is in. Liability 100%. Contact Person: Caroline / 6319 0174.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ6474J (570734)
[SKM5207P]
TP
CHAN WYMEN
Sep 18 2018 3:00PM
[KOH CHENG CHYE]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	07/11/18 16:35		Adjuster Immediate Advice						1	Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
2	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
3	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
4	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
5	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
6	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
7	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
8	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
9	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
10	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
11	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
12	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
13	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
14	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
15	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
16	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
17	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
18	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
19	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
20	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
21	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
22	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
23	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
24	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
25	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
26	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
27	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
28	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
29	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
30	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
31	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
32	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
33	22/03/19 15:44		General View						1	Load JPG	<input checked="" type="checkbox"/>	
34	22/03/19 15:44		General View						1	Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
36	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
37	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
38	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
39	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
40	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
41	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
42	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
44	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
45	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
46	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
47	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
48	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
49	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
50	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
51	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
52	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
53	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
54	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
55	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
56	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
57	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
58	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
59	22/03/19 15:44	General View	 Load JPG	<input checked="" type="checkbox"/>
60	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	22/03/19 15:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	22/03/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	22/03/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	22/03/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	22/03/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	22/03/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	22/03/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	22/03/19 15:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/09/18 09:31	TP SKL8682K GIA Report (1/3) From:OD - Reg. No: SKM5207P, Claimant: KOH CHENG CHYE	 Load PDF	
2	21/09/18 09:31	TP SKZ6474J GIA Report (2/3) From:OD - Reg. No: SKM5207P, Claimant: KOH CHENG CHYE	 Load PDF	
3	21/09/18 09:31	E-filed GIA report From:OD - Reg. No: SKM5207P, Claimant: KOH CHENG CHYE	 Load PDF	
4	21/09/18 09:32	Email - PRI	 Load PDF	
5	21/09/18 09:36	Estimate	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/19 11:17	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18017260/T1CD3E2

Date: 26/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A27849501QMY

Claimant Vehicle No: SKZ6474J

Insured Vehicle No: SKM5207P

Date of Loss: 18/09/2018

Nature of Claim: TP

Claim No: 570734

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ6474J

Make & Model: BMW 216D, 1.5 D GRAN TOURER LED NAV 7 SEATER (A)

Engine No: 35479420B37C15A

Reg. Date: 29/01/2016 (Man. Year: 2015)

Chassis No: WBA2E32060P837008

Colour: Blue

Odometer: 30804 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size: 205/55 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,374.05	7,505.20	1,868.85	19.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,396.00	9,962.00	2,434.00	19.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,770.05	17,467.20	4,302.85	19.76
+ GST 7.00/7.00% (S\$)	1,523.90	1,222.70	301.20	19.77
Nett Amount (S\$)	23,293.95	18,689.90	4,604.05	19.77

INSPECTION

Date of Assignment: 21/09/2018

Date Inspected: 24/09/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2019)
Parts:	M1-MPV	BMW 216D 1.5 D GRAN TOURER LED NAV 7 SEATER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ6474J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
3	1		*REAR SILENCER	Bent	1,167.45 FS	*1,167.45 FS
4	1		*TAILPIPE TRIM CHROME	Cut	107.85 FS	*107.85 FS
5	1		*HOLDER EXHAUST SYSTEM	Deformed	55.80 FS	*27.20 FS
6	1		*BOOTLID	Bent	1,174.95 FS	*1,174.95 FS
7	1		*TAIL PANEL	Not Necessary	355.20 FS	*- FS
8	1		*FRT IMPACT ABSORBER	Deformed	47.80 FS	*47.80 FS
9	1		*GRILLE BUMPER MIDDLE OPEN (PDC)	Not Necessary	95.05 FS	*- FS
10	1		*LH FINISHER (LUXURY LINE)	Not Necessary	52.55 FS	*- FS
11	1		*LH SUPPORT FOG LAMP (GESCHLOSSEN)	Not Necessary	77.60 FS	*- FS
12	1		*FRT BUMPER PANEL PRIMED (PMA)	Deformed	842.00 FS	*842.00 FS
13	1		*GRILLE SIDE OPEN LH (LUXURY LINE+PD	Not Necessary	95.85 FS	*- FS
14	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	60.00 FS	*- FS
15	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	60.00 FS	*- FS
16	1		*REAR BUMPER CARRIER	Bent	423.80 FS	*423.80 FS
17	1		*SUPPORT	Deformed	48.45 FS	*48.45 FS
18	1		*RR BUMPER LH INNER SIDE GUIDE	Deformed	65.90 FS	*65.90 FS
19	1		*RR BUMPER RH INNER SIDE GUIDE	Deformed	65.90 FS	*65.90 FS
20	1		*REAR BUMPER TRIM STRIP (CHROM)	Missing	105.65 FS	*105.65 FS
21	1		*REAR BUMPER PANEL PRIMED (LINES PDC	Deformed	966.25 FS	*966.25 FS
22	1		*SET MOUNTS PDC SENSOR REAR	Necessary	62.95 FS	*62.95 FS
23	1		*REAR BUMPER TOWING FLAP EYE PRIMED	Deformed	41.80 FS	*41.80 FS
24	1		*LICENCE PLATE HOLDER	Deformed	68.95 FS	*68.95 FS
25	1		*FRT LH GRILLE (LUXURY)	Cut	86.05 FS	*86.05 FS
26	1		*FRT RH GRILLE (LUXURY)	Cut	86.05 FS	*86.05 FS
27	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
28	1		*PLAQUE 74MM	Necessary	69.50 FS	*69.50 FS
29	1		*REAR WINDOW	Not Necessary	655.40 FS	*- FS
30	1		*AIR DUCT	Deformed	190.50 FS	*190.50 FS
31	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
32	8		*DECOUPLING RING PDC TORQUE CONVERTER	Necessary	40.40 FS	*40.40 FS
33	2		*PDC SENSOR MEDITERRANBLAU WC10	Distorted	761.30 FS	*761.30 FS
34	1		*BLIND RIVET AVIBVLB (23PCS)	Not Necessary	12.65 FS	*- FS
35	5		*SCREW (SF PLUS M5X15)	Not Necessary	2.75 FS	*- FS
36	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	281.55 FS	*- FS
37	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
38	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
40	19		*PUNCH RIVET N4	Not Necessary	10.45 FS	*- FS
41	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
42	1		*FRT BUMPER TOP CARRIER	Bent	368.90 FS	*368.90 FS
43	4		*BLIND RIVET NUT M6	Necessary	10.20 FS	*10.20 FS
44	1		*(DG/SL) GLASS PRIMER 30ML	Not Necessary	27.85 FS	*- FS
45	1		*CLAMPING BUSH	Bent	54.30 FS	*54.30 FS
46	1		*HOLDER EXHAUST SYSTEM	Not Necessary	27.20 FS	*- FS
Total Parts (\$\$)					9,374.05	7,505.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRT BUMPER, REAR BUMPER, REAR TAILGATE, END PANEL, REINFORCEMENT & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	5,100.00	4,250.00
2	PAINTING ON FRT BUMPER, REAR BUMPER, REAR TAILGATE, END PANEL, TRUNK FLOOR	New	4,235.00	3,811.00
3	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
4	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
5	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
6	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION	New	250.00	250.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) TAILGATE	New	118.00	100.00
9	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL) END PANEL	New	531.00	0.00
10	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	451.00	451.00
Gross Labour Cost (S\$)			12,396.00	9,962.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >