

ASS. REC. BY:

REP

CS / SPF 18017 304 / Grd 304

social instruction

Surveyor

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Frankie Thuy

of

SPF

Date/Time:

24/09/18

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJG 8524Y

Insured:

QX782Z

at Workshop m/s

Xin Yun Auto

Tel:

9839 1666

of

8 kaki Bkt Ave 4 # 05-23

Policy No:

Claim No:

AEMD/105/009/2018/117

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/09/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

12:23pm 24/9/18

Person Contacted:

Fabian

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJG 8524Y - X

QX782Z - X

Submit LIS \$7000 @ 10 days

Red: \$6263.38, 47%.

Surveyor

X22.

REF:

SPF

1950F

ASSIGNMENT

(-2023)

From:

Date:

Estimated Cost:

OD TP W/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/9

Estimate Give later

2/10

Repair limit \$10K
Email marking to repairer

RECEIVED 10 OCT 2018

Date/Time, File Pass to?

☐

Preli. Report

1) typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / LB: (\$ 7,000.00)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

280

280




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
PUBLIC TRANSPORT SECURITY COMMAND		Ref : CS/SPF18017304/Grd3	
(SINGAPORE POLICE FORCE) NO 132 PAYA LEBAR ROAD (GEYLANG BASE)SINGAPORE 409014		Date : 24-09-2018	
		Code : SPF2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 782Z	Veh. Inspected	SJG 8524Y
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/1005/009/2018/117	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	24/09/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/09/2018	Inspection Date	
Survey held at	8 KAKI BUKIT AVE 4 #05-23		
Repairer	XIN YUN AUTO PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SJG8524Y

Our Ref : AEMD/105/009/2018/117

Tel: 64784841

Fax: 64784848

Date : 24 Sep 2018

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 # 01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

**ACCIDENT INVOLVING GOVT VEHICLE QX782Z AND OTHER VEHICLE SJG8524Y
ALONG PAYA LEBAR ROAD TRAVELLING TOWARDS PIE ON 20/9/2018.**

We refer to the above matter.

- 2 Kindly arrange for a pre-repair survey for vehicle SJG8524Y at Xin Yun Auto Pte Ltd,
Blk 8 Kaki Bukit Ave 4 #05-23 Premier @ Kaki Bukit, Singapore 415675.
- 3 For appointment kindly contact Ms Yi Xin @98391555/Mr Fabian 98391666.
- 4 Thank you.

Yours faithfully,


Frankie Thay
Safe Driving Manager
for ASST DIRECTOR

A FORCE FOR THE NATION

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/09/2018 14:10
Date Of Accident	20/09/2018 18:00
Exact Location Of Accident	PAYA LEBAR RD/PIE ALONG RD 1 TRAVELLING RD 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG8524Y
Insured/Policyholder	
Name Of Registered Owner	WONG YIT LONG(HUANG RILONG)
NRIC No	S7731950F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93216119
Alternative Phone No	OTHERS-93216119

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.4A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102328553
Cover Note Number	

Driver

Name of Driver	WONG YIT LONG(HUANG RILONG)
NRIC No	S7731950F
Date Of Birth	26/10/1977
Occupation	INDOOR
Date Of Driving Pass	07/10/2003
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93216119
Fax Number	
Contact Number	OTHERS-93216119
Email Address	NOEMAIL

Address	BLK 710 #07-241 CLEMENTI WEST STREET 2
Postcode	120710
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : TANG XIOA HAN GENDER: : FEMALE
Passenger 2	NAME: : QIAN QUIMEI GENDER: : FEMALE
Passenger 3	NAME: : TANG SHENGPING GENDER: : FEMALE
Passenger 4	NAME: : LI HUATIAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS
Police Station Address	ROAD: 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No. T/20180921/2147

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX782Z
-----------------------------	--------

Vehicle Make/Model/Colour	HYUNDAI AVANTE 1.6 AT ABS D/AB 2WD 4DR
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	SHEREEN LAU
NRIC/Passport Number	
Contact Number	98342104
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLP8254E
Vehicle Make/Model/Colour	TOYOTA ISIS 1.8LX A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KIM LENG
NRIC/Passport Number	S6837631I
Contact Number	94890808
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 

Policyholder's Signature
Date & Time:


X 

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre Personnel's Signature
Name: Singapore 415933
NRIC/FIN No.: Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

SKETCH PLAN

PIE
A: SJG8524Y
B: QX782Z
C: SLP8254E




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Reporting Centre Personnel's Signature
Name: Tel: 67492305
NRIC/FIN No: Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180921/2147

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

1 of 4
Report No. T/20180921/2147

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/09/2018 16:43		Vide Report No.:		Station Diary No.: 39	
Informant's Particulars					
Name of Informant: WONG YIT LONG			Address: APT BLK 710 CLEMENTI WEST STREET 2 #09-241 SINGAPORE 120710		
ID Type / ID No.: NRIC NO / S7731950F			Contact No.: Home/Office: Mobile: 93216119		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 40	Date of Birth: 26/10/1977	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: STALL OWNER			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 20/09/2018 18:00	Type of Location: Bend
Location: Along Road 1 Traveling Toward Road 2 PAYA LEBAR ROAD PAN ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Pedestrian Crossing		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX782Z	Car	HYUNDAI		White	Slightly Damaged	0
SJG8524Y	Car	HONDA	JAZZ 1.4A	Yellow	Seriously Damaged	4
SLP8254E	Car	TOYOTA	ISIS	White	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180921/2147

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 4

Report No. T/20180921/2147

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SJG8524Y	NTUC Income Insurance Co-Operative Limited	5102328553	17/07/2018	16/07/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	SHEREEN LAU		ID No.	NIL
Related Vehicle	QX782Z (Car)		Contact No.	98342104
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	WONG YIT LONG		ID No.	S7731950F
Related Vehicle	SJG8524Y (Car)		Contact No.	93216119
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	Slight
Driver				
Name	TAN KIM LENG		ID No.	S6837631I
Related Vehicle	SLP8254E (Car)		Contact No.	94890808
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20180921/2147

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 4

Report No. T/20180921/2147

CONTINUATION OF REPORT

Brief Details.

On 20/09/2018, at about 1800hours, I was driving my vehicle SJG8524Y along Paya Lebar Road. As I entered the filter lane of Paya Lebar Road towards PIE, the vehicle in front of me SLP8254E had jammed its brake as there was pedestrian crossing on the road. So due to this, I had also jammed brake my vehicle and managed to stop my vehicle on time. However, there is a police vehicle QX782Z behind me whom did not managed to stop on time and as such, QX782Z had collided onto my vehicle, which had caused my vehicle to move forward and my vehicle had collided onto the rear of vehicle SLP8254E. After which all 3 of us had came out of the vehicle and I had discovered that the front and back of my vehicle sustained damages. All 3 drivers of the vehicle did not sustained any visible injuries.

I would like to state that I have an in-car camera in my vehicle. I am currently lodging this report as instructed by the police officer driving the police vehicle.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1950F
Vehicle Details	
Vehicle No.:	SJG8524Y
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.4A
Primary Colour:	Yellow
Manufacturing Year:	2008
Engine No.:	L13A55000946
Chassis No.:	JHMGD18508S214763
Maximum Power Output:	60.0 kW (80 bhp)
Open Market Value:	\$13,896.00
Original Registration Date:	17 Jul 2008
First Registration Date:	17 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$13,896.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$18,583.00
COE Rebate Amount:	\$17,865.00
Total Rebate Amount:	\$17,865.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Sep 2018

OK



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Estimate cost of repairs for SJG 8524Y/ Chassis no: JHMGD185085214763

Parts Replacement:

S/no	Parts Description	Qty	Parts Price	Remarks
1	Front bumper	1	\$627.50	DD
2	Front bumper reinforcement	1	\$154.80	DD
3	Front bonnet	1	\$464.70	XR
4	Front grille emblem (H)	1	\$27.42	NEC
5	Front grille	1	\$ 121.60	CRA
6	Front bumper LH dust cover	1	\$27.10	
7	F/LH fog lamp	1	\$257.10	XNN
8	F/RH fog lamp	1	\$257.10	
9	Front bumper lower grille	1	\$121.60	CRA
10	Front bumper LH Side vent cover	1	\$26.00	X JNN
11	Front bumper RH Side vent cover	1	\$26.00	X JNN
12	Front LH Headlamp	1	\$486.20	CRA
13	Front RH Headlamp	1	\$486.20	XNN
14	Front LH Headlamp bracket	1	\$26.70	DIS
15	Front RH Headlamp bracket	1	\$26.70	XNN
16	Rear tailgate	1	\$997.40	BUC
17	Rear tailgate LH shock absorber	1	\$123.20	XNN
18	Rear tailgate RH shock absorber	1	\$123.20	XNN
19	Rear tailgate inner trim cover	1	\$330.20	CRA
20	Rear tailgate weather strip	1	\$ 50.50	TN
21	Rear tailgate Honda emblem	1	\$27.10	JNEC
22	Rear tailgate Jazz emblem	1	\$31.60	
23	R/L taillamp assy	1	\$283.60	CRA
24	R/R taillamp assy	1	\$283.60	CRA
25	Rear tailgate lock assy	1	\$119.40	BT
26	Rear tailgate lock catch	1	\$29.00	DIS
27	Rear tailgate weathers trip	1	\$97.20	TN
28	Rear bumper	1	\$690.80	DIS
29	Rear bumper tow cover	1	\$37.10	XNTF
30	Rear end panel	1	\$299.40	BUC
31	Rear end panel top garnish	1	\$120.40	CRA
32	Rear end panel back garnish	1	\$63.10	XNS
33	R/H fender inner garnish cover	1	\$168.60	CRA
34	R/R fender inner garnish cover	1	\$168.60	CRA
35	Rear spare tyre compartment box	1	\$380.20	XR
36	Rear silencer	1	\$580.80	X R
	Air Con Condenser	1	\$691.70	DD
Sub Total			\$ 8,141.72	
Less 20%			\$ 1,628.34	
Parts Total			\$ 6,513.38	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

S/no	Nett Parts			
1	Front bumper clips		\$ 35 40.00	JNEC
2	Rear bumper clips		\$ 35 40.00	JNEC
3	Rear end panel top garnish clips		\$ 35 40.00	JNEC
4	Windscreen sealant		\$ 60 150.00	JNEC
5	Reverse sensors		\$ 200 240.00	Shurt
Sub Total			\$ 510.00	
Parts Grand Total			\$ 7,023.38	

757674

Estimate cost of repairs for SJG 8524Y/ Chassis no: JHMGD185085214763

Labour Charges

S/no	Labour Charges	Repairer Estimate	Remarks
1	To labour charges for removing front bumper assy, front bonnet out to facilitate repairs and replacement of damaged parts and include straightening of radiator support panel	\$1,000	600
2	To labour charge for respraying font bonnet, front bumper and support panel	\$1,000	600
3	To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts	\$1,800	1000
4	To labour charge for removing and fixing rear tailgate glass	\$240	120
5	To labour charge for respraying rear tailgate, rear bumper, end panel and spare tyre compartment	\$1600	1000
6	To labour charge for removing rear silencer out to facilitate repair and replacement of damaged parts	\$180	90



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

7	To labour charge for removing rear reverse sensors out to facilitate replacement of damaged parts	\$200	50
8	To supply body sealant and apply anti-rust on all parts damaged area	\$140	80
9	To supply font and back number plate	\$80	DD
Labour Grant Total		\$6240	
Grade Total for Parts and Labour		\$13,263.38	

10. To labour Charge for replacement air can condenser & refill air can gas.

\$120. - 100

LS \$7,000
10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

13036.74



辛运汽车服务有限公司

Estimate cost of repairs for SJG 8524Y/ Chassis no: JHMGD185085214763

S/no	Parts Description	Qty	Parts Price	Remarks
1	Front bumper	1	\$627.50	DD
2	Front bumper reinforcement	1	\$154.80	DD
3	Front bonnet	1	\$464.70	X R
4	Front grille emblem (H)	1	\$27.42	NEC
5	Front grille	1	\$ 121.60	CRA
6	Front bumper LH dust cover	1	\$27.10	} X NN
7	F/LH fog lamp	1	\$257.10	
8	F/RH fog lamp	1	\$257.10	} X NN
9	Front bumper lower grille	1	\$121.60	
10	Front bumper LH Side vent cover	1	\$26.00	X J NN
11	Front bumper RH Side vent cover	1	\$26.00	X J NN
12	Front LH Headlamp	1	\$486.20	CRA
13	Front RH Headlamp	1	\$486.20	X NN
14	Front LH Headlamp bracket	1	\$26.70	DIS
15	Front RH Headlamp bracket	1	\$26.70	X NN
16	Rear tailgate	1	\$997.40	BUC
17	Rear tailgate LH shock absorber	1	\$123.20	X NN
18	Rear tailgate RH shock absorber	1	\$123.20	X NN
19	Rear tailgate inner trim cover	1	\$330.20	CRA
20	Rear tailgate weather strip	1	\$ 50.50	TN
21	Rear tailgate Honda emblem	1	\$27.10	J NEC
22	Rear tailgate Jazz emblem	1	\$31.60	J NEC
23	R/L taillamp assy	1	\$283.60	CRA
24	R/R taillamp assy	1	\$283.60	CRA
25	Rear tailgate lock assy	1	\$119.40	BT
26	Rear tailgate lock catch	1	\$29.00	DIS
27	Rear tailgate weathers trip	1	\$97.20	TN
28	Rear bumper	1	\$690.80	DIS
29	Rear bumper tow cover	1	\$37.10	X NT
30	Rear end panel	1	\$299.40	BUC
31	Rear end panel top garnish	1	\$120.40	CRA
32	Rear end panel back garnish	1	\$63.10	X NS
33	R/H fender inner garnish cover	1	\$168.60	CRA
34	R/R fender inner garnish cover	1	\$168.60	CRA
35	Rear spare tyre compartment box	1	\$380.20	X R
36	Rear silencer	1	\$580.80	X R
	Air Con Condenser	1	\$691.70	DD
Sub Total			\$ 8,141.72	
Less 20%			\$ 1,628.34	
Parts Total			\$ 6,513.38	

\$5954.92

Less 1,190.98

4,763.93



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

S/no	Nett Parts		
1	Front bumper clips	\$ 35 40.00	NEC
2	Rear bumper clips	\$ 35 40.00	NEC
3	Rear end panel top garnish clips	\$ 35 40.00	NEC
4	Windscreen sealant	\$ 60 150.00	NEC
5	Reverse sensors	\$ 200 240.00	Sherry
Sub Total		\$ 510.00	
Parts Grand Total		\$ 7,023.38	

- \$ 35
 - \$ 35
 - \$ 35
 - \$ 60
 - \$ 200
 \$ 365

Estimate cost of repairs for SJG 8524Y/ Chassis no: JHMGD185085214763
Labour Charges

S/no	Labour Charges	Repairer Estimate	Remarks
1	To labour charges for removing front bumper assy, front bonnet out to facilitate repairs and replacement of damaged parts and include straightening of radiator support panel	\$1,000	500
2	To labour charge for respraying font bonnet, front bumper and support panel	\$1,000	500
3	To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts	\$1,800	900
4	To labour charge for removing and fixing rear tailgate glass	\$240	120
5	To labour charge for respraying rear tailgate, rear bumper, end panel and spare tyre compartment	\$1600	1000
6	To labour charge for removing rear silencer out to facilitate repair and replacement of damaged parts	\$180	90

\$ 500
 \$ 700
 1,200
 ✓ 120
 1,400
 120



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

7	To labour charge for removing rear reverse sensors out to facilitate replacement of damaged parts	\$200	50	✓
8	To supply body sealant and apply anti-rust on all parts damaged area	\$140	80	✓
9	To supply front and back number plate	\$80	80	DD
Labour Grant Total		\$6240		
Grade Total for Parts and Labour		\$13,263.38		

10. To Labour charge for replacement
air con condenser & refuel air
con gas. \$120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LS \$6,750
10 days
Labour 4,670.00
S/Nett 365.00
Parts: 4,763.93
9,798.93

Lump sum \$7,900.00
10 days LAI \$800
Total: \$8,700.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
PUBLIC TRANSPORT SECURITY COMMAND		Ref : CS/SPF18017304/Grd3e2		
(SINGAPORE POLICE FORCE) NO 132 PAYA LEBAR ROAD (GEYLANG BASE) SINGAPORE 409014		Date : 29-10-2018		
ATTN : FRANKIE THAY		Code : SPF2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 782Z	Veh. Inspected	SJG 8524Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/1005/009/2018/117	Excess (\$)	0.00	
Assign From	FRANKIE THAY	Assign Date	24/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMGD18508S214763	Colour	YELLOW	
Odometer	183117	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/45 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/45 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/45 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2018	Inspection Date	24/09/2018	
Survey held at	8 KAKI BUKIT AVE 4 #05-23			
Repairer	XIN YUN AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 8524Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	627.50	627.50
1	FRONT BUMPER REINFORCEMENT	DENTED	154.80	154.80
1	FRONT BONNET	TO REPAIR SEE LABOUR	464.70	-
1	FRONT GRILLE EMBLEM (H)	NECESSARY	27.42	27.42
1	FRONT GRILLE	CRACKED	121.60	121.60
1	FRONT BUMPER LH DUST COVER	NOT NECESSARY	27.10	-
1	F/LH FOG LAMP	NOT NECESSARY	257.10	-
1	F/RH FOG LAMP	NOT NECESSARY	257.10	-
1	FRONT BUMPER LOWER GRILLE	CRACKED	121.60	121.60
1	FRONT BUMPER LH SIDE VENT COVER	NOT NECESSARY	26.00	-
1	FRONT BUMPER RH SIDE VENT COVER	NOT NECESSARY	26.00	-
1	FRONT LH HEADLAMP	CRACKED	486.20	486.20
1	FRONT RH HEADLAMP	NOT NECESSARY	486.20	-
1	FRONT LH HEADLAMP BRACKET	DISTORTED	26.70	26.70
1	FRONT RH HEADLAMP BRACKET	NOT NECESSARY	26.70	-
1	REAR TAILGATE	BUCKLED	997.40	997.40
1	REAR TAILGATE LH SHOCK ABSORBER	NOT NECESSARY	123.20	-
1	REAR TAILGATE RH SHOCK ABSORBER	NOT NECESSARY	123.20	-
1	REAR TAILGATE INNER TRIM COVER	CRACKED	330.20	330.20
1	REAR TAILGATE WEATHER STRIP	TORN	50.50	50.50
1	REAR TAILGATE HONDA EMBLEM	NECESSARY	27.10	27.10
1	REAR TAILGATE JAZZ EMBLEM	NECESSARY	31.60	31.60
1	R/L TAILLAMP ASSY	CRACKED	283.60	283.60
1	R/R TAILLAMP ASSY	CRACKED	283.60	283.60
1	REAR TAILGATE LOCK ASSY	BENT	119.40	119.40
1	REAR TAILGATE LOCK CATCH	DISTORTED	29.00	29.00
1	REAR TAILGATE WEATHERSTRIP	TORN	97.20	97.20
1	REAR BUMPER	DISTORTED	690.80	690.80
1	REAR BUMPER TOW COVER	NOT FITTED	37.10	-
1	REAR END PANEL	BUCKLED	299.40	299.40
1	REAR END PANEL TOP GARNISH	CRACKED	120.40	120.40
1	REAR END PANEL BACK GARNISH	NO SUCH PARTS	63.10	-
1	R/H FENDER INNER GARNISH COVER	CRACKED	168.60	168.60

Report Ref No. CS/SPF18017304/Grd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	R/R FENDER INNER GARNISH COVER	CRACKED	168.60	168.60
1	REAR SPARE TYRE COMPARTMENT BOX	TO REPAIR SEE LABOUR	380.20	-
1	REAR SILENCER	TO REPAIR SEE LABOUR	580.80	-
1	AIR CON CONDENSER	DENTED	691.70	691.70
	LESS 20% DISCOUNT		-1,766.68	-1,190.98
			7,066.74	4,763.94
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	35.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	40.00	35.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	40.00	35.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	60.00
1	REVERSE SENSORS (SN)	SHORTED	240.00	200.00
	FRONT AND BACK NUMBER PLATE (SN)	DENTED	80.00	80.00
			590.00	445.00
	<u>LABOUR</u>			
	TO LABOUR CHARGES FOR REMOVING FRONT BUMPER ASSY, FRONT BONNET OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS AND INCLUDE STRAIGHTENING OF RADIATOR SUPPORT PANEL. INCLUSIVE OF THE REPAIR OF FRONT BONNET, REAR SPARE TYRE COMPARTMENT BOX AND REAR SILENCER.		1,000.00	600.00
	TO LABOUR CHARGE FOR RESPRAYING FRONT BONNET, FRONT BUMPER AND SUPPORT PANEL.		1,000.00	600.00
	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE, REAR BUMPER, END PANEL AND SPARE TYRE PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.		1,800.00	1,000.00
	TO LABOUR CHARGE FOR REMOVING AND FIXING REAR TAILGATE GLASS.		240.00	120.00
	TO LABOUR CHARGE FOR RESPRAYING REAR TAILGATE, REAR BUMPER, END PANEL AND SPARE TYRE COMPARTMENT.		1,600.00	1,000.00
	TO LABOUR CHARGE FOR REMOVING REAR SILENCER OUT TO FACILITATE REPAIR AND REPLACEMENT OF DAMAGED PARTS.		180.00	90.00
	TO LABOUR CHARGE FOR REMOVING REAR REVERSE SENSORS OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS.		200.00	50.00

Report Ref No. CS/SPF18017304/Grd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY BODY SEALANT AND APPLY ANTI-RUST ON ALL PARTS DAMAGED AREA.		140.00	80.00
	TO LABOUR CHARGE FOR REPLACEMENT AIR CON CONDENSER & REFILL AIR CON GAS.		120.00	100.00
			6,280.00	3,640.00
GRAND TOTAL			13,936.74	8,848.94
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,000.00

Report Ref No. CS/SPF18017304/Grd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.