

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

A

25-Sep-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8305 M

1 pc	Rear bumper <i>x repair</i>	\$	811.11
1 pc	Rear bumper o/s side bracket <i>x</i>	\$	52.20
	<i>Rear fender o/s x repair</i>	\$	863.31
	Less 20%	\$	172.66
		\$	690.65
S/NETT			
1 set	Rear bumper clips	\$	48.00 <i>x</i>
	Sundry	\$	50.00 <i>20</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>50</i>
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the rear o/s fender of the same, etc.	\$	650.00 <i>400</i>
	To putty and spray painting on the rear bumper, rear o/s fender	\$	400.00 <i>360</i>
	To apply rustproofing on the repaired and replaced panels	\$	120.00 <i>x</i>
	Total	\$	2,138.65

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultant's hereby notify the Repairer of the following:

- To resurvey the damaged parts
- To display damaged parts for a survey
- Parts prices are based on the "No Fault" basis
- Third party survey is not allowed
- No illegal modification to the vehicle and is subject to the approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kahin (KAK)
25/9/18 1110h
3 Pp.
KIP
John Alvin Rep. pth