



新福德車廠私人有限公司

Adrian Lkk  
- AXA

**NEW HOCK TECK MOTOR PTE. LTD.**

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883  
Email: admin@nhtmotor.com Website: www.nhtmotor.com  
Tel: 6747 9241 Fax: 6741 7276  
UEN: 201718370K

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

TPAXA  
Vic

24/09/2018

Accident date: 22/09/2018

Estimated repair cost for vehicle no: SJV1611X BMW 118i 5DR 1.6 A '11

CHASSIS: WBA1A32050E638969

| S/n | Qty | Items  | U/price  | Amount          |
|-----|-----|--|----------|-----------------|
| 1   | 1   | Rear Boot Lid <i>Rys</i>                           |          | \$1,408.45 +    |
| 2   | 2   | Rear Boot Lid Hinge                                | \$75.90  | \$151.80 +      |
| 3   | 2   | Rear Boot Lid Shock Absorber                       | \$115.20 | \$230.40 +      |
| 4   | 1   | Rear Boot Lid Inner Lock                           |          | \$255.70 +      |
| 5   | 1   | Rear Boot Lid Inner Rubber                         |          | \$166.95 +      |
| 6   | 1   | Rear Boot Lid Inner Trim Board                     |          | \$305.05 +      |
| 7   | 1   | Rear Boot Lid Windscreen Seal Assy                 |          | \$595.25 +      |
| 8   | 2   | Rear Tail Lamp <i>could</i>                        | \$369.50 | \$739.00 ✓      |
| 9   | 2   | Rear Tail Lamp Lower Bracket <i>new</i>            | \$56.85  | \$113.70 +      |
| 10  | 1   | Rear Bumper <i>deband</i>                          |          | \$1,260.80 ✓    |
| 11  | 1   | Rear Bumper Lower <i>deband</i>                    |          | \$485.30 ✓      |
| 12  | 10  | Rear Bumper Clip <i>new</i>                        | \$6.50   | \$65.00 30 +    |
| 13  | 2   | Rear Bumper Side Retainer <i>new</i>               | \$87.85  | \$175.70 +      |
| 14  | 2   | Rear Bumper Number Plate Lamp                      | \$23.20  | \$46.40 +       |
| 15  | 1   | Rear Bumper Reinforcement <i>new</i>               |          | \$588.00 +      |
| 16  | 4   | Rear Bumper Reverse Sensor <i>2 pieces damaged</i> | \$236.85 | \$947.40 -17370 |
| 17  | 4   | Rear Bumper Reverse Sensor Bracket <i>new</i>      | \$58.60  | \$234.40 +      |
| 18  | 1   | Rear End Panel <i>Regis</i>                        |          | \$697.45 +      |
| 19  | 1   | Rear End Panel Top Garnish <i>new</i>              |          | \$277.20 +      |
| 20  | 2   | Rear Fender Inner Trim Board <i>new</i>            | \$415.50 | \$831.00 X      |
| 21  | 1   | Rear Spare Tyre Panel <i>new</i>                   |          | \$1,800.85 +    |
| 22  | 1   | Rear Spare Tyre Panel Top Cover <i>new</i>         |          | \$254.60 +      |
| 23  | 1   | Rear Exhaust <i>Best</i>                           |          | \$1,350.60 ✓    |
| 24  | 1   | Rear Exhaust Chrome Pipe <i>new</i>                |          | \$218.65 +      |
| 25  | 1   | Rear Exhaust Aluminium Cover <i>new</i>            |          | \$285.10 +      |
| 26  | 1   | Rear Centre Exhaust <i>new</i>                     |          | \$948.75 +      |

4339.40

Subtotal :- \$14,433.50

412243

**Labour charges**

|   |      |                           |
|---|------|---------------------------|
| To remove & refit cushion               |      | <del>\$280.00</del> 50    |
| To remove & refit rear windscreen       |      | \$120.00 X                |
| Gum                                     |      | \$50.00 X                 |
| To remove & refit reverse sensor        |      | <del>\$100.00</del> 60    |
| To remove & refit rear & centre exhaust |      | <del>\$380.00</del> 100 X |
| To check wiring                         |      | <del>\$100.00</del> 30    |
| Towing fee                              |      | \$100.00 X                |
| Tuff kote                               | 1490 | \$150.00 X                |
| Panel beating                           |      | <del>\$1,600.00</del> 600 |
| Spray painting                          |      | <del>\$1,600.00</del> 650 |

**Subtotal :-** \$4,480.00

**Total:-** \$18,913.50

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total: 5612.43  
 4/s: 4.5K  
 0504p  
 (4.5K 0504p)