

Allswell Motor Traders

25 Defu Lane 9, Singapore 339266
Tel : +65 6679 1146 Email: ben@allswellmotor.com.sg

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(3rd party claim against

Estimate repair

Vehicle No: AK136TU
Make & Model: Toyota Vios 1.5
Chassis No: _____

Date of survey : _____

Submitted by : BH
COE expiry : 27-07-2021
Engine No. : _____

6 Days.
part by part.
before paint photos.
26/9/18
Insurance SY6016R
Gueo Qip.

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear bumper / ee	01	\$941.20	329.1	
02	LH rear lamp / car	01	\$374.30	/	
03	LH rear reflector / ee	01	\$55.00	/	
04	LH fender X repair	01	\$896.00	X	X repair
05	End panel / bic	01	\$491.40	/	
				1209.8	
				25% 977.35	
	Special nett				
01	Clip for lamp / bumper /	01	\$24.00		
	\$24 / pack				
	Labour description				
01	Dismantle / Assembly of affected parts.	01	\$360.00	250	
02	Panel knocking of rear end panel including welding	01	\$660.00	550	
03	Spray painting on all affected parts including anti-rust paint	01	\$600.00	/	
				2561.35	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.