


INS. CASE OWNER: BORRATEDO | CC3 / AIG1801 | 7 mo, UH639 | LKK: UH639 | IDAC:

Surveyor: Andrus | DOI: ASSIGNMENT | W/A/18 | Date / Time: 11/9/18
 Registered in Meriden: W/A/18

Pre-assign / CCU / FTE: GBG 61714
 Insured Vehicle No.: 860641254559 | Claim No.: 860641254559
 Name of Insured: DAIMLER TRUCK MANAGEMENT(S) INC | Policy No.: 860641254559
 Insured Tel No.: _____ | HI#: W/A/18 | Make / Model: MERCEDES
 Excess Sec II :SS: _____ | D.O.A.: W/A/18 | Place of Accident: BOONLAY WAY - MERIDEN 1WTO ST
 Is driver the owner? (YES / NO) NO | Nature of Accident: _____
 If NO: Driver Name / Age: TAMMY SHEWA BOWEN | OI GIA REPORT: YES / NO: NO | TP GIA REPORT: YES / NO: NO
 Driver Tel No.: _____ | (V/L: YES / NO) _____ | Insured Liability: % Final? Yes / No



Date/Time	STAGE	DATE / PIC
<u>2/11/18</u>	Non-Reporting Itr (1st)	
<u>11/10/18</u>	Non-Reporting Itr (2nd)	
<u>04/10/18</u>	Non-Reporting Itr (Final)	
<u>04/10/18</u>	Notification Itr (if non-pickup)	
<u>04/10/18</u>	Call OI	<u>04/10/18 - vic</u>
<u>04/10/18</u>	After call Itr to OI	
<u>04/10/18</u>	Documentation Check List: Handler	
<u>04/10/18</u>	Documentation Check List: Typist	
<u>04/10/18</u>	Notification Itr (if non-pickup)	
<u>04/10/18</u>	After call Itr to OI	
<u>04/10/18</u>	Authorisation To Act	
<u>04/10/18</u>	Release Voucher	
<u>04/10/18</u>	Final Repair Bill	
<u>04/10/18</u>	Car Rental Invoice	
<u>04/10/18</u>	Towing Invoice	
<u>04/10/18</u>	LIW/GIA	
<u>04/10/18</u>	Medical Bill	
<u>04/10/18</u>	PIR	
<u>04/10/18</u>	Mandate/Reject Instruction	
<u>04/10/18</u>	LOD	
<u>04/10/18</u>	Payment Breakdown Form	
<u>04/10/18</u>	Post-Repair Photos	
<u>04/10/18</u>	Others	

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: 49 \$S 2,600.00 | 4 days | Reduction: 68 % | Email Call

FINAL SETTLEMENT Date/Time: 19/10/18 Confirm with: OVAN Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 | If NO or B 28, Ass. Li: (OLD RATE - ENDED TP)

Repair Cost: \$S 2,600.00

Loss of Rental (LOR): \$S _____ (_____ days)
 Loss of Use (LOU): \$S 350.00 x 5 (_____ days)
 Loss of Income (LOI): \$S _____ (_____ days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/TA Search: \$S 7.45
 Medical: \$S _____
 Disbursement: \$S _____ (e.g. Tow/Independent)
 Legal Cost: \$S _____

Total: \$S 2,957.45 Global Sum \$S: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 2,957.45 Name 1: LIU'S BROTHER AUTO ENGINEERING WORKSHOP
 Payee 2: (Strike if N.A.) \$S _____ Name 2: _____
 Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

A16/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: G28460

at Workshop m/s: 1st 30

of _____

Insured: GAB61514

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 14

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 9 Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS _____

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: G28460C Yr Regn: 8.05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Car

Make: Toyota hiace c.c. 2494

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 426638 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFH502P700025752

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or C Stine.

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/9/14 D.O.I. 24/9/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>ETA 9205 29/8/2020 1yr 11m.</u>
	<u>NETT 4795</u>
	<u>Ls \$2,600.00</u>
	<u>(REV. \$5,777.60 (68%))</u>
	<u>MV: \$14,000.00 (cost)</u>
	<u>LA: \$ 9,205.00 (cost)</u>
	<u>NETT: \$ 4,795.00 (cost)</u>

Date/Time, File Pass to? : Prel. Report : Final Report

1) _____ Date/Time, File Return to? _____

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
S - RS - SI	_____
Photos	_____
Others	_____
TOTAL	_____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18017326/Uhb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 24-09-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 6151Y	Veh. Inspected	GY 8464C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/09/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/09/2018	Inspection Date	24/09/2018
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532617931. Tel: 6744-1730 / 731. Fax: 6744-5246. Email: liusbto@gmail.com

Invoice/Ref No: GY8464C180914

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 24-09-18

Address Motor Claims Department

Vehicle No: GY8464C

78 Shenton Way #07-16

Model/Make: Toyota Hiace

AIG Building

Singapore 079120

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>905/20/Seat</i>	\$ 1,472.50	
2	Tailgate "Toyota Logo" Motif <i>neu</i>	\$ 70.50	
3	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 15.00	SN 105-N
4	Tailgate "8 PAX" Sticker <i>neu</i>	\$ 15.00	SN 105-N
5	Tailgate Inner Lock <i>11</i>	\$ 359.00	X
6	Tailgate Weatherstrip <i>tw1</i>	\$ 387.90	
7	Tailgate Windscreen Moulding <i>ns</i>	\$ 219.00	X
8	Tailgate Windscreen Sealant <i>neu</i>	\$ 50.00	SN 405-N
9	Tailgate Number Plate & Base <i>11</i>	\$ 48.00	SN X
10	Bumper <i>Seat</i>	\$ 496.50	
11	Bumper Clips 1 set <i>neu</i>	\$ 65.00	
12	Bumper Side Holder 02 pcs (@\$69.10) <i>11</i>	\$ 138.20	X
13	Bumper Lower Bracket 04 pcs (@\$103.00) <i>Seat</i>	\$ 412.00	
14	Tail Lamps 02 pcs (@ \$365.10) <i>11</i>	\$ 730.20	X
15	End Panel Outer <i>2</i>	\$ 566.10	X
16	End Panel Inner <i>2</i>	\$ 936.20	X
17	End Panel Top Plate <i>11</i>	\$ 166.50	X
18	End Panel Sealant <i>11</i>	\$ 50.00	SN X
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 120.00	- 100
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	- 60
	Remove and replace rear exhaust pipe system to facilitate repairs <i>11</i>	\$ 80.00	- X
	Remove and refix rear Bumper distance sensor <i>11</i>	\$ 90.00	- X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 880.00	- 400
	To putty & spray painting & including touch up paint on accident affected area	\$ 800.00	- 450
	To apply Rust Proofing, rescal tuff-coating treatment on accident area	\$ 80.00	- 30

Total Parts & Labour of estimate for damaged vehicle

\$ 8,377.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

not approved
LKK
1/5 \$2600/2
24/9/18
take photo of accident
Helen

P-2904.4
257

2178.30
S.N-60
(dam-1060)

3298.30
2638



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 22 Sep 2018 / 12:34:31
Receipt Date/Time : 22 Sep 2018 / 12:34:31

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180922-000601

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBG6151Y As at 14 Sep 2018/15:30:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - GBG6151Y Enquiry Fee 20180922123327557513	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559		Credit Card: Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

h

Subject: RE: Request for 3rd party claims survey GY8464C Claims against GBG6151Y
***LKK REF:CC3/AIG18017326/Uhb3

From: vicalpeh@lkkauto.com
To: liusbro@ymail.com
Cc: admin-a@lkkauto.com; vicalpeh@lkkauto.com
Date: Friday, 5 October 2018, 2:55:26 PM SGT

Without Prejudice

Dear Susan,

Please find attached DV for your further action.

Kindly also forward a copy of the Authorization to Act Letter duly signed by the owner for payment processing

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Best Regards,

Vic Alpeh - Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

Our Ref: GY8464C180914

Date: 29/09/2018

Your Ref:

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Chartis Building
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG JUNCTION OF JURONG EAST STREET 31 AND BOON LAY WAY
INVOLVING GY8464C AND GBG6151Y ON 14/09/2018**

We/I, Messers Goldbell Leasing Pte Ltd (Nric / ROC No: 199001196N), the registered owners of m/vehicle – **GY8464C** at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my on his recommendation for **S\$2,600-00** being the repair for **04** Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **GBG6151Y** when the same was involved in the aforesaid accident with our/my m/vehicle – **GY8464C**.

We/I whereby you are the insurers of m/vehicle **GBG6151Y** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GY8464C** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	2,600-00
(b) LOU for pre-repair notice 02 days @\$70-00		140-00
(c) LOU Fee for 04 days @\$70-00		280-00
(d) GIA / LTA search fee		7-45

Total Amount

S\$ 3,027-45

We/I enclose herewith copies of the supporting documents for vehicle no. **GY8464C** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,


The owner of m/vehicle **GY8464C**
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws



04 OCTOBER 2018

DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531
ATTN: THE CLAIMS DEPT

By Post & By Email

Dear Sir/Madam,

OUR REF : CC3/AIG18017326/Uhb3
YOUR REF : GBG 6151Y
ACCIDENT INVOLVING GBG 6151Y AND GY 8464C ALONG BOONLAY WAY ON
14.09.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of GY 8464C against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle GY 8464C. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,


Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

Azrin.bejaramin@daimler.com
(Email)

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Thursday, 4 October, 2018 2:28 PM
To: Azrin.bejaramin@daimler.com
Cc: Admin A; Vic (LKKAuto)
Subject: YOUR REF: GBG 6151Y_ACCIDENT INVOLVING GBG 6151Y AND GY 8464C ALONG BOONLAY WAY ON 14.09.2018



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

04 OCTOBER 2018

DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD **By Post & By Email**
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531
ATTN: THE CLAIMS DEPT

Dear Sir/Madam,

OUR REF : CC3/AIG18017326/Uhb3
YOUR REF : GBG 6151Y
ACCIDENT INVOLVING GBG 6151Y AND GY 8464C ALONG BOONLAY WAY ON 14.09.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of GY 8464C against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle GY 8464C. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

AUTHORISATION TO ACT

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

We / I, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of GY8464C (vehicle No.) hereby authorize M/s Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and/or rental and/or loss of use ("claim") for my / our vehicle no. GY8464C that was damaged pursuant to the accident which occurred on 14/09/2018 (date) along Junction Of Jurong East Street 31 And Boon Lay Way (location) involving vehicle no / s GBG6151Y ("the accident").

We / I further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

We / I further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / is concerned.

Dated this 14th (day) of October (month) 20 18 (years)



Signed by "the third party claimant"
Messers Goldbell Leasing Pte Ltd
199001196N
GY8464C



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, LIU'S BROTHER AUTO ENGINEERING WORKSHOP ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,600.00 (Repair Cost), S\$350.00 (Loss of Rental/Use), S\$7.45 (Disbursement), for vehicle no. GY 8464C that was damaged pursuant to the accident which occurred on 14/09/2018 (date) along BOONLAY WAY (location) involving vehicle no/s GBG 6151Y. This is pursuant to the inspection conducted on 24/09/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GOLDBELL LEASING PTE LTD ("the third party claimant") of vehicle no. GY 8464C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GY 8464C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 14th (day) of October (month) **2018** (year)


LKK

Signed by appointed surveyor



Signed by "the workshop" (with chop)

Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 | Tel: 6744-1730 / 731 | Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GY8464C180914

Final Bill

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 29-09-18

Address Motor Claims Department

Vehicle No: GY8464C

78 Shenton Way #07-16

Model/Make: Toyota Hiace

AIG Building

Singapore 079120

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 1,472.50	\$ -
2	Tailgate "Toyota Logo" Motif	\$ 70.50	\$ -
3	Tailgate "70 KM/H" Sticker	\$ 15.00	\$ -
4	Tailgate "8 PAX" Sticker	\$ 15.00	\$ -
5	Tailgate Inner Lock	\$ 359.00	\$ -
6	Tailgate Weatherstrip	\$ 387.90	\$ -
7	Tailgate Windscreen Moulding	\$ 219.00	\$ -
8	Tailgate Windscreen Sealant	\$ 50.00	\$ -
9	Tailgate Number Plate & Base	\$ 48.00	\$ -
10	Bumper	\$ 496.50	\$ -
11	Bumper Clips 1 set	\$ 65.00	\$ -
12	Bumper Side Holder 02 pcs (@\$69.10)	\$ 138.20	\$ -
13	Bumper Lower Bracket 04 pcs (@\$103.00)	\$ 412.00	\$ -
14	Tail Lamps 02 pcs (@ \$365.10)	\$ 730.20	\$ -
15	End Panel Outer	\$ 566.10	\$ -
16	End Panel Inner	\$ 936.20	\$ -
17	End Panel Top Plate	\$ 166.50	\$ -
18	End Panel Sealant	\$ 50.00	\$ -
	To check all wiring & electrical component for proper function	\$ 50.00	\$ -
	Remove & reinstall Windscreen Glass to facilitate repairs & perform wiper	\$ 120.00	\$ -
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	\$ -
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 80.00	\$ -
	Remove and refix rear Bumper distance sensor	\$ 90.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 880.00	\$ -
	To putty & spray painting & including touch up paint on accident affect	\$ 800.00	\$ -
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 8,377.60

Total amount in Lump Sum Basis for repaired vehicle

\$ 2,600.00

SDLS: Two Thousand Six Hundred Only



M/s Liu's Brother Auto Engrg Wks

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 22 Sep 2018 / 12:34:31

Receipt Date/Time : 22 Sep 2018 / 12:34:31

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180922-000601

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBG6151Y As at 14 Sep 2018/15:30:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - GBG6151Y Enquiry Fee 20180922123327557513	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559		Credit Card Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Sep 2018 Edit Reg		24 Sep 2018 00:00 Edit Adj Rpt	S\$2,600.00 Edit Estimates	S\$2,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 199803778Z								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GY8464C	Date of Loss:	14/09/2018 15:00 - :59 [156 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8696412545SG	Policy/Cover Note No.:	0999994835 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBG6151Y	Policy No. (Claimant):	D-18090757MFCV						
Repairer:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GY8464C (8696412545SG)
[GBG6151Y]

TP

GOLDBELL LEASING PTE LTD

Sep 14 2018 3:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Liu's Brother Auto Engineering Workshop (kaki Bukit)

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	24/09/18 17:40	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
2	24/09/18 17:40	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
3	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
4	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
5	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
6	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
7	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
8	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
9	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
10	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
11	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
12	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
13	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
14	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
15	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
16	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
17	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
18	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
19	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
20	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
21	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
22	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
23	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
24	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
25	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
26	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
27	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
28	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
29	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
30	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
31	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
32	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
33	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	
34	24/09/18 17:40	G							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	24/09/18 17:40	G	Load JPG	<input checked="" type="checkbox"/>
36	24/09/18 17:40	G	Load JPG	<input checked="" type="checkbox"/>
37	24/09/18 17:40	G	Load JPG	<input checked="" type="checkbox"/>
38	24/09/18 17:40	G	Load JPG	<input checked="" type="checkbox"/>
39	24/09/18 17:40	G	Load JPG	<input checked="" type="checkbox"/>
40	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
41	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
42	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
43	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
44	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
45	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
46	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
47	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
48	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
49	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
50	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
51	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
52	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
53	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
54	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
55	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
56	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
57	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
58	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
59	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
60	24/09/18 17:41	G	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/18 16:42	TP GIA REPORT	Load PDF	
2	04/10/18 13:34	TP ESTIMATE - MARKED	Load PDF	
3	08/11/18 10:12	WORKSHOP INVOICE	Load PDF	
4	08/11/18 10:12	AUTHORISATION TO ACT FORM	Load PDF	
5	08/11/18 10:12	Release Voucher	Load PDF	
6	08/11/18 10:12	LTA SEARCH	Load PDF	
7	08/11/18 10:12	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/09/18 15:35	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBG6151Y (Insd veh)	Model:	TOYOTA HIACE 2.0 (M)
	GY8464C (TP veh)		
Date of Accident:	14/09/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	8,377.60	
Final Repair Cost	:	\$	2,600.00	
Loss of Use	:	\$	350.00	5.00 days at \$70.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	7.45	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	2,957.45	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability <u>100</u> (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No:		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Liu's Brother Auto Engineering Workshop	:	\$ 2,957.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

08 Nov
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18017326/UHB3Q2
Date: 08/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994835
Claimant Vehicle No : GY8464C	Insured Vehicle No :	GBG6151Y
Date of Loss: 14/09/2018	Nature of Claim:	TP Claim No: 8696412545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY8464C	Engine No:	2KD1341081
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHS02P700025752
Reg. Date:	30/08/2005 (Man. Year: 2005)	Odometer:	426638 km
Colour:	Silver		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	CST TIRE 6 mm	Rear Left Side:	CST TIRE 6 mm
Front Right Side:	CST TIRE 6 mm	Rear Right Side:	CST TIRE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,197.60	2,238.30	3,959.30	63.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,060.00	1,120.00	51.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,377.60	3,298.30	5,079.30	60.63
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	8,377.60	2,600.00	5,777.60	68.96
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,957.45		

INSPECTION

Date of Assignment:	24/09/2018	
Date Inspected:	24/09/2018 Inspected At:	Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented / Bent	1,472.50 F	*1,472.50 FL
2	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Necessary	70.50 F	*70.50 FL
3	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
4	1		*REAR TAILGATE 8PAX STICKER	Necessary	15.00 FS	*10.00 FS
5	1		*REAR TAILGATE INNER LOCK	Not Necessary	359.00 F	*- FL
6	1		*REAR TAILGATE WEATHERSTRIP	Twisted	387.90 F	*387.90 FL
7	1		*REAR TAILGATE WINDSCREEN MOULDING	No such part	219.00 F	*- FL
8	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
9	1		*REAR TAILGATE NUMBER PLATE & BASE	Not Necessary	48.00 FS	*- FS
10	1		*REAR BUMPER	Bent	496.50 F	*496.50 FL
11	1		*SET REAR BUMPER CLIP	Necessary	65.00 F	*65.00 FL
12	2		*REAR BUMPER SIDE HOLDER	Not Necessary	138.20 F	*- FL
13	4		*REAR BUMPER LOWER BRACKET	Bent	412.00 F	*412.00 FL
14	2		*REAR TAIL LAMPS	Not Necessary	730.20 F	*- FL
15	1		*REAR END PANEL OUTER	Repair	566.10 F	*- FL
16	1		*REAR END PANEL INNER	Repair	936.20 F	*- FL
17	1		*REAR END PANEL TOP PLATE	Not Necessary	166.50 F	*- FL
18	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,197.60	2,964.40
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	726.10
Total Parts (S\$)	6,197.60	2,238.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER	New	120.00	100.00
3	REMOVE AND REFIX TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
4	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	80.00	0.00
5	REMOVE AND REFIX REAR BUMPER DISTANCE SENSOR	New	90.00	0.00
6	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	880.00	400.00
7	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	800.00	450.00
8	TO APPLY & RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00
Gross Labour Cost (S\$)			2,180.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >