

Our Ref: GY8464C180914

Date: 29/09/2018

Your Ref:

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Chartis Building
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG JUNCTION OF JURONG EAST STREET 31 AND BOON LAY WAY
INVOLVING GY8464C AND GBG6151Y ON 14/09/2018**

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**), the registered owners of m/vehicle – **GY8464C** at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my on his recommendation for **S\$2,600-00** being the repair for **04** Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **GBG6151Y** when the same was involved in the aforesaid accident with our/my m/vehicle – **GY8464C**.

We/I whereby you are the insurers of m/vehicle **GBG6151Y** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GY8464C** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	2,600-00
(b) LOU for pre-repair notice 02 days @\$70-00		140-00
(c) LOU Fee for 04 days @\$70-00		280-00
(d) GIA / LTA search fee		7-45

Total Amount

S\$ 3,027-45

We/I enclose herewith copies of the supporting documents for vehicle no. **GY8464C** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle **GY8464C**
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GY8464C180914

Final Bill**Customer**Name: AIG Asia Pacific Insurance Pte LtdAddress Motor Claims Department78 Shenton Way #07-16AIG Building Singapore 079120Date: 29-09-18Vehicle No: GY8464CModel/Make: Toyota Hiace
Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 1,472.50	\$ -
2	Tailgate "Toyota Logo" Motif	\$ 70.50	\$ -
3	Tailgate "70 KM/H" Sticker	\$ 15.00	\$ -
4	Tailgate "8 PAX" Sticker	\$ 15.00	\$ -
5	Tailgate Inner Lock	\$ 359.00	\$ -
6	Tailgate Weatherstrip	\$ 387.90	\$ -
7	Tailgate Windscreen Moulding	\$ 219.00	\$ -
8	Tailgate Windscreen Sealant	\$ 50.00	\$ -
9	Tailgate Number Plate & Base	\$ 48.00	\$ -
10	Bumper	\$ 496.50	\$ -
11	Bumper Clips 1 set	\$ 65.00	\$ -
12	Bumper Side Holder 02 pcs (@S\$69.10)	\$ 138.20	\$ -
13	Bumper Lower Bracket 04 pcs (@S\$103.00)	\$ 412.00	\$ -
14	Tail Lamps 02 pcs (@ S\$365.10)	\$ 730.20	\$ -
15	End Panel Outer	\$ 566.10	\$ -
16	End Panel Inner	\$ 936.20	\$ -
17	End Panel Top Plate	\$ 166.50	\$ -
18	End Panel Sealant	\$ 50.00	\$ -
	To check all wiring & electrical component for proper function	\$ 50.00	\$ -
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water	\$ 120.00	\$ -
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	\$ -
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 80.00	\$ -
	Remove and refix rear Bumper distance sensor	\$ 90.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 880.00	\$ -
	To putty & spray painting & including touch up paint on accident affect	\$ 800.00	\$ -
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 8,377.60

Total amount in Lump Sum Basis for repaired vehicle

\$ 2,600.00

SDLS: Two Thousand Six Hundred Only

M/s Liu's Brother Auto Engrg Wks

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 22 Sep 2018 / 12:34:31

Receipt Date/Time : 22 Sep 2018 / 12:34:31

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180922-000601

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBG6151Y As at 14 Sep 2018/15:30:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - GBG6151Y Enquiry Fee 20180922123327557513	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 1196N

Vehicle Details

Vehicle No.: GY8464C
Vehicle to be Exported: No
Intended Deregistration Date: 22 Sep 2018
Vehicle Make: TOYOTA
Vehicle Model: HIACE MANUAL
Primary Colour: White
Manufacturing Year: 2005
Engine No.: 2KD1341081
Chassis No.: JTFHS02P700025752
Maximum Power Output: -
Open Market Value: \$23,804.00
Original Registration Date: 30 Aug 2005
First Registration Date: 30 Aug 2005
Transfer Count: 1
Actual ARF Paid: \$1,191.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Aug 2020
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 5
PQP Paid: \$25,292.00
COE Rebate Amount: \$9,790.00
Total Rebate Amount: \$9,790.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.
The information contained herein is correct as at 22 Sep 2018

OK