

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1114/2018/GW
Date : 25-Sep-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : HITACHI CAPITAL ASIA PACIFIC PTE LTD
Address : 111 Somerset Road #14-05
Singapore 238164
Telephone : (HP) 68336277
Type of Claim : Third Party Claims
Policy No. : VPX / P2063400
Vehicle No : **SLV7398Z**
Model Code : Audi Q7 2.0 TFSI Qu
Model / Year : Jan-18
Engine No : CYR 054505
Chassis No : WAUZZZ4M0JD020044
Mileage : 10418 KM
Date In : 24-Sep-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Sep-18
Place of Accident : 2 Hillview Rise

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 7398 Z.

S/N	Nature of Jobs			Estimated Charges
1	To tow and recover vehicle from scene of accident.	S/N	\$	280.00 ✕
2	To remove and transfer front wire harness for headlights, horns, outside temperature sensor , headlight washer assy and front parking aid.	S/N	\$	480.00 ✓
3	To remove and renew aircon condensor, radiaotor, additional radiaotor, coolant pipes, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N	\$	1,400.00 ?
4	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N	\$	280.00 ✕.
5	To suspend engine. To dismantle front suspension assy. Inspect for damages and renew accordingly .	S/N	\$	2,800.00 ?
SUB-TOTAL LABOUR CHARGES			:	\$ 5,240.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 7398 Z.

S/N	Nature of Jobs	Estimated Charges
6	To dismantle and renew front bumper, lhs front fender, bonnet, both headlights and lhs front door. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 8,000.00 <i>600x5 = 3000 without Lock Carrier 3000.</i>
7	To respray front bumper, both front bumper spoiler, lhs front fender, rhs front fender, bonnet, bonnet hinges, lhs front door, door cover, and both front wheel arch cover.	\$ 7,100.00 <i>Wheel Arch = 200x2 = 400 4x600 = 2400 Spoiler = 400 Door Cover : 250 3450.</i>
8	To renew lhs front rim. To carry out wheel alignment.	S/N \$ 280.00 ✓
9	To carry out diagnostic check.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 21,004.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7398 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted.</i>	\$ 2,252.00	✓
2	FRONT BUMPER FIXING PARTS ²	\$ 382.00	?
3	TOWING CAP <i>Missing</i>	\$ 34.00	✓
4	FRONT AIR GUIDE-RH /LH <i>RH Distorted</i>	2 \$ 114.00 57	?
5	FRONT BUMPER END CAP -LH/RH [?]	2 \$ 60.00	?
6	FRONT BUMPER CLOSING ELEMENT <i>tom</i>	\$ 237.00	✓
7	FRONT BUMPER GRILLE -LOWER CENTRE <i>Dist.</i>	\$ 180.00	✓
8	UNDERRUN BAR <i>Distorted</i>	\$ 700.00	✓
9	FRONT BUMPER CLOSING ELEMENT [?]	\$ 180.00	?
10	FRONT BUMPER SPOILER-LH/RH [?]	2 \$ 366.00	?
11	FRONT BUMPER OUTER SPOILER-LH/RH [?]	2 \$ 76.00	?
12	RADIATOR GRILLE <i>let</i>	\$ 2,027.00	✓
13	RADIOATR GRILLE COVER <i>new</i>	\$ 60.00	+
14	RADIATOR GRILLE INNER COVER <i>new</i>	\$ 54.00	+
15	RADIATOR GRILLE COVER CAP <i>new</i>	\$ 89.00	+
16	RADIATOR BRACKET <i>new</i>	\$ 89.00	+
17	CAMERA <i>not new</i>	\$ 1,023.00	+
18	FRONT BUMPER AIR GUIDE GRILLE-LH <i>let</i>	\$ 260.00	✓
19	FRONT BUMPER END CAP -LH [?]	\$ 29.00	?
20	FRONT BUMPER AIR GUIDE GRILLE-RH <i>missing</i>	\$ 260.00	✓
SUB-TOTAL SPARE PARTS		\$ 8,472.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7398 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT BUMPER END CAP-RH ?	\$	29.00 ?
22	FRONT BUMPER INNER SPOILER-RH/LH ?	2 \$	62.00 ?
23	FOAM FILLER PIECE <i>could</i>	\$	147.00 ✓
24	FRONT BUMPER CARRIER <i>Bent</i>	\$	753.00 ✓
25	FRONT BUMPER GUIDE SECTION-LH/RH ?	2 \$	74.00 ?
26	FRONT BUMPER SUPPORT-LH/RH ?	2 \$	62.00 ?
27	FRONT BUMPER COVER <i>Rehnd</i>	\$	112.00 ✓
28	SIGN ' CAUTION ' <i>new</i>	\$	12.00 ✓
29	AIR CONDITIONER STICKER <i>new</i>	\$	7.00 ✓
30	FRONT SENSOR <i>new</i>	4 \$	842.00 ✓
31	FRONT SIDE SENSOR <i>new</i>	2 \$	421.00 ✓
32	FRONT SENSOR SEAL RING <i>new</i>	6 \$	21.00 ✓
33	FANFARE- LOW TONE <i>new</i>	\$	200.00 ✓
34	FANFARE- HIGH TONE <i>new</i>	\$	200.00 ✓
35	FRONT FENDER-LH <i>Distorted.</i>	\$	1,422.00 ✓
36	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$	67.00 ✓
37	FRONT FENDER BRACKET-LH <i>Bent</i>	\$	56.00 ✓
38	FRONT FENDER BRACE -LH <i>Bent</i>	\$	89.00 ✓
39	FRONT WHEEL HOUSING LINER=LH/RH <i>2 new</i>	2 \$	430.00 ✓
40	FRONT WHEEL HOUSING LINER-LH REAR /RH REAR <i>new</i>	2 \$	430.00 ✓
SUB-TOTAL SPARE PARTS		\$	5,436.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7398 Z .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	2 \$	93.00 *
42	BONNET <i>Repair</i>	\$	4,295.00 *
43	BONNET ATTACHEMENT PARTS <i>?</i>	\$	84.00 *
44	BONNET LID HINGE-LH/RH	2 \$	146.00 +
45	GAS FILLED STRUT	\$	121.00 +
46	STOP BUFFER	2 \$	17.00 +
47	FRONT IMPACT PROTECTION	\$	92.00 *
48	HEADLAMPS COVER-LH/RH <i>?</i>	2 \$	178.00 *
49	SLIDE MEMBER COVER PLATE-RH <i>?</i>	\$	39.00 *
50	FRONT BUMPER LOCKING MECHANISM <i>new</i>	2 \$	14.00 *
51	BONNET STRIKER PLATE -LH/RH <i>new</i>	2 \$	214.00 *
52	BONNET BOWDEN CABLE <i>new</i>	\$	50.00 *
53	BONNET LID LOCK WITH MICRO	2 \$	383.00 *
54	BONNET LID LOCK CABLE <i>new</i>	2 \$	132.00 *
55	BONNET RELEASE LEVER <i>new</i>	\$	12.00 *
56	FRONT BUMPER WIRING	\$	565.00 *
57	FRONT WHEEL COVER-LH-RH <i>new</i>	2 \$	1,004.00 *
58	LED HEADLIGHT-LH/RH <i>hit on left, RH ?</i>	2 \$	17,698.00 % 2.
59	HEADLIGHT CONTROL UNIT-LH/RH <i>new</i>	2 \$	1,314.00 +
60	HEADLIGHT POWER MODULE <i>new</i>	\$	695.00 *
SUB- TOTAL SPARE PARTS		\$ 27,146.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7398 Z .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	FAN FOR HEADLAMPS <i>new</i>	2 \$	689.00 ✕
62	HEADLIGHT MOUNTIN-LH/RH ?	2 \$	206.00 ?
63	HEADLIGHT CLINDER-LH/RH ?	2 \$	348.00 ?
64	WASH WATER RESERVOIR ?	\$	190.00 ?
65	FRONT DOOR-LH <i>Repair</i>	\$	3,274.00 ✕
66	FRONT DOOR OUTER DOOR SEAL-LH	\$	218.00 ✕
67	BONDING AGENT	\$	43.00 ✕
68	CLENING SOLUTION	\$	64.00 ✕
69	APPLICATOR	\$	7.00 ✕
70	DOOR ATTACHEMENT PARTS	\$	85.00 ✕
71	FRONT DOOR INNER SEAL	\$	244.00 ✕
72	FRONT DOOR CATCH	\$	112.00 ✕
73	FRONT DOOR CATCH COVER	\$	15.00 ✕
74	LOCK CARRIER MOUNTING ?	\$	1,048.00 ?
75	A/C CONDENSER WITH FLUID RESERVOIR ?	\$	847.00 ?
76	PRESSURE SENDER ?	\$	165.00 ?
77	PRESSURE SENDER VALVE ?	\$	46.00 ?
78	RADIATOR ?	\$	630.00 ?
79	COOLANT CONCENTRATE 1.5 LTR ?	4 \$	133.00 ?
80	RESERVOIR ?	\$	87.00 ?
SUB- TOTAL SPARE PARTS		\$	8,451.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7398 Z .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	INTERCOOLANT ?	\$	549.00 ?
82	RADIAOTOR AIR DUCT=LH/RH ?	\$	38.00 ?
83	INTERCOOLER BRACKET ?	\$	121.00 ?
84	AIR DUCT-LH/RH ?	2 \$	48.00 ?
85	UPPER AIR DUCT-LH ?	\$	35.00 ?
86	LOWER AIR DUCT-RH ?	\$	35.00 ?
87	TWIN FAN RING ?	\$	261.00 ?
88	RADIATOR FAN WITH CONTROL UNIT ?	\$	1,609.00 ?
89	FRONT COOLANT PIPE-OUTER ?	\$	60.00 ?
90	CENTRE COOLANT PIPE-OUTER ?	\$	70.00 ?
91	COOLANT HOSE ?	\$	6.00 ?
92	SPRING BAND CLAMP ?	2 \$	18.00 ?
93	FRONT DOOR COVER-LH <i>2yr</i>	\$	608.00 <i>R.</i>
94	ADHESIVE TAPE <i>in</i>	\$	23.00 ✓
95	NOISE INSULATION <i>for ?</i>	\$	608.00 ?
96	FRONT ALUMINIUM RIM-LH <i>lt</i>	\$	1,005.00 ✓
97	RUBBER VALBE <i>the in</i>	4 \$	12.00 <i>X.</i>
98	FRONT WISHBONE LINK-LH ?	\$	353.00 ?
99	FRONT SUSPENSION GUIDE-LH ?	\$	887.00 ?
100	FRONT TRACK CONTROL ARM-LH ?	\$	282.00 ?
SUB-TOTAL SPARE PARTS		\$	6,628.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 7398 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
101	FRONT UPPER TRACK CONTROL ARM-LH ?	\$ 282.00	?
102	FRONT WHEEL BEARING HOUSING-LH ?	\$ 971.00	?
103	SWIVEL JOINT ?	\$ 192.00	?
104	WHEEL HUB ?	\$ 433.00	?
105	WHEEL BEARING ASSEMBLY ?	\$ 283.00	?
106	FRONT SUSPENSION FORK-LH ?	\$ 331.00	?
107	RETAINER FOR BRAKE HOSE ?	\$ 12.00	?
108	FRONT COUPLING ROD-LH ?	\$ 124.00	?
109	GAS SHOCK ABSORBER ?	\$ 456.00	?
110	GAS SHOCK ABSORBER RUBBER STOP ?	\$ 35.00	?
111	LEVEL SENSOR ?	\$ 286.00	?
112	SPEED SENSOR ?	\$ 87.00	?
113	DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS ?	\$ 2,210.00	?
114	STEERING GEAR TRACK ROD JOINT ?	\$ 6,433.00	?
115	TIE ROD END-LH ?	\$ 174.00	?
116	FRONT NO. PLATE <i>Nec</i>	S/N \$ 25.00	✓
117	SUNDRIES ?	\$ 1,000.00	?
TOTAL SPARE PARTS		: \$ 69,467.00	
TOTAL LABOUR CHARGES		: \$ 21,004.00	
GRANDTOTAL		: \$ 90,471.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *26/09/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 18 Days*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant