

ASS. REC. BY

REF

CS/MSG18017341/T1SD3^{SR}

Special Instruction

Surveyor
menmen

Taufik

ASSIGNMENT (Office)

From (Person)

Ong Chin Kiat

of

MSIG

Date/Time

24/9/18 @ 3:50pm

Estimated Cost

Bill to

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S/Y 8225R

Insured:

at Workshop m/s

Performance Motor

Tel:

9116 5600

of

303 Alexandra Rd

Policy No:

B27572562SMP

Claim No:

570987

Sum Insured

Excess:

\$750.00

Make of Veh:

D.O.A.

20/09/18

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

4:18pm @ 24/9/18

Person Contacted:

Kevin

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

S/Y 8225R-X

25/09/18

@ 17:49 p.m. revised IA to Ong Chin Kiat via menmen.

27/09/18

@ 10:55 a.m. mandate requested authorize repair to Ong Chin Kiat via menmen.

03/10/18

@ 09:27 a.m. mandate revoked by Eng Huey N. Vehicle is not economical to be repaired. It will be settled on Constructive total loss basis via menmen.

Surveyor

Tanpin

REF:

MS16

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$92K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Kevin.

Veh No:

SSY 8225R

Yr Regn:

2013 Aug.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW - 520I

c.c

1997

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

89783

T/Radio:

Insured / Std / NI / NA

Eng/No:

WKA5A52050P333558.

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

285/30R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24/9/18Q

Survey held at

PML

Des. of Damages: (Fr) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Limit \$16K.

04/10/18 @ 9:04 a.m. revert Constructive total loss basis to Kevin Geyner via email.

04/10/18 Submit Total Loss as Constructive.

RECEIVED 04 OCT 2018

Date/Time, File Pass to?

04/10/18
Typist



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7-8 days

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

200

10

Report Format:

Total Loss

Lump Sum / I.B.I: (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18017341/T1sd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 24-09-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SJY 8225R	
Policy No.	B27572562SMP	Coverage (\$)	0.00	
Claim No.	570987	Excess (\$)	750.00	
Assign From	MERIMEN (ONG CHIN KIAT)	Assign Date	24/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/09/2018	Inspection Date	24/09/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Sep 2018		24 Sep 2018 15:50 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HO THIAM GUAN, ID: S7836289H, Tel: +6596467856, Email: RHOTG@YAHOO.COM.SG		
Vehicle Reg. No.:	SJY8225R	Date of Loss:	20/09/2018 19:00 - :59 [60 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 570987	Policy/Cover Note No.:	B27572562SMP (Comprehensive) Coverage: 01/09/2018 - 31/08/2019
		Excess:	S\$750.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Ong Chin Kiat - 6594 2558]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/09/2018]		
Driver/Custodian:	HO THIAM GUAN (39 / Male), NRIC: S7836289H, Tel: +6596467856		
Adj Asg. Remarks:	Car in, pls revert. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 4 October 2018 9:04 AM
To: 'Han Kwan Yong'; 'Kevin Leong Wai Kit'
Cc: 'PBSP'; sur@lkkauto.com; 'Ong Chin Kiat'
Subject: RE: SJY 8225R OD (MSIG)

Dear Mr. Han/Kevin,

Kindly inform the vehicle will be settled on Constructive total loss basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Han Kwan Yong [mailto:han.kwan.yong@simedarby.com.sg]
Sent: Thursday, 27 September 2018 10:40 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>; PBSP <pml-pbsp@simedarby.com.sg>;
sur@lkkauto.com; Ong Chin Kiat <chinkiat_ong@sg.msig-asia.com>
Subject: RE: SJY 8225R OD (MSIG)

Dear Shirley,

We are unable to accept/repair at limit not exceed \$16,000.00.

Feedback from our workshop requested \$20,000.00 (min) before excess, supplementary & GST.

Thank you.

Regards,

Han K.Y.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, September 25, 2018 4:16 PM
To: Han Kwan Yong <han.kwan.yong@simedarby.com.sg>
Cc: Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>; PBSP <pml-pbsp@simedarby.com.sg>;
sur@lkkauto.com
Subject: SJY 8225R OD (MSIG)

Dear Han,

As spoken, kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 16,000.00 on part by part basis.

Shirley Hiew (LKK Auto)

From: Han Kwan Yong <han.kwan.yong@simedarby.com.sg>
Sent: Thursday, 27 September 2018 10:40 AM
To: Shirley Hiew (LKK Auto)
Cc: Kevin Leong Wai Kit; PBSP; sur@lkkauto.com; Ong Chin Kiat
Subject: RE: SJY 8225R OD (MSIG)

Dear Shirley,

We are unable to accept/repair at limit not exceed \$16,000.00.

Feedback from our workshop requested \$20,000.00 (min) before excess, supplementary & GST.

Thank you.

Regards,

Han K.Y.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Tuesday, September 25, 2018 4:16 PM
To: Han Kwan Yong <han.kwan.yong@simedarby.com.sg>
Cc: Kevin Leong Wai Kit <kevin.leong.waikit@simedarby.com.sg>; PBSP <pml-pbsp@simedarby.com.sg>; sur@lkkauto.com
Subject: SJY 8225R OD (MSIG)

Dear Han,

As spoken, kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 16,000.00 on part by part basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SJY8225R (570987)**

OD

Sep 20 2018 7:00PM

[HO THIAM GUAN]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 03/10/2018 09:27 AM.

To LKK_HQ

Subject Alert - Adj Mandate Revoked - SJY8225R - Claim Handler: Ong Chin Kiat

Revoked: Veh not economical to be repaired. It will be settled on Constructive total loss basis

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 27 Sep 2018

Preliminary Advice

Vehicle No	: SJY8225R	Accident Date	: 20/09/2018
Make	: BMW 520I	Policy No.	: B27572562SMP
Assignment Date	: 24/09/2018	Excess	: S\$750.00
Date of Inspection	: 24/09/2018	Est. Duration of Repair	: 7 - 8 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,130.25
Revised Amount	:S\$	15,551.50
Check Items (Estimated)	:S\$	7,377.95
Total	:S\$	22,929.45

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	75,177.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,823.00

Remarks

- () The vehicle is economical/not economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Other Comments : Repairer asking \$ 20,000.00 (min) before excess, supplementary & GST.
Please take note : margin for repair is \$ 16,823.00

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 25 Sep 2018

Preliminary Advice

Vehicle No	: SJY8225R	Accident Date	: 20/09/2018
Make	: BMW 520I	Policy No.	: B27572562SMP
Assignment Date	: 24/09/2018	Excess	: S\$750.00
Date of Inspection	: 24/09/2018	Est. Duration of Repair	: 7 - 8 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,130.25
Revised Amount	:S\$	15,551.50
Check Items (Estimated)	:S\$	7,377.95
Total	:S\$	22,929.45

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	75,177.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,823.00

Remarks

- () The vehicle is economical/not economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Other Comments : WE ARE STILL PENDING REPAIR COST FROM REPAIRER

Please take note

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/09/2018 12:45
Date Of Accident	20/09/2018 19:45
Exact Location Of Accident	ALONG JALAN BOON LAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJY8225R
Insured/Policyholder	
Name Of Registered Owner	HO THIAM GUAN
NRIC No	S7836289H
Email Address	RHOTG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96467856
Alternative Phone No	OTHERS-96467856
Vehicle Particulars	
Manufacturer	BMW
Model	520
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27572562SMP
Cover Note Number	
Driver	
Name of Driver	HO THIAM GUAN
NRIC No	S7836289H
Date Of Birth	03/12/1978
Occupation	INDOOR
Date Of Driving Pass	25/10/2002
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96467856
Fax Number	
Contact Number	OTHERS-96467856
Email Address	RHOTG@YAHOO.COM.SG

Address	167 WESTWOOD AVENUE
Postcode	648256
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU5434E
Vehicle Make/Model/Colour	KIA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LOW THIAM SEWE
NRIC/Passport Number	S0485224I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

21/09/2018

(3-40) (3-40) (3-40) (3-40) (3-40)


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

KEVIN LEONG WAI KIT
PerformanceMotors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Jalan Boon Lay on 20/09/2018 at 1945 hrs, driving on the extreme right lane, but at a sudden, there is this blue truck (AU5429E) turn out from Enterprise Road, and directly swerve into my lane. I immediately honked horn and at the same time E-Brake. But unfortunately the distance was too near for me to brake in time and ended up hitting his back.

At the junction of Enterprise Road where he swerved out, there is actually a stop line. He failed to stop and rashly drove out and goes directly to the extremely right lane. This is a 3 lane road.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

21/09/2018

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre
Name:
NRIC/FIN No.:

KEVIN LEONG WAI KIT
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6289H
Vehicle Details	
Vehicle No.:	SJY8225R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520I AT D/AB 2WD 4DR LED NAV
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	B4620553N20B20B
Chassis No.:	WBA5A32050D333558
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$47,458.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$53,442.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2023
PARF Rebate Amount:	\$37,409.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2023
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$79,223.00
COE Rebate Amount:	\$37,768.00
Total Rebate Amount:	\$75,177.00

The information contained herein is correct as at 24 Sep 2018

OK


MSIG

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888, Fax +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

BROKER'S COPY
SIME MOTOR PRIVATE
RENEWAL CERTIFICATE

Policy Number	Period of Insurance	Place of Issue
B 27572562 SMP	01/09/2018 to 31/08/2019	SINGAPORE
Name and Address of Insured	Date of Issue	Account Number
Ho Thiam Guan (He Tianyuan) 167 Westwood Avenue The Wood Singapore 642856	17/08/2018	212165
Premium	GST	Total Due
SGD1,018.26	SGD71.28	SGD1,089.54

RISK NUMBER 1
SIME MOTOR PRIVATE
OCCUPATION

Trader (Fuel)

FINANCIAL INTEREST

 United Overseas Bank Limited
 as Hire Purchase Owners

SCOPE OF COVER Comprehensive

INTEREST INSURED

REGISTRATION NO. SJY8225R
 MAKE/MODEL BMW S20I AT
 ENGINE NUMBER B4620553N20B20B
 CHASSIS NUMBER WBA5A32050D333558
 YEAR OF MFG 2013
 CAPACITY 1997 C.C.
 SEATING CAPACITY 5 (INCL. DRIVER)
 WINDSCREEN UNLIMITED

SUM INSURED
 INCL. COE/PARF YES
 OFF-PEAK CAR NO
 NO CLAIM DISCOUNT 50.00% (or F/D)
 GOOD DRIVER'S DISCOUNT SGD53.59
 NCD PROTECTOR COVERED
 EXCESS SGD750
 ANNUAL PREMIUM SGD1,018.26

ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit,
 rust-proofing and other accessories that are factory fitted.

AUTHORISED DRIVERS

Ho Thiam Guan (He Tianyuan)

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7836289H**
 Name: **HO THIAM GUAN (HE TIANYUAN)**

Birth Date: **03 Dec 1978**
 Issue Date: **16 Sep 2003**

000844920J




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7836289H**

Name: **HO THIAM GUAN (HE TIANYUAN)**
何添源

Race: **CHINESE**
 Date of Birth: **03-12-1978** Sex: **M**
 Country of Birth: **SINGAPORE**





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	25 Oct 2002

NP 428A

Licence No: S7836289H



306377

NRIC No: **S7836289H**

Blood Group: **O+** Date of issue: **29-01-1999**

Address: **187 WESTWOOD AVENUE SINGAPORE 648256**

No: **S7836289H** Date: **25/04/2015**




Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48517
Date Estimated : 21/09/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ho Thiam Guan (He Tianyuan)
167, WESTWOOD AVE
The Woods

Singapore 648256

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY8225R	D333558	30/08/2013	520iA	0

DESCRIPTION

VALUE

To replace frt bumper, frt support, frt V-strut, carrier, reinforcement, both grille & all attachments cause by accident.

3400 4,250.00

Painting on frt bumper, frt bonnet & frt left side panel

2898 3,221.00

To replace radiator assembly, fan housing with fan including to conduct pressure test, bleed bleed cooling system and check for leak.

7,702 826.00

To replace charge air cooler including conduct checks for leak and proper function.

7,451 531.00

To replace air con condenser and air con hose including to vacuum system, top up freon gas and check for leak.

7,852 1,003.00

To check electrical wiring systems at the front section for proper function.

150 177.00

To replace left headlight.

408 481.00

To carry out body cavity preservation.
(Per panel) Bonnet

100 118.00

To carry out body cavity preservation.
(Per panel) Front left side panel

7,100 118.00

—To supply front emboss number plate.

83 83.00

To tow accident vehicle to PML workshop.

195 195.00

Sundries.

150 150.00

Total Labour 1: 11,153.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X.



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48517
Date Estimated : 21/09/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJY8225R	D333558	30/08/2013	520iA	0

DESCRIPTION	QTY	PRIC	VALUE
CHARGE AIR COOLER	1	609.75	609.75
RADIATOR	1	1,030.95	1,030.95
FRT LH FENDER	1	863.35	863.35
BONNET	1	2,224.70	2,224.70
SET MOUNTS PDC SENSOR FRT (PDC)	1	58.60	58.60
FRT LH BOTTOM DEFORMATION ELEMENT	1	101.70	101.70
FRT RH BOTTOM DEFORMATION ELEMENT	1	101.70	101.70
FRT BUMPER CARRIER	1	684.75	684.75
FRT BUMPER BOTTOM MOUNT	1	157.50	157.50
FRT BUMPER LH SPACER	1	9.45	9.45
FRT BUMPER RH SPACER	1	9.45	9.45
SUPPORT	1	16.60	16.60
GRILLE AIR INLET MIDDLE	1	80.65	80.65
LH OPEN GRILLE AIR INLET (LINES)	1	80.00	80.00
FRT SHOCK ABSORBER	1	48.00	48.00
FRT BUMPER LH PROTECTIVE RUBBER STR	1	41.15	41.15
FRT BUMPER PANEL PRIMED (PDC)	1	1,277.55	1,277.55
FRT TOWING LUG COVER PRIMED	1	46.45	46.45
FRT LH GRILLE (BASIS)	1	120.50	120.50
FRT RH GRILLE (BASIS)	1	120.50	120.50
BMW EMBLEM	1	69.50	69.50
LH SUPPORT	1	18.40	18.40
RH SUPPORT	1	18.40	18.40
CONNECTION TOP FRT	1	159.65	159.65
CONNECTION TOP REAR	1	197.30	197.30
LH HEADLAMP SUPPORT	1	126.10	126.10
AIR DUCT	1	293.50	293.50
AIR DUCT BRAKE LH	1	51.50	51.50
SEAL BONNET REAR	1	29.35	29.35
FRT LH LOCATOR SEAL	1	55.80	55.80
SEAL ENGINE BONNET FRT	1	42.30	42.30
LH HEADLIGHT LED TECHNOLOGY	1	4,203.70	4,203.70
CONDENSER AIR CONDITIONING	1	1,028.45	1,028.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts : 13,977.25

Vehicle ID / 3rd Party / Uninsured / 3rd Party / 3rd Party / 3rd Party

Chassis No. 24/9/180/750

Engine No. 750

VIN 97495844

Prevent

7-08 days

7-08 days

7-08 days

7-08 days

7-08 days

7-08 days

Labour 1	:	11,153.00
Parts	:	13,977.25
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,759.12
Grand Total	:	26,889.37

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

...CLAIM SUBFOLDER...(Pending for Survey Report)

Total Loss

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	21 Sep 2018		24 Sep 2018 15:50 Edit Adj Rpt	S\$15,551.50 Edit Estimates	S\$15,551.50 View Rpt	Pending for Survey Report

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HO THIAM GUAN, ID: S7836289H, Tel: +6596467856, Email: RHOTG@YAHOO.COM.SG		
Vehicle Reg. No.:	SJY8225R	Date of Loss:	20/09/2018 19:00 - :59 [60 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 570987	Policy/Cover Note No.:	B27572562SMP (Comprehensive) Coverage: 01/09/2018 - 31/08/2019
		Excess:	S\$750.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Ong Chin Kiat - 6594 2558]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/10/2018]		
Driver/Custodian:	HO THIAM GUAN (39 / Male), NRIC: S7836289H, Tel: +6596467856		
Adj Asg. Remarks:	Car in, pls revert. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (03/10/2018): Alert - Adj Mandate Revoked - SJY8225R - Claim Handler: Ong Chin Kiat

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)




Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									
































Claim Documents

































***SJY8225R (570987)**
OD
Sep 20 2018 7:00PM
[HO THIAM GUAN]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter







View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/09/18 12:58	Accident Statement	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/18 17:49	Adjuster Immediate Advice	 Load HTM	
2	27/09/18 10:57	Adjuster Immediate Advice	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/09/18 14:42	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 14:42	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
4	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
5	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
6	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
7	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
8	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
9	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
10	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
11	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
12	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
13	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
14	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
15	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
16	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
17	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
18	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
19	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
20	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
21	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
22	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
23	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
24	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
25	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
26	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
27	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
28	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
29	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
30	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>
31	27/09/18 14:42	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
32	27/09/18 14:42	General View	 Load JPG	✓
33	27/09/18 14:42	General View	 Load JPG	✓
34	27/09/18 14:42	General View	 Load JPG	✓
35	27/09/18 14:42	General View	 Load JPG	✓
36	27/09/18 14:42	General View	 Load JPG	✓
37	27/09/18 14:42	General View	 Load JPG	✓
38	27/09/18 14:42	General View	 Load JPG	✓
39	27/09/18 14:42	General View	 Load JPG	✓
40	27/09/18 14:42	General View	 Load JPG	✓
41	27/09/18 14:42	General View	 Load JPG	✓
42	27/09/18 14:42	General View	 Load JPG	✓
43	27/09/18 14:42	General View	 Load JPG	✓
44	27/09/18 14:42	General View	 Load JPG	✓
45	27/09/18 14:42	General View	 Load JPG	✓
46	27/09/18 14:42	General View	 Load JPG	✓
47	27/09/18 14:42	General View	 Load JPG	✓
48	27/09/18 14:42	General View	 Load JPG	✓
49	27/09/18 14:42	General View	 Load JPG	✓
50	27/09/18 14:42	General View	 Load JPG	✓
51	27/09/18 14:42	General View	 Load JPG	✓
52	27/09/18 14:42	General View	 Load JPG	✓
53	27/09/18 14:42	General View	 Load JPG	✓
54	27/09/18 14:42	General View	 Load JPG	✓
55	27/09/18 14:42	General View	 Load JPG	✓
56	27/09/18 14:42	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/09/18 10:30	COE PARF - SJY8225R	 Load PDF	
2	24/09/18 10:30	Estimate	 Load PDF	
3	24/09/18 10:30	TP GU5434E GIA Report	 Load PDF	
4	24/09/18 10:36	email from workshop to arrange OD survey	 Load PDF	
5	02/10/18 17:57	Signed DV	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/09/18 14:39	ESTIMATE.pdf	 Load PDF	
2	04/10/18 12:10	LTA REBATE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser ▼
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/09/18 12:58	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/09/18 12:54	Accident Photo	 Load JPG	✓
2	21/09/18 12:54	Accident Photo	 Load JPG	✓
3	21/09/18 12:54	Accident Photo	 Load JPG	✓
4	21/09/18 12:54	Accident Photo	 Load JPG	✓
5	21/09/18 12:54	Accident Photo	 Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
6	21/09/18 12:54	Accident Photo	 Load JPG	✓
7	21/09/18 12:54	Accident Photo	 Load JPG	✓
8	21/09/18 12:54	Accident Photo	 Load JPG	✓
9	21/09/18 12:54	Accident Photo	 Load JPG	✓
10	21/09/18 12:54	Accident Photo	 Load JPG	✓
11	21/09/18 12:54	Accident Photo	 Load JPG	✓
12	21/09/18 12:54	Accident Photo	 Load JPG	✓
13	21/09/18 12:54	Accident Photo	 Load JPG	✓
14	21/09/18 12:54	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/09/18 12:52	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18017341/T1SD3S2

Date: 04/10/2018

REFERENCE

Insured/Claimant:	HO THIAM GUAN	Policy No:	B27572562SMP	
Date of Loss:	20/09/2018	Nature of Claim:	OD	Claim No: 570987

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY8225R		
Make & Model:	BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)	Engine No:	B4620553N20B20B
Reg. Date:	30/08/2013 (Man. Year: 2013)	Chassis No:	WBA5A32050D333558
Colour:	White	Odometer:	89783 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$92,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	285/30R20	Rear Tyre Size:	285/30R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,210.25	8,400.50	5,809.75	40.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,920.00	7,151.00	3,769.00	34.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,130.25	15,551.50	9,578.75	38.12
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	24,380.25	14,801.50	9,578.75	39.29
+ GST 7.00/7.00% (S\$)	1,706.62	1,036.11	670.51	39.29
Nett Amount (S\$)	26,086.87	15,837.61	10,249.26	39.29

INSPECTION

Date of Assignment:	24/09/2018	
Date Inspected:	24/09/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	0.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(EXCLUDE CHECK ITEMS S\$7,377.95 NETT)

TOTAL LOSS ASPECT

Market Value :	\$92,000.00
OMV :	\$47,458.00
PARF Rebate (1) :	\$37,409.00
Quota Premium Paid :	\$79,223.00
COE Rebate (2) :	\$37,768.00
Total Rebate (1) + (2) = :	\$75,177.00

The total amount incurred will be Market Value \$92,000.00 minus Total Rebate \$75,177.00 = \$16,823.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2018)

Parts: 143 BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJY8225R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CHARGE AIR COOLER	*Check	609.75 FS	*- FS
2	1		*RADIATOR	*Check	1,030.95 FS	*- FS
3	1		*FRT LH FENDER	Repair	863.35 FS	*- FS
4	1		*BONNET	Bent	2,224.70 FS	*2,224.70 FS
5	1		*SET MOUNTS PDC SENSOR FRT (PDC)	*Check	58.60 FS	*- FS
6	1		*FRT LH BOTTOM DEFORMATION ELEMENT	*Check	101.70 FS	*- FS
7	1		*FRT RH BOTTOM DEFORMATION ELEMENT	*Check	101.70 FS	*- FS
8	1		*FRT BUMPER CARRIER	*Check	684.75 FS	*- FS
9	1		*FRT BUMPER BOTTOM MOUNT	*Check	157.50 FS	*- FS
10	1		*FRT BUMPER LH SPACER	Necessary	9.45 FS	*9.45 FS
11	1		*FRT BUMPER RH SPACER	Necessary	9.45 FS	*9.45 FS
12	1		*SUPPORT	*Check	16.60 FS	*- FS
13	1		*GRILLE AIR INLET MIDDLE	*Check	80.65 FS	*- FS
14	1		*LH OPEN GRILLE AIR INLET (LINES)	*Check	80.00 FS	*- FS
15	1		*FRT SHOCK ABSORBER	*Check	48.00 FS	*- FS
16	1		*FRT BUMPER LH PROTECTIVE RUBBER STR	*Check	41.15 FS	*- FS
17	1		*FRT BUMPER PANEL PRIMED (PDC)	Deformed	1,277.55 FS	*1,277.55 FS
18	1		*FRT TOWING LUG COVER PRIMED	Not Necessary	46.45 FS	*- FS
19	1		*FRT LH GRILLE (BASIS)	Necessary	120.50 FS	*120.50 FS
20	1		*FRT RH GRILLE (BASIS)	Necessary	120.50 FS	*120.50 FS
21	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
22	1		*LH SUPPORT	*Check	18.40 FS	*- FS
23	1		*RH SUPPORT	*Check	18.40 FS	*- FS
24	1		*CONNECTION TOP FRT	*Check	159.65 FS	*- FS
25	1		*CONNECTION TOP REAR	*Check	197.30 FS	*- FS
26	1		*LH HEADLAMP SUPPORT	*Check	126.10 FS	*- FS
27	1		*AIR DUCT	Cracked	293.50 FS	*293.50 FS
28	1		*AIR DUCT BRAKE LH	*Check	51.50 FS	*- FS
29	1		*SEAL BONNET REAR	Necessary	29.35 FS	*29.35 FS
30	1		*FRT LH LOCATOR SEAL	*Check	55.80 FS	*- FS
31	1		*SEAL ENGINE BONNET FRT	Necessary	42.30 FS	*42.30 FS
32	1		*LH HEADLIGHT LED TECHNOLOGY	Cracked	4,203.70 FS	*4,203.70 FS
33	1		*CONDENSER AIR CONDITIONING	*Check	1,028.45 FS	*- FS
34	1		*FRONT EMBOSS NUMBER PLATE	*Check	83.00 FS	*- FS
35	1		*SUNDRIES	*Check	150.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,210.25 8,400.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT BUMPER, FRT SUPPORT, FRT V-STRUT, CARRIER, REINFORCEMENT, BOTH GRILLE & ALL ATTACHMENTS CAUSE BY ACCIDENT.	New	4,250.00	3,400.00
2	PAINTING ON FRT BUMPER, FRT BONNET & FRT LEFT SIDE PANEL.	New	3,221.00	2,898.00
3	TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING TO CONDUCT PRESSURE TEST, BLEED BLEED COOLING SYSTEM AND CHECK FOR LEAK. (*Check)	New	826.00	0.00
4	TO REPLACE CHARGE AIR COOLER INCLUDING CONDUCT CHECKS FOR LEAK AND PROPER FUNCTION. (*Check)	New	531.00	0.00
5	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK. (*Check)	New	1,003.00	0.00
6	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION.	New	177.00	150.00
7	TO REPLACE LEFT HEADLIGHT.	New	481.00	408.00
8	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL) BONNET.	New	118.00	100.00
9	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL) FRONT LFT SIDE PANEL. (*Check)	New	118.00	0.00
10	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.	New	195.00	195.00
Gross Labour Cost (S\$)			10,920.00	7,151.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >