

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 25 Sep 2018

Preliminary Advice

Vehicle No	: SJY8225R	Accident Date	: 20/09/2018
Make	: BMW 520I	Policy No.	: B27572562SMP
Assignment Date	: 24/09/2018	Excess	: S\$750.00
Date of Inspection	: 24/09/2018	Est. Duration of Repair	: 7 - 8 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,130.25
Revised Amount	:S\$	15,551.50
Check Items (Estimated)	:S\$	7,377.95
Total	:S\$	22,929.45

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	75,177.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,823.00

Remarks

() The vehicle is economical/not economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

(X) Other Comments : WE ARE STILL PENDING REPAIR COST FROM REPAIRER