

ASS. REC. BY:

REF:

CS/C118017344/ 4qdz<sup>m</sup>

Special Instruction:

Surveyor:  
reiner

Marku

ASSIGNMENT (Office)

From (Person):

Janyu Tay

of

C11

Date/Time:

24/9/18 @ 3:30pm

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 9956M

Insured:

SKB1410C

at Workshop in/

Think One Autocare

Tel:

9128 6488

of

No. 18 Defu Ave 2

Policy No:

DMPCSN3045861700

Claim No:

SNM18D04563C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/09/18

25/09/18 @ 10:30am

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

4:30pm @ 24/9/18

Person Contacted:

Karen

Vehicle-IN/OUT

Date/Time

Action/Instruction (✓) Estimate

PA 9956M - X

SKB1410C - NA / INC / 5010010 / h4

D.O.A. 13/6/15

Surveyor

REF:

CT1

# ASSIGNMENT

From:

Date:

25/11/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

PA 9956M

at Workshop m/s

Think One Auto

of

No. 18 Defu Ave 2

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10:30 am @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>up</sup>

LTA 7520

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

PA9956M

Yr Regn:

1/1/0

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Regns

Make:

Toyota

c.c 2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp Reading

400302

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDH 221000 2558

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-12-5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/9/18

D.O.I.

25/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

8/10/18

Confirmed H/S. # 1800 with driver. Used \$ 19186.75, 91%

RECEIVED 09 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 09/10 turist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Report Format :

UIC-TP

Lump Sum / I.B. (\$)

1800

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. SI

Photos

Others

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18017344/Uqd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 24-09-2018		
		Code : CTI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKB 1410C	Veh. Inspected	PA 9956M	
Policy No.	DMPCSN3045861700	Coverage (\$)	0.00	
Claim No.	SNM18D04563C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	24/09/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	19/09/2018	Inspection Date	25/09/2018	
Survey held at	THINK ONE AUTOCARE PTE LTD NO.18 DEFU AVENUE 2 SINGAPORE 539522			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2018		24 Sep 2018 15:31 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LOH HAK KENG, ID: S0244470D		
Main Claimant:	THINK ONE LEASING PTE LTD, Co. Reg. No.: 201115609M		
Vehicle Reg. No.:	PA9956M	Date of Loss:	19/09/2018 18:00 - :59
Claim Type:	TP / SNM18D04563C02	Policy/Cover Note No.:	DMPCSN3045861700 (Comprehensive)
Vehicle Reg. No. (Insured):	SKB1410C	Policy No. (Claimant):	5062480296-05
		Excess:	S\$0.00
Repairer:	Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2, 539522 Ubi - Tel: 68443300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/10/2018]		
Driver/Custodian (Insured):	LOH HAK HENG (66 / Male), NRIC: S0244470D, Tel: +6581573963		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/09/2018 11:03
Date Of Accident	19/09/2018 18:30
Exact Location Of Accident	ANG MO KIO AVE 8
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PA9956M
Insured/Policyholder	
Name Of Registered Owner	THINK ONE LEASING PTE LTD
Co Reg No	201115609M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96788288
Alternative Phone No	OFFICE-65553300

### Vehicle Particulars

Manufacturer	TOYOTA
Model	REGIUS ACE-3.0 D DX (A)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	5062480296-05
Cover Note Number	

### Driver

Name of Driver	MOHAMAD JANI BIN SAIYADI
NRIC No	S1688727G
Date Of Birth	31/10/1965
Occupation	OUTDOOR
Date Of Driving Pass	27/11/1991
Driving Experience	26 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90959481
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address

APT BLK 633 ANG MO KIO AVENUE 6 #06-5157

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions RAINING  
Road Surface WET

### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

### Circumstances of Accident

ON THE 19.09.2018 AT ABOUT 1630HR. MY VEHICLE PA9956M WAS STATIONERY AT THE LOADING & UNLOADING BAY AWAIT FOR THE FRONT BUS TO MOVE OFF, ALSO UNSURE HOW THE VEHICLE OF SKB1410C COLLIDE AT MY REAR RIGHT PORTION OF MY VEHICLE. NO INJURIES INCURRED IN THIS ACCIDENT. AT THAT TIME OF POINT I HAVE 13 PASSENGER ONBOARD. I DONT HAVE THE NAME LIST.


### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKB1410C  
Vehicle Make/Model/Colour  
Details Of Properties VEHICLE B  
Vehicle Category PRIVATE CAR  
Name of Driver LOH HAK KENG VINCENT  
NRIC/Passport Number S0244470D  
Contact Number 81573963  
Address BLK 821 YISHUN STREET 81  
#04-624  
Postcode 760821  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 19.9.2018 at about 1630HR. My vehicle PA9956M was stationery at the loading & unloading bay await for the front bus to move off, also unsure how the vehicle of SKB1410C collide at my rear Right Portion of my vehicle. No injuries incurred in this accident. At that time of point. I have 13 passengers onboard. I don't have the name list.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Think One Autocare Pte Ltd  
18 Dery Lane, Avenue 2  
Singapore 539522  
Tel: 6342 8800 Fax: 6342 4988  
Name:  
NRIC/FIN No.:



## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5609M

## Vehicle Details

Vehicle No.:	PA9956M
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	REGIUS ACE 3.0DX A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1KD1789151
Chassis No.:	KDH2210002558
Maximum Power Output:	-
Open Market Value:	\$39,827.00
Original Registration Date:	16 Nov 2010
First Registration Date:	16 Nov 2010
Transfer Count:	1
Actual ARF Paid:	\$1,992.00

## Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

## Intended COE Rebate Details

COE Expiry Date:	15 Nov 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,002.00
COE Rebate Amount:	\$7,520.00
<b>Total Rebate Amount:</b>	<b>\$7,520.00</b>

The information contained herein is correct as at 25 Sep 2018

OK



4/5 \$1800  
Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

Not Allowed  
25/3/18  
4/5 \$1800  
thrupt. Alway  
4/5

PA9956M Toyota Regius Ace 3.0

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>DS 687.40</i>	\$ 1,660.00
2	2	Rear bumper bracket <i>11</i>	\$ 172.00 <i>X</i>
3	1	Rear bumper inner beam <i>NS</i>	\$ 287.00 <i>X</i>
4	1	Rear tailgate assy <i>6.500 n/c</i>	\$ 2,662.00 <i>X</i>
5	1	Rear tailgate lock mechanism <i>11</i>	\$ 266.00 <i>X</i>
6	1	Rear tailgate lock catch <i>11</i>	\$ 65.00 <i>X</i>
7	2	Rear tailgate hinges <i>11</i>	\$ 166.00 <i>X</i>
8	2	Rear tailgate damper <i>11</i>	\$ 375.00 <i>X</i>
9	1	Rear tailgate weatherstrip <i>11</i>	\$ 288.00 <i>X</i>
10	1	Rear tailgate inner board <i>11</i>	\$ 190.00 <i>X</i>
11	1	Rear tailgate centre logo <i>11</i>	\$ 68.00 <i>X</i>
12	1	Rear tailgate windscreen glass moulding <i>NS</i>	\$ 295.00 <i>X</i>
13	1	Rear tailgate lock actuator <i>11</i>	\$ 189.00 <i>X</i>
14	1	Rear tailgate outer garnish <i>11</i>	\$ 176.00 <i>X</i>
15	1	Rear tailgate lock cylinder <i>11</i>	\$ 191.00 <i>X</i>
16	1	Rear left taillamp <i>11</i>	\$ 885.00 <i>X</i>
17	1	Rear right taillamp <i>310 387.50</i>	\$ 885.00 <i>✓</i>
18	1	Rear left taillamp lower panel <i>11</i>	\$ 109.00 <i>X</i>
19	1	Rear right taillamp lower panel <i>cut</i>	\$ 109.00 <i>✓</i>
20	1	Rear right fender panel assy <i>11</i>	\$ 6,800.00 <i>X</i>
21	1	Rear end lower panel <i>11</i>	\$ 1,275.00 <i>X</i>
22	1	Rear spare tyre carrier <i>11</i>	\$ 376.00 <i>X</i>
23	1	Rear wiper blade assy <i>11</i>	\$ 166.00 <i>X</i>
24	1	Rear wiper motor assy <i>11</i>	\$ 476.00 <i>X</i>
25	1	Rear exhaust muffler assy <i>11</i>	\$ 2,400.00 <i>X</i>
26	2	Rear exhaust muffler rubber mounting <i>11</i>	\$ 38.00 <i>X</i>
			\$ 20,569.00
Less 25%			\$ 5,142.25
			\$ 15,426.75

7-1183.90  
887.92

Special Nett Items

1	10	Rear bumper clips <i>11</i>	\$ 50.00 <i>✓</i>
2	12	Rear tailgate inner board clips <i>11</i>	\$ 30.00 <i>X</i>
3	4	Rear tailgate outer garnish clips <i>11</i>	\$ 20.00 <i>X</i>
4	1	Rear tailgate '70km/h' sticker <i>11</i>	\$ 30.00 <i>X</i>
5	1	Rear windscreen glass sealant <i>11</i>	\$ 80.00 <i>X</i>
6	1	Rear blind spot mirror <i>11</i>	\$ 450.00 <i>X</i>
7	1	Rear right fender panel sealant <i>11</i>	\$ 80.00 <i>X</i>
8	1	Rear bumper reverse sensor <i>11</i>	\$ 250.00 <i>X</i>
9	1	Rear no plate <i>11</i>	\$ 80.00 <i>X</i>
			\$ 1,070.00

**Total Parts**

**\$ 16,496.75**

**Think One Autocare Pte Ltd**  
**No.18 Defu Avenue 2**  
**Singapore 539522**  
**Tel: 6844 3300 Fax: 6842 4988**

**PA9956M Toyota Regius Ace 3.0**

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,800.00 650
2	To putty and spray painting rear portion.	\$ 1,800.00 400
3	To check rear lighting and wiring.	\$ 50.00 20
4	To remove and install rear tailgate lock mechanism.	11 \$ 80.00 X
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00 ✓
6	To apply anti rust proofing to rear affected area.	11 \$ 120.00 X
7	To remove and install rear windscreen glass to facilitate the repair.	11 \$ 140.00 X
8	To remove and install rear bumper reverse sensor.	\$ 80.00 40
9	To remove and install rear exhaust muffler assy.	11 \$ 150.00 X
10	Towing service.	11 \$ 120.00 X
<b>Total labour :</b>		<b>\$ 4,490.00</b>

**Total parts : \$ 16,496.75**

**Total labour : \$ 4,490.00**

**Total repair cost : \$ 20,986.75**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118017344/UQD3N2

Date: 10/10/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3045861700
Claimant Vehicle No :	PA9956M	Insured Vehicle No :	SKB1410C
Date of Loss:	19/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04563C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	PA9956M	Engine No:	1KD1789151
Make & Model:	TOYOTA REGIUS ACE, 3.0 D DX (A)	Chassis No:	KDH2210002558
Reg. Date:	16/11/2010 (Man. Year: 2008)	Odometer:	400302 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,496.75	937.92	15,558.83	94.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,490.00	1,340.00	3,150.00	70.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>20,986.75</b>	<b>2,277.92</b>	<b>18,708.83</b>	<b>89.15</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,800.00</b>		
<b>(\$\$)</b>	<b>20,986.75</b>	<b>1,800.00</b>	<b>19,186.75</b>	<b>91.42</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,469.07</b>	<b>126.00</b>	<b>1,343.07</b>	<b>91.42</b>
<b>Nett Amount (\$\$)</b>	<b>22,455.82</b>	<b>1,926.00</b>	<b>20,529.82</b>	<b>91.42</b>

## INSPECTION

Date of Assignment:	24/09/2018	
Date Inspected:	25/09/2018	Inspected At:

Think One Autocare Pte Ltd (HQ)  
No. 18 Defu Avenue 2  
Singapore 539522

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source:	(Last Synchronised: 10 Oct 2018)
Parts:	N/A TOYOTA REGIUS ACE 3.0 D DX (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA9956M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Distorted	1,660.00 FL	*687.40 FL
2	2		*REAR BUMPER BRACKET	Not Necessary	172.00 FL	*- FL
3	1		*REAR BUMPER INNER BEAM	No such part	287.00 FL	*- FL
4	1		*REAR TAILGATE ASSY (BADLY DENTED)	Not Consistent With The Impact	2,662.00 FL	*- FL
5	1		*REAR TAILGATE LOCK MECHANISM	Not Necessary	266.00 FL	*- FL
6	1		*REAR TAILGATE LOCK CATCH	Not Necessary	65.00 FL	*- FL
7	2		*REAR TAILGATE HINGES	Not Necessary	166.00 FL	*- FL
8	2		*REAR TAILGATE DAMPER	Not Necessary	375.00 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	288.00 FL	*- FL
10	1		*REAR TAILGATE INNER BOARD	Not Necessary	190.00 FL	*- FL
11	1		*REAR TAILGATE CENTRE LOGO	Not Necessary	68.00 FL	*- FL
12	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	295.00 FL	*- FL
13	1		*REAR TAILGATE LOCK ACTUATOR	Not Necessary	189.00 FL	*- FL
14	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	176.00 FL	*- FL
15	1		*REAR TAILGATE LOCK CYLINDER	Not Necessary	191.00 FL	*- FL
16	1		*REAR LEFT TAILLAMP	Not Necessary	885.00 FL	*- FL
17	1		*REAR RIGHT TAILLAMP	Broken	885.00 FL	*387.50 FL
18	1		*REAR LEFT TAILLAMP LOWER PANEL	Not Necessary	109.00 FL	*- FL
19	1		*REAR RIGHT TAILLAMP LOWER PANEL	Cut	109.00 FL	*109.00 FL
20	1		*REAR RIGHT FENDER PANEL ASSY	Repair	6,800.00 FL	*- FL
21	1		*REAR END LOWER PANEL	Repair	1,275.00 FL	*- FL
22	1		*REAR SPARE TYRE CARRIER	Not Necessary	376.00 FL	*- FL
23	1		*REAR WIPER BLADE ASSY	Not Necessary	166.00 FL	*- FL
24	1		*REAR WIPER MOTOR ASSY	Not Necessary	476.00 FL	*- FL
25	1		*REAR EXHAUST MUFFLER ASSY	Not Necessary	2,400.00 FL	*- FL
26	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	38.00 FL	*- FL
27	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
28	12		*REAR TAILGATE INNER BOARD CLIPS	Not Necessary	30.00 FS	*- FS
29	4		*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
30	1		*REAR TAILGATE 70KM/H STICKER	Not Necessary	30.00 FS	*- FS
31	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
32	1		*REAR BLIND SPOT MIRROR	Not Necessary	450.00 FS	*- FS
33	1		*REAR RIGHT FENDER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
35	1		*REAR NO PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 21,639.00 1,233.90  
 - List Item Discount on L Items 25.00/25.00% (S\$) 5,142.25 295.98

Total Parts (S\$) 16,496.75 937.92

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	-------------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,800.00	650.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,800.00	480.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	-
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	150.00	150.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	-
7	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	-
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	40.00
9	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	150.00	-
10	TOWING SERVICE	New	120.00	-
Gross Labour Cost (\$\$)			4,490.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >