

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1096/2018/GW
Date : 22-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms. Koh Poh Hong
Address : 17 F Jalan Hock Drive
Singapore 538200
Telephone : (HP) 96660018
Type of Claim : Third Party Claims
Policy No. : 2100426879-03
Vehicle No : **SKV 186 B**
Model Code : Audi A1 Sb 1.0 TFSI
Model / Year : Aug-15
Engine No : CHZ 002482
Chassis No : WAUZZZ8X9FB028134
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Allan Wu / Johnny Boo
Accident Date : 20-Sep-18
Place of Accident : Research Link (OPP Innvovation 4.0 BLDG)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 186 B.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N	\$ 280.00	✓
2	To remove and transfer rear boot lid rear wire harness, rear wiper and rear boot lid lock system.	S/N	\$ 360.00	✓
3	To dismantle and renew rear bumper & rear lid. Reorganize rear crash management components. Reinstall all parts removed.		\$ 1,500.00	1000
4	To respray rear boot lid and rear bumper		\$ 1,600.00	1100
5	To install rear windscreen.	S/N	\$ 480.00	✓
6	To remove and renew lhs rear exhaust silencer. Align to position.	S/N	\$ 480.00	X
7	To carry out diagnostic check.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 4,892.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 186 B

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Deformed</i>	\$ 1,281.00	✓
2	REAR BUMPER FIXING PARTS <i>Ne new</i>	\$ 64.00	+
3	REAR BUMPER SPOILER <i>lit</i>	\$ 366.00	✓
4	REAR LIGHT REFLECTOR-LH/RH <i>Ne new</i>	2 \$ 52.00	X
5	REAR BUMPER CARRIER <i>?</i>	\$ 432.00	?
6	REAR BUMPER GUIDE SECTION-LH/RH <i>ne m</i>	2 \$ 84.00	+
7	REAR SILENCER	\$ 600.00	+
8	REAR SILENCER DUAL CLIP	\$ 53.00	+
9	REAR SILENCER BRACKET	\$ 53.00	*
10	REAR SENSOR	2 TBC	+
11	BOOT LID <i>Dented</i>	\$ 2,268.00	✓
12	BOOT LID ATTACHEMENT PARTS <i>?</i>	\$ 246.00	?
13	BALL STUD <i>ne m</i>	\$ 36.00	+
14	ADHESIVE PIECE <i>?</i>	\$ 14.00	✓
15	AUDI EMBLEM <i>per</i>	\$ 83.00	✓
16	TFSI EMBLEM	\$ 83.00	✓
17	REAR WINDSCREEN <i>Ne new</i>	\$ 680.00	X
18	REAR SPOILER REPAIR KIT <i>Ne</i>	\$ 147.00	✓
19	PRIMER <i>Ne</i>	\$ 19.00	✓
20	SUNDRIES <i>?</i>	\$ 500.00	?
TOTAL SPARE PARTS		\$ 7,061.00	
TOTAL LABOUR CHARGES		\$ 4,892.00	
GRAND TOTAL		\$ 11,953.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King.
Surveyed Date : 27/09/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant