

ASSIGNMENT (Office) 28/09/18 ✓

REF C33/MSG18011743/Ggd327

From (Person): Chhia Nyuk Pui of MSG Date/Time: 27/09/18 @ 4:42pm

Estimated Cost: Bill to

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: FBH 636A Insured: SGL 8435E

at Workshop n/a: Tai Hin Enterprise Tel: 8380 2233

of: 10 Kuki Bldg Rd 2 # 0/- 16

Policy No: A29 026313 QMX Claim No: 562474

Sum Insured: Excess:

Make of Veh: D.O.A 19/06/2018

Client's Record: 28/06/2018

CA / REV / REP. / REV 24 HRS wp

Date/Time: 5:35pm @ 27/6/18 Person Contacted: Jacky H.O.D. Endorsement: Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	FBH 636A - NA/INC 18011743/24	D.O.A 19/06/2018
	SGL 8435E - NA/INC 18011743/24	D.O.A 19/06/2018

- Advise Margin Repair value

Margin Repair value 3K

Repair days 85

Note, \* MV: 666471 ; CTB 713 ; NV: 5287.

LY \$ 4000, 5 days.

UPED \$ 4000, 50%.)

TG Lim

Lim

11/10/18

RECEIVED 11 OCT 2018

MSD  
Merimen

REF: msln

ASSIGNMENT

From: Date: 28062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBH 636A

at Workshop m/s

Tai Hin

of 10 Kaki Bukit Rd 2 # 01-16

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$6000

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Date / Time

Action / Instruction

\$3000 - \$4000

29/6/18

Submit PRS Report

Date/Time: File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1 - 5 - 10 - 15

Photos

Notes

1

2018

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

120

10

130

Veh No:

FBH 636A

Yr Regn:

27 Feb 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Runner

Make:

Piaggio Gilera c.c. 198

Colour:

Black

A/C

Insured / Std / NI / NA

Sp. Reading

80657

T/Radio: Insured / Std / NI / NA

Eng/No.

C/No:

ZAPM 4640100007045

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size:

F:

120/80-14

R:

140/60-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

28-06-18

Survey held at

w/s

3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

ant.

The U/C / Chassis frame / Body Structure affected due to collision.

## Nivitha (LKK Auto)

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Monday, 24 September 2018 5:59 PM  
**To:** Chhia Nyuk Pui; SUR; assignments  
**Cc:** Veron Chen (LKKAuto)  
**Subject:** RE: Our ref: 562474

Dear Nyuk Pui,

Thank you for the email.

Dear Assignment Team,

FYNA.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chhia Nyuk Pui <NyukPui\_Chhia@sg.msig-asia.com>  
**Sent:** Monday, 24 September 2018 4:32 PM  
**To:** SUR <sur@lkkauto.com>  
**Cc:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Our ref: 562474

Dear LKK

**\*FBH636A (562474). [SGL8435E]**

Please do a paper re for us and advise us the margin repair value.

We have sent back via Merimen.

Thanks.

Chhia Nyuk Pui  
Senior Executive, Claims Services  
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | [nyukpui\\_chhia@sg.msig-asia.com](mailto:nyukpui_chhia@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | [www.msig.com.sg](http://www.msig.com.sg) | Follow us on @MSIG\_SG

A member of **MS&AD** INSURANCE GROUP

---

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

CHIA S ARUL LLC  
ADVOCATES & SOLICITORS  
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS



Our ref: AS.181694.rm

Your ref: To be advised

10 SEP 2018

MSIG Insurance (S) Pte Ltd  
16 Raffles Quay  
#24 - 01 Hong Leong Building  
Singapore 048581

BY PDX

CHONG KHIAM KIAT  
324C SENGKANG EAST WAY  
#15-603  
SINGAPORE 543324

BY CERTIFICATE OF  
POSTING

Dear Sirs,

ACCIDENT INVOLVING FBH 636A & SGL 8435E ALONG JUNCTION OF  
COMPASSVALE STREET AND PUNGGOL ROAD ON 19 JUNE 2018

We refer to the above matter.

We act for MUHAMMAD HAMDAN BIN DUL JALIL, the owner of motor vehicle FBH 636A involved in the captioned accident.

We were instructed by our client to claim damages against you in connection with a road traffic accident along JUNCTION OF COMPASSVALE STREET AND PUNGGOL ROAD ON 19 JUNE 2018 involving our client's motor vehicle FBH 636A and your motor vehicle SGL 8435E driven by you at the material time.

We are instructed that the accident was caused by your negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

a)	Costs of Repairs	S\$ 8,000.00
b)	GIA Report	S\$ 29.00
c)	Survey Report fee	S\$ 745.00
d)	Towing fee	S\$ 40.00
e)	Loss of Use (12days x \$50)	S\$ 600.00
e)	Costs	S\$ 2,000.00
	Total	S\$ 11,414.00

A copy of each of the following supporting documents is enclosed.

- a) copy of our client's GIA report;
- b) copy of the LTA search;
- c) copy of the Final repair bill; and
- d) copy of the survey report, invoice and photographs of our client's motor vehicle.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,

  
MR ARULCHELVAN S

Enclosure(s)

Seidling NPO  
Notsturm Katze

# MOTO 51 PTE LTD

Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : moto51@n51.com.sg  
Company Reg. No. : 201536417C

MUHAMMAD HAMDAN BIN DUL JALIL  
BLK 862 TAMPINES ST 83 #04-406  
SINGAPORE 520862

Contact : 67858609 91159643, 85990432

## TAX INVOICE

Date : 21/08/2018

Date in : 23/06/2018

Vehicle Num. : FBH636A

Make/Model : PIAGGIO GILERA RUNNER ST 200-2012

Chassis/Eng# : ZAPM4640100007045/M464M0010382

Accident Date : 19/06/2018

Claim No : CLM13298

Reference : JUNE-04/2018

Policy No. : 5086035319-01 (17/03/2019)

LUMPSUM REPAIR BILL  
AS PER SURVEYOR REPORT  
REF : CAS/18-07/044 DATED 25/06/2018  
BY CONSTANT APPRAISER SERVICES

Amount S\$

8,000.00



E. & O.E. Sub S\$ : 8,000.00

Total Amount S\$ : 8,000.00

for MOTO 51 PTE LTD



# AUTOBAY TOWING

1 Kaki Bukit Avenue 6  
#01-55 AutoBAY @ Kaki Bukit  
Singapore 417883  
Tel: 9015 8686 (Ah Boon)

## CASH SALE

No. \_\_\_\_\_

Date: 23/6/18

Sold to: clm 13298 FBH 636A

CROWN

Item	Quantity	Description	Unit Price	Amount
		Auto Hub to V6: DAC		<del>1</del> 40
		Repairing		1
E. & O. E.			Sub Total :	
			GST Tax :	
			Total :	<del>1</del> 40

Issued by: \_\_\_\_\_

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## INVOICE

To: Muhammad Hamdan Bin Dul Jalil  
c/o 2 Kaki Bukit Ave 2  
#01-17 Kaki Bukit Autohub  
Singapore 417921

Date : 17/07/2018

Invoice No : IV18-07044/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle FBH 636A (Inclusive Of Photographs And Transport Charges)  Our reference : CAS/18-07/044	\$745.00
Total	\$745.00

E. & O.E

**Constant Appraiser Services**



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## Automobile Inspection Report

To: Muhammad Hamdan Bin Dul Jalil  
c/o 2 Kaki Bukit Ave 2  
#01-17 Kaki Bukit Autohub  
Singapore 417921

Date : 17/07/2018

Reference No : CAS/18-07/044

### General Information

Registration No. : FBH 636A  
Accident Date : 19/06/2018

### Particulars of Damaged Vehicle

Colour	: Black	Make & Model	: Piaggio Gilera Runner ST200
Engine Capacity	: 198 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 80657	Engine No.	: M464M0010382
Chassis No.	: ZAPM4640100007045	Steering	: Affected
Registration Date	: 27/02/2013	Brake	: In Order

### Tyre Condition

	Size	Make	Balance
Front Tyre	120/70R14	MICHELIN	90%
Rear Tyre	140/60R13	MICHELIN	90%

### Inspection

Repairer : Moto 51 Pte Ltd  
2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921

### Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$10,752.60  
Revised Amount : \$8,000.00  
Less Excess : -  
Nett Total : \$8,000.00

### Remarks

- (A) Survey was done on 25/06/2018
- (B) Re-survey was done on 28/06/2018
- (C) Re-survey after repair was done on 12/07/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

**Constant Appraiser Services**

Vehicle No : FBH 636A

Our ref : CAS/18-07/044

**Adjustment On Repair Costs And Replacement Of Parts:**

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
		<u>PARTS REPLACEMENT – LIST ITEMS</u>				
1	1pc	Body center cover	Grazed/Broken	269.00	269.00	BT✓
2	1pc	Body lower fairing	Grazed	371.00	371.00	CUT✓
3	1pc	Brake disc	Bent/Warped	280.00	<del>280.00</del>	NNX
4	1pc	Brake lever LH	Serviceable	105.00	-	
5	1pc	Brake lever RH	Grazed	105.00	105.00	CUT
6	1pc	Engine cylinder head	Mounting Broken	1,572.00	<del>1,572.00</del>	NCX
7	1pc	Engine cylinder head gasket	Necessary	220.00	<del>220.00</del>	NCX
8	1pc	Exhaust muffler	Dented/Bent	980.00	980.00	BT✓
9	1pc	Exhaust muffler heat shield	Grazed/Broken	117.00	117.00	BR✓
10	1pc	Exhaust pipe heat shield	Grazed	44.00	<del>44.00</del>	R X
11	2pcs	Fork assy R/L @ \$420.00	Bent/Twisted	840.00	840.00	NN NN NN
12	1pc	Fork bottom bracket	Bent	256.00	256.00	BTX
13	1pc	Front cover	Broken	79.00	79.00	BR✓
14	1pc	Front cover emblem	Necessary	42.00	42.00	NEC
15	1pc	Front cowl	Grazed	218.00	218.00	CUT
16	1pc	Front cowl inner garnish	Grazed/Broken	313.00	313.00	BR✓
17	1pc	Front fender	Grazed	113.00	<del>113.00</del>	CUT R X
18	1pc	Front signal LH	Serviceable	98.00	-	
19	1pc	Front signal RH	Grazed	98.00	98.00	SCR✓
20	1pc	Front wheel rim	Dented/Warped	441.00	<del>441.00</del>	NN NEC
21	1pc	Front wheel rim shaft	Bent	65.00	65.00	BT✓
22	1pc	Handle bar	Bent	189.00	189.00	BT✓
23	1pc	Handle bar cover inner	Serviceable	98.00	-	
24	1pc	Handle bar cover outer	Broken	115.00	115.00	BR✓
25	1pc	Headlamp assy	Serviceable	286.00	-	
26	1pc	Mirror RH	Grazed	152.00	<del>152.00</del>	NN;
27	1pc	Passenger hand grip RH	Serviceable	110.00	-	
28	1pc	Rear mudguard reflector	Necessary	31.00	31.00	NEC
29	1pc	Rear mudguard	Grazed/Deformed	161.00	161.00	BT✓
30	2pcs	Rear side cover R/L @ \$192.00	Grazed/Broken	384.00	384.00	CUT✓
31	2pcs	Rear signal R/L @ \$67.00	Serviceable	134.00	-	
32	1pc	Rear step RH	Grazed	86.00	86.00	BT✓
33	2pcs	Side fairing R/L @ \$155.00	Grazed/Broken	310.00	310.00	CUT✓

**Constant Appraiser Services**

Vehicle No : FBH 636A

Our ref : CAS/18-07/044

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
		<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>				
34	1pc	Step board plate RH	Grazed/Twisted	91.00	91.00	BT✓
35	1pc	Step board RH	Grazed	171.00	171.00	SCR✓
		Less 10%		8,944.00 (894.40)	8,113.00 (811.30)	
		Sub total		8,049.60	7,301.70	
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>				
1	1set	Emblem set	Necessary	144.00	<del>144.00</del> 120	NEC✓
2	1pc	Engine oil	Necessary	45.00	<del>45.00</del>	NN✓
3	2pcs	Fork oil seal R/L @ \$32.00	Necessary	64.00	<del>64.00</del> 50	} NEC
4	1pc	Front no plate	Necessary	25.00	<del>25.00</del> 20	
5	1set	Front wheel rim bearing set	Necessary	62.00	<del>62.00</del> 50	
6	1set	Handle bar balancer set	Grazed	98.00	<del>98.00</del> 70	cut✓
7	1set	Handle bar grip set	Serviceable	72.00	-	
8	1pc	Rear no plate	Serviceable	25.00	-	
9	1pc	Steering corn/bearing	Necessary	158.00	<del>158.00</del> 120	NEC✓
		Sub total		8,742.60	7,897.70	
		<u>LABOUR &amp; MISC. CHARGES</u>				
1		To remove, reinstall electrical wiring harness, check lighting. (to FR)		60.00	30.00	
2		To remove, install engine with transmission. (to FR)		350.00	<del>250.00</del>	NNX
3		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident		700.00	<del>600.00</del> 400.00	
4		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		500.00	<del>350.00</del> 200.00	
5		To Straighten body frame to the original position		400.00	<del>300.00</del> 100.00	
		Grand total		10,752.60	9,427.70	
Recommended cost of lump sum repair (To its pre-accident condition)					8,000.00	

**Constant Appraiser Services**

Vehicle No : FBH 636A

Our ref : CAS/18-07/044

**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$8,000.00** on a contractual basis. Under normal circumstances, the repair period would be about **12 (Twelve)** working days.

Yours faithfully,

**Constant Appraiser Services**



Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA

Repair days 85

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jun 2018		27 Jun 2018 16:42 <a href="#">Edit Adj Rpt</a>	<b>S\$4,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>CHONG KHIAM KIAT</b> , ID: S7523552F, Tel: +6593658293, Email: chong_khiam_kiat@moe.edu.sg								
Main Claimant:	<b>MUHAMMAD HAMDAN BIN DUL JALIL</b> , ID: S9106328Z								
Vehicle Reg. No.:	<b>FBH636A</b>	Date of Loss:	19/06/2018 17:00 - :59 [63 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 562474</b>	Policy/Cover Note No.:	A29026313QMX (Comprehensive) Coverage: 28/09/2017 - 27/09/2018						
Vehicle Reg. No. (Insured):	<b>SGL8435E</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Tai Hin Enterprise Co (KAKI BUKIT)</b> 10 KAKI BUKIT ROAD 2, #01-16 FIRST EAST CENTRE, 417868 Kaki Bukit - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 26/09/2018]								
Driver/Custodian (Insured):	CHONG KHIAM KIAT (42 / Male), NRIC: S7523552F, Tel: +6593658293								
Adj Asg. Remarks:	Liability is 100% head to rear. TP reject our SJE list. Proceed to appoint LKK as the SJE. Pls contact Mr Jacky Siah at 8380 2233.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (24/09/2018): Report Send Back Alerts - FBH636A (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBH636A (562474)  
[SGL8435E]  
TP  
MUHAMMAD HAMDAN BIN DUL JALIL  
Jun 19 2018 5:00PM  
[CHONG KHIAM KIAT]  
Tai Hin Enterprise Co

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)












**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	27/06/18 11:07	<b>Accident Statement</b> <small>From: SC - Reg. No: SGL8435E, Claimant: CHONG KHIAM KIAT</small>	Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
2	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
3	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
4	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
5	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
6	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
7	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
8	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
9	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
10	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
11	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
12	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
13	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
14	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
15	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
16	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
17	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
18	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
19	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
20	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
21	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
22	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
23	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
24	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
25	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
26	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
27	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
28	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
29	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
30	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
31	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	
32	29/06/18 16:11	General View	Load JPG	<input checked="" type="checkbox"/>	



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/06/18 11:07	<b>FBH636A GIA Rpt</b> From: SC - Reg. No: SGL8435E, Claimant: CHONG KHIAM KIAT	 Load PDF	
2	27/06/18 11:08	<b>Email frm TP - PRI</b>	 Load PDF	
3	27/06/18 11:08	<b>PRI</b>	 Load PDF	
4	24/09/18 14:16	<b>LOD &amp; SUPPORTING DOCUMENTS PART 1</b>	 Load PDF	
5	24/09/18 14:16	<b>LOD &amp; SUPPORTING DOCUMENTS PART 2</b>	 Load PDF	
6	24/09/18 14:16	<b>SURVEY REPORT</b>	 Load PDF	
7	24/09/18 14:16	<b>SURVEY PHOTOS PART 1</b>	 Load PDF	
8	24/09/18 14:16	<b>SURVEY PHOTOS PART 2</b>	 Load PDF	
9	24/09/18 14:16	<b>SURVEY PHOTOS PART 3</b>	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/10/18 12:30	<b>COLOUR PHOTO</b>	 Load PDF	
2	15/10/18 12:30	<b>PRS Invoice</b>	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18011743/GQD3E2-1

Date: 15/10/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A29026313QMX

Claimant Vehicle  
No : FBH636A

Insured Vehicle No :

SGL8435E

Date of Loss: 19/06/2018

Nature of Claim:

TP

Claim No: 562474

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH636A**

Make &amp; Model: PIAGGIO GILERA RUNNER, 198cc ST 200

Engine No: M464M0010382

Reg. Date: 27/02/2013 (Man. Year: 2012)

Chassis No: ZAPM4640100007045

Colour: Black

Odometer: 80657 km

Engine Capacity: 198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 120/70-14

Rear Tyre Size:

140/60-13

Front Left Side: Michelin 4 mm

Rear Left Side:

Michelin 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,742.60	4,307.20	4,435.40	50.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	730.00	1,280.00	63.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,752.60</b>	<b>5,037.20</b>	<b>5,715.40</b>	<b>53.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,752.60</b>	<b>4,000.00</b>	<b>6,752.60</b>	<b>62.80</b>

### INSPECTION

Date of Assignment: 27/06/2018

Date Inspected: 28/06/2018 Inspected At:

 Tai Hin Enterprise Co (KAKI BUKIT)  
 10 KAKI BUKIT ROAD 2, #01-16 FIRST  
 EAST CENTRE  
 Singapore 417868

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$6,000.00(EST)-LTA REIMBURSEMENT VALUE: \$713.00=NETT VALUE: \$5,287.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 15 Oct 2018)	
<b>Parts:</b>	N/A	PIAGGIO GILERA RUNNER 198cc ST 200 (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBH636A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY CENTER COVER	Bent	269.00 FL	*269.00 FL
2	1		*BODY LOWER FAIRING	Cut	371.00 FL	*371.00 FL
3	1		*BRAKE DISC	Not Necessary	280.00 FL	*- FL
4	1		*BRAKE LEVER LH	Serviceable	105.00 FL	*- FL
5	1		*BRAKE LEVER RH	Cut	105.00 FL	*105.00 FL
6	1		*ENGINE CYLINDER HEAD (MOUNTING BROKEN)	Not Consistent With The Impact	1,572.00 FL	*- FL
7	1		*ENGINE CYLINDER HEAD GASKET (NECESSARY)	Not Consistent With The Impact	220.00 FL	*- FL
8	1		*EXHAUST MUFFLER	Bent	980.00 FL	*980.00 FL
9	1		*EXHAUST MUFFLER HEAT SHIELD	Broken	117.00 FL	*117.00 FL
10	1		*EXHAUST PIPE HEAT SHIELD	Repair	44.00 FL	*- FL
11	2		*FORK ASSY R/L	Not Necessary	840.00 FL	*- FL
12	1		*FORK BOTTOM BRACKET	Not Necessary	256.00 FL	*- FL
13	1		*FRONT COVER	Broken	79.00 FL	*79.00 FL
14	1		*FRONT COVER EMBLEM	Necessary	42.00 FL	*42.00 FL
15	1		*FRONT COWLING	Cut	218.00 FL	*218.00 FL
16	1		*FRONT COWLING INNER GARNISH	Broken	313.00 FL	*313.00 FL
17	1		*FRONT FENDER	Cut	113.00 FL	*113.00 FL
18	1		*FRONT SIGNAL LH	Serviceable	98.00 FL	*- FL
19	1		*FRONT SIGNAL RH	Scratched	98.00 FL	*98.00 FL
20	1		*FRONT WHEEL RIM	Not Necessary	441.00 FL	*- FL
21	1		*FRONT WHEEL RIM SHAFT	Bent	65.00 FL	*65.00 FL
22	1		*HANDLE BAR	Bent	189.00 FL	*189.00 FL
23	1		*HANDLE BAR COVER INNER	Serviceable	98.00 FL	*- FL
24	1		*HANDLE BAR COVER OUTER	Broken	115.00 FL	*115.00 FL
25	1		*HEADLAMP ASSY	Serviceable	286.00 FL	*- FL
26	1		*MIRROR RH	Not Necessary	152.00 FL	*- FL
27	1		*PASSENGER HAND GRIP RH	Serviceable	110.00 FL	*- FL
28	1		*REAR MUDGUARD REFLECTOR	Necessary	31.00 FL	*31.00 FL
29	1		*REAR MUDGUARD	Bent	161.00 FL	*161.00 FL
30	2		*REAR SIDE COVER R/L	Cut	384.00 FL	*384.00 FL
31	2		*REAR SIGNAL R/L	Serviceable	134.00 FL	*- FL
32	1		*REAR STEP RH	Bent	86.00 FL	*86.00 FL
33	2		*SIDE FAIRING R/L	Cut	310.00 FL	*310.00 FL
34	1		*STEP BOARD PLATE RH	Bent	91.00 FL	*91.00 FL
35	1		*STEP BOARD RH	Scratched	171.00 FL	*171.00 FL
36	1		*SET EMBLEM	Necessary	144.00 FS	*120.00 FS
37	1		*ENGINE OIL	Not Necessary	45.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	2		*FORK OIL SEAL R/L	Necessary	64.00 FS	*50.00 FS
39	1		*FRONT NO PLATE	Necessary	25.00 FS	*20.00 FS
40	1		*SET FRONT WHEEL RIM BEARING	Necessary	62.00 FS	*50.00 FS
41	1		*SET HANDLE BAR BALANCER	Cut	98.00 FS	*70.00 FS
42	1		*SET HANDLE BAR GRIP	Serviceable	72.00 FS	*- FS
43	1		*REAR NO PLATE	Serviceable	25.00 FS	*- FS
44	1		*STEERING CORN / BEARING	Necessary	158.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,637.00</b>	<b>4,738.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>894.40</b>	<b>430.80</b>
<b>Total Parts (\$\$)</b>	<b>8,742.60</b>	<b>4,307.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING (TO FR)	New	60.00	30.00
2	TO REMOVE, INSTALL ENGINE WITH TRANSMISSION (TO FR)	New	350.00	0.00
3	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	400.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	500.00	200.00
5	TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION	New	400.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,010.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >