

ASS. REC. BY:

REF:

TM1 / CC3 / TMU 8017388 / KLB 52

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.:

Yes or No

Lum Sum:

1.3-1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 101B

Yr Regn:

07.17

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make:

Renault Corolla c.c. 1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

58174

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUX 283483

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

NII / S/Rim / STD A/Rim or

Tyre Size:

F: Giti

215/60R16

R: GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

3

mm

L/Bal.

2

mm

L/Bal.

3

mm

D.O.A.

20/9/18

D.O.A.

21/9/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19

File pass to Catherine

86535.40 (Red. 33568.29, 83%)

SHD 101B - CC3 / TMU 8017388 / KLB 52

SLW 272D - NA / TMU 8017388 / KLB 52

RA: 0503 2018

RA: 20092018

26/9 @ 2:26 pm email GIA & ESTIMATE to TM1

RECEIVED 20 SEP 2018

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

25

Resurvey No. of Trip:

Survey Fee:

250

Transportation:

S + RS, SI

Factors

Others

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech Invs (\$)



: Weekend (\$)

Report Format:

TP

Lump Sum / I.B.I. (\$)

8535.40

TOTAL

10

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 26 September 2018 2:26 PM
To: 'Motor Claims'
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD DOA: 21/9/2018, SHD 101B (TP VEHICLE), SLW 2772D (OI VEHICLE)
Attachments: ESTIMATE SHD 101B.pdf; GIA SHD 101B_0001.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle **SHD 101B** M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2018 13:21
Date Of Accident	20/09/2018 09:40
Exact Location Of Accident	JURONG EAST AVENUE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD101B
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	KHOO KWEE LONG
NRIC No	S1689057Z
Date Of Birth	03/04/1965
Occupation	OUTDOOR
Date Of Driving Pass	03/06/2015
Driving Experience	3 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81802118
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 74 WHAMPOA DRIVE #12-338
Postcode	320074
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 20.09.2018 at about 0940hours, I was travelling straight on the extreme right lane along Jurong East Avenue 1 when the traffic light turn green. I slowly moved forward. Suddenly I felt an impact. Vehicle B (SLW2772D) hit onto my taxi's rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW2772D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH KUOK KEEN
NRIC/Passport Number	S8613951J
Contact Number	97568241
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pu see attach GA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Signature of Reporting Centre

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD101B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Sep 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003411
Chassis No.:	VF1ABL15AUC283483
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	24 Jul 2017
First Registration Date:	24 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2025
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	23 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$30,848.00
Total Rebate Amount:	\$45,846.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Sep 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 101B**AAD1809-191***Not Notified
Resurvey B4 paint 86535.40*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 101B

VF1ABL15AUC283483

RENAULT

LATITUDE

20.9.2018

TOKIO MARINE**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Not</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56 X
15	1 TAILLAMP RH	\$	<i>SL</i> 552.55 X
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70 X
17	1 TAILLAMP LH	\$	<i>SL</i> 552.55 X
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70 X
19	1 BOOT REAR	\$	<i>Bu</i> 2,872.68 ✓
20	1 BOOT FINISHER	\$	<i>SL</i> 470.06 X
21	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05 X
22	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35 X
23	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35 X
24	1 BOOT BADGE 'RENAULT'	\$	<i>Bu</i> 225.36 ✓
25	1 BOOT BADGE	\$	<i>Bu</i> 225.36 ✓
26	1 BOOT STRUT LH	\$	<i>SL</i> 276.08 X
27	1 BOOT STRUT RH	\$	<i>SL</i> 276.08 X
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84 X
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84 X

Trans-cab Auto Services Pte Ltd**AAD1809-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 101B

30	1 BOOT INNER TRIM	\$	Sn 586.45 X
31	1 BOOT SWITCH	\$	Sn 168.13 X
32	1 BOOT LOCK	\$	R 202.67 X
33	1 BOOT LOCK CATCH	\$	R 74.40 X

	\$	16,046.87
10%	\$	7.44
	\$	16,039.43

14442.17

Special Nett

1	1SET PARKING AID	\$	Sn 700.00 X
2	1SET REAR BUMPER CLIP	\$	na 66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na 20.00 X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na 10.00 X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	Sn 17.82 X
11	2 REAR WINDSCREEN SEALANT	\$	na 80.00 X
12	1 WINDSCREEN MOULDING	\$	na 100.00 X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 X

TOTAL \$ 1,244.82**TOTAL PARTS \$ 17,284.25**

15686.99

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00 4001

Trans-cab Auto Services Pte Ltd**AAD1809-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 101B

To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	~ 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	~ 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00	~ 220.00 X
TOTAL	\$	6,780.00	

Over All Total \$ 40,103.69

22466.99

(PART-BY-PART)**Repair Days****10 DAYS**

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claim Documents

***SHD101B (M1804696)**
[SLW2772D]
TP
TRANS-CAB SERVICES PTE LTD
Sep 20 2018 9:00AM
[CHIA JIE YI VANESSA (XIE JIEYI)]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	21/09/18 09:31	Accident Statement From:SC - Reg. No: SLW2772D, Claimant: CHIA JIE YI VANESSA (XIE JIEYI)	1	Load HTM	
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)		Thumbnail	Print
1	20/09/18 13:44	Accident Statement	1	Load HTM	

Photos/Images


3 per page ▼ ☒

No	Finalized On	Trans-Cab Services Pte Ltd (HQ)		Thumbnail	Print
1	20/09/18 13:43	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	20/09/18 13:43	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	20/09/18 13:43	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
4	20/09/18 13:43	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
5	20/09/18 13:43	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
6	20/09/18 13:43	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
7	20/09/18 13:43	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	27/09/18 16:45	General View	1	Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page ▼ ☒

No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	26/09/18 15:44	EST	1	Load PDF	
2	26/09/18 15:45	LKK NOTIFICATION TO SURVEY TRANS CAB-ASSIGN	1	Load PDF	
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)		Thumbnail	Print

Assessment Reports			1 per page ▼	✓
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	20/09/18 13:41	Sketch Plan [Linked Accident Report Documents]	 Load JPG	✓
2	20/09/18 13:41	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	✓

Linked Accident Report Documents

Assessment Reports			View	View in Browser ▼	1 per page ▼	✓
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)	Thumbnail	Print		
1	20/09/18 13:44	Accident Statement	 Load HTM			
Photos/Images			3 per page ▼	✓		
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)	Thumbnail	Print		
1	20/09/18 13:43	Accident Photo	 Load JPG	✓		
2	20/09/18 13:43	Accident Photo	 Load JPG	✓		
3	20/09/18 13:43	Accident Photo	 Load JPG	✓		
4	20/09/18 13:43	Accident Photo	 Load JPG	✓		
5	20/09/18 13:43	Accident Photo	 Load JPG	✓		
6	20/09/18 13:43	Accident Photo	 Load JPG	✓		
7	20/09/18 13:43	Accident Photo	 Load JPG	✓		
Documentation			1 per page ▼	✓		
No	Finalized On	Trans-Cab Services Pte Ltd (HQ)	Thumbnail	Print		
1	20/09/18 13:41	Sketch Plan	 Load JPG	✓		
2	20/09/18 13:41	Sketch Plan #2	 Load JPG	✓		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2018		26 Sep 2018 15:46 Edit Adj Rpt	S\$6,535.40 Edit Estimates	S\$6,535.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHIA JIE YI VANESSA (XIE JIEYI) , ID: S8841826C		
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD101B	Date of Loss:	20/09/2018 09:00 - :59 [13 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1804696	Policy/Cover Note No.:	MT000760 (Comprehensive) Coverage: 05/02/2018 - 04/02/2019
Vehicle Reg. No. (Insured):	SLW2772D	Policy No. (Claimant):	
		Excess:	S\$7,000.00
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/10/2018]		
Adj Asg. Remarks:	PLS. CHECK CONSISTENCY OF THE DAMAGE.THKS		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18017388/KTBS2
Date: 03/10/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT000760
Claimant Vehicle No :	SHD101B	Insured Vehicle No :	SLW2772D
Date of Loss:	20/09/2018	Nature of Claim:	TP
		Claim No:	M1804696

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD101B	Engine No:	M9R8839C003411
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283483
Reg. Date:	24/07/2017 (Man. Year: 2016)	Odometer:	58174 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Goodyear 3 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,686.99	5,545.40	10,141.59	64.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,780.00	990.00	5,790.00	85.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,466.99	6,535.40	15,931.59	70.91
+ GST 7.00/7.00% (S\$)	1,572.69	457.48	1,115.21	70.91
Nett Amount (S\$)	24,039.68	6,992.88	17,046.80	70.91

INSPECTION

Date of Assignment:	26/09/2018	
Date Inspected:	21/09/2018	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.5 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2018)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD101B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
25	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*- FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
42	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
44	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
45	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
46	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	17,291.68	6,143.22
- List Item Discount on L Items 10.00/10.00% (S\$)	1,604.69	597.82
Total Parts (S\$)	15,686.99	5,545.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
Gross Labour Cost (\$\$)			6,780.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >