

3/0/2008

ASS. REC. BY:

REF: CS/TU/8009214/RISBT

Special Instruction:

SUBJECT:

Report

ASSIGNMENT (Office)

From (Person):

Joel Nuh

of

TU

Date/Time:

30/8/2018

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 9813 R

Insured:

PA 9596 T

at Workshop in/s

Eclipse Auto

Tel:

8128 8789

of

155 Kaki Bukit Ave 1 Shun Li Ind Park

Policy No:

Claim No:

MC20182417

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

17/08/2018

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

21/08/2018 3.12pm

Person Contacted:

Frankie

Vehicle

☒ IN / ☐ OUT

Date/Time	Action/Instruction ( X ) Estimate	
	SKV 9813 R - NA / INC / 3007001 / 24	Out: 17/09/18
	PA 9596 T - CVC / TU / 18006484 / 10/3	Out: 05/04/18
22/5/18	Dismantled	
	Submit HS & 3,500/- @ 5 days	
	(\$3500/- Red - 50%)	

*[Signature]*

10/10/2018

URGENT

An not given items to indicate as NH

RECEIVED 10 OCT 2018

260-160 =

Surveyor: Farouk

REF:

35822

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 9813Rat Workshop m/s Eclipseof 155, KAKI BUKIT AVE / SHUN LIPKInsured: 111 / PRS

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKV 9813R Yr Regn: 2015 / 04Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: NISSAN QASHQAI 1.2 c.c. 1197Colour: Brown A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 18857 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: \_\_\_\_\_

C/No: SYNFEA3114147876Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☐ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 215/60R17R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 11/05/18D.O.I. 21/05/18Survey held at EclipseDes. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop orN/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/5/18 Submit PRS Report

RECEIVED 4 MAY 2018

Date/Time: File Pass to?

10/10/18

1) Typist

Date/Time: File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 2Survey Fee: 80Transportation: 80

S = RS, SI

Photos

Others

TOTAL

170

Report Format :

Lump Sum / I.B.I.: (\$ 3,500/- L15)Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

## Catherine Chong (LKK Auto)

---

**From:** Olivia Lau (LKKAuto) <olivialau@lkkauto.com>  
**Sent:** Thursday, 30 August, 2018 2:39 PM  
**To:** Hsiao Tong (LKKAuto); assignments; Admin A  
**Subject:** FW: Our ref : MC20182417

---

**From:** Mekavathanan Sarangapani  
**Sent:** Thursday, 30 August 2018 2:38:42 PM (UTC+08:00) Kuala Lumpur, Singapore  
**To:** Olivia Lau (LKKAuto)  
**Cc:** Lalitha Krishnan - III; Gabriel Wee; Joel Nah Shern Ern; williamchia@comfortdelgrobos.com.sg; Pooi Chin Han Daniel  
**Subject:** Our ref : MC20182417

Lod from Vehicle Claims Specialists – Please speak to workshop and resolve this claim please- Please do up a paper survey .

William - any issue with liability . CCTV footage fwded to us yet

Meka

## Mekavathanan Sarangapani


**From:** Mekavathanan Sarangapani  
**Sent:** Saturday, June 09, 2018 12:45 PM  
**To:** Olivia Lau (olivialau@lkkauto.com)  
**Cc:** Gabriel Wee; Lalitha Krishnan - III  
**Subject:** Our ref : MC20182417

Why no direct settlement for this case ?

Meka

Main		Offer Processing	Claim Details	Adjuster
<b>CLAIM SUBFOLDER DETAILS</b>				
Insured:	COMFORTDELGRO BUS PTE LTD, Co. Reg. No.: 199607256W			
Main Claimant:	LIEW TIAN SOON, ID: S1383582I			
Vehicle Reg. No.:	SKV9813R	Date of Loss:		
Claim Type:	TP / MC2018/2417	Policy/Cover Note No.:		
Vehicle Reg. No. (Insured):	PA9596T	Policy No. (Claimant):		
		Excess:		
Repairer:	Eclipse Auto Pte Ltd (HQ) <b>PROFILE</b> 155 Kaki Bukit Avenue 1, Shun Li Industries			
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by La			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 62463356 ... [Handled by MOHD RA]			
<b>CLAIM REGISTERED</b>				
<b>ACCIDENT REPORT</b> (Closed)				
Audit Log		Accident Report	Print Sketch Plan	Print Addendum Form
OWN VEHICLE		TP VEHICLE/INJURY DETAILS		DOCUMENT
Related Accident Reports				
• <b>PA9596T</b> ... MCD518064642 submitted on 18/05/2018 11:07 to India International Insurance Pte Ltd [CURRENTLY VIEWING] • TP reported: SKV9813R.				
• <b>SKV9813R</b> ... MNA118064884 submitted on 18/05/2018 15:09 to NTUC Income Insurance Co-operative [purchased] • TP reported: PA9596T.				
Accident Report Basic Information				

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driving my bus veh No. PA95967  
 Turning to Tampines Central A  
 While turning right, I signalled right  
 and Veh SKV 9813R hit my Right back side  
 of my bus.

**ACCIDENT STATEMENT**

Date Of Report	18/05/2018 10:02
Date Of Accident	17/05/2018 19:15
Exact Location Of Accident	TAMPINES CENTRAL AVE 4
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	PA9596T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORTDELGRO BUS PTE LTD
Co Reg No	199607256W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-92473057

**Vehicle Particulars**

Manufacturer	SCANIA
Model	KUB4X2 9.3L A/T ABS TURBO-9.3 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

**Insurance Company**


Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO











Date:

**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	M481
Claimant Vehicle No :	SKV9613R	Insured Vehicle No :	PA91
Date of Loss:	17/05/2018	Nature of Claim:	TP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SKV9613R	
Make & Model:	NISSAN QASHQAI, 1.2 (A)	
Reg. Date:	26/10/2015 (Man. Year: 2015)	E
Colour:	Brown	C
Engine Capacity:	1197 cc	C
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footb
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-a

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R17	Rear Tyre Size:	
Front Left Side:	Continental 6 mm	Rear Left Side:	
Front Right Side:	Continental 6 mm	Rear Right Side:	

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's
Parts	0.00	0.00
Miscellaneous Items	0.00	0.00
Labour	0.00	0.00
Paintwork Labour	0.00	0.00
Towing	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment:	21/05/2018	
Date Inspected:	21/05/2018	Inspected At:
		Eclipse Auto Pte Ltd (HQ) 155 Kaki Bukit Avenue 1, Shun Li Industrial F Singapore 416012
Estimated Period of Repair:	0.0 days	

Best Regards,

Mekavathanan

HOD

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street, #04/#05 IOB Building, Singapore 049711

DID: 6347 6105 Fax: 6224 4174



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located

both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

No	Subject Matter	Current	Revised	Remarks
1	Reserves			
	TPPD	PRESERVE		
	TPPI	PRESERVE		
	UNINSURED LOSS	PRESERVE		
	SUBRO	PRESERVE		
	LPPN			

	Investigation Fees	
	Survey Fees	
	Legal Fees	
	Others	
2	Fraud Check	
3	Upload to merimen	
4	Grant Rights	
5	Payment	

29/8/18 59,577

CLAIM NO. (URE / CORAC / PREMIER / DIRECT / SINGPOST)	MC20182417/01
DATE OF ACCIDENT	17/5/18
CLAIM OFFICER	ZS / SP / SN / MP / WH / CM / KL / HR / BP / DP
LOD FROM	Vehicle Claims Specialist
PRX / EMAIL	<input checked="" type="checkbox"/> YES / DATE: 30/8/18
INSURED VEHICLE	P49 596 T
TYPE OF CLAIMANT	DRIVER / PASSENGER (IV) / PASSENGER (TP) / RIDER / PILLION / CYCLIST / PEDESTRAIN / COMPANY / <u>OWNER</u> Liew Tian Soon
TYPE OF CLAIM	<input checked="" type="checkbox"/> TPD / TPI / UL / SUBRO / TPPD / OD
CASE TYPE	<input checked="" type="checkbox"/> DO / PC / NC / REOPEN
PREMIUM LIVE UPDATED	<input checked="" type="checkbox"/> YES / DATE: 4/9/18
MERIMEN SCAN	YES / DATE:
RIGHTS GRANTED	NOT NEEDED / YES / DATE:
MERIMEN COMPLETED	YES / DATE:

**Joel Nah Shern Ern**

---

**From:** Joel Nah Shern Ern  
**Sent:** Thursday, 30 August, 2018 2:55 PM  
**To:** 'JB GEM'  
**Cc:** Pooi Chin Han Daniel  
**Subject:** acknowledgement of LOD

Dear all,

We have received the acknowledgement of the LOD.

*Joel Nah*

**Motor Claims Department**  
**India International Insurance Pte Ltd**  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6100 Ext 206 Fax: 6224 4174



**VEHICLE CLAIMS SPECIALIST PTE LTD**  
6A SHENTON WAY #04-02 to 08 OUE DOWNTOWN GALLERY  
SINGAPORE 068815  
Email: [VCSSG01@GMAIL.COM](mailto:VCSSG01@GMAIL.COM)



Your Reference: PA 9596T

Our Reference: VCS/SKV 9813R/EA/PA

**WITHOUT PREJUDICE**

Date: 23<sup>rd</sup> August 2018

**INDIA INTERNATIONAL INSURANCE PTE LTD**

**BY HAND**

64 Cecil Street  
#05 IOB Building  
Singapore 049711

Attention: Motor Claims Department

Dear Sirs

We are in receipt of your claim, which is being handled by us.  
We will keep you informed of the progress of your claim.  
Our Ref: MC 2018 24/7  
Name: [Signature]  
Date: [Signature]  
India International Insurance Pte Ltd

**ACCIDENT INVOLVING VEHICLES NOS. SKV 9813R AND PA 9596T ALONG  
TAMPINES CENTRAL 4 ON 17<sup>th</sup> MAY 2018 AT ABOUT 1930 HOURS**

We represent for LIEW TIAN SOON, the owner of motor vehicle SKV 9813R.

We are instructed by LIEW TIAN SOON, to claim damages against your insured in connection with a road traffic accident on 17<sup>th</sup> May 2018 at about 1930 hours along Tampines Central 4 involving our customer's vehicle registration number SKV 9813R and vehicle registration number PA 9596T driven by your insured at the material time.

We are instructed that the accident was caused by your insured's negligent driving and/or management of your insured's vehicle. As a result of the accident, our customer's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

(a)	Repair Cost	\$ 7,000.00
(b)	Loss of Use (\$100 x 11 days)	\$ 1,100.00
(c)	E-Day Licence	\$ 40.00
(d)	Survey Fee	\$ 450.00
(e)	LTA / GIA search fee	\$ 37.00
(f)	Incidentals	\$ 100.00
(g)	Admin Fee	\$ 850.00
<b>TOTAL</b>		<b><u>\$S 9,577.00</u></b>



**VEHICLE CLAIMS SPECIALIST PTE LTD** UEN No. 201802773H  
6A SHENTON WAY #04-02 to 08 OUE DOWNTOWN GALLERY

SINGAPORE 068815

Email: [VCSSG01@GMAIL.COM](mailto:VCSSG01@GMAIL.COM)

Page 2

Your Reference: PA 9596T

Our Reference: VCS/SKV 9813R/EA/PD

Date: 23<sup>rd</sup> August 2018

A copy each of the supporting documents is enclosed:

- (a) Accident report of our client;
- (b) Repair Bill from Eclipse Auto Pte Ltd;
- (c) LTA search of your insured vehicle and copy Receipts of e-day licence ;
- (d) Invoice and Survey Report, inclusive of colour copy photographs of our client's damaged vehicle

Please note that you should send us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to refer the matter to solicitors commence legal proceedings against your insured without further notice to you or your insured. As we aware, your costs in this case will escalate.

Please also note that if your insured has a counterclaim against our client arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



VCS  
Encs



## Enquire Vehicle & Owner Information ( Vehicle No. PA9596T As At 17 May 2018 / 19:30:00 )

### Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SKV9813R

### Current Owner Details

- Owner ID Type: Company

Owner ID: 199607256W

Owner Name: COMFORTDELGRO BUS PTE. LTD.

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 205

Registered Street Name: BRADDELL ROAD

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 579701

### Current Vehicle Details

Vehicle No.: PA9596T

Make Description/Model: SCANIA / KUB4X2 9.3L A/T ABS TURBO

Insurance Company Name: INDIA INT'L INS PTE LTD



Hariram Gopalakrishnan has successfully logged out.

Your last login date and time was 21 May 2018, 13:42:16.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

#### Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount (\$\$)	Log Date/Time
1	Vehicle	PA9596T	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	21 May 2018 / 13:43:35



to One/Metering



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4 0005229 2

Print Date/Time : 18 May 2018 / 23:14:40

Receipt Date/Time : 18 May 2018 / 23:14:40

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-180518-002480

Previous Receipt No. :

S/N Item Description/

Business Transaction Reference No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Usage Date: 18 May 2018 (Fri)

1 Sales of e-Day Licence - SKV9813R  
e-Day Licence @\$20.00 x 1  
20180518231259694740

20.00	0.00	20.00
-------	------	-------

Sub-Total	20.00	0.00	20.00
-----------	-------	------	-------

Total Before Rounding	20.00	0.00	20.00
-----------------------	-------	------	-------

Rounding Difference			0.00
---------------------	--	--	------

Total Amount Payable			20.00
----------------------	--	--	-------

Paid By

xxxxxxxxxxxx6011	Credit Card: Visa/MasterCard	20.00
------------------	---------------------------------	-------

Total		20.00
-------	--	-------

Cash Change		0.00
-------------	--	------

Tendered Amount		20.00
-----------------	--	-------

Excess Refundable Amount		0.00
--------------------------	--	------

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/05/2018 14:54
Date Of Accident	17/05/2018 19:30
Exact Location Of Accident	ALONG TAMPINES CENTRAL 4
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV9813R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIEW TIAN SOON
NRIC No	S1383582I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96723514
Alternative Phone No	OFFICE-96723514

### Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084608467-01
Cover Note Number	

### Driver

Name of Driver	LIEW TIAN SOON
NRIC No	S1383582I
Date Of Birth	08/09/1959
Occupation	INDOOR
Date Of Driving Pass	22/05/1986
Driving Experience	31 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96723514
Fax Number	
Contact Number	OFFICE-96723514
Email Address	NOEMAIL

Address BLK 230B TAMPINES STREET 24  
#05-31  
Postcode 525230  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 3  
Passenger 1  
NAME: : -  
GENDER: : FEMALE  
Passenger 2  
NAME: : -  
GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of Intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG LANE 1 TAMPINES CENTRAL 4. SUDDENLY VEHICLE B CUT ONTO MY LANE AND HIT ONTO MY VEHICLE FRONT LEFT PORTION.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PA9596T  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category BUS  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Person's Signature  
Name:  
NUIC/VIN No.:



# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement


## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
 Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



## INVOICE

TO : LIEW TIAN SOON  
C/O: ECLIPSE AUTO PTE LTD  
155 KAKI BUKIT AVE 1 #01-00,  
SHUNLI INDUSTRIAL PARK  
SINGAPORE 416012

Invoice No.: 518/EA657  
Date: 30-May-2018

### PARTICULARS

Vehicle Registration No.: SKV 9813 R  
Date of Loss: 17-May-2018  
Date of Assessment: 21-May-2018

### SERVICES

### FEES

1. Assessment with report Photographs -  
Including films, developing, storage and Transport.

\$450.00

**TOTAL** \$450.00

**SINGAPORE DOLLARS FOUR HUNDRED FIFTY ONLY**

We would appreciate your cheque crossed and made payable to:  
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

**AEON AUTO CONSULTANTS LLP**



### **AEON AUTO CONSULTANTS LLP**

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874  
Telephone +65 97687958 Facsimile +65 68264112 Email [amas@aeonac.com](mailto:amas@aeonac.com)  
Reg. No. LL0701273L (registered with limited liability)

## AUTOMOBILE ASSESSMENT REPORT

TO: LIEW TIAN SOON  
C/O: ECLIPSE AUTO PTE LTD  
155 KAKI BUKIT AVE 1 #01-00,  
SHUNLI INDUSTRIAL PARK  
SINGAPORE 416012

Our Reference: 518/EA657  
Date: 30-May-2018

### ASSESSMENT OF VEHICLE NO. SKV 9813 R

DATE OF LOSS: 17-May-2018

We have carried out a physical assessment at ECLIPSE AUTO PTE LTD,  
155 Kaki Bukit Ave 1 #01-00 Shunli Industrial Park, Singapore 416012, according to your instruction  
on 21-May-2018 and are pleased to submit our report herewith.

### 1. VEHICLE PARTICULARS

Registration No.: SKV 9813 R  
Make & Model: NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR  
Year of Registration: 2015  
Engine Capacity: 1197  
Chassis No.: SJNFEAJ11U1487876  
Engine No.: HRA2190027A  
Colour: BROWN  
Mileage (km): 18857

### 2. VEHICLE CONDITION

Body Paint: GOOD  
Steering: SERVICEABLE  
Foot Brake: SERVICEABLE  
Parking Brake: SERVICEABLE  
Modification: NIL

### 3. TYRE PARTICULARS & CONDITION


Front  
RH Make/Size/Thread: CONTINENTAL 215/60 R17 – 75%  
LH Make/Size/Thread: CONTINENTAL 215/60 R17 – 75%  
  
Rear  
RH Make/Size/Thread: CONTINENTAL 215/60 R17 – 75%  
LH Make/Size/Thread: CONTINENTAL 215/60 R17 – 75%

#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

#### 5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$12,998.19
Adjusted Amount:	\$9,361.45
Lump Sum:	\$7,000.00
Estimated Repair Days:	8 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

**ASSESSMENT REPORT FOR VEHICLE NO. SKV 9813 R**

**PARTS (LIST ITEMS)**

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Repair	1,054.30	-
2	FRONT BONNET RUBBER GUIDE STOPPER L/R	Bent	16.00	16.00 Xnn
1	FRONT LH HEADLAMP CLIP	Necessary	6.50	6.50
1	FRONT LH HEADLAMP LOWER BRACKET	Bent	31.40	31.40 Xnn
1	FRONT GRILLE	Repair	507.40	-
6	FRONT GRILLE CLIPS	Necessary	39.00	39.00 Xnn
1	FRONT BUMPER	Cracked	646.00	646.00
1	FRONT BUMPER LH FOGLAMP	Cracked	320.70	320.70 Xnn
1	FRONT BUMPER INNER SPONGE	Cracked	207.20	207.20 Xnn
1	FRONT BUMPER LOWER REINFORCEMENT	Repair	715.20	-
1	FRONT BUMPER LOWER REINFORCEMENT IMPACT SPONGE (LH)	Repair	207.20	-
1	FRONT BUMPER REINFORCEMENT 'TOP'	Repair	357.60	-
2	FRONT BUMPER REINFORCEMENT BRACKET L/R	Repair	248.60	-
2	FRONT BUMPER SIDE RETAINER L/R	Bent	46.00	46.00
1	FRONT LH FENDER	Bent	677.10	677.10
1	FRONT LH FENDER OUTER ARCH GARNISH	Cracked	541.40	541.40
1	FRONT SUPPORT PANEL ASSY	Repair	692.20	-
1	FRONT LH KNUCKLE	Repair	376.90	-
1	FRONT LH KNUCKLE BEARING	Jammed	305.60	305.60 Xnn
1	FRONT LH LOWER ARM	Repair	218.60	-
1	FRONT LH SHOCK ABSORBER	Bent	439.40	439.40 Xnn
1	FRONT LH 17" SPORT RIM (ORIGINAL)	Bent	1,044.30	1,044.30
			8,698.60	4,320.60
			Less 30% discount	2,509.58
			Parts Total:	3,024.42

**PARTS (NETT ITEMS)**

1	FRONT BONNET INNER WEATHER STRIP	Cut	59.60	59.60 Xnn
1	FRONT BONNET MECHANISM LOCK	Bent	67.90	67.90 Xnn
1	FRONT BONNET OUTER WEATHER STRIP	Repair	59.60	-
1	FRONT GRILLE 'LOGO' EMBLEM	Reuse	65.00	-
1	FRONT GRILLE OUTER CHROME GARNISH	Cracked	789.40	789.40 Xnn
1	FRONT LH HEADLAMP	Cracked	569.10	569.10
1	FRONT LH HEADLAMP H.I.D BARLAST (ORIGINAL)	Faulty	450.10	450.10 Xnn
1	FRONT LH HEADLAMP H.I.D BULB (ORIGINAL)	Faulty	387.50	387.50 Xnn
1	FRONT BUMPER FOGLAMP CHROME GARNISH	Cracked	75.10	75.10 Xnn
1	ENGINE LOWER WATER SPLASH	Cracked	286.40	286.40 Xnn
1	FRONT LH FENDER INNER SHIELD	Cracked	87.90	87.90
1	FRONT LH ABS SENSOR	Faulty	323.70	323.70 Xnn
			3,221.30	3,096.70
			Less 10% discount	322.13
			Parts Total:	2,899.17
				2,787.03

**ASSESSMENT REPORT FOR VEHICLE NO. SKV 9813 R**

**SPECIAL NETT ITEMS**

1	FRONT LH HEADLAMP 'SIGNAL' BULB	Faulty	15.00	15.00	XAN
1	FRONT LH HEADLAMP LOW BEAM BULB	Faulty	25.00	25.00	XAN
1	FRONT BUMPER CLIPS - SET	Necessary	30.00	30.00	
1	ENGINE LOWER WATER SPLASH CLIPS - SET	Necessary	30.00	30.00	XAN
1	FRONT LH FENDER INNER SHIELD CLIPS - SET	Necessary	30.00	30.00	
1	FRONT LH FENDER OUTER ARCH GARNISH CLIPS - SET	Necessary	30.00	30.00	
1	FRONT LH 215/60R17 TYRE	Cut	380.00	380.00	266
				702	
		Special Nett Total :	540.00	540.00	

**LABOUR**

S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing.	140.00	120.00 30
2	To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	450.00	400.00 X
3	To road test driving, check and resetting wheel alignments system.	180.00	160.00 60
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	1,000.00 600
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,400.00	1,250.00 600
6	To apply anti-rust chemical on repaired and replaced panel.	100.00	80.00 40
		Labour Total :	3,470.00 3,010.00
		<b>TOTAL (PARTS &amp; LABOUR) \$</b>	<b>12,998.19 9,361.45</b>

The workshop has agreed to undertake the repair on a Lump Sum basis.  
The final adjusted Lump Sum contract amount is  
**\$7,000.00 (SINGAPORE DOLLARS SEVEN THOUSAND ONLY)**



Amas Ong  
Automobile Assessor

2072.91  
591.30  
356.00  
1330.00  
4350.21  
209  
3480.16  
4/3-3.5w  
5 days

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1






































## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 May 2018 <a href="#">Edit Reg</a>		30 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>




























Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORTDELGRO BUS PTE LTD</b> , Co. Reg. No.: 199607256W								
Main Claimant:	<b>LIEW TIAN SOON</b> , ID: S13835821								
Vehicle Reg. No.:	<b>SKV9813R</b>	Date of Loss:	17/05/2018 19:00 - :59 [30 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MC2018/2417</b>	Policy/Cover Note No.:	M485742/02 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>PA9596T</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Eclipse Auto Pte Ltd (HQ)</b> 155 Kaki Bukit Avenue 1, Shun Li Industrial Park #01-01, 416012 Kaki Bukit - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Lalitha Krishnan</b> - 6347 6139]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... <b>[Final Rpt due 26/09/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (24/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SKV9813R - Claim Handler: Lalitha Krishn...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKV9813R (MC2018/2417)  
[PA9596T]  
TP  
LIEW TIAN SOON  
May 17 2018 7:00PM  
[COMFORTDELGRO BUS PTE LTD]  
Eclipse Auto Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	10/10/18 11:13	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	10/10/18 11:13	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
4	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
5	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
6	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
7	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
8	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
9	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
10	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
11	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
12	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
13	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
14	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
15	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
16	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
17	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
18	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
19	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
20	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
21	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
22	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
23	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
24	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
25	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
26	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
27	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
28	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
29	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
30	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
31	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
32	10/10/18 11:13	General View		Load JPG	<input checked="" type="checkbox"/>
33	10/10/18 11:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	10/10/18 11:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	10/10/18 11:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	10/10/18 11:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
37	10/10/18 11:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
39	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
40	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
41	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
42	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
43	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
44	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
45	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
46	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
47	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
48	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
49	10/10/18 11:13	Reinspection Photo		<input checked="" type="checkbox"/>
50	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
51	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
52	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
53	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
54	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
55	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
56	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
57	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
58	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
59	10/10/18 11:14	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/05/18 17:24	LKKPhotosIn6-1.pdf		<input type="checkbox"/>
2	23/05/18 17:24	LKKPhotosIn6-2.pdf		<input type="checkbox"/>
3	10/10/18 14:33	PRS Invoice		<input type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/05/18 08:40	Singapore Accident Statement		<input type="checkbox"/>
2	05/09/18 10:25	Letter of Demand from Third Party VEHICLE CLAIMS SPECIALIST		<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18009214/R1SBE2-1

Date: 10/10/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M485742/02

Claimant Vehicle  
No: SKV9813R

Insured Vehicle No: PA9596T

Date of Loss: 17/05/2018

Nature of Claim: TP

Claim No: MC2018/2417

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV9813R

Make &amp; Model: NISSAN QASHQAI, 1.2 (A)

Engine No: HRA2190027A

Reg. Date: 26/10/2015 (Man. Year: 2015)

Chassis No: SJNFEAJ11U1487876

Colour: Brown

Odometer: 18857 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,528.19	3,020.21	6,507.98	68.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,330.00	2,140.00	61.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,998.19</b>	<b>4,350.21</b>	<b>8,647.98</b>	<b>66.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,998.19</b>	<b>3,500.00</b>	<b>9,498.19</b>	<b>73.07</b>

INSPECTION

Date of Assignment: 30/08/2018

Date Inspected: 21/05/2018 Inspected At:

Eclipse Auto Pte Ltd (HQ)  
155 Kaki Bukit Avenue 1, Shun Li  
Industrial Park #01-01  
Singapore 416012

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2018)
<b>Parts:</b>	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKV9813R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,054.30 FL	*- FL
2	2		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Not Necessary	16.00 FL	*- FL
3	1		*FRONT LH HEADLAMP CLIP	Necessary	6.50 FL	*6.50 FL
4	1		*FRONT LH HEADLAMP LOWER BRACKET	Not Necessary	31.40 FL	*- FL
5	1		*FRONT GRILLE	Repair	507.40 FL	*- FL
6	6		*FRONT GRILLE CLIPS	Not Necessary	39.00 FL	*- FL
7	1		*FRONT BUMPER	Cracked	846.00 FL	*846.00 FL
8	1		*FRONT BUMPER LH FOGLAMP	Not Necessary	320.70 FL	*- FL
9	1		*FRONT BUMPER INNER SPONGE	Not Necessary	207.20 FL	*- FL
10	1		*FRONT BUMPER LOWER REINFORCEMENT	Repair	715.20 FL	*- FL
11	1		*FRONT BUMPER LOWER REINFORCEMENT IMPACT SPONGE (LH)	Repair	207.20 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT TOP	Repair	357.60 FL	*- FL
13	2		*FRONT BUMPER REINFORCEMENT BRACKET L/R	Repair	248.60 FL	*- FL
14	2		*FRONT BUMPER SIDE RETAINER L/R	Bent	46.00 FL	*46.00 FL
15	1		*FRONT LH FENDER	Bent	677.10 FL	*677.10 FL
16	1		*FRONT LH FENDER OUTER ARCH GARNISH	Cracked	541.40 FL	*541.40 FL
17	1		*FRONT SUPPORT PANEL ASSY	Repair	692.20 FL	*- FL
18	1		*FRONT LH KNUCKLE	Repair	376.90 FL	*- FL
19	1		*FRONT LH KNUCKLE BEARING	Not Necessary	305.60 FL	*- FL
20	1		*FRONT LH LOWER ARM	Repair	218.60 FL	*- FL
21	1		*FRONT LH SHOCK ABSORBER	Not Necessary	439.40 FL	*- FL
22	1		*FRONT LH 17 SPORT RIM (ORIGINAL)	Bent	1,044.30 FL	*1,044.30 FL
23	1		*FRONT BONNET INNER WEATHERSTRIP	Not Necessary	59.60 FN	*- FN
24	1		*FRONT BONNET MECHANISM LOCK	Not Necessary	67.90 FN	*- FN
25	1		*FRONT BONNET OUTER WEATHERSTRIP	Repair	59.60 FN	*- FN
26	1		*FRONT GRILLE LOGO EMBLEM	Reuse	65.00 FN	*- FN
27	1		*FRONT GRILLE OUTER CHROME GARNISH	Not Necessary	789.40 FN	*- FN
28	1		*FRONT LH HEADLAMP	Cracked	569.10 FN	*569.10 FN
29	1		*FRONT LH HEADLAMP H.I.D BARLAST (ORIGINAL)		450.10 FN	*- FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*FRONT LH HEADLAMP H.I.D BULB (ORIGINAL)	Not Necessary	387.50 FN	*- FN
31	1		*FRONT BUMPER FOGLAMP CHROME GARNISH	Not Necessary	75.10 FN	*- FN
32	1		*ENGINE LOWER WATER SPLASH	Not Necessary	286.40 FN	*- FN
33	1		*FRONT LH FENDER INNER SHIELD	Cracked	87.90 FN	*87.90 FN
34	1		*FRONT LH ABS SENSOR	Not Necessary	323.70 FN	*- FN
35	1		*FRONT LH HEADLAMP SIGNAL BULB	Not Necessary	15.00 FS	*- FS
36	1		*FRONT LH HEADLAMP LOW BEAM BULB	Not Necessary	25.00 FS	*- FS
37	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
38	1		*SET ENGINE LOWER WATER SPLASH CLIPS	Not Necessary	30.00 FS	*- FS
39	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
40	1		*SET FRONT LH FENDER OUTER ARCH GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
41	1		*FRONT LH 215/60R17 TYRE (70%)	Cut	380.00 FS	*266.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>12,459.90</b>	<b>3,974.30</b>
- List Item Discount on L Items 30.00/30.00% (S\$)	2,609.58	888.39
- Nett Item Discount on N Items 10.00/10.00% (S\$)	322.13	65.70
<b>Total Parts (S\$)</b>	<b>9,528.19</b>	<b>3,020.21</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTNG HEADLAMP FOCUSING	New	140.00	30.00
2	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	450.00	0.00
3	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	180.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	600.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,400.00	600.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>3,470.00</b>	<b>1,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >