

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EP 2232 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	\$ 1,697.00	X
2	REAR BUMPER STICKY PAD	4 TBC	+
3	REAR BUMPER FIXING PARTS	\$ 166.00	+
4	REAR WHEEL HOUSING LINER-LH	\$ 32.00	+
5	REAR BUMPER SPOILER <i>new</i>	\$ 206.00	+
6	REAR BUMPER GUIDE SECTION-LH <i>new</i>	\$ 57.00	+
7	REAR LIGHT REFLECTOR-LH/RH	2 \$ 70.00	+
8	REAR BUMPER SEAL RING	4 \$ 14.00	+
9	SIDE PANEL-LH <i>Distorted</i>	\$ 2,006.00	✓ 1604.80
10	REAR WINDOW <i>New</i>	\$ 704.00	✓ 563.20
11	REAR SIDE WINDOW-LH <i>new</i>	\$ 502.00	✓ 401.20
12	REAR SIDE WINDOW TRIM STRIPS-LH <i>new</i>	\$ 388.00	+
13	PRIMER <i>per</i>	2 \$ 37.00	✓ 14.56
14	REAR WHEEL HOUSING LINER -LH <i>new</i>	\$ 532.00	+
15	REAR REINFORCEMENT FOR C PILLAR-LH <i>new</i>	\$ 172.00	? X
16	REAR DOOR-LH <i>Dented</i>	\$ 2,190.00	✓ 1752
17	REAR OUTER DOOR SEAL-LH <i>new</i>	\$ 139.00	✓ 111.20
18	BONDING AGENT <i>new</i>	\$ 43.00	? 34.16 ✓
19	CLENIING SOLUTION <i>new</i>	\$ 64.00	? X
20	APPLICATOR <i>new</i>	\$ 7.00	? X
SUB-TOTAL SPARE PARTS		\$ 9,026.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EP 2232 R.

S/N	Parts Description	Damage Parts	
		S/NETT	RE
21	REAR DOOR INNER SEAL-LH <i>not ne</i>	\$	165.00 <i>X</i>
22	REAR DOOR CATCH-LH <i>not ne</i>	\$	82.00 <i>X</i>
23	REAR DOOR CATCH COVER-LH <i>not ne</i>	\$	14.00 <i>X</i>
24	REAR DOOR EXTERIOR HANDLE-LH <i>Repair</i>	\$	207.00 <i>+</i>
25	REAR DOOR HANDLE HOUSING-LH <i>Repair</i>	\$	26.00 <i>+</i>
26	REAR DOOR SLIDE VALVE -LH <i>2</i>	\$	11.00 <i>+</i>
27	REAR DOOR MOUNTING BAR-LH <i>not ne</i>	\$	143.00 <i>+</i>
28	REAR WINDOW REGULATOR-LH	\$	220.00 <i>+</i>
29	REAR RIM -LH <i>let</i>	\$	659.00 <i>- 527.00</i>
30	REAR TYRE RUBBER VALVE-LH <i>not ne</i>	4 \$	12.00 <i>+</i>
31	ACRYLIC SEALANT <i>2</i>	S/N \$	180.00 <i>✓</i>
32	CAVITY WAX <i>na</i>	S/N \$	140.00 <i>✓</i>
33	STONE CHIP	S/N \$	180.00 <i>✓</i>
34	METAL FILLER POWDER <i>2</i>	S/N \$	280.00 <i>✓</i>
35	REAR WINDSCREEN SEALANT <i>2 nec</i>	S/N \$	200.00 <i>✓</i>
36	1/4 GLASS SEALNT	S/M \$	100.00 <i>✓</i>
37	SUNDRIES <i>the nec</i>	\$	500.00 <i>? X</i>
TOTAL SPARE PARTS		\$	12,145.00
TOTAL LABOUR CHARGES		\$	17,632.00
GRAND TOTAL		\$	29,777.00

30.187

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Ling

Surveyed Date

: 25/09/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorized, 14 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699


Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1097/2018/GW 14-Nov-18 Jeffery Tan 1 EP 2232 R Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labour</u>			
1	To carry out rear solar film installation. <i>NOC</i> (Special Nett)	\$ 400.00	
		\$ 400.00	
TOTAL		\$ 400.00	

For Premium Automobiles Pte Ltd


14/11/18

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1097/2018/GW
Date : 22-Sep-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

14 days - ok - jb - 20 Dec 18

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Mr. Eu Kee Hoe, Gregory
Address : 21 A Simei Street 4
#06-42
Singapore 528718
Telephone : (HP) 97351206
Type of Claim : Own damage claims
Policy No. : 2100507392-01
Vehicle No : **EP 2232 R**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Apr-17
Engine No : CHZ 325699
Chassis No : WAUZZZ8V3H1060083
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Allan Wu / Johnny Boo
Accident Date : 20-Sep-18
Place of Accident : East Point Mall Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EP 2232 R

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N	\$ 280.00	\$ 280.00
2	To renew lhs 1/4 glass and rear windscreen to facilitate fender renewal.	S/N	\$ 600.00	\$ 600.00
3	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	\$ 280.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	\$ 1,400.00
5	To remove and reinstall rear seat assy, back rest, ABCD pillar trims, curtain air bags, safety belts, carpaets, roof liner, carpets, sill trims, etc.	S/N	\$ 1,400.00	\$ 1,400.00
TOTAL LABOUR CHARGES		:	<u>\$ 3,960.00</u>	<u>\$ 3,960.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EP 2232 R

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
			\$ 3,960.00
6	To dismantle rear bumper, rear lid and lhs rear door. Cut out and weld lhs rear fender, lhs rear inner side panel and lhs rear wheel shousing. Renew lhs rear door. Re-organize rear crash management components. Reinstall all parts removed.	\$ 8,400.00	\$ 3,500.00
7	To respray rear bumper, lhs rear fender, lhs rear door, lhs ill panel, door entrances, roof channel, drain panel, door handle, end panelling, lhs side inner panel and lhs wheel hosuing . To carry out stone chip treatment and joint sealer works.	\$ 5,500.00	\$ 2,850.00
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
9	<i>Added labour charges - see attached</i>	\$ 400.00	\$ 400.00
10	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 18,732.00	\$ 11,182.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EP 2232 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,697.00	
2	REAR BUMPER STICKY PAD	4 TBC	
3	REAR BUMPER FIXING PARTS	\$ 166.00	
4	REAR WHEEL HOUSING LINER-LH	\$ 32.00	
5	REAR BUMPER SPOILER	\$ 206.00	
6	REAR BUMPER GUIDE SECTION-LH	\$ 57.00	
7	REAR LIGHT REFLECTOR-LH/RH	2 \$ 70.00	
8	REAR BUMPER SEAL RING	4 \$ 14.00	
9	SIDE PANEL-LH	\$ 2,006.00	\$ 1,604.80
10	REAR WINDOW	\$ 704.00	\$ 563.20
11	REAR SIDE WINDOW-LH	\$ 502.00	\$ 401.20
12	REAR SIDE WINDOW TRIM STRIPS-LH	\$ 388.00	
13	PRIMER	2 \$ 37.00	\$ 14.56
14	REAR WHEEL HOUSING LINER -LH	\$ 532.00	
15	REAR REINFORCEMENT FOR C PILLAR-LH	\$ 172.00	
16	REAR DOOR-LH	\$ 2,190.00	\$ 1,752.00
17	REAR OUTER DOOR SEAL-LH	\$ 139.00	\$ 111.20
18	BONDING AGENT	\$ 43.00	\$ 34.16
19	CLENING SOLUTION	\$ 64.00	
20	APPLICATOR	\$ 7.00	
SUB-TOTAL SPARE PARTS		\$ 9,026.00	\$ 4,481.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EP 2232 R.

S/N Parts Description	c/f	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 4,481.12
21 REAR DOOR INNER SEAL-LH		\$ 165.00	
22 REAR DOOR CATCH-LH		\$ 82.00	
23 REAR DOOR CATCH COVER-LH		\$ 14.00	
24 REAR DOOR EXTERIOR HANDLE-LH		\$ 207.00	
25 REAR DOOR HANDLE HOUSING-LH		\$ 26.00	
26 REAR DOOR SLIDE VALVE -LH		\$ 11.00	
27 REAR DOOR MOUNTING BAR-LH		\$ 143.00	
28 REAR WINDOW REGULATOR-LH		\$ 220.00	
29 REAR RIM -LH		\$ 659.00	\$ 527.20
30 REAR TYRE RUBBER VALVE-LH	4	\$ 12.00	
31 ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
32 CAVITY WAX	S/N	\$ 140.00	\$ 140.00
33 STONE CHIP	S/N	\$ 180.00	\$ 180.00
34 METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
35 REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
36 1/4 GLASS SEALNT	S/M	\$ 100.00	\$ 100.00
37 SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		\$ 12,145.00	\$ 6,088.32
TOTAL LABOUR CHARGES		\$ 18,732.00	\$ 11,182.00
GRAND TOTAL		\$ 30,877.00	\$ 17,270.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1097/2018/GW

14-Nov-18

Jeffery Tan

1

EP 2232 R

Audi A3 Sedan 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labour</u>			
1	To carry out rear solar film installation. (Special Nett) <i>Ne</i>	\$ 400.00	\$ 400.00
		<u>\$ 400.00</u>	<u>\$ 400.00</u>
	TOTAL	\$ 400.00	

For Premium Automobiles Pte Ltd

888 Adrian Ling

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLJ 908 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1097/2018/MAS

26 Feb 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR EP 2232 R, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **EP 2232 R**, claimant, **Mr. Eu Kee Hoe, Gregory**, please find the related document per attached.

1. A copy of the Original invoice no. 85013465 – S\$17,837.24
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – EP 2232 R

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6473 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone: 6388 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2323
8828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 1 12:33

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013465 Date: 16/02/2019 Order: EP2232R Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: EP2232R (V 33327) Regn Date: 19/04/2017 Mileage: 43556 WIP No.: 25711
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V3H1060083 Engine: CHZ 325699 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: To install rear windscreen solar film	400.00	1.00	400.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	280.00	1.00	280.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 2723

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408690
Telephone: 6388 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2323
8628 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 12:33

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013465 Date : 16/02/2019 Order : EP2232R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: EP2232R (V 33327) Regn Date: 19/04/2017 Mileage: 43556 WIP No.: 25711
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V3H1060083 Engine: CHZ 325699 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT, BACK REST, ABCD PILLAR TRIMS, CURTAIN AIRBAG, SAFETY BELTS, CARPETS, ROOF LINER, SILL TRIM ETC	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER, LHS REAR INNER SIDE PANEL AND LHS REAR WHEEL HOUSING. RENEW LHS REAR DOOR. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	3500.00	1.00	3,500.00
S	BODYWORK	M: TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, DOOR HANDLE, END PANELLING AND REAR BUMPER. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	2850.00	1.00	2,850.00
S	BODYWORK	M: TO RENEW LHS REAR RIM AND CARRY OUT WHEEL	280.00	1.00	280.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408688
Telephone: 6386 2223

Customer Service

Service Appointment: 6365 2323
24-hour Breakdown Service: 9628 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 3 12:33

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013465 Date: 16/02/2019 Order: EP2232R Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: EP2232R (V 33327) Regn Date: 19/04/2017 Mileage: 43556 WIP No.: 25711
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V3H1060083 Engine: CHZ 325699 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (43)

		Details	Qty	Unit Price	Amount
S	BODYWORK	ALIGNMENT M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	1080.00	1.00	1,080.00
		TO SUPPLY ACRYLIC SEALANT,CAVITY WAX,STONE CHIP,METAL FILLER POWDER,REAR WINDSCREEN SEALANT AND 1/4 GLASS SEALANT			
X	A8V5809837	SUBPART Less 020%	1.00	2006.00	1,504.80
X	A8V5845297K NVB	SIDE WINDO Less 020%	1.00	501.50	401.20
X	A8V5833051C	(A) (SK) DOOR (15/10/18) Less 020%	1.00	2190.00	1,752.00
X	A8V5845501E NVB	REAR WINDOW Less 020%	1.00	704.00	563.20
X	A8V0601025DC	(V) (SK) RIM 16" C4E Less 020%	1.00	659.00	527.20
X	A8V5839911C	SEAL Less 020%	1.00	139.00	111.20
X	AD 355205A2	BONAGENT Less 020%	1.00	42.70	34.16
X	AD 00920002	PRIMER (DG) Less 020%	1.00	18.20	14.56

Parts	5,008.32	Sub-Total	16,670.32
Labour	0.00	7% GST	1,166.92
Sublet	12,262.00	Grand Total	17,837.24
Menus	0.00		
Lubricant	0.00		

Customer

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: EP 2232 R

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1097/2018/TF
16th November 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V3H1060083
Vehicle Regn No. : **EP 2232 R**
Vehicle Mileage : 43556 KM
Vehicle Owner : Mr Eu Kee Hoe Gregory
Certificate No : 2100507392-01
Own Damage Excess : S\$ 642.00 (inclusive of 7% GST)
Accident Date : 20/09/2018
Place : Eastpoint Mall Carpark
Repair Cost : \$ 17,837.24
WIP No. : 25711
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :

16-Nov-2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Pending for Survey Report
Main	25 Sep 2018		25 Sep 2018 13:55 Edit Adj Rpt	S\$17,270.32 Edit Estimates	S\$17,270.32 View Rpt		Cancel Case

Main		Reference	Claim Details	Documents	Show All
------	--	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: **EU KEE HOE, GREGORY**, ID: S1121195Z, Tel: +6597351206, Email: GREGORYEU@GMAIL.COM

Vehicle Reg. No.: **EP2232R** Date of Loss: 20/09/2018 12:00 - :59
[17 Months and 1 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 5412095788SG** Policy/Cover Note No.: 2100507392-01 (Comprehensive)
Excess: S\$600.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Mohd Zawaye, Norsazani**]
Norsazani.Zawaye@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 04/10/2018]**

Driver/Custodian: **EU KEE HOE, GREGORY (63 / Male)**, NRIC: S1121195Z, Tel: +6597351206 Email: GREGORYEU@GMAIL.COM

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (26/09/2018): Alert - Adj Mandate Approved (S\$18099.00) - EP2232R - Claim Handler: Mohd Zawaye...
- AIG_SG (25/09/2018): EP2232R / OD / 20/09/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EP2232R (5412095788SG)

OD

Sep 20 2018 12:50PM

[EU KEE HOE, GREGORY]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Assessment Reports			1 per page ▼ ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 13:39	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 13:27	General View	Load JPG	☒
2	26/09/18 13:27	Chassis Number	Load JPG	☒
3	26/09/18 13:27	General View	Load JPG	☒
4	26/09/18 13:27	General View	Load JPG	☒
5	26/09/18 13:27	General View	Load JPG	☒
6	26/09/18 13:27	General View	Load JPG	☒
7	26/09/18 13:27	General View	Load JPG	☒
8	26/09/18 13:27	General View	Load JPG	☒
9	26/09/18 13:27	General View	Load JPG	☒
10	26/09/18 13:27	General View	Load JPG	☒
11	26/09/18 13:27	General View	Load JPG	☒
12	26/09/18 13:27	General View	Load JPG	☒
13	26/09/18 13:27	General View	Load JPG	☒
14	26/09/18 13:27	General View	Load JPG	☒
15	26/09/18 13:27	General View	Load JPG	☒
16	26/09/18 13:27	General View	Load JPG	☒
17	26/09/18 13:27	General View	Load JPG	☒
18	26/09/18 13:27	General View	Load JPG	☒
19	26/09/18 13:27	General View	Load JPG	☒
20	26/09/18 13:27	General View	Load JPG	☒
21	26/09/18 13:27	General View	Load JPG	☒
22	26/09/18 13:27	General View	Load JPG	☒
23	26/09/18 13:27	General View	Load JPG	☒
24	26/09/18 13:27	General View	Load JPG	☒
25	26/09/18 13:27	General View	Load JPG	☒
26	26/09/18 13:27	General View	Load JPG	☒
Documentation			1 per page ▼ ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/09/18 13:28	Singapore Accident Statement	Load PDF	
2	26/09/18 13:28	Certificate of Insurance	Load PDF	
3	26/09/18 13:28	Driver's Driving License	Load PDF	
4	26/09/18 13:28	ESTIMATE	Load PDF	
5	01/03/19 16:28	DISCHARGE VOUCHER	Load PDF	
6	01/03/19 16:28	SUPPLEMENTARY	Load PDF	

Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
7	01/03/19 16:28	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/18 15:26	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/18 15:21	Accident Photo	 Load JPG	☒
2	20/09/18 15:21	Accident Photo	 Load JPG	☒
3	20/09/18 15:21	Accident Photo	 Load JPG	☒
4	20/09/18 15:21	Accident Photo	 Load JPG	☒
5	20/09/18 15:21	Accident Photo	 Load JPG	☒
6	20/09/18 15:21	Accident Photo	 Load JPG	☒
7	20/09/18 15:21	Accident Photo	 Load JPG	☒
8	20/09/18 15:21	Accident Photo	 Load JPG	☒
9	20/09/18 15:21	Accident Photo	 Load JPG	☒
10	20/09/18 15:21	Accident Photo	 Load JPG	☒
11	20/09/18 15:21	Accident Photo	 Load JPG	☒
12	20/09/18 15:21	Accident Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/18 15:16	Sketch Plan	 Load JPG	☒
2	20/09/18 15:16	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST There are no document checklists configured.	Reset Save Print
--	---

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18017399/AQBS2
Date: 01/03/2019

REFERENCE

Insured/Claimant: EU KEE HOE, GREGORY Policy No: 2100507392-01
Date of Loss: 20/09/2018 Nature of Claim: OD Claim No: 5412095788SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EP2232R** Engine No: CHZ325699
Make & Model: AUDI A3, 999cc TFSI (A) Chassis No: WAUZZZ8V3H1060083
Reg. Date: 19/04/2017 (Man. Year: 2017) Odometer: 34871 km
Colour: Grey
Engine Capacity: 999 cc
Market Value/New Car Price: S\$95,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	12,145.00	6,088.32	6,056.68	49.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,032.00	11,182.00	6,850.00	37.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,177.00	17,270.32	12,906.68	42.77
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	29,577.00	16,670.32	12,906.68	43.64
+ GST 7.00/7.00% (S\$)	2,070.39	1,166.92	903.47	43.64
Nett Amount (S\$)	31,647.39	17,837.24	13,810.15	43.64

INSPECTION

Date of Assignment: 25/09/2018 Premium Automobiles Pte Ltd (UBI)
Date Inspected: 25/09/2018 Inspected At: 55 Ubi Road 1
Estimated Period of Repair: 14.0 days Singapore 408699

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,697.00 FS	*- FS
2	4		*REAR BUMPER STICKY PAD (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	166.00 FS	*- FS
4	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	32.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Not Necessary	206.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	57.00 FS	*- FS
7	2		*REAR LIGHT REFLECTOR - LH/RH	Not Necessary	70.00 FS	*- FS
8	4		*REAR BUMPER SEAL RING	Not Necessary	14.00 FS	*- FS
9	1		*SIDE PANEL - LH	Distorted	2,006.00 FS	*1,604.80 FS
10	1		*REAR WINDOW	Necessary	704.00 FS	*563.20 FS
11	1		*REAR SIDE WINDOW - LH	Necessary	502.00 FS	*401.20 FS
12	1		*REAR SIDE WINDOW TRIM STRIPS - LH	Not Necessary	388.00 FS	*- FS
13	2		*PRIMER	Necessary	37.00 FS	*14.56 FS
14	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	532.00 FS	*- FS
15	1		*REAR REINFORCEMENT FOR C PILLAR - LH	Not Necessary	172.00 FS	*- FS
16	1		*REAR DOOR - LH	Dented	2,190.00 FS	*1,752.00 FS
17	1		*REAR OUTER DOOR SEAL - LH	Necessary	139.00 FS	*111.20 FS
18	1		*BONDING AGENT	Necessary	43.00 FS	*34.16 FS
19	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
20	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
21	1		*REAR DOOR INNER SEAL - LH	Not Necessary	165.00 FS	*- FS
22	1		*REAR DOOR CATCH - LH	Not Necessary	82.00 FS	*- FS
23	1		*REAR DOOR CATCH COVER - LH	Not Necessary	14.00 FS	*- FS
24	1		*REAR DOOR EXTERIOR HANDLE - LH	Repair	207.00 FS	*- FS
25	1		*REAR DOOR HANDLE HOUSING - LH	Repair	26.00 FS	*- FS
26	1		*REAR DOOR SLIDE VALVE - LH	Not Necessary	11.00 FS	*- FS
27	1		*REAR DOOR MOUNTING BAR - LH	Not Necessary	143.00 FS	*- FS
28	1		*REAR WINDOW REGULATOR - LH	Not Necessary	220.00 FS	*- FS
29	1		*REAR RIM - LH	Cut	659.00 FS	*527.20 FS
30	4		*REAR TYRE RUBBER VALVE - LH	Not Necessary	12.00 FS	*- FS
31	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
32	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
33	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
34	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
36	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
37	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	12,145.00	6,088.32
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	New	280.00	280.00
2	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL.	New	600.00	600.00
3	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	New	280.00	280.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEAT ASSY, BACK REST, ABCD PILLAR TRIMS, CURTAIN AIR BAGS, SAFETY BELTS, CARPETS, ROOF LINER, CARPETS, SILL TRIMS, ETC.	New	1,400.00	1,400.00
6	TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER, LHS REAR INNER SIDE PANEL AND LHS REAR WHEEL HOUSING. RENEW LHS REAR DOOR. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	8,400.00	3,500.00
7	TO RESPRAY LHS REAR FENDER, LHS REAR DOOR, LHS ILL PANEL, DOOR ENTRANCE, ROOF CHANNEL, DRAIN PANEL, DOOR HANDLE, END PANELLING, LHS SIDE INNER PANEL AND LHS WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	New	4,800.00	2,850.00
8	TO REMEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
10	TO CARRY OUT REAR SOLAR FILM INSULATION.	New	400.00	400.00
Gross Labour Cost (S\$)			18,032.00	11,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >