

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBB7783T/1809136

24th September 2018

The Manager
Motor Claim Department
India International Insurance Pte Ltd
64 Cecil Street
#04/05 IOB Building
Singapore 049711

Date of Accident : 24TH August 2018
Location : Onan Road
Third Party Claim Vehicle No : SH 7404 E
Repair Cost For Vehicle No : GBB 7783 T Nissan Cabstar

*not authorized
h/c
H/cy.
who photo attached
26/9/18*

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front corner panel (Nett)	10/324 1	389.90	\$ 389.90 —
2	Headlamp assy RH (Nett)	11 1	393.60	\$ 393.60 x
3	Headlamp end panel RH (Nett)	11 1	85.00	\$ 85.00 x
4	Front bumper fascia (Nett)	cur/721 1	945.10	\$ 945.10 —
5	Front bumper side bracket RH (Nett)	34 1	87.50	\$ 87.50 —
6	Front door assy RH (Nett)	5-13-00 1	1,496.50	\$ 1,496.50 —
7	Front door hinge top (Nett)	11 1	76.10	\$ 76.10 x
8	Front door hinge bottom (Nett)	11 1	76.10	\$ 76.10 x
9	Front door step garnish RH (Nett)	garn 6 1	139.40	\$ 139.40 —
10	Front door lamp RH (Nett)	310 1	48.50	\$ 48.50 —
11	Front wheel arch panel RH (Nett)	11 1	1,646.40	\$ 1,646.40 x
12	Front grille (Nett)	11 1	578.60	\$ 578.60 x
13	Front grille emblem (Nett)	11 1	65.10	\$ 65.10 x
16	Front wheel rim RH (s/nett)	11 1	248.80	\$ 248.80 x
17	Front wheel tyre RH (s/nett)	11 1	280.00	\$ 280.00 ?
18	Front door sticker RH (s/nett)	11 1	28.00	\$ 28.00 —
				\$ 6,584.60

10%

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBB7783T/1809136

24th September 2018

Balance b/f	\$ 6,584.60
<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking & welding front door RH, front wheel arch panel RH, front corner panel RH, remove & install all damage parts, straighten & re-align body	\$ 980.00 600
Remove & refix front door board, glass. Lock & etc	\$ 100.00 60
Tuff-kote on damage parts	\$ 80.00 60
Body lettering on front door RH	me \$ 280.00 ✓
Computerize wheel alignment	\$ 120.00 60
Spray painting on damage parts	\$ 1,000.00 600
Check all lighting after repairs	\$ 40.00 20
Labour Charge	<u>\$ 2,600.00</u>
Total Amount	<u>\$ 9,184.60</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: