

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 26 Sep 2018

Preliminary Advice

Vehicle No	: SLM5373E	Accident Date	: 21/09/2018
Make	: BMW 116D	Policy No.	: DMPCSN1764911700
Assignment Date	: 24/09/2018	Excess	: S\$500.00
Date of Inspection	: 25/09/2018	Est. Duration of Repair	: 5 days
Inspection At	: Sime Darby Services Pte Ltd (HQ) NO. 9 DEFU LANE 1 Singapore 539484		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,553.10
Revised Amount	:S\$	10,859.25
Check Items (Estimated)	:S\$	4,074.85
Total	:S\$	14,934.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	96,000.00
COE / PARF Rebate	:S\$	52,587.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,413.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :