

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 48516
Date Estimated : 21/09/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Hong Shi Ling
Blk 8 Marsiling Drive
#10-30

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 730008

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLM5373E	5G86423	31/03/2017	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMP *	3.20	10.00		32.00 <i>me</i>
# INTAKE GRILLE *	20.30	1.00		20.30 <i>CR</i>
# IMPACT ABSORNER TOP *	42.45	1.00		42.45 <i>CR</i>
# SET PDC HOLDER FRONT *	23.10	1.00		23.10 <i>me</i>
# FRONT PANEL V STRUT *	110.00	1.00		110.00 <i>BT</i>
# RH MOUNT FOR HOOD *	7.70	1.00		7.70 <i>me</i>
# CONDENSER AIR CONDITIONING *	1,028.45	1.00		1,028.45 <i>TX</i>
# LABEL COOLANT 500+/-10G *	23.80	1.00		23.80 <i>me</i>
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05 <i>me</i>

Total Labour :
Total Parts : 1,340.85
Total Labour & Parts : 1,340.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: