

7/200/2002

ASS. REC. BY:

REF: CS/FCI/8017409 / Adm 12/ Special Instruction:

Surveyor: Aaron.

ASSIGNMENT (Office)

From (Person): CC3 Karen Tan

of FCI

Date/Time: 25/09/2018 1pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 3496J

Insured:

SH 6506B

at Workshop m/s:

Huameng

Tel:

6747 8064

of

Blk 1 Kaki Bukit Ave 6 #01-61

Policy No:

Claim No:

D180070004MTSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 20092018

(Client's Record)

CA / REV / REP. / REV 24 HRS DS'

H.O.D. Endorsement:

Date/Time: 25/09/2018 2.30pm

Person Contacted:

Jure

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJT 3496J - C66 / 176 / 180 / 13 / 18 / Area 3 DUA: 12072018
	SH 6506B - CC3 / C71 / 7017773 / K1263712 DUA: 12092017
24/9/18 @ 4.38pm	Informed Karen Tan, we are pending estimate from repairer.
27/12/18 @ 5.07pm	Revised to Karen Tan by email.
	LS \$7500, 6 days (Red \$13413, 64%)
	MV \$326600; LPA \$21712; NV \$10288

REF: FCI

ASSIGNMENT

From: Date: 25092018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS.

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJT3496J-

Yr Regn: 2009 / Oct.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4-

C.C. 1798

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

130543.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU2228K7AA017698

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R17

R:

225/50R17.

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

ob

mm

R/Bal.

ob

mm

L/Bal.

ob

mm

L/Bal.

ob

mm

D.O.A.

D.O.I.

25/09/18

Survey held at

Hua Meng

Des. of Damages: Frt / Rear / ☒ O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

T.P / 1st Cap.

MV: 321C.

PV: 21.7K

Nett: 10.3K

RECEIVED 28 DEC 2018

Date/Time, File Pass to?

1) 27/12/18

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

☐ : Preli. Report☐ : Final Report

7P

7500

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos

Other

TOTAL

10x15: 150

170 + 150

50

50

52

472

MOTOR SURVEY ASSIGNMENT

Date	24-09-2018	Our Ref No. D18007004MFSH
Accident Date	20-09-2018	Claim Type. Third Party
Insured Vehicle	SH6506B	Third Party Vehicle. SJT3496J
Survey Location	AUTOBAY@KAKIBUKIT 1 KAKI BUKIT AVENUE 6BLK C #01-61/01-34	
Contact Person.	JUNE	
Contact No.	67478064/ 67465519	Fax No. 67434896
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA MENG SPRAY PAINTING WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 27 December 2018 5:02 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007004MFSH/1
Attachments: CSFCI18017409Aqb.pdf

Dear Karen,

Enclosed herewith preliminary advice of SJT 3496J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 27 September 2018 4:38 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007004MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SJT 3496J on 25/09/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 25 September 2018 2:18 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007004MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007004MFSH

Date: 27 December 2018

Our Ref: CS/FCI18017409/Aqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJT 3496J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/09/2018 at the premises of M/s HUA MENG, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>20,913.00</u>
Revised Estimate Amount	: S\$ <u>7,500.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 27 September 2018 4:38 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007004MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SJT 3496J on 25/09/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 25 September 2018 2:18 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007004MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 25 September, 2018 1:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007004MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0641J
Vehicle Details	
Vehicle No.:	SJT3496J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8T FSI MU CVT ABS D/AB 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	CDH059370
Chassis No.:	WAUZZZ8K7AA017698
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$35,932.00
Original Registration Date:	01 Oct 2009
First Registration Date:	01 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$35,932.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Sep 2019
PARF Rebate Amount:	\$19,762.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,830.00
COE Rebate Amount:	\$1,950.00
Total Rebate Amount:	\$21,712.00

The information contained herein is correct as at 26 Sep 2018

OK



☐ Audi A4 1.8A TFSI MU (New 10-yr COE) \$58,800 \$5,880 /yr 27-Mar-2009 1,798 cc 121,000 km Luxury Available

Low Mileage Clocked. Fully Serviced And Maintained By Agent With Receipt To Show. No Expenses Spared For Preventive Maintenance And Always Kept In Top Condition. Well Maintained Exterior And Interior....

Roadlink Auto Pte Ltd

☆ Posted: 26-Sep-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



☐ Audi A4 Avant 3.2 FSI Quattro S-Line \$34,800 \$14,170 /yr 15-May-2009 3,197 cc - Stationwagon Available

Super Rare V6 Avant. Ideal For Short Term Drive! Unique And Charming Stationwagon. Top Notch Condition! A Well Designed Everyday Car With Sporty Appearance And Powerful Performance Engine. Perfect For...

☆ Posted: 02-Aug-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



☐ Audi A4 Avant 2.0A TFSI (New 10-yr COE) \$72,900 \$7,280 /yr 16-Jun-2009 1,984 cc 115,185 km Stationwagon Available

A Sedan Power House. A Combination Of Power, Comfort And Functionality. Impeccable Condition, Well Maintained By Owner. Road Tax Just Renewed And Inspection Just Completed. This Will Be Your Best Buy ...

☆ Posted: 13-Aug-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



Save up to 25% on petrol

Compare the latest petrol discount credit cards on sgCarMart. Enjoy discounts as high as 25% on your petrol bills.

Find out more!



☐ Audi A4 2.0A TFSI Quattro S-tronic \$30,800 \$11,920 /yr 27-Jul-2009 1,984 cc 134,000 km Luxury Available

95% Loan Welcome. 2.0 Model Audi A4. High OMV Of \$41,810. No Repair Needed! Well Maintained By Owner. Servicing Done Regularly. Always Parked Under Shelter. Enjoy A Comfortable And Serene Ride In The ...

Euro Performance Asia Pte Ltd

☆ Posted: 13-Sep-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



☐ Audi A4 1.8A TFSI MU \$26,800 \$10,300 /yr 06-Aug-2009 1,798 cc 146,000 km Luxury Available

Owner Consignment Unit, Very Low Mileage Done, Minimal Losses For A Year. Cheaper Than Renting A Car. Guaranteed PARF Rebate Is \$18,000 Not Included The Scrap Body Price. Car Is In Good Condition, Abl...

☆ Posted: 21-Sep-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



☐ Audi A4 Avant 2.0A TFSI \$33,800 \$14,700 /yr 25-Aug-2009 1,984 cc 135,000 km Stationwagon Available

New 6 Month Road Tax/New Front Suspension With This Avant, Spacious Boot To Fit Huge Load Or Any Pets To Bring Along For Outing, Viewing By Appointment.

☆ Posted: 17-Sep-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



☐ Audi A4 Avant 2.0A TFSI S-Line \$32,999 \$13,770 /yr 26-Aug-2009 1,984 cc - Stationwagon Available

No Gimmicks! Price Negotiable, Low Mileage Done, 100% Beautiful Condition, Low Depreciation, Low Interest Rate, Most Worthy Buy, Call Now For Viewing.

☆ Posted: 22-Sep-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



☐ Audi A4 2.0A TFSI Quattro S-tronic \$37,800 \$12,590 /yr 09-Nov-2009 1,984 cc 130,000 km Luxury Available

95% Loan Welcome. Sporty Grey Unit. 2.0 Model Audi A4. High OMV Of \$47,458. No Repair Needed! Well Maintained By Owner. Servicing Done Regularly. Always Parked Under Shelter. Enjoy A Comfortable And S...

Euro Performance Asia Pte Ltd

☆ Posted: 10-Aug-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



☐ Audi A4 1.8A TFSI MU \$32,888 \$13,060 /yr 18-Nov-2009 1,798 cc 167,000 km Luxury Available

Loan Up To 100% Loan Available! Balloon Scheme To Lighten Your Monthly Installment. Vehicle In Showroom Condition. Fully Stock Condition. Best For Short Term Use With Low Depreciation. Accident Free U...

☆ Posted: 21-Sep-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi



☐ Audi A4 Avant 2.0A TFSI Quattro S-tronic S-Line (New 10-yr COE) \$99,800 \$9,970 /yr 08-Dec-2009 1,984 cc - Stationwagon Available

Engine Overhaul Was Done And 5k Spent In Aug 2018, New Transmission Was Done And Almost 8k Spent In June 2017, New Fuel Pump, 80% New Tyres All Receipts Are Available. Perfect Ideal Vehicle For COE Ren...

☆ Posted: 16-Sep-2018 Tags: 2009 Audi A4, 2009 audi a4, Audi A4, audi a4, Audi, A4, a4, Used Audi

SHORTLISTED HISTORY

Compare [4]

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SIOW HUI PENG

762 BEDOK RESERVOIR ROAD

#12-15

S 479246

TP 1st Cap

Xiao Chau

Date

:05.10.2018

Vehicle no

:SJT 3496 J

Make/Model

:AUDI A4

Accident date

:20.09.2018

No	DESCRIPTION	Qty	Amount (S\$)
<u>List Items</u>			
1	Front RH door Distorted	1	\$ 1980 ✓
2	Fron RH door glass xren	1	\$ 187x
3	Front RH door glass outer moulding xren	1	\$ 220x
4	Front RH door outer handle ut	1	\$ 110 ✓
5	Front RH door outer handle key lock xren	1	\$ 280 x
6	Front RH door inner lock Dmgd	1	\$ 286 ✓
7	Front RH door inner board crushed	1	\$ 1650 ✓
8	Front RH door inner weather strip xren	1	\$ 154 ✓
9	Front RH door inner top rubber xren	1	\$ 308 x
10	Front RH door power window motor Dmgd	1	\$ 264 ✓
11	Front RH door power window regulator Dmgd	1	\$ 297 ✓
12	Front RH door side mirror xren	1	\$ 1298 +
13	Front RH door top hinge 3 xren	1	\$ 110 x
14	Front RH door lower hinge	1	\$ 110 x
15	Front RH door stopper xren	1	\$ 93.5x
16	Rear RH door Distorted	1	\$ 1980 ✓
17	Rear RH door glass outer moulding xren	1	\$ 220 x
18	Rear RH door top hinge 3 Best	1	\$ 110 ✓
19	Rear RH door lower hinge	1	\$ 110 ✓
20	Rear RH door stopper xren	1	\$ 93.5x
21	Rear RH door inner board xren	1	\$ 1650x
22	Rear RH door weather strip xec	1	\$ 165 ✓
23	Rear RH door top rubber xren	1	\$ 308 +
24	Rear RH door inner lock Dmgd	1	\$ 319 ✓
25	Rear RH fender Repair	1	\$ 1914 +
26	Rear RH fender quarter glass moulding xren	1	\$ 253 x
27	RH rocker panel Repair	1	\$ 781 +
28	Rear bumper Repair	1	\$ 935 x
29	Rear bumper RH holder xren	1	\$ 27 x
Total			\$ 16213

7425
705375

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SIOW HUI PENG
762 BEDOK RESERVOIR ROAD
#12-15
S 479246

Date :05.10.2018
Vehicle no :SJT 3496 J
Make/Model :AUDI A4
Accident date :20.09.2018

No	Description	Qty	Amount (\$\$)
----	-------------	-----	---------------

Special Nett Items

1	Rear RH sport rim <i>He rev</i>	1	\$ 800 <i>x</i>
2	Rear RH tyre <i>Lot</i>	1	\$ 300 <i>250</i>
Total			\$ 1100

Labour Cost

1	Remove & reinstall door <i>glass & fittings</i>		\$ 300 <i>160</i>
2	Remove & reinstall roof lining & cushion		\$ 150 <i>x</i>
3	Remove, replace & repair consistent to the accident		\$ 1600 <i>800</i>
4	Respray painting		\$ 1400 <i>1100</i>
5	Tuff kote		\$ 150 <i>x</i>
Total			\$ 3600

Grand Total \$ 20913

total 9363.75.
1/5 : 7.5k.
06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017409/Aqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6506B	Veh. Inspected	SJT 3496J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007004MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	25/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WAUZZZ8K7AA017698	Colour	BLACK	
Odometer	130543	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	DUNLOP	6 mm	
L/H Front Tyre	225/50 R17	DUNLOP	6 mm	
R/H Rear Tyre	225/50 R17	DUNLOP	6 mm	
L/H Rear Tyre	225/50 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/09/2018	Inspection Date	25/09/2018	
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 3496J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT RH DOOR	DISTORTED	1,980.00	1,980.00
1	FRONT RH DOOR GLASS	NOT NECESSARY	187.00	-
1	FRONT RH DOOR GLASS OUTER MOULDING	NOT NECESSARY	220.00	-
1	FRONT RH DOOR OUTER HANDLE	CUT	110.00	110.00
1	FRONT RH DOOR OUTER HANDLE KEY LOCK	NOT NECESSARY	280.00	-
1	FRONT RH DOOR INNER LOCK	DAMAGED	286.00	286.00
1	FRONT RH DOOR INNER BOARD	CRACKED	1,650.00	1,650.00
1	FRONT RH DOOR INNER WEATHER STRIP	NECESSARY	154.00	154.00
1	FRONT RH DOOR INNER TOP RUBBER	NOT NECESSARY	308.00	-
1	FRONT RH DOOR POWER WINDOW MOTOR	DAMAGED	264.00	264.00
1	FRONT RH DOOR POWER WINDOW REGULATOR	DAMAGED	297.00	297.00
1	FRONT RH DOOR SIDE MIRROR	NOT NECESSARY	1,298.00	-
1	FRONT RH DOOR TOP HINGE	NOT NECESSARY	110.00	-
1	FRONT RH DOOR LOWER HINGE	NOT NECESSARY	110.00	-
1	FRONT RH DOOR STOPPER	NOT NECESSARY	93.50	-
1	REAR RH DOOR	DISTORTED	1,980.00	1,980.00
1	REAR RH DOOR GLASS OUTER MOULDING	NOT NECESSARY	220.00	-
1	REAR RH DOOR TOP HINGE	BENT	110.00	110.00
1	REAR RH DOOR LOWER HINGE	BENT	110.00	110.00
1	REAR RH DOOR STOPPER	NOT NECESSARY	93.50	-
1	REAR RH DOOR INNER BOARD	NOT NECESSARY	1,650.00	-
1	REAR RH DOOR WEATHER STRIP	NECESSARY	165.00	165.00
1	REAR RH DOOR TOP RUBBER	NOT NECESSARY	308.00	-
1	REAR RH DOOR INNER LOCK	DAMAGED	319.00	319.00
1	REAR RH FENDER	TO REPAIR SEE LABOUR	1,914.00	-
1	REAR RH FENDER QUARTER GLASS MOULDING	NOT NECESSARY	253.00	-
1	RH ROCKER PANEL	TO REPAIR SEE LABOUR	781.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	935.00	-
1	REAR BUMPER RH HOLDER	NOT NECESSARY	27.00	-

Report Ref No. CS/FCI18017409/Aqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 5% DISCOUNT		-	-371.25
			16,213.00	7,053.75
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH SPORT RIM (SN)	NOT NECESSARY	800.00	-
1	REAR RH TYRE (SN)	CUT	300.00	250.00
			1,100.00	250.00
	<u>LABOUR</u>			
	REMOVE & REINSTALL DOOR FITTINGS.		300.00	160.00
	REMOVE & REINSTALL ROOF LINING & CUSHION.	NOT NECESSARY	150.00	-
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR RH FENDER, RH ROCKER PANEL AND REAR BUMPER.		1,600.00	800.00
	RESPRAY PAINTING.		1,400.00	1,100.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
			3,600.00	2,060.00
	GRAND TOTAL		20,913.00	9,363.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,500.00

Report Ref No. CS/FCI18017409/Aqbn2

MARKET VALUE: \$32,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$21,712.00=NETT VALUE: \$10,288.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.