

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 01 Oct 2018

Preliminary Advice

Insured Vehicle No : SLL7922M
TP Vehicle No : SHA9723M
Make : HYUNDAI I40
Date of Inspection : 25/09/2018
Inspection At : Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint
Singapore 568047

Accident Date : 18/09/2018
Assignment Date : 24/09/2018
Est. Duration of Repair : 10 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front & o/s rear portion, o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,822.28
Revised Amount	:S\$	19,499.74
Check Items (Estimated)	:S\$	139.92
Total	:S\$	19,639.66

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.