

PDI TUAS

PDI TUAS

WANG SHIYA, JEAN
331 CHO A CHU KANG AVENUE 3
#02-01
Singapore, 689869
Singapore

Tan Jiah 97495749
WP 26/11/2016
03 days
surv @ LK Auto
Resurvey before paint

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV037586
Quote No. SER/QUO/1801592
QuoteDate 24/09/18
Salesperson Jimmy Lee
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Touran 7 1.6 TDI CL 85kW EQP	45,914	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKW6365G	WVGZZZ1TZW044246	30/05/17	Jimmy Lee
Engine Code	Labor Type	Engine No.	Model Code
	1N	DGD 023782	5T132Z

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		840 2,520.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		✓ 480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		✓ 280.00
	Nett				
	Sum Labor				5,680.00
P 5TA807305	BUMPER REINFORCEMENT	1	Pieces		7 616.70
P 5TA807393	BUMPER BRACKET LHS	1	Pieces		34.20
P 5TA807394	BUMPER BRACKET RHS	1	Pieces		34.20
P 5TA807417 GRU	REAR BUMPER	1	Pieces		de 1,863.87
P 5TA807568 9B9	REAR LOWER SPOILER	1	Pieces		unt 373.15
P 5TA807863	REAR CENTER STRIP	1	Pieces		unt 79.67
	Sum Item				3,001.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sum Labor		5,680.00
Sum Item		3,001.79
Total SGD		8,681.79
7% GST	8,681.79	607.73
Total SGD Incl. GST		9,289.52