



WEARNES

3223

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

74064 - C00001

Mr Mohammad Ahshik Bin Kader Bakas
12 Jalan Bilal

Singapore 468864

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Mohammad Ahshik B

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 24/09/2018

WIP No. : 29145

Veh.In/Out:

*Tel.No. : Mobile: 97948172

Reg.No. : SFT1121B

Reg.date : 25/07/2017

Mileage : 0

Chassis No: SALCA2AN5HH700425

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR BUMPER, REPAIR BOOTLID, TOW COVER, ETC	0	2400.00	0	2,400.00	S	1200
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, REAR BOOTLID, ETC	0	2000.00	0	2,000.00	S	1000
280	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	0	486.00	0	486.00	S	✓
	BUMPER COVER REAR DS	1.0 EA	1928.20		1,928.20	S	de -
	TOW EYE COVER REAR D	1.0 EA	432.10		432.10	S	de -
	LAMP - FOG - REAR LH	1.0 EA	337.00		337.00	S	?
	LAMP - FOG - REAR RH	1.0 EA	337.00		337.00	S	?

Tanji 97495247
'wp'

03 days
07/11/18 2:45 pm

Resing before part

sure/akantow

Gross Total. 7,920.30

Labour Total 4,886.00
Parts Total 3,034.30
Package Total 0.00

Net..... 7,920.30
GST @ 7.0% 554.42
Total..... 8,474.70
Paid..... 0.00
Please Pay.. 8,474.70

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated