

SERVICE ESTIMATE

74064 - C00001 SL: SERVICE SALES - PC

Mr Mohammad Ahshik Bin Kader Bakas
12 Jalan Bilal

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 24/09/2018

WIP No. : 29145

Singapore 468864

Veh.In/Out:

*Tel.No. : Mobile: 97948172

Reg.No. : SFT11218

Closed by : Paul Ong Qing Yong

Reg.date : 25/07/2017

Svc Consultant :

Mileage : 0

Remarks : Mr Mohammad Ahshik B

Chassis No: SALCA2AN5HH700425

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REPAIR BOOTLID, TOW COVER, ETC	0	2400.00	0		2,400.00	S
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, REAR BOOTLID, ETC	0	2000.00	0		2,000.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
	BUMPER COVER REAR DS	1.0 EA	1928.20			1,928.20	S
	TOW EYE COVER REAR D	1.0 EA	432.10			432.10	S
	LAMP - FOG - REAR LH	1.0 EA	337.00			337.00	S
	LAMP - FOG - REAR RH	1.0 EA	337.00			337.00	S

Gross Total. 7,920.30

Labour Total 4,886.00
Parts Total 3,034.30
Package Total 0.00

Net..... 7,920.30
GST @ 7.0% 554.42
Total..... 8,474.70
Paid..... 0.00
Please Pay.. 8,474.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated