

INS. CASE OWNER:

CC 4 / VP 180 17424, Uha3n2

LKK:

IDAC:

## ASSIGNMENT

Surveyor:

Mappus

DOI:

24/09/18

Date / Time:

24/9/2018

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

56K 57390

Name of Insured:

Teng Seng Ming Picky

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

23/9/2018

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Teng Hui Kai Eugene

Driver Tel No.:

9066 0827

(V/L: YES / NO)

Claim No.:

18/18/18/VP05/020931 G4

Policy No.:

218VP05019633

Make / Model:

T-MOS

Place of Accident:

P16

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

STN 9004M

56K 57390

5044942.8



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

7/10/18

5044942.8 - CS/Rel 14500136/14500136; DOA: 30/12/13  
56K 57390 - CS/Rel 14500136/14500136; DOA: 23/09/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

08/10/18

- FILE REBUND. OLD INVOLVED IN A 3  
- VEH. C.C. 4 OLD WYS 2ND CAR.  
- TYPE REPORT FOR WANDATE APPROVAL.  
- REPORT DONE.17/10/18  
19/10/18- 960K WANDATE APPROVAL TO LPC BY GUAL  
- LPC APPROVED WANDATE

20/10/18

- SEND 1ST OFFER TO TP.  
- TP REJECTED OFFER.  
- RE 760K WANDATE FOR LOR.

12/01/19

- 960K 2ND OFFER TO TP.  
- TP ACCEPTED OFFER. ALL BOSS IN ORDER

PRELIMINARY ADVICE Date/Time:

26/9

Sent By:

JW

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L19

S\$ 6,500.00 ( 5 days) Reduction: 64 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100 (Assessed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

S\$ 6,500.00

(3 JEH. C.C.; OLD 2ND)

Loss of Rental (LOR):

S\$ 780.00 ( 5 days) x 150

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Norm/Reject/Private Settle

2) Report Format:

3) Survey fee: 400.00

Total:

S\$ 7,257.45

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 7,257.45

Name 1:

ZOOM AUTOWORKS PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

-

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

-

(08/11/13) wef

ASS. REC. BY: MORUJ

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SDY 49423at Workshop m/s: Room

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7122A

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SDY 49423Yr Regn: 9115Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Toyotac.c. 1988Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 5-6 958

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 25460 0051510Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/55R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or 9 CCE1212

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 23/9/18D.O.I. 24/9/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21A 59847L/S \$6,500.00Gross: \$11,594.60 (64%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VP05/020931  
Our ref: CC4/LPC18017424/Uha3

Date: 26.09.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SDY 4942B**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.09.2018 at the premises of M/s Zoom Autowerks Pte Ltd have the following to report:-

Workshop Estimate Amount	: S\$	18,094.60
Revised Estimate Amount	: S\$	8,125.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	8,125.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 7122A

### Vehicle Details

Vehicle No.: SDY4942B  
Vehicle to be Exported: No  
Intended Deregistration Date: 26 Sep 2018  
Vehicle Make: TOYOTA  
Vehicle Model: HARRIER ELEGANCE 2.0 A  
Primary Colour: White  
Manufacturing Year: 2015  
Engine No.: 3ZRB604253  
Chassis No.: ZSU600051510  
Maximum Power Output: 111.0 kW (148 bhp)  
Open Market Value: \$25,778.00  
Original Registration Date: 22 Sep 2015  
First Registration Date: 22 Sep 2015  
Transfer Count: 0  
Actual ARF Paid: \$23,090.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 21 Sep 2025  
PARF Rebate Amount: \$17,317.00

### Intended COE Rebate Details

COE Expiry Date: 21 Sep 2025  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$61,001.00  
COE Rebate Amount: \$42,630.00  
**Total Rebate Amount: \$59,947.00**

The information contained herein is correct as at 26 Sep 2018

OK



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130  
Tel: 9450 7920  
\* zoomautowerks@gmail.com

25 September 2018

REG NO.: SDY 4942 B  
MAKE/MODEL: TOYOTA HARRIER

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	99.70
1	Rear tailgate	1,669.00
2	Rear tailgate dampers	523.20
1	Rear tailgate inner board	455.20
1	Rear tailgate lock	599.20
1	Rear tailgate logo	76.80
2	Rear tailgate reflectors	889.00
1	Rear tailgate rubber	326.10
1	Rear tailgate "HARRIER" emblem	69.10
1	Rear tailgate outer moulding	226.50
1	Rear tailgate inner handle	136.90
1	Rear tailgate outer opening switch	184.80
2	Rear taillamps	1,138.20
1	Rear end panel	717.20
1	Rear end panel inner garnish	255.70
1	Rear keyless sensor	329.80
1	Rear bumper	1,385.00
2	Rear bumper brackets	169.80
1	Rear bumper inner sponge	156.30
1	Rear bumper lower diffuser	529.10
2	Rear bumper reflectors	103.00
2	Rear bumper side retainers	169.80
1	Rear floor panel	1,048.50
1	Rear floor board	655.20
1	Rear exhaust silencer	1,068.50
2	Rear exhaust mountings	97.00
1	Rear fender	1,446.90
2	Rear fender inner air vents	260.90
2	Rear fender inner shields	336.40
2	Rear fender inner trims	1,470.00
		\$ 16,592.80
Less 25%		\$ 4,148.20
		\$ 12,444.60

c/f:

\$

12,444.60

SPECIAL NETT ITEMS

- |   |                               |
|---|-------------------------------|
| 1 | Rear windscreen sealant       |
| 1 | Rear bumper clip (1 set)      |
| 1 | Rear number plate with holder |
| 1 | Rear reverse sensor (1 set)   |
| 1 | Rear reverse camera           |
| 1 | Rear floor sound insulator    |

21	\$	80.00	40
21	\$	50.00	✓
11	\$	50.00	X
shuf	\$	350.00	200
11	\$	480.00	X
11	\$	180.00	X
	\$	1,190.00	

290

S/NLABOUR CHARGES

- |   |  |
|---|--|
| 1 | To remove, replaced damaged lamps and check up rear wiring.  |
| 2 | To remove and refit inner garnishes.                         |
| 3 | To remove and refit rear reverse sensor and camera.          |
| 4 | To transfer rear tailgate mechanism and wiring assembly.     |
| 5 | To remove and refit rear windscreen glass.                   |
| 6 | To remove, refit and replace exhaust silencer and mountings. |
| 7 | To apply undercoating.                                       |
| 8 | Panel beating.   |
| 9 | To re-spray painting on the affected areas.                  |

\$	80.00	30
\$	150.00	100
\$	180.00	50
\$	120.00	80
\$	180.00	120
\$	150.00	X
\$	200.00	60
\$	1,800.00	800
\$	1,600.00	1000
\$	4,460.00	

2240

GRAND TOTAL :

\$ 18,094.60

LKH Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130  
Tel: 9450 7920  
\* zoomautowerks@gmail.com

25 September 2018

REG NO.: SDY 4942 B  
MAKE/MODEL: TOYOTA HARRIER

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	99.70
1	Rear tailgate	1,669.00
2	Rear tailgate dampers	523.20
1	Rear tailgate inner board	455.20
1	Rear tailgate lock	599.20
1	Rear tailgate logo	76.80
2	Rear tailgate reflectors	889.00
1	Rear tailgate rubber	326.10
1	Rear tailgate "HARRIER" emblem	69.10
1	Rear tailgate outer moulding	226.50
1	Rear tailgate inner handle	136.90
1	Rear tailgate outer opening switch	184.80
2	Rear taillamps	1,138.20
1	Rear end panel	717.20
1	Rear end panel inner garnish	255.70
1	Rear keyless sensor	329.80
1	Rear bumper	1,385.00
2	Rear bumper brackets	169.80
1	Rear bumper inner sponge	156.30
1	Rear bumper lower diffuser	529.10
2	Rear bumper reflectors	103.00
2	Rear bumper side retainers	169.80
1	Rear floor panel	1,048.50
1	Rear floor board	655.20
1	Rear exhaust silencer	1,068.50
2	Rear exhaust mountings	97.00
1	Rear fender	1,446.90
2	Rear fender inner air vents	260.90
2	Rear fender inner shields	336.40
2	Rear fender inner trims	1,470.00
		\$ 16,592.80
Less 25%		\$ 4,148.20
		\$ 12,444.60



c/f:

\$

12,444.60

**SPECIAL NETT ITEMS**

1	Rear windscreen sealant	21	\$	80.00	40
1	Rear bumper clip (1 set)	21	\$	50.00	—
1	Rear number plate with holder	11	\$	50.00	X
1	Rear reverse sensor (1 set)	shuf	\$	350.00	200
1	Rear reverse camera	11	\$	480.00	X
1	Rear floor sound insulator	11	\$	180.00	X
				\$	1,190.00
					290

**S/N LABOUR CHARGES**

1	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	30
2	To remove and refit inner garnishes.		\$	150.00	100
3	To remove and refit rear reverse sensor and camera.		\$	180.00	50
4	To transfer rear tailgate mechanism and wiring assembly.		\$	120.00	80
5	To remove and refit rear windscreen glass.		\$	180.00	120
6	To remove, refit and replace exhaust silencer and mountings.	11	\$	150.00	X
7	To apply undercoating.		\$	200.00	60
8	Panel beating.		\$	1,800.00	800
9	To re-spray painting on the affected areas.		\$	1,600.00	1000
				\$	4,460.00
					2240

**GRAND TOTAL :****\$ 18,094.60**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 24 September 2018 10:18 AM  
**To:** Zoom Autowerks; Catherine Chong (LKK Auto); assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** Our Ref: 18/18/18/VP05/020931 RE: Pre-Repair Inspection for SDY 4942 B // Accident on 23/09/2018 @ 16:30HR at along PIE(Changi), before Paya Lebar Exit involving Vehicle Number SDY 4942 B & SGK 5739 D  
**Attachments:** SDY 4942 B.PDF

11.01am @ 24/9/18  
person @ Elin  
vehicle In

Without Prejudice  
Save as to Costs

Dear Sir/Mdm

Thank you for confirming the appointment of a Single Joint Expert.

Dear Catherine/Nivitha

Please arrange Marcus Chua to conduct the third party survey.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

**From:** Zoom Autowerks [mailto:zoomautowerks@gmail.com]  
**Sent:** Monday, 24 September, 2018 10:15 AM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG  
**Subject:** Re: Pre-Repair Inspection for SDY 4942 B // Accident on 23/09/2018 @ 16:30HR at along PIE(Changi), before Paya Lebar Exit involving Vehicle Number SDY 4942 B & SGK 5739 D

Dear Lili,

Please arrange Marcus Chua, thank you.

On Mon, Sep 24, 2018, 09:47 ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor

surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

**From:** Zoom Autowerks [mailto:[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)]

**Sent:** Monday, 24 September, 2018 9:34 AM

**To:** MT\_Claim\_SG

**Subject:** Pre-Repair Inspection for SDY 4942 B // Accident on 23/09/2018 @ 16:30HR at along PIE(Changi), before Paya Lebar Exit involving Vehicle Number SDY 4942 B & SGK 5739 D

Dear Sir/Madam,

We are instructed by Foo Lily to notify you of a road traffic accident on 23

/09/2018

at about 16:30HR at along PIE(Changi), before Paya Lebar Exit involving our client's vehicle registration number SDY 4942 B and vehicle registration number SGK 5739 D driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

**Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178**

**08.**

Warmest Regards,

**Elin Cai**

**Zoom Autowerks Pte Ltd**

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)

***- Please note our change in mailing/registered address with effect from 1st July 2018 -***

## Mei Kwan (LKKAUTO)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Thursday, 27 September, 2018 11:48 AM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** MT\_Claim\_SG; Vic (LKKAUTO)  
**Subject:** RE: Our Ref: 18/18/18/VP05/020931 RE: Pre-Repair Inspection for SDY 4942 B // Accident on 23/09/2018 @ 16:30HR at along PIE(Changi), before Paya Lebar Exit involving Vehicle Number SDY 4942 B & SGK 5739 D  
**Attachments:** 27092018114556.pdf  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
**Categories:** HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

**Sent:** Thursday, 27 September, 2018 11:25 AM

**To:** ONG LI LI

**Cc:** MT\_Claim\_SG; Admin A; Vic (LKKAUTO); Hsiao Tong (LKKAUTO)

**Subject:** RE: Our Ref: 18/18/18/VP05/020931 RE: Pre-Repair Inspection for SDY 4942 B // Accident on 23/09/2018 @ 16:30HR at along PIE(Changi), before Paya Lebar Exit involving Vehicle Number SDY 4942 B & SGK 5739 D

**'WITHOUT PREJUDICE'**

**SAVE AS TO COSTS**

**LPC ref: 18/18/18/VP05/020931**

**LKK REF: CC4/LPC18017424/Uha3**

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SDY 4942B

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Kindly let us have a copy of your insured's GIA report for our necessary action.

**From:** Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

**Sent:** Monday, 24 September, 2018 10:15 AM

**To:** ONG LI LI

**Cc:** MT\_Claim\_SG

**Subject:** Re: Pre-Repair Inspection for SDY 4942 B // Accident on 23/09/2018 @ 16:30HR at along PIE(Changi), before Paya Lebar Exit involving Vehicle Number SDY 4942 B & SGK 5739 D

Dear Lili,

Please arrange Marcus Chua, thank you.

On Mon, Sep 24, 2018, 09:47 ONG LI LI <[llong@lonpac.com](mailto:llong@lonpac.com)> wrote:

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

**Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178**

**08.**

Warmest Regards,

**Elin Cai**

**Zoom Autowerks Pte Ltd**

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)

**- Please note our change in mailing/registered address with effect from 1st July 2018 -**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)





## ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email: zoomautowerks@gmail.com | Contact: 9450 7920

Co. Reg No.: 201725603G

### PROFORMA INVOICE

To: **Lonpac Insurance Bhd.**  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

Invoice No. : ZP0000107  
Date : 4/10/2018  
VRN : SDY 4942 B  
Make & Model : Toyota Harrier  
DOA : 23/9/2018  
Terms : COD

S/N.	Description	Qty	U/P	Amt
1	Repair & Respray Accident Affected Portions			6,500.00
2	Loss of Rental (\$220.00 x 5Days)			1,100.00
3	LTA Search Fee			7.45

**TOTAL :**

**\$7,607.45**

I agree to the price as listed above and confirm that  
goods are received in good condition.



(Customer's Signature )

(by Zoom Autowerks Pte Ltd)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18017424/Uha3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 20-06-2019



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGK 5739D	Veh. Inspected	SDY 4942B
Policy No.	Z18VP05019633	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020931	Excess (\$)	0.00
Assign From	GERALD	Assign Date	24/09/2018

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600051510	Colour	WHITE
Odometer	56958	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	ACCEIERA	7 mm
L/H Front Tyre	235/55 R18	ACCEIERA	7 mm
R/H Rear Tyre	235/55 R18	ACCEIERA	7 mm
L/H Rear Tyre	235/55 R18	ACCEIERA	7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	23/09/2018	Inspection Date	24/09/2018
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDY 4942B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR WINDSCREEN MOULDING	NECESSARY	99.70	99.70
1	REAR TAILGATE	BADLY DENTED	1,669.00	1,669.00
2	REAR TAILGATE DAMPERS	NOT NECESSARY	523.20	-
1	REAR TAILGATE INNER BOARD	DEFORMED / TORN	455.20	455.20
1	REAR TAILGATE LOCK	SHORTED / DENTED	599.20	559.10
1	REAR TAILGATE LOGO	NOT NECESSARY	76.80	-
2	REAR TAILGATE REFLECTORS	NOT NECESSARY	889.00	-
1	REAR TAILGATE RUBBER	TWISTED	326.10	326.10
1	REAR TAILGATE "HARRIER" EMBLEM	NECESSARY	69.10	69.10
1	REAR TAILGATE OUTER MOULDING	NOT NECESSARY	226.50	-
1	REAR TAILGATE INNER HANDLE	NOT NECESSARY	136.90	-
1	REAR TAILGATE OUTER OPENING SWITCH	NOT NECESSARY	184.80	-
2	REAR TAILLAMPS	O/S CRACKED	1,138.20	569.10
1	REAR END PANEL	DENTED	717.20	717.20
1	REAR END PANEL INNER GARNISH	TWISTED	255.70	255.70
1	REAR KEYLESS SENSOR	SHORTED	329.80	329.80
1	REAR BUMPER	DISTORTED	1,385.00	1,385.00
2	REAR BUMPER BRACKETS	BENT	169.80	169.80
1	REAR BUMPER INNER SPONGE	TORN	156.30	156.30
1	REAR BUMPER LOWER DIFFUSER	DISTORTED	529.10	529.10
2	REAR BUMPER REFLECTORS	NOT NECESSARY	103.00	-
2	REAR BUMPER SIDE RETAINERS	BENT	169.80	169.80
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,048.50	-
1	REAR FLOOR BOARD	NOT NECESSARY	655.20	-
1	REAR EXHAUST SILENCER	NOT NECESSARY	1,068.50	-
2	REAR EXHAUST MOUNTINGS	NOT NECESSARY	97.00	-
1	REAR FENDER	NOT NECESSARY	1,446.90	-
2	REAR FENDER INNER AIR VENTS	NOT NECESSARY	260.90	-
2	REAR FENDER INNER SHIELDS	NOT NECESSARY	336.40	-

Report Ref No. CC4/LPC18017424/Uha3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIMS	NOT NECESSARY	1,470.00	-
	LESS 25% DISCOUNT		-4,148.20	-1,865.00
			12,444.60	5,595.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	SHORTED	350.00	200.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-
1	REAR FLOOR SOUND INSULATOR (SN)	NOT NECESSARY	180.00	-
			1,190.00	290.00
	<b><u>LABOUR</u></b>			
	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES.		150.00	100.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA.		180.00	50.00
	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY.		120.00	80.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	NOT NECESSARY	150.00	-
	TO APPLY UNDERCOATING.		200.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,800.00	800.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,600.00	1,000.00
			4,460.00	2,240.00
	<b>GRAND TOTAL</b>		<b>18,094.60</b>	<b>8,125.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,500.00</b>

Report Ref No. CC4/LPC18017424/Uha3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.