



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130  
Tel: 9450 7920  
\* zoomautowerks@gmail.com

25 September 2018

REG NO.: SDY 4942 B  
MAKE/MODEL: TOYOTA HARRIER

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	99.70
1	Rear tailgate	1,669.00
2	Rear tailgate dampers	523.20
1	Rear tailgate inner board	455.20
1	Rear tailgate lock	599.20
1	Rear tailgate logo	76.80
2	Rear tailgate reflectors	889.00
1	Rear tailgate rubber	326.10
1	Rear tailgate "HARRIER" emblem	69.10
1	Rear tailgate outer moulding	226.50
1	Rear tailgate inner handle	136.90
1	Rear tailgate outer opening switch	184.80
2	Rear taillamps	1,138.20
1	Rear end panel	717.20
1	Rear end panel inner garnish	255.70
1	Rear keyless sensor	329.80
1	Rear bumper	1,385.00
2	Rear bumper brackets	169.80
1	Rear bumper inner sponge	156.30
1	Rear bumper lower diffuser	529.10
2	Rear bumper reflectors	103.00
2	Rear bumper side retainers	169.80
1	Rear floor panel	1,048.50
1	Rear floor board	655.20
1	Rear exhaust silencer	1,068.50
2	Rear exhaust mountings	97.00
1	Rear fender	1,446.90
2	Rear fender inner air vents	260.90
2	Rear fender inner shields	336.40
2	Rear fender inner trims	1,470.00
		\$ 16,592.80
Less 25%		\$ 4,148.20
		\$ 12,444.60

c/f:

\$

12,444.60

SPECIAL NETT ITEMS

1	Rear windscreen sealant	21	\$	80.00	40
1	Rear bumper clip (1 set)	21	\$	50.00	—
1	Rear number plate with holder	11	\$	50.00	X
1	Rear reverse sensor (1 set)	shuf	\$	350.00	200
1	Rear reverse camera	11	\$	480.00	X
1	Rear floor sound insulator	11	\$	180.00	X
				\$	1,190.00
				290	

S/N      LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	30
2	To remove and refit inner garnishes.		\$	150.00	100
3	To remove and refit rear reverse sensor and camera.		\$	180.00	50
4	To transfer rear tailgate mechanism and wiring assembly.		\$	120.00	80
5	To remove and refit rear windscreen glass.		\$	180.00	120
6	To remove, refit and replace exhaust silencer and mountings.	11	\$	150.00	X
7	To apply undercoating.		\$	200.00	60
8	Panel beating.		\$	1,800.00	800
9	To re-spray painting on the affected areas.		\$	1,600.00	1000
				\$	4,460.00
				2240	

GRAND TOTAL :

\$ 18,094.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: