

INS. CASE OWNER:

Wany Kuan | CC 4, Asm 180 15428, Upay,

LAC:
IDAC:

71695

Surveyor:

mteew

DOI:

ASSIGNMENT

25/9/18

Date / Time:

25/9/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHP 663K

Name of Insured:

Tom-Cab Srs P/L

Insured Tel No.:

HP:

Excess Sec II :\$

5,000.00

D.O.A.:

1-9-18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Sm Moses

Driver Tel No.:

94231633

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

VP 2/P1 680520

K. Latitude

Bukit Merah Central

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

KPS



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

25/9

CH

Tel 48381

SHP 663K

to reject 70 claim.

18/10/18 - Email to IP. Reqt.

3/11/18 - RCPass to Mark Kuan to close

Reluct Case

14-10-18

400

Hare Ting

RECEIVED 03 DEC 2018

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to CI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to CI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

26/11

Sent By:

mteew

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(\$

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

Email

Call

Repair Cost:

\$

Loss of Rental (LOR):

\$

(\$

days)

Loss of Use (LOU):

\$

(\$

x

days)

Loss of Income (LOI):

\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

\$

Medical:

\$

Disbursement:

\$

Legal Cost:

\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

350.00

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: F3L4838Lat Workshop m/s KES Kelen

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒ N/S	☐ O/S
☐	☐

Bal. or Market Value: plc.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or NoCA / REV / REP. / 24 HRS ATA 5154

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: F3L4838L Yr Regn: 1/1/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda AFS125 c.c. 125Colour: Black A/C: Insured / Std / NI / NASp. Reading: 30693 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MLHJA213665000890Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 80-90-57R: 90-80-177

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 25/9/18

Survey held at: _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S, Fnt, O/S, B.L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L/S \$ 850 Cred \$ 1035/57%.

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6343K
Vehicle Details	
Vehicle No.:	FBL4838L
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Sep 2018
Vehicle Make:	HONDA
Vehicle Model:	AFS125MSF
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	JA213E2000990
Chassis No.:	MLHJA2136G5000990
Maximum Power Output:	-
Open Market Value:	\$1,780.00
Original Registration Date:	07 Nov 2016
First Registration Date:	07 Nov 2016
Transfer Count:	1
Actual ARF Paid:	\$267.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,353.00
COE Rebate Amount:	\$5,154.00
Total Rebate Amount:	\$5,154.00

The information contained herein is correct as at 26 Sep 2018

OK



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

not Allowed
state
various
tel: 62533561
Take photo After repair
25/9/18

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 24-09-2018

VEHICLE NO. : FBL4838L
ACCIDENT DATE : 11-09-2018 16:45
THIRD PARTY REF. : SHF663K

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE FBL4838L HONDA WAVE 125

QTY PARTS DESCRIPTION

AMOUNT (SGD)

1	1	MUFFLER PROTECTOR
2	2	FRONT SIGNAL LAMP @\$65.00
3	1	SIDE COWLING (LH)
4	1	FRONT FENDER
5	1	FRONT FORK ASSY
6	1	STEERING CONE && BEARING
7	1	HORN COVER
8	1	SIDE MIRROR (LH)
9	1	GEAR PEDAL
10	1	FRONT FOOTREST BAR
11	1	METER COVER
12	1	BASKET
13	1	HEAD LAMP
14	1	HEAD LAMP COVER

SEA	95.00	—
MS/SNO	130.00	170 LH
CN7/CN	160.00	—
n	65.00	x
n	250.00	x
n	65.00	x
cm	68.00	—
CN7	58.00	—
n	52.00	x
SH	68.00	—
n	75.00	x
CN	56.00	—
cm	88.00	—
n	80.00	x
1,300.00		
LESS 3 x 102		
65.00		
TOTAL (A)		1,235.00

LABOUR CHARGES

1	1	TO press FORK ASSY <i>realign</i>	200.00	Ro
2	1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD/CUT, PANEL BE- ATING & RENEW PARTS	250.00	200



簡福星噴漆工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6261 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : FEL4838L
ACCIDENT DATE : 11-08-2018 16:45
THIRD PARTY REF. : SHP663K

#	QTY	PARTS DESCRIPTION
3	1	SPRAY PAINTING

AMOUNT (SG\$)

200.00

TOTAL (D)

650.00

ESTIMATE TOTAL

1,885.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Service Request Details

Claim

S8M00WRS

Reference

None

Loss Date

September 11, 2018

Request Date

September 25, 2018

Due Date

October 2, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Look for Lucy at Blk 1 Kaki Bukit Ave 6 #01-13
25092018 @ 11:44am
Alie veh in

marus.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration

FBL4838L

Make

TPVD HONDA

Model

WAVE 125

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Hsiao Tong (LKKAuto)


From: Hsiao Tong (LKKAuto)
Sent: Thursday, 18 October 2018 2:28 PM
To: 'alicechau@kanfs.net'
Cc: Admin A
Subject: RE: RE: FBL4838L (TP) - Liability *** LKK REF: CC4/ASM18017428/Upa3

Without Prejudice

Hi Sirs,

We refer to the above matter.

We regret to inform your that we have our principal instruction to deny liability based on BOLA scenario 33.

	T-JUNCTION			
33.		Vehicle X- Overtaking from the right Vehicle Y- Changing lane or turning Reason: Vehicle should not overtake from the right against the flow of traffic	100%	0%

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: alicechau <alicechau@kanfs.net>
Sent: Tuesday, 9 October 2018 10:41 AM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Fw: RE: FBL4838L (TP) - Liability *** LKK REF: CC4/ASM18017428/Upa3

Dear Hsiao Tong,

We refer to the mentioned claim.

Kindly advise on the liability.

Thank you.

Regards,
Alice
Kan Fook Sing Motor Workshop
Tel:6747 9560
Fax:6748 1006

----- Forwarded Message -----

From:"alicechau" <alicechau@kanfs.net>
To:"Mei Kwan (LKKAuto)" <Meikwan@lkkauto.com>, "Hsiao Tong (LKKAUTO)" <chewht@lkkauto.com>
Cc:admin-a@lkkauto.com
Sent:Tue, 2 Oct 2018 16:35:15 +0800
Subject:RE: FBL4838L (TP) - Liability *** LKK REF: CC4/ASM18017428/Upa3

Dear Mei Kwan & Hsiao Tong,

Attached herewith accident photos for your reference.

Please click the below link for the witness video:

<https://drive.google.com/open?id=17GuXFD4tem4tsKKB2su5n2zxR4aTh5as>

<https://drive.google.com/open?id=1LXMV2W0RDLTrGtyfMWp9IfIXTWuaL96N>

Kindly advise on the liability.

Thank you.

Regards,
Alice
Kan Fook Sing Motor Workshop
Tel:6747 9560
Fax:6748 1006

----- Original Message -----

From:"Mei Kwan (LKKAuto)" <Meikwan@lkkauto.com>
To:"alicechau@kanfs.net" <alicechau@kanfs.net>
Cc:Admin A <admin-a@lkkauto.com>, "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>
Sent:Tue, 25 Sep 2018 08:26:41 +0000
Subject:RE: FBL4838L (TP) - Liability *** LKK REF: CC4/ASM18017428/Upa3

> **'WITHOUT PREJUDICE'**

> **SAVE AS TO COSTS**

>

> Dear Sir / Madam,


>

> We refer to the above matter.

- >
- > Please be informed that we are currently **pending verification for direct settlement.**
- >
- > Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.
- >

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attached AIA Report

- >
- >

Circumstances of Accident

On 11.09.2018 at about 1700hours, I was travelling straight along Bukit Merah Central when I made a stop to check for oncoming vehicle, when I check there's no oncoming vehicle, I slowly made a right turn with right signal on. Suddenly I felt an impact. Vehicle B (FBL4838L) came at a fast speed and hit onto my taxi's right side portion

- >
- > **Please provide us the evidence i.e. video/ scene photo.**
- >
- > Please note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.
- >
- > Our respective case handler will look into the matter and revert to you in due course.
- >
- > **To check availability of the case handler, you may contact the undersigned.**
- >
- > Thank you.
- > Best Regards,
- > **Mei Kwan | Admin**
- > **LKK Auto Consultants Pte Ltd**
- > Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
- > Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
- >
- >
- > **From:** alicechau <alicechau@kanfs.net>
- > **Sent:** Tuesday, 25 September, 2018 2:06 PM
- > **To:** Admin A <admin-a@lkkauto.com>
- > **Subject:** FBL4838L (TP) - Liability

>
> Dear Sirs,
>
> Accident involving vehicle FBL4838L & SHF663K on 11-09-2018
>
> We refer to the above-mentioned accident.
>
> Kindly advise on liability.
>
> Thank you.
>
> Regards,
> Alice
> Kan Fook Sing Motor Workshop
> Tel:6747 9560
> Fax:6748 1006

----- End of Original Message -----

----- End of Forwarded Message -----



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18017428/Upa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WANG PETER		Date : 12-12-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHF 663K	Veh. Inspected	FBL 4838L	
Policy No.	VPX/P1680520	Coverage (\$)	0.00	
Claim No.	S8M00WRS	Excess (\$)	0.00	
Assign From		Assign Date	25/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA AFS125	c.c	125	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MLHJA2136G5000990	Colour	BLACK	
Odometer	30693	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80-90-17	MICHELIN	7 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90-80-17	MICHELIN	7 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/09/2018	Inspection Date	25/09/2018	
Survey held at	KAN FOOK SING MOTOR WORKSHOP 1 KAKI BUKIT AVE 6 #01-108/ #01-13 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 4838L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	MUFFLER PROTECTOR (CONSISTENT)	SCRATCHED	85.00	85.00
2	FRONT SIGNAL LAMP @\$65.00 (CONSISTENT)	N/S BROKEN	130.00	65.00
1	SIDE COWLING (LH) (CONSISTENT)	CUT / CRACKED	160.00	160.00
1	FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	65.00	-
1	FRONT FORK ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	STEERING CONE & BEARING (CONSISTENT)	NOT NECESSARY	65.00	-
1	HORN COVER (CONSISTENT)	CRACKED	68.00	68.00
1	SIDE MIRROR (LH) (CONSISTENT)	CUT	58.00	58.00
1	GEAR PEDAL (CONSISTENT)	TO REPAIR SEE LABOUR	52.00	-
1	FRONT FOOTREST BAR (CONSISTENT)	BENT	68.00	68.00
1	METER COVER (CONSISTENT)	TO REPAIR SEE LABOUR	75.00	-
1	BASKET (CONSISTENT)	CRACKED	56.00	56.00
1	HEAD LAMP (CONSISTENT)	CRACKED	88.00	88.00
1	HEAD LAMP COVER (CONSISTENT)	TO REPAIR SEE LABOUR	80.00	-
	LESS 5% DISCOUNT		-65.00	-
	LESS 10% DISCOUNT		-	-64.80
			1,235.00	583.20
LABOUR				
	TO REALIGN FORK ASSY .		200.00	80.00
	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS,WELD/CUT,PANEL BEATING & RENEW PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER,FRONT FORK ASSY,GEAR PEDAL,METER COVER AND HEAD LAMP COVER.		250.00	200.00
	SPRAY PAINTING.		200.00	200.00
			650.00	480.00
GRAND TOTAL			1,885.00	1,063.20

Report Ref No. CC4/ASM18017428/Upa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			850.00
---	--	--	--------

Report Ref No. CC4/ASM18017428/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

884000WRS

Reference

CC-A/ASM10017420/Upa3u2

Loss Date

11 September 2018

Request Date

25 September 2018

Claim Date

Vendor Name

LAK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

FBL483BL

Make

TPVD HONDA

Model

WAVE 125

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

WANG Peter

peter.wang@laxa.com.sg

Actions

Next Step

Wait for Approve Invoice

Add to notes

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type		Document Subtype				
+ Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
LAKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LAK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Inspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 LKK Adjustment 1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 December 2018
 Email to TP_Reject dkl 181018.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2018
 LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2018
 LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 December 2018
 TP ESTIMATE - MAILED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	1 October 2018
 Google map screenshot - 1 line only.JPG	Evidence	Others	WANG Peler	27 September 2018
 SHE663K INSD GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	25 September 2018
 FTBL483BL TP GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragati	25 September 2018
 PRI EMAIL RECEIVED FROM WORKSHOP.png	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	25 September 2018