



# 簡福星摩呀王廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147  
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428  
 E-mail: ryan@kanfs.net/ patricia@kanfs.net  
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883  
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

*not allowed  
 take photo after repair  
 25/9/18*

AXA INSURANCE SINGAPORE PTE LTD  
 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 24-09-2018

VEHICLE NO. : FBL4838L  
 ACCIDENT DATE : 11-09-2018 16:45  
 THIRD PARTY REF. : SHF663K

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE FBL4838L HONDA WAVE 125

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	MUFFLER PROTECTOR	85.00
2	2	FRONT SIGNAL LAMP @\$65.00	130.00
3	1	SIDE COWLING (LH)	160.00
4	1	FRONT FENDER	65.00
5	1	FRONT FORK ASSY	250.00
6	1	STEERING CONE && BEARING	65.00
7	1	HORN COVER	68.00
8	1	SIDE MIRROR (LH)	58.00
9	1	GEAR PEDAL	52.00
10	1	FRONT FOOTREST BAR	68.00
11	1	METER COVER	75.00
12	1	BASKET	56.00
13	1	HEAD LAMP	88.00
14	1	HEAD LAMP COVER	80.00
			1,300.00
LESS 5% 102			65.00
TOTAL (A)			1,235.00

LABOUR CHARGES

1	1	TO <del>press</del> FORK ASSY <i>realign</i>	200.00
2	1	REMOVE ALL NECESSRAY AFFECTED PARTS FOR REPAIRS, WELD/CUT, PANEL BE- ATING & RENEW PARTS	250.00



# 簡福星噴呔王廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147  
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428  
 E-mail: ryan@kanfs.net/ patricia@kanfs.net  
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883  
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : FBL4838L  
 ACCIDENT DATE : 11-09-2018 16:45  
 THIRD PARTY REF. : SHF663K

#	QTY	PARTS DESCRIPTION
3	1	SPRAY PAINTING

AMOUNT (SG\$)
200.00

TOTAL ( D )

650.00
--------

ESTIMATE TOTAL

1,885.00
----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: