



Your Ref: C0468884

Date: 18th October 2018

Our Ref: CS3/AXA18001787/Grbs2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

Attn: Wong Wee Fu

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO SLC 1994S
INSURED VEHICLE: SHB 9926P ACCIDENT DATE: 25/01/2018**

We thank you for your instruction on 25/09/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLC 1994S from M/s PAR Automotive Consultancy.
- b) Final Repair Bill of SLC 1994S from M/s TwinCar Automotive Pte Ltd.
- c) Colour damaged vehicle photographs of SLC 1994S.

Pre-Repair Inspection Date : 30/01/2018 at M/s TwinCar Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLC 1994S
Make & Model	: Toyota Lexus RX450H
Year of Registration	: 2009
Chassis Number	: JTBC11A402015860
Engine Capacity	: 3456 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.